

Information

ASS. REC. BY:

REF CS/INC19006789/71903

Special Instructions:

Surveyor:

Wukh

ASSIGNMENT (Office)

From (Person):

Annie Koh

of

INC

Date/Time: 16/4/19 @ 9:47am

Estimated Cost:

Bill to:

OD ☒ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMJ 1436M

Insured:

SDA 8856S

at Workshop m/s

BP Auto

Tel:

6266 0555

of

48 Joh Guan Rd East # 01-121

Policy No:

Claim No:

MT/1040072-002

Sum Insured:

Excess:

D.O.A 12/4/2019

Make of Veh:

H.O.D. Endorsement:

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time:

9:58am 16/4/19

Person Contacted:

Yvonne

Vehicle ☒ INT ☐ EXT

Date/Time	Action/Instruction (✓) Estimate
	SMJ 1436M - X
	SDA 8856S - NA / TP I TP 016071/h +

20A: 22/4/19

Surveyor *Tariff*

REF: INC

ASSIGNMENT

From: Date: 16/4/19

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMJ 1436M

at Workshop n/s

of 48 toh Guan Rd East #01-121

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 up}

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SMJ 1436M Yr Regn: 219 Feb

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avante

c.c

1591

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading:

1471

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KM HDS41 CMK4866154

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

7

mm

R/Bal.

2

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

D.O.I.

16/4/19 5.20pm

Survey held at

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

4/5/7700 8 days submit *unconfirm*
(Red P 8579.52 53%)

RECEIVED 18 OCT 2019

Date/Time, File Pass to?

☐

: Preli. Report

1) 18/10 *train*

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

) Photos

) Others

TOTAL

Report Format:

Lump Sum / L.B.I. (\$

TP

7700

Unconfirmed

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 16 April 2019 9:55 AM
To: 'assignments@lkkauto.com'
Cc: Thio Tse Kiat; Teng Ken Leong
Subject: RE: TP CASES FARMED OUT TO LKK ON 16/04/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 16 April 2019 9:47 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 16/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	OI VEH	DOA	Additional Remarks
1	Serene Lim	MT/1040072-002	SMJ1436M	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	/ 6266 0555		SDA8856S	12/4/19	
2	Muhammad Airwan	MT/1032714-002	SKW3185D	HUA HONG PTE LTD	25D SUNGEI KADUT STREET 1 SINGAPORE 729332	Jerleen / Mrs Tan / 6661 9688	14:00-16:00	YP130C	18/2/19	
3	David Phua	MT/1034482-002	SLM4505Z	MUNICH AUTOMOBILES PTE LTD	30 TEBAN GARDENS CRESCENT SINGAPORE 608927	Tan Kok Ting / 6566 7666	13:00-15:00	SKA5008K	2/3/19	9051 5581

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh

Senior Admin Assistant, Motor Insurance

T +65 6430 7899

www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/04/2019 16:33
Date Of Accident	12/04/2019 09:45
Exact Location Of Accident	ALONG DUNEARN RD TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ1436M
Insured/Policyholder	
Name Of Registered Owner	YANG LIU
NRIC No	S8169564D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97859502
Alternative Phone No	OTHERS-97859502

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AD AVANTE 1.6 GLS (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN034796
Cover Note Number	

Driver

Name of Driver	YANG LIU
NRIC No	S8169564D
Date Of Birth	21/05/1981
Occupation	INDOOR
Date Of Driving Pass	22/08/2013
Driving Experience	5 YEARS AND 7 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-97859502
Fax Number	
Contact Number	OTHERS-97859502
Email Address	NOEMAIL

Address	103 CLEMENTI STREET 14 #12-127 SPORE 120103
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDA8856S
Vehicle Make/Model/Colour	HONDA VEZEL 1.5X CVT
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.




II. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: 
NRIC/IN No.: 

16. Sep. 2019 11:58

62973839

Date	No.
SMJ 1436 M	
Hyundai Avante	List
KM HD 841 CM KU 866154	
Front Door RH	1831.10
Rear Door RH	1775.20
Rear Door Inner Trim Board RH	497.90
Rear Fender RH	1768.30
Rear 16" Sport Rim RH	1091.50

Pls help to check "List"

To: Kiat Mang

From: SK Automobile

SK AUTOMOBILE PTE LTD
ROC No: 201500007H
41 TGH Ocean Road East #01-121
Enterprise Hub, Singapore 068508
Tel: 6266 0555 Fax: 6266 3155
Email: yvonne@sk-auto.com.sg

BP Auto
(UEN No. 53378133K)
48 Toh Guan East #01-121
Toh Guan Enterprise, S (608566)
Tel: 6266 0555 Fax : 6266 3155

TO	: NTUC INCOME INSURANCE	DATE	: 15-Apr-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT :			
OWNER PARTICULAR		VEHICLE DETAILS	
NAME	:	VEHICLE NO.	: SMJ1436M
ADDRESS	:	MODEL / MAKE	: HYUNDAI AD AVANTE
TEL. NO.	:	CHASSIS NO.	: KMHD841CMKU866154
OWNER INSURANCE	: AXA INSURANCE PTE LTD	ACCIDENT DETAIL	
POLICY NO.	: CN034796	DATE	: 12-Apr-19
		TIME	: 09:45 Hrs
PERSON INCHARGE :			

QUOTATION SUMMARY **PAGE 01**
CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR RH	1	\$ 1,931.30	\$ bt 1,931.30
2	FRONT DOOR BLACK FRAME STICKER 'HORIZONTAL' RH	1	\$ 28.40	\$ ne 28.40
3	FRONT DOOR BLACK FRAME STICKER 'VERTICAL' RH	1	\$ 22.60	\$ ne 22.60
4	FRONT DOOR GLASS OUTER MOULDING RH	1	\$ 109.60	\$ xm 109.60
5	FRONT DOOR MECHANISM LOCK RH	1	\$ 225.60	\$ bt 225.60
6	FRONT DOOR RUBBER GIUDE STOPPER RH	2	\$ 23.40	\$ xm 46.80
7	FRONT DOOR WEATHER STRIP RH	1	\$ 143.20	\$? 143.20
8	REAR DOOR RH	1	\$ 1,875.30	\$ bt 1,875.30
9	REAR DOOR BLACK FRAME STICKER 'HORIZONTAL' RH	1	\$ 28.40	\$ ne 28.40
10	REAR DOOR BLACK FRAME STICKER 'VERTICAL' RH	1	\$ 22.60	\$ ne 22.60
11	REAR DOOR GLASS OUTER MOULDING RH	1	\$ 109.60	\$ xm 109.60
12	REAR DOOR HINGES TOP & LOWER RH	2	\$ 51.30	\$ i 102.60
13	REAR DOOR INNER TRIM BOARD RH	1	\$ 597.20	\$ crav 597.20
14	REAR DOOR POWER WINDOW SUPPORT BOARD RH	1	\$ 294.20	\$ crav 294.20
15	REAR DOOR POWER WINDOW MOTOR RH	1	\$ 389.40	\$ xm 389.40
16	REAR DOOR RUBBER GUIDE STOPPER RH	2	\$ 23.40	\$ xm 46.80
17	REAR DOOR MECHANISM LOCK RH	1	\$ 225.60	\$ xm 225.60
18	REAR DOOR WEATHER STRIP RH	1	\$ 143.20	\$? 143.20
19	REAR DOOR STEP GARNISH RH	1	\$ 179.40	\$ xm 179.40
20	REAR FENDER RH	1	\$ 1,968.40	\$ bt 1,968.40
21	REAR FENDER INNER SHIELD RH	1	\$ 165.40	\$ ne 165.40
22	REAR WINDSCREEN MOULDING	1	\$ 199.70	\$ ax 199.70
23	ROCKER SIDE PANEL 'OUTER' RH	1	\$ 1,899.40	\$ Rx 1,899.40
24	REAR BUMPER	1	\$ 594.60	\$ de 594.60
25	REAR BUMPER SIDE RETAINER RH	1	\$ 49.30	\$ x 49.30
26	REAR BUMPER INNER SIDE SHIELD RH	1	\$ 179.80	\$ xm 179.80
27	REAR SUSPENSION SHOCK ABSORBER RH	1	\$ 289.60	\$ xm 289.60

188.10
 *bt
 ne
 1775.20
 *x
 *bt
 497.20
 *crav
 *x
 ne
 1768.30
 ne
 de
 ne

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	REAR SUSPENSION WHEEL HUB RH	1	\$ 465.10	\$ M X 465.10
29	REAR SUSPENSION WHEEL HUB BEARING RH	1	\$ 591.20	\$ M X 591.20
30	REAR 16" SPORT RIM RH	1	\$ 987.60	\$ act 987.60

TOTAL PRICE \$ 13,911.90

LESS -20% \$ (2,782.38)

SUB TOTAL PRICE \$ 11,129.52

8871.20

7103.36

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR DOOR INNER TRIM BOARD CLIPS SET RH <i>NEC</i>	1	\$ 60.00	\$ 30 60.00
2	REAR DOOR STEP GARNISH CLIPS SET RH	1	\$ 30.00	\$ X M 30.00
3	REAR FENDER SEALANT RH <i>NEC</i>	1	\$ 120.00	\$ 40 120.00
4	REAR FENDER INNER SHIELD CLIPS SET RH	1	\$ 60.00	\$ X M 60.00
4	REAR WINDSCREEN SEALANT WITH PRIMER	1	\$ 100.00	\$ 40 100.00
5	ROCKER SIDE PANEL SEALANT RH	1	\$ 100.00	\$ 40 100.00
6	REAR BUMPER CLIPS SET	1	\$ 60.00	\$ X M 60.00

TOTAL

\$ 530.00

150.

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,600.00	1000.	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,400.00	900.	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 120.00	40.	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30.	
TO DISMANTLE & REINSTALL FRONT DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	60.	
TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	60.	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	120.	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	30.	
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	\$ 250.00	150? ^{Xm.}	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 80.00	60.	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	60.	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	20.	

TOTAL

\$ 4,620.00

2380.

QUOTATION SUMMARY

PAGE 04

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	11,659.52
TOTAL LABOUR COST	:	\$	4,620.00
TOTAL REPAIR COST	:	\$	16,279.52

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

7103.36
150
2380
9633.36
20% - 7706.70
4154 7700
17/4/19

Taughlin 97495749
16/4/19 e 1715
wp
Lumpsum
Resurvey after repair
suvekkauto.com
8 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19006789/T1qd3s2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 21-10-2019



ATTN: SERENE LIM

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SDA 8856S	Veh. Inspected	SMJ 1436M
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1040072-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	16/04/2019

2. Vehicle Particulars & Condition

Make & Model	HYUNDAI AVANTE	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	KMHD841CMKU866154	Colour	WHITE
Odometer	1471 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEXEN	7 mm
L/H Front Tyre	195/65 R15	NEXEN	7 mm
R/H Rear Tyre	195/65 R15	NEXEN	7 mm
L/H Rear Tyre	195/65 R15	NEXEN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	12/04/2019	Inspect Date / Time	16/04/2019 (05:20 PM)
Survey held at	BP AUTO 48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	8 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 1436M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT DOOR RH	BENT	1,931.30	1,831.10
1	FRONT DOOR BLACK FRAME STICKER 'HORIZONTAL' RH	NECESSARY	28.40	28.40
1	FRONT DOOR BLACK FRAME STICKER 'VERTICAL' RH	NECESSARY	22.60	22.60
1	FRONT DOOR GLASS OUTER MOULDING RH	NOT NECESSARY	109.60	-
1	FRONT DOOR MECHANISM LOCK RH	BENT	225.60	225.60
2	FRONT DOOR RUBBER GUIDE STOPPER RH @ \$23.40	NOT NECESSARY	46.80	-
1	FRONT DOOR WEATHER STRIP RH	NECESSARY	143.20	143.20
1	REAR DOOR RH	BENT	1,875.30	1,775.20
1	REAR DOOR BLACK FRAME STICKER 'HORIZONTAL' RH	NECESSARY	28.40	28.40
1	REAR DOOR BLACK FRAME STICKER 'VERTICAL' RH	NECESSARY	22.60	22.60
1	REAR DOOR GLASS OUTER MOULDING RH	NOT NECESSARY	109.60	-
2	REAR DOOR HINGES TOP & LOWER RH @ \$51.30	BENT	102.60	102.60
1	REAR DOOR INNER TRIM BOARD RH	CRACKED	597.20	497.20
1	REAR DOOR POWER WINDOW SUPPORT BOARD RH	CRACKED	294.20	294.20
1	REAR DOOR POWER WINDOW MOTOR RH	NOT NECESSARY	389.40	-
2	REAR DOOR RUBBER GUIDE STOPPER RH @ \$23.40	NOT NECESSARY	46.80	-
1	REAR DOOR MECHANISM LOCK RH	NOT NECESSARY	225.60	-
1	REAR DOOR WEATHER STRIP RH	NECESSARY	143.20	143.20
1	REAR DOOR STEP GARNISH RH	NOT NECESSARY	179.40	-
1	REAR FENDER RH	BENT	1,968.40	1,768.30
1	REAR FENDER INNER SHIELD RH	NECESSARY	165.40	165.40
1	REAR WINDSCREEN MOULDING	NECESSARY	199.70	199.70
1	ROCKER SIDE PANEL 'OUTER' RH	TO REPAIR SEE LABOUR	1,899.40	-
1	REAR BUMPER	DEFORMED	594.60	594.60
1	REAR BUMPER SIDE RETAINER RH	NECESSARY	49.30	49.30
1	REAR BUMPER INNER SIDE SHIELD RH	NOT NECESSARY	179.80	-
1	REAR SUSPENSION SHOCK ABSORBER RH	NOT NECESSARY	289.60	-
1	REAR SUSPENSION WHEEL HUB RH	NOT NECESSARY	465.10	-
1	REAR SUSPENSION WHEEL HUB BEARING RH	NOT NECESSARY	591.20	-
1	REAR 16" SPORT RIM RH	CUT	987.60	987.60

Report Ref No. CS/INC19006789/T1qd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-2,782.38	-1,775.84
			11,129.52	7,103.36
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR DOOR INNER TRIM BOARD CLIPS RH (SN)	NECESSARY	60.00	30.00
1	SET REAR DOOR STEP GARNISH CLIPS RH (SN)	NOT NECESSARY	30.00	-
1	REAR FENDER SEALANT RH (SN)	NECESSARY	120.00	40.00
1	SET REAR FENDER INNER SHIELD CLIPS RH (SN)	NOT NECESSARY	60.00	-
1	REAR WINDSCREEN SEALANT WITH PRIMER (SN)	NECESSARY	100.00	40.00
1	ROCKER SIDE PANEL SEALANT RH (SN)	NECESSARY	100.00	40.00
1	SET REAR BUMPER CLIPS (SN)	NOT NECESSARY	60.00	-
			530.00	150.00
	<u>LABOUR</u>			
	TO DISMANTLE & REOLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF ROCKER SIDE PANEL 'OUTER' RH.		1,600.00	1,000.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POILISHING AFFECTED AREA.		1,400.00	900.00
	TO APPLY ANTI-RUST & TUFF KOTE.		120.00	40.00
	TO PERFORM LIGHTING & WIRING CHECK.		80.00	30.00
	TO DISMANTLE & REINSTALL FRONT DOOR INNER COMPARTMENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING.		250.00	60.00
	TO DISMANTLE & REINSTALL REAR DOOR INNER COMPARTMENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING.		250.00	60.00
	TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST.		150.00	120.00
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR DISTANCE SETTING.		80.00	30.00
	TO DISMANTLE & REPLACED REAR UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS.	NOT NECESSARY	250.00	-
	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT.		80.00	60.00
	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR.		280.00	60.00

Report Ref No. CS/INC19006789/T1qd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION.		80.00	20.00
			4,620.00	2,380.00
GRAND TOTAL			16,279.52	9,633.36
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (UNCONFIRM)				7,700.00

Report Ref No. CS/INC19006789/T1qd3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.