

ASS. REC. BY:

REF: CS/CT1 19006794/JS d302 Special Instruction:

Conveyer: HWI JIL

ASSIGNMENT (Office)

Minimum

From (Person): Irene Tay Hui Ring of CT1

Date/Time: 16.4.19 15.36 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMD 9155 C

Insured: SJT 6046E

at Workshop m/s Torque 5 Bodyworks

Tel: 64524457

of 8 Kati Butia Ave 4, #01-49

Policy No: DMPCSN 3020751801

Claim No: SNM19D201656002

Sum Insured:

Excess:

Make of Veh:

D.O.A. 13.4.2019

(Client's Record)

17.4.2019. ✓

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 16.4.19 4.18pm Person Contacted:

Bach

Vehicle IN/OUT

Date/Time	Action/Instruction Estimate (✓)
	SMD 9155 C -X
	SJT 6046 E -X

Surveyor Huee Jie

REF: CT1

ASSIGNMENT

From:

Date 17. 4. 2019

Veh No:

SMD 9155C

Yr Regn:

12 Sep 2018

Estimated Cost:

Type: ☒ M/Car / ☐ M/Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

OD ☒ (TP) WS / ☐ TP RES / ☐ OD RES / ☐ EVA / ☐ INV / ☐ MV

Truck / Trailer or

To inspect Vehicle No:

SMD 9155C

Make:

Hyundai Elantra

cc 1591

at Workshop m/s

Torque 5 Bodyworks

Colour

silver

A/C: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

of

8 Kaki Bukit Ave 4, #01-49

Sp. Reading

5048

T/Radio: ☐ Insured / ☐ Std / ☐ NI / ☐ NA

Insured:

Eng/No:

Policy No.

C/No:

KMHD841CMJU748464

Claims No.

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Sum Insured:

Excess:

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

(Client's Record)


Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Make of Veh:

Modi:

Nil / STD A/Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size:

F: 195/65R15

R:

BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / ☐ YOKO or

Nexen

Bal. or Market Value:

\$68K

Front

Rear

IDAC Accident Report:

Consistent? : Yes or No

R/Bal.

6

mm

R/Bal.

6

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

6

mm

L/Bal.

6

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

13/4/19

D.O.I.

17/4/19

Lum Sum:

%

3 Val: Yes or No

Survey held at

Torque 5

CA / REV / REP. / 24 HRS

"wp"

Des. of Damages: ☒ ☐ Red / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

Vehicle: IN / OUT

Date:

Person Contacted:

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Confirmed L/S \$9500/- 7 days of repair.
(\$ 21,460.90 Red - 69%)

RECEIVED 27 JUN 2019

[Signature]

21/6/2019

Date/Time, File Pass to?

27/06/19

☐

: Preli. Report

1) Typist

☒

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

220

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

220

Report Format :

Lump Sum / I.B.I. (\$ 9,500/- 45)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Apr 2019		16 Apr 2019 15:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	WANG WENLIANG, ID: S78864198		
Vehicle Reg. No.:	SMD9155C	Date of Loss:	13/04/2019 16:00 - :59
Claim Type:	TP / SNM19D201656C02	Policy/Cover Note No.:	DMPCSN3020751801
Vehicle Reg. No. (Insured):	SJT6046E	Policy No. (Claimant):	VPA/P2183732
		Excess:	S\$1,000.00
Repairer:	Torque 5 Bodyworks Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 64524457		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 26/04/2019]		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[➤ Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	6419B

Vehicle Details

Vehicle No.:	SMD9155C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Apr 2019
Vehicle Make:	HYUNDAI
Vehicle Model:	ELANTRA AD 1.6 GLS AT (AMS)
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	G4FGJU260678
Chassis No.:	KMHD841CMJU748464
Maximum Power Output:	93.8 kW (125 bhp)
Open Market Value:	\$12,535.00
Original Registration Date:	12 Sep 2018
First Registration Date:	12 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$12,535.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Sep 2028
PARF Rebate Amount:	\$9,401.00

Intended COE Rebate Details

COE Expiry Date:	11 Sep 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$30,209.00
COE Rebate Amount:	\$24,167.00
Total Rebate Amount:	\$33,568.00

The information contained herein is correct as at 15 Apr 2019

OK

From: Torque 5 Assessment [mailto:assessment@torque5.com]
Sent: Thursday, June 27, 2019 12:02 PM
To: 'Hwee Jie (LKK Auto)'
Cc: 'Torque 5 Assessment'; claims@torque5.com; sam.chang@torque5.com
Subject: RE: SMD 9155 C - After Repair Photo & Finalisation .

Dear Hwee Jie ,



We hereby confirm the lump sum COR \$9500 with 07 days .

Thank you.



Warmest Regards,
Lucas Chow
Assessor | Motor Claims
Department

Hotline (65) 6452 4457 | Fax (65) 6452 4584
Mobile (65) 8131 6518
Email lucas.chow@torque5.com
Address 8 Kaki Bukit Ave 4, #01-49/50/51/52/53/54
Premier @ KB, Singapore 415875
www.torque5.com



Vehicle in

Email: sm@idac.com.sg

Tel no: 6555 6888 Fax no: 6454 3279

Personal Particulars of Owner & Driver (Vehicle A)

Date of Accident: 16 / 04 / 2019 (dd/mm/yy) Time of Accident: 16 : 46 (24-HR-FORMAT)

Vehicle No.: SMD 9155C Vehicle Make & Model: Hyundai Elantra

Exact location of Accident: CTE Expressway (Exit road from PE)

Policyholder's Name / IC No.: Wang Wenliang (S7R86419B)

Driver's Name / IC No.: _____ (As Above) ☒

Driver's Contact No.: 8266 5525 Company Contact No.: _____

Driver's Address: 14 Ang Mo Kio Central 3 #12-27 Singapore 567748

Insurance Company: AXA Email address (if any): _____

Relationship between Owner & Driver: (Please **CIRCLE** one only)

☒ Owner / ☐ Spouse / ☐ Children / ☐ Friend / ☐ Parents / ☐ Sibling / ☐ Relative / ☐ Employee / ☐ Hirer or Others specify: _____

What do you wish to claim? (Please **TICK** one only)

☐ Own Insurance / ☒ Other Vehicle (The one you want to claim against) / ☐ Reporting (For Record Purpose)

Exact purpose for which the vehicle
Was being used at time of accident?

Occupation (nature of job) ☒ Indoor / ☐ Outdoor

☒ Private use / ☐ Work purpose

No. of Passengers (Including Driver): 04

Weather condition & Road conditions? (On the day of accident)

☒ Clear & Dry / ☐ Raining & Wet / ☐ After-Rain & Wet / ☐ Drizzling & Wet / Others: _____

Was there any video captured by your Car Camera? ☐ Yes / ☒ No

Any Injuries: ☐ Yes / ☒ No (If YES) Injured Person's Name: _____

Injuries Sustain: _____ Injured Person in Which Vehicle: _____

Police Report filed: ☐ Yes / ☒ No (If YES) Which Police Station: _____

The Other Party(s) Details:

1. Driver's Name / IC No.: _____ Vehicle No: SJT 6046 E ☒

Driver's Contact No.: _____ Insurance Company (If any): _____

2. Driver's Name / IC No.: _____ Vehicle No: SKZ 1121 L ☒

Driver's Contact No.: _____ Insurance Company (If any): _____

*Independent Witness (If Any): _____ Contact No: _____

Preferred Workshop Name: _____ Contact No: _____

*If no proper documents are produced, IDAC should not file the report. Information will be discarded after one week.


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Vehicle A: SMC 9159C
 Vehicle B: SGT 6046E
 Vehicle C: SKZ 1181L

STIP ROAD TOWARDS PIE
 (At CTE) →


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On the stated date & time, I (Vehicle A: SMC 9159C) was travelling straight at the mentioned destination. As vehicle C (SKZ 1181L) came to a stop, I followed suit & kept a distance. All of a sudden, I felt a large impact from my rear portion & realised that vehicle B (SGT 6046E) had collided into my vehicle. Due to the large impact, it caused my vehicle to propel forward & collide into vehicle C. I would like to state that this is a 3 cars chain collision.


Passenger 1: Wang Min (wife)
 Passenger 2: Wang Pei Bi (Daughter)
 Passenger 3: Wang Pei Zhuo (Son)

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI, ELANTRA AD 1.6 GLS AT
(AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040010
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Head lamp lower bracket (LH)	1.00	0.00	0.00 CKH✓
2	Front bumper lower beam	1.00	0.00	0.00 BR✓
3	Front support air guide (LH)	1.00	0.00	0.00 BTV✓
4	Front bumper QTR fog lamp (LH)	1.00	0.00	0.00 BR✓
5	Bootlid sensor wire harness	1.00	0.00	0.00 CUT✓
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

Re survey 17/4/19

1630 hrs

Tellim Nir

List Items Subtotal S\$ 0.00
Total S\$ 0.00



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI, ELANTRA AD 1.6 GLS AT (AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040007
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper DEF /	1.00	0.00	0.00
2	Rear bumper retainer (LH) ?	1.00	0.00	0.00
3	Rear bumper retainer (RH) ?	1.00	0.00	0.00
4	Rear bumper bracket (LH) ?	1.00	0.00	0.00
5	Rear bumper bracket (RH) ?	1.00	0.00	0.00
6	Rear bumper reinforcement ?	1.00	0.00	0.00
7	Rear bumper lower garnish DEF /	1.00	0.00	0.00
8	Rear bumper lower garnish Repeat X	1.00	0.00	0.00
9	Rear bumper undercover (LH) DEF /	1.00	0.00	0.00
10	Rear bumper reflector (LH) CKA /	1.00	0.00	0.00
11	Rear bumper reflector (RH) CKA /	1.00	0.00	0.00
12	Reverse sensor shorted ? (S/N)	2.00	0.00	0.00
13	Reverse sensor harness wire set ?	1.00	0.00	0.00 NN X
14	Bootlid BVC /	1.00	0.00	0.00
15	Bootlid lock Jam /	1.00	0.00	0.00
16	Bootlid lock catch un X	1.00	0.00	0.00
17	Bootlid hinge (LH) un X	1.00	0.00	0.00
18	Bootlid hinge (RH) un X	1.00	0.00	0.00
19	Bootlid lock switch un X	1.00	0.00	0.00
20	Bootlid lock sensor ?	1.00	0.00	0.00
21	Bootlid emblem - Logo	1.00	0.00	0.00
22	Bootlid emblem - Elantra	1.00	0.00	0.00
23	Bootlid emblem - S	1.00	0.00	0.00
24	Bootlid insulator CUT /	1.00	0.00	0.00
25	Bootlid rubber beading ?	1.00	0.00	0.00
26	Bootlid lamp (LH) ?	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI, ELANTRA AD 1.6 GLS AT (AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040007
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
27	Bootlid lamp (RH) ?	1.00	0.00	0.00 BRV
28	License lamp (LH) n n x	1.00	0.00	0.00
29	License lamp (RH) n n x	1.00	0.00	0.00
30	Tail lamp (LH) ?	1.00	0.00	0.00 } BRV
31	Tail lamp (RH) ?	1.00	0.00	0.00 }
32	Tail lamp lower bracket (LH) n n x	1.00	0.00	0.00
33	Tail lamp lower bracket (RH) n n x	1.00	0.00	0.00
34	Tail lamp inner panel (LH) n n x	1.00	0.00	0.00
35	Tail lamp inner panel (RH) n n x	1.00	0.00	0.00
36	End panel ?	1.00	0.00	0.00 DDV
37	End panel top garnish ?	1.00	0.00	0.00 CRV
38	Spare tyre top board n n x	1.00	0.00	0.00 DDV
39	Spare tyre panel ?	1.00	0.00	0.00 RA
40	Rear fender inner trim (LH) ?	1.00	0.00	0.00 CUTV
41	Rear fender inner trim (RH) n n x	1.00	0.00	0.00
42	Front bumper CUT /	1.00	0.00	0.00
43	Front bumper retainer (LH) n n x	1.00	0.00	0.00 BRV
44	Front bumper retainer (RH) n n x	1.00	0.00	0.00
45	Front bumper sponge ?	1.00	0.00	0.00 BRV
46	Front bumper reinforcement ?	1.00	0.00	0.00 DDV
47	Front bumper bracket (LH) n n x	1.00	0.00	0.00
48	Front bumper bracket (RH) n n x	1.00	0.00	0.00
49	Front bumper towing cap n n x	1.00	0.00	0.00
50	Front bumper lower garnish SLE /	1.00	0.00	0.00
51	Front number plate garnish DEF /	1.00	0.00	0.00
52	Radiator grille ?	1.00	0.00	0.00 CUTV
53	Radiator grille emblem - Logo ?	1.00	0.00	0.00 NECV

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT (AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040007
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
54	Fog lamp garnish (LH) nnx ?	1.00	0.00	0.00 C4TV
55	Fog lamp garnish (RH) nnx	1.00	0.00	0.00
56	Fog lamp (LH) nnx ?	1.00	0.00	0.00 BRV
57	Fog lamp (RH) nnx	1.00	0.00	0.00
58	Head lamp (LH) ?	1.00	0.00	0.00 C4TV
59	Head lamp (RH) nnx	1.00	0.00	0.00
60	Front bumper weather strip DEF /	1.00	0.00	0.00
61	Front support panel nnx ?	1.00	0.00	0.00
62	Front support panel top garnish ?	1.00	0.00	0.00 C4TV
63	A/C condenser ?	1.00	0.00	0.00 DDVX
64	Radiator nnx	1.00	0.00	0.00
65	Bonnet nnx	1.00	0.00	0.00
66	Bonnet lock nnx	1.00	0.00	0.00
67	Front bumper under cover ?	1.00	0.00	0.00 NNx
68	Rear exhaust muffler ?	1.00	0.00	0.00 BTV
69	Rear exhaust mid pipe nnx	1.00	0.00	0.00
70	Rear exhaust heat shield ?	1.00	0.00	0.00 NNx
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

Section: Special Nett Items

71	Reverse camera nnx	1.00	550.00	550.00
72	Rear number plate & casing nnx	1.00	45.00	45.00
73	Front number plate & casing DEF /	1.00	45.00	45.00
74	Rear bumper clip set ncc /	1.00	50.00	50.00 30
75	Bootlid insulator clip set ncc	1.00	45.00	45.00 20
76	Rear bumper undercover clip set ncc /	1.00	30.00	30.00 20

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI, ELANTRA AD 1.6 GLS AT (AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040007
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
77	Bootlid spoiler <i>nn x</i>	1.00	700.00	700.00
78	Tail lamp clip set <i>?</i>	1.00	30.00	<i>20</i> 30.00
79	End panel top garnish clip set <i>!</i>	1.00	30.00	<i>20</i> 30.00
80	End panel sealant <i>?</i>	1.00	50.00	<i>30</i> 50.00
81	Spare tyre panel sealant <i>!</i>	1.00	50.00	<i>X</i> 50.00
82	Spare tyre panel insulator matt <i>nn x</i>	1.00	280.00	280.00
83	Rear fender inner trim clip set (LH) <i>?</i>	1.00	45.00	<i>25</i> 45.00 <i>NECV</i>
84	Rear fender inner trim clip set (RH) <i>nn x</i>	1.00	45.00	45.00
85	Front bumper clip set <i>necl</i>	1.00	50.00	<i>50.00</i> <i>30</i>
86	Front bumper undercover clip set <i>!</i>	1.00	45.00	<i>45.00</i> <i>NNX</i>
87	Front support panel top garnish clip set <i>?</i>	1.00	30.00	<i>20</i> 30.00 <i>NECV</i>
88	Engine coolant <i>nn x</i>	1.00	120.00	120.00
89	Auto transmission fluid 1 Litre <i>nn x</i>	1.00	80.00	80.00
90	A/C condenser o-ring set <i>nn x</i>	1.00	30.00	30.00
91	Horn set <i>nn x</i>	1.00	160.00	160.00

Amt S\$ 2,510.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 2,510.00

Section: Labour Items

92	To R&R rear bumper reverse sensor	1.00	80.00	<i>80.00</i> <i>30</i>
93	to check wiring & lighting system	1.00	100.00	<i>50</i> <i>100.00</i> <i>50</i>
94	To conduct head lamp focus	1.00	160.00	<i>160.00</i> <i>X</i> <i>NECV</i>
95	To supply under coding / putty on parts replaced	1.00	100.00	<i>100.00</i> <i>?</i>
96	To perform anti-rust treatment on affected areas	1.00	80.00	<i>80.00</i> <i>?</i>
97	To R&R bootlid mechanism	1.00	150.00	<i>150.00</i> <i>50</i>
98	To R&R rear trims, garnish & seats assy	1.00	220.00	<i>220.00</i> <i>X</i>
99	To R&R rear exhaust assy	1.00	250.00	<i>250.00</i> <i>70</i>

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI, ELANTRA AD 1.6 GLS AT (AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040007
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
100	To vacuum & refill 134a refrigerants	1.00	160.00	160.00 ?
101	To R&R a/c condenser, radiator assy	1.00	300.00	300.00 X
102	To repair, replace & realign damaged areas	1.00	1,800.00	1,800.00 1200
103	To spray painting on affected areas	1.00	1,600.00	1,600.00 1000
104	To perform water seepage test after repair	1.00	160.00	160.00 30
105	To car wash & polish vehicle after repair	1.00	150.00	150.00 30
106	Sundries	1.00	50.00	50.00 20

Amt S\$ 5,360.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 5,360.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:


Hwee Jia - LKK
L/s 7 days.



9180 3151

hweejia@lkkauto.com

List Items Subtotal	S\$ 0.00
Special Nett Items Subtotal	S\$ 2,510.00
Labour Items Subtotal	S\$ 5,360.00
Total	S\$ 7,870.00



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI, ELANTRA AD 1.6 GLS AT
(AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040007
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Rear bumper DEF /	1.00	659.40	659.40 490
2	Rear bumper retainer (LH)	1.00	62.00	62.00
3	Rear bumper retainer (RH)	1.00	62.00	62.00
4	Rear bumper bracket (LH) } nec /	1.00	140.00	140.00
5	Rear bumper bracket (RH)	1.00	140.00	140.00
6	Rear bumper reinforcement DD /	1.00	328.00	328.00 250
7	Rear bumper lower garnish DEF /	1.00	260.10	260.10
8	Rear bumper undercover (LH) DEF /	1.00	120.00	120.00
9	Rear bumper reflector (LH) CRA /	1.00	99.00	99.00
10	Rear bumper reflector (RH) CRA /	1.00	99.00	99.00
11	Bootlid BUL /	1.00	1,020.00	1,020.00
12	Bootlid lock Jam /	1.00	120.80	120.80
13	Bootlid lock catch	1.00	93.00	93.00 x
14	Bootlid hinge (LH) } nux	1.00	117.00	117.00 x
15	Bootlid hinge (RH)	1.00	117.00	117.00 x
16	Bootlid lock switch	1.00	154.00	154.00 x
17	Bootlid lock sensor BR /	1.00	296.00	296.00
18	Bootlid emblem - Logo	1.00	80.00	80.00 30
19	Bootlid emblem - Elantra } nec /	1.00	48.00	48.00
20	Bootlid emblem - S	1.00	32.00	32.00
21	Bootlid insulator CUT /	1.00	221.00	221.00
22	Bootlid rubber beading CUT /	1.00	150.00	150.00
23	Bootlid lamp (LH) BR /	1.00	170.00	170.00
24	Bootlid lamp (RH) BR /	1.00	170.00	170.00
25	License lamp (LH) nux	1.00	85.00	85.00 x
26	License lamp (RH) nux	1.00	85.00	85.00 x

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI, ELANTRA AD 1.6 GLS AT (AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040007
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
27	Tail lamp (LH) BR ✓	1.00	364.80	364.80
28	Tail lamp (RH) BR ✓	1.00	364.80	364.80
29	Tail lamp lower bracket (LH) ~ ~ x	1.00	36.00	36.00 x
30	Tail lamp lower bracket (RH) ~ ~ x	1.00	36.00	36.00 x
31	Tail lamp inner panel (LH) ~ ~ x	1.00	105.70	105.70 x
32	Tail lamp inner panel (RH) ~ ~ x	1.00	105.70	105.70 x
33	End panel DO -	1.00	455.00	455.00
34	End panel top garnish CRA -	1.00	102.00	102.00
35	Spare tyre top board DP ✓	1.00	290.00	290.00
36	Spare tyre panel R x	1.00	730.00	730.00 x
37	Rear fender inner trim (LH) CUT ✓	1.00	550.00	550.00
38	Rear fender inner trim (RH) ~ ~ x	1.00	550.00	550.00 x
39	Front bumper CUT ✓	1.00	654.00	654.00 450
40	Front bumper retainer (LH) BR ✓	1.00	56.00	56.00
41	Front bumper retainer (RH) ~ ~ x	1.00	56.00	56.00 x
42	Front bumper sponge BR ✓	1.00	125.00	125.00
43	Front bumper reinforcement DO ✓	1.00	655.00	655.00 250
44	Front bumper bracket (LH) ~ ~ x	1.00	78.00	78.00 x
45	Front bumper bracket (RH) ~ ~ x	1.00	78.00	78.00 x
46	Front bumper towing cap ~ ~ x	1.00	65.00	65.00 x
47	Front bumper lower garnish SCR ✓	1.00	398.00	398.00
48	Front number plate garnish DEF ✓	1.00	170.00	170.00
49	Radiator grille CUT ✓	1.00	480.00	480.00 200
50	Radiator grille emblem - Logo ~ ~ ✓	1.00	92.00	92.00 50
51	Fog lamp garnish (LH) CUT ✓	1.00	200.00	200.00
52	Fog lamp garnish (RH) ~ ~ x	1.00	200.00	200.00 x
53	Fog lamp (LH) BR ✓	1.00	514.00	514.00 280

Continue on next page...



Torque 5 Pte Ltd
 No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
 Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
 Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI ELANTRA AD 1.6 GLS AT (AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040007
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
54	Fog lamp (RH) <i>nnx</i>	1.00	514.00	514.00 X
55	Head lamp (LH) <i>CUT</i>	1.00	1,352.00	1,352.00 10x0
56	Head lamp (RH) <i>nnx</i>	1.00	1,352.00	1,352.00 X
57	Front bumper weather strip <i>DEF</i>	1.00	130.00	130.00
58	Front support panel <i>nnx</i>	1.00	665.30	665.30 X
59	Front support panel top garnish <i>CUT</i>	1.00	125.60	125.60
60	A/C condenser <i>nnx</i>	1.00	991.00	991.00 X
61	Radiator <i>nnx</i>	1.00	1,027.50	1,027.50 X
62	Bonnet <i>nnx</i>	1.00	1,312.00	1,312.00 X
63	Bonnet lock <i>nnx</i>	1.00	236.70	236.70 X
64	Front bumper under cover <i>nnx</i>	1.00	137.20	137.20 X
65	Rear exhaust muffler <i>BT</i>	1.00	720.00	720.00 550
66	Rear exhaust mid pipe <i>nnx</i>	1.00	622.30	622.30 X
67	Rear exhaust heat shield <i>nnx</i>	1.00	190.00	190.00 X

Amt S\$

21,814.90

20% Discount

Discount (0.00%) S\$ 0.00

Subtotal S\$

21,814.90

Section: Special Nett Items

68	Reverse camera <i>nnx</i>	1.00	550.00	550.00 X
69	Rear number plate & casing <i>nnx</i>	1.00	45.00	45.00 X
70	Front number plate & casing <i>DEF</i>	1.00	45.00	45.00
71	Rear bumper clip set <i>nei</i>	1.00	50.00	50.00 30
72	Bootlid insulator clip set <i>nei</i>	1.00	45.00	45.00 20
73	Rear bumper undercover clip set <i>nei</i>	1.00	30.00	30.00 20
74	Bootlid spoiler <i>nnx</i>	1.00	700.00	700.00 X
75	Tail lamp clip set <i>nei</i>	1.00	30.00	30.00 20

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI, ELANTRA AD 1.6 GLS AT
(AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040007
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
76	End panel top garnish clip set <i>nee</i>	1.00	30.00	30.00 20
77	End panel sealant <i>nee</i>	1.00	50.00	50.00 30
78	Spare tyre panel sealant <i>nn x</i>	1.00	50.00	50.00 x
79	Spare tyre panel insulator matt <i>nn x</i>	1.00	280.00	280.00 x
80	Rear fender inner trim clip set (LH) <i>nee</i>	1.00	45.00	45.00 25
81	Rear fender inner trim clip set (RH) <i>nn x</i>	1.00	45.00	45.00 x
82	Front bumper clip set <i>nee</i>	1.00	50.00	50.00 30
83	Front bumper undercover clip set <i>nn x</i>	1.00	45.00	45.00 x
84	Front support panel top garnish clip set <i>nee</i>	1.00	30.00	30.00 20
85	Engine coolant <i>nn x</i>	1.00	120.00	120.00 x
86	Auto transmission fluid 1 Litre <i>nn x</i>	1.00	80.00	80.00 x
87	A/C condenser o'ring set <i>nn x</i>	1.00	30.00	30.00 x
88	Horn set <i>nn x</i>	1.00	160.00	160.00 x
89	Reverse sensor set <i>Shorted</i>	1.00	250.00	250.00 200

Amt S\$ 2,760.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 2,760.00

Section: Labour Items

90	To R&R rear bumper reverse sensor	1.00	80.00	80.00 30
91	to check wiring & lighting system	1.00	100.00	100.00 20
92	To conduct head lamp focus	1.00	160.00	160.00 20
93	To supply under coding / putty on parts replaced	1.00	100.00	100.00 30
94	To perform anti-rust treatment on affected areas	1.00	80.00	80.00 20
95	To R&R bootlid mechanism	1.00	150.00	150.00 50
96	To R&R rear trims, garnish & seats assy	1.00	220.00	220.00 x
97	To R&R rear exhaust assy	1.00	250.00	250.00 70
98	To vacuum & refill 134a refrigerants	1.00	160.00	160.00 60

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI, ELANTRA AD 1.6 GLS AT
(AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040007
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
99	To R&R a/c condenser, radiator assy	1.00	300.00	300.00 60
100	To repair, replace & realign damaged areas	1.00	1,800.00	1,800.00 1200
101	To spray painting on affected areas	1.00	1,600.00	1,600.00 1000
102	To perform water seepage test after repair	1.00	160.00	160.00 30
103	To car wash & polish vehicle after repair	1.00	150.00	150.00 80
104	Sundries	1.00	50.00	50.00 20

Amt S\$ 5,360.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 5,360.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

List Items Subtotal S\$ 21,814.90
Special Nett Items S\$ 2,760.00
Subtotal
Labour Items Subtotal S\$ 5,360.00
Total S\$ 29,934.90

30,960.90



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

SUPPLEMENTARY REPORT

Vehicle No : SMD9155C
Make & Model : HYUNDAI, ELANTRA AD 1.6 GLS AT
(AMS), KMHD841CMJU748464
Year of Manufacture : 2018

Estimation No. : E19040010
DOA : 16/04/2019

No	Description	Qty	U/P	Amt
Section: List Items				
1	Head lamp lower bracket (LH) <i>CRA-</i>	1.00	197.00	197.00 <i>A</i>
2	Front bumper lower beam <i>BR-</i>	1.00	120.00	120.00 <i>A</i>
3	Front support air guide (LH) <i>BT-</i>	1.00	93.00	93.00 <i>A</i>
4	Front bumper QTR fog lamp (LH) <i>BR-</i>	1.00	236.00	236.00 <i>A</i>
5	Bootlid sensor wire harness <i>CUT-</i>	1.00	380.00	380.00 <i>200 A</i>
				Amt S\$ 1,026.00
<i>20% Discount</i> Discount (0.00%)				S\$ 0.00
				Subtotal S\$ 1,026.00

Total - \$980.00 / 1/5 7 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

List Items Subtotal S\$ 1,026.00
Total S\$ 1,026.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Apr 2019		16 Apr 2019 15:36 Edit Adj Rpt	\$9,500.00 Edit Estimates	\$9,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	WANG WENLIANG, ID: S78864198								
Vehicle Reg. No.:	SMD9155C	Date of Loss:	13/04/2019 16:00 - :59 [7 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201656C02	Policy/Cover Note No.:	DMPCSN3020751801						
Vehicle Reg. No. (Insured):	SJT6046E	Policy No. (Claimant):	VPA/P2183732						
		Excess:	S\$1,000.00						
Repairer:	Torque 5 Bodyworks Pte Ltd (Kaki Bukit) 8 Kaki Bukit Ave 4,, #01-49/50/51/52/53/54 Premier @ Kaki Bukit, 415875 Kaki Bukit - Tel: 64524457								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 26/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMD9155C (SNM19D201656C02)
[SJT6046E]
TP
WANG WENLIANG
Apr 13 2019 4:00PM
[-]
Torque 5 Bodyworks Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print					
1	15/04/19 10:38	Accident Statement			Load HTML					
Photos/Images							3 per page		☒	
No	Finalized On	Alpine Motors Pte Ltd (HQ)		Thumbnail	Print					
1	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
2	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
3	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
4	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
5	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
6	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
7	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
8	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
9	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
10	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
11	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
12	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
13	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
14	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
15	15/04/19 10:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
16	15/04/19 10:37	Driving License [Linked Accident Report Documents]			Load JPG		☒			
17	15/04/19 10:37	Insurance policy [Linked Accident Report Documents]			Load JPG		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	27/06/19 11:52	General View			Load JPG		☒			
2	27/06/19 11:52	General View			Load JPG		☒			
3	27/06/19 11:52	General View			Load JPG		☒			
4	27/06/19 11:52	General View			Load JPG		☒			
5	27/06/19 11:52	General View			Load JPG		☒			
6	27/06/19 11:52	General View			Load JPG		☒			
7	27/06/19 11:52	General View			Load JPG		☒			
8	27/06/19 11:52	General View			Load JPG		☒			
9	27/06/19 11:52	General View			Load JPG		☒			
10	27/06/19 11:52	General View			Load JPG		☒			

Assessment Reports			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
11	27/06/19 11:52	General View	 Load JPG	☒
12	27/06/19 11:52	General View	 Load JPG	☒
13	27/06/19 11:52	General View	 Load JPG	☒
14	27/06/19 11:52	General View	 Load JPG	☒
15	27/06/19 11:52	General View	 Load JPG	☒
16	27/06/19 11:52	General View	 Load JPG	☒
17	27/06/19 11:52	General View	 Load JPG	☒
18	27/06/19 11:52	General View	 Load JPG	☒
19	27/06/19 11:52	General View	 Load JPG	☒
20	27/06/19 11:52	General View	 Load JPG	☒
21	27/06/19 11:52	General View	 Load JPG	☒
22	27/06/19 11:52	General View	 Load JPG	☒
23	27/06/19 11:52	General View	 Load JPG	☒
24	27/06/19 11:52	General View	 Load JPG	☒
25	27/06/19 11:52	General View	 Load JPG	☒
26	27/06/19 11:52	General View	 Load JPG	☒
27	27/06/19 11:52	General View	 Load JPG	☒
28	27/06/19 11:52	General View	 Load JPG	☒
29	27/06/19 11:52	General View	 Load JPG	☒
30	27/06/19 11:52	General View	 Load JPG	☒
31	27/06/19 11:52	General View	 Load JPG	☒
32	27/06/19 11:52	General View	 Load JPG	☒
33	27/06/19 11:52	General View	 Load JPG	☒
34	27/06/19 11:52	General View	 Load JPG	☒
35	27/06/19 11:52	General View	 Load JPG	☒
36	27/06/19 11:52	General View	 Load JPG	☒
37	27/06/19 11:52	General View	 Load JPG	☒
38	27/06/19 11:52	General View	 Load JPG	☒
39	27/06/19 11:52	General View	 Load JPG	☒
40	27/06/19 11:52	General View	 Load JPG	☒
41	27/06/19 11:52	General View	 Load JPG	☒
42	27/06/19 11:52	General View	 Load JPG	☒
43	27/06/19 11:52	General View	 Load JPG	☒
44	27/06/19 11:52	General View	 Load JPG	☒
45	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
46	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
47	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
48	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
49	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
50	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
51	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
52	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
53	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
54	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
55	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
56	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
57	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
58	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
59	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
60	27/06/19 11:53	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
61	27/06/19 11:53	Reinspection Photo		☒
62	27/06/19 11:53	Reinspection Photo		☒
63	27/06/19 11:53	Reinspection Photo		☒
64	27/06/19 11:53	Reinspection Photo		☒
65	27/06/19 11:53	Reinspection Photo		☒
66	27/06/19 11:53	Reinspection Photo		☒
67	27/06/19 11:53	Reinspection Photo		☒
68	27/06/19 11:53	Reinspection Photo		☒
69	27/06/19 11:53	Reinspection Photo		☒
70	27/06/19 11:53	Reinspection Photo		☒
71	27/06/19 11:53	Reinspection Photo		☒
72	27/06/19 11:53	Reinspection Photo		☒
73	27/06/19 11:53	Reinspection Photo		☒
74	27/06/19 11:53	Reinspection Photo		☒
75	27/06/19 11:53	Reinspection Photo		☒
76	27/06/19 11:53	Reinspection Photo		☒
77	27/06/19 11:53	Reinspection Photo		☒
78	27/06/19 11:53	Reinspection Photo		☒
79	27/06/19 11:53	Reinspection Photo		☒
80	27/06/19 11:53	Reinspection Photo		☒
81	27/06/19 11:53	Reinspection Photo		☒
82	27/06/19 11:53	Reinspection Photo		☒
83	27/06/19 11:53	Reinspection Photo		☒
84	27/06/19 11:53	Reinspection Photo		☒
85	27/06/19 11:53	Reinspection Photo		☒
86	27/06/19 11:53	Reinspection Photo		☒
87	27/06/19 11:53	Reinspection Photo		☒
88	27/06/19 11:53	Reinspection Photo		☒
89	27/06/19 11:53	Reinspection Photo		☒
90	27/06/19 11:53	Reinspection Photo		☒
91	27/06/19 11:53	Reinspection Photo		☒
92	27/06/19 11:53	Reinspection Photo		☒
93	27/06/19 11:53	Reinspection Photo		☒
94	27/06/19 11:53	Reinspection Photo		☒
95	27/06/19 11:53	Reinspection Photo		☒
96	27/06/19 11:53	Reinspection Photo		☒
97	27/06/19 11:53	Reinspection Photo		☒
98	27/06/19 11:53	Reinspection Photo		☒
99	27/06/19 11:53	Reinspection Photo		☒
100	27/06/19 11:53	Reinspection Photo		☒
101	27/06/19 11:53	Reinspection Photo		☒
102	27/06/19 11:53	Reinspection Photo		☒
103	27/06/19 11:53	Reinspection Photo		☒
104	27/06/19 11:53	Reinspection Photo		☒
105	27/06/19 11:53	Reinspection Photo		☒
106	27/06/19 11:53	Reinspection Photo		☒
107	27/06/19 11:53	Reinspection Photo		☒
108	27/06/19 11:53	Reinspection Photo		☒
109	27/06/19 11:53	Reinspection Photo		☒
110	27/06/19 11:53	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
111	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
112	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
113	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
114	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
115	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
116	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
117	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
118	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
119	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
120	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
121	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
122	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
123	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
124	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
125	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
126	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
127	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
128	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
129	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
130	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
131	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
132	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
133	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
134	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
135	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
136	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
137	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
138	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
139	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
140	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
141	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
142	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
143	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
144	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
145	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
146	27/06/19 11:53	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/04/19 15:36	PRS - SMD9155C	 Load PDF	
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	15/04/19 10:37	Sketch Plan [Linked Accident Report Documents]	 Load JPG	☒
2	15/04/19 10:37	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/07/19 12:13	Supplementary	 Load PDF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	15/04/19 10:38	Accident Statement	 Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	15/04/19 10:33	Accident Photo	 Load JPG	☒
2	15/04/19 10:33	Accident Photo	 Load JPG	☒
3	15/04/19 10:33	Accident Photo	 Load JPG	☒
4	15/04/19 10:33	Accident Photo	 Load JPG	☒
5	15/04/19 10:33	Accident Photo	 Load JPG	☒
6	15/04/19 10:33	Accident Photo	 Load JPG	☒
7	15/04/19 10:33	Accident Photo	 Load JPG	☒
8	15/04/19 10:33	Accident Photo	 Load JPG	☒
9	15/04/19 10:33	Accident Photo	 Load JPG	☒
10	15/04/19 10:33	Accident Photo	 Load JPG	☒
11	15/04/19 10:33	Accident Photo	 Load JPG	☒
12	15/04/19 10:33	Accident Photo	 Load JPG	☒
13	15/04/19 10:33	Accident Photo	 Load JPG	☒
14	15/04/19 10:33	Accident Photo	 Load JPG	☒
15	15/04/19 10:33	Accident Photo	 Load JPG	☒
16	15/04/19 10:37	Driving License	 Load JPG	☒
17	15/04/19 10:37	Insurance policy	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Alpine Motors Pte Ltd (HQ)	Thumbnail	Print
1	15/04/19 10:37	Sketch Plan	 Load JPG	☒
2	15/04/19 10:37	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19006794/JSD3E2

Date: 08/07/2019

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3020751801

Claimant Vehicle
No: SMD9155CInsured Vehicle
No: SJT6046E

Date of Loss: 13/04/2019

Nature of Claim: TP

Claim
No: SNM19D201656C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD9155C

Make & Model: HYUNDAI ELANTRA, 1.6 (A)

Reg. Date: 12/09/2018 (Man. Year: 2018)

Colour: Silver

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: G4FGJU260678

Chassis No: KMHD841CMJU748464

Odometer: 5048 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,650.90	9,293.68	16,357.22	63.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,310.00	2,620.00	2,690.00	50.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,960.90	11,913.68	19,047.22	61.52
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	30,960.90	9,500.00	21,460.90	69.32
+ GST 7.00/7.00% (S\$)	2,167.26	665.00	1,502.26	69.32
Nett Amount (S\$)	33,128.16	10,165.00	22,963.16	69.32

INSPECTION

Date of Assignment: 16/04/2019

Date Inspected: 17/04/2019 Inspected At:

Torque 5 Bodyworks Pte Ltd (Kaki Bukit)
8 Kaki Bukit Ave 4., #01-49/50/51/52/53/54
Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: ONG HWEE JIE**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Jul 2019)	
Parts: 143	HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMD9155C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	659.40 F	*490.00 FL
2	1		*REAR BUMPER RETAINER (LH)	Necessary	62.00 F	*62.00 FL
3	1		*REAR BUMPER RETAINER (RH)	Necessary	62.00 F	*62.00 FL
4	1		*REAR BUMPER BRACKET (LH)	Necessary	140.00 F	*140.00 FL
5	1		*REAR BUMPER BRACKET (RH)	Necessary	140.00 F	*140.00 FL
6	1		*REAR BUMPER REINFORCEMENT	Dented	328.00 F	*250.00 FL
7	1		*REAR BUMPER LOWER GARNISH	Deformed	260.10 F	*260.10 FL
8	1		*REAR BUMPER UNDERCOVER (LH)	Deformed	120.00 F	*120.00 FL
9	1		*REAR BUMPER REFLECTOR (LH)	Cracked	99.00 F	*99.00 FL
10	1		*REAR BUMPER REFLECTOR (RH)	Cracked	99.00 F	*99.00 FL
11	1		*BOOTLID	Buckled	1,020.00 F	*1,020.00 FL
12	1		*BOOTLID LOCK	Jammed	120.80 F	*120.80 FL
13	1		*BOOTLID LOCK CATCH	Not Necessary	93.00 F	*- FL
14	1		*BOOTLID HINGE (LH)	Not Necessary	117.00 F	*- FL
15	1		*BOOTLID HINGE (RH)	Not Necessary	117.00 F	*- FL
16	1		*BOOTLID LOCK SWITCH	Not Necessary	154.00 F	*- FL
17	1		*BOOTLID LOCK SENSOR	Broken	296.00 F	*296.00 FL
18	1		*BOOTLID EMBLEM - LOGO	Necessary	80.00 F	*30.00 FL
19	1		*BOOTLID EMBLEM - ELANTRA	Necessary	48.00 F	*48.00 FL
20	1		*BOOTLID EMBLEM - S	Necessary	32.00 F	*32.00 FL
21	1		*BOOTLID INSULATOR	Cut	221.00 F	*221.00 FL
22	1		*BOOTLID RUBBER BEADING	Cut	150.00 F	*150.00 FL
23	1		*BOOTLID LAMP (LH)	Broken	170.00 F	*170.00 FL
24	1		*BOOTLID LAMP (RH)	Broken	170.00 F	*170.00 FL
25	1		*LICENSE LAMP (LH)	Not Necessary	85.00 F	*- FL
26	1		*LICENSE LAMP (RH)	Not Necessary	85.00 F	*- FL
27	1		*TAIL LAMP (LH)	Broken	364.80 F	*364.80 FL
28	1		*TAIL LAMP (RH)	Broken	364.80 F	*364.80 FL
29	1		*TAIL LAMP LOWER BRACKET (LH)	Not Necessary	36.00 F	*- FL
30	1		*TAIL LAMP LOWER BRACKET (RH)	Not Necessary	36.00 F	*- FL
31	1		*TAIL LAMP INNER PANEL (LH)	Not Necessary	105.70 F	*- FL
32	1		*TAIL LAMP INNER PANEL (RH)	Not Necessary	105.70 F	*- FL
33	1		*END PANEL	Dented	455.00 F	*455.00 FL
34	1		*END PANEL TOP GARNISH	Cracked	102.00 F	*102.00 FL
35	1		*SPARE TYRE TOP BOARD	Dented	290.00 F	*290.00 FL
36	1		*SPARE TYRE PANEL	Repair	730.00 F	*- FL
37	1		*REAR FENDER INNER TRIM (LH)	Cut	550.00 F	*550.00 FL
38	1		*REAR FENDER INNER TRIM (RH)	Not Necessary	550.00 F	*- FL
39	1		*FRONT BUMPER	Cut	654.00 F	*450.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*FRONT BUMPER RETAINER (LH)	Broken	56.00 F	*56.00 FL
41	1		*FRONT BUMPER RETAINER (RH)	Not Necessary	56.00 F	*- FL
42	1		*FRONT BUMPER SPONGE	Broken	125.00 F	*125.00 FL
43	1		*FRONT BUMPER REINFORCEMENT	Dented	655.00 F	*250.00 FL
44	1		*FRONT BUMPER BRACKET (LH)	Not Necessary	78.00 F	*- FL
45	1		*FRONT BUMPER BRACKET (RH)	Not Necessary	78.00 F	*- FL
46	1		*FRONT BUMPER TOWING CAP	Not Necessary	65.00 F	*- FL
47	1		*FRONT BUMPER LOWER GARNISH	Scratched	398.00 F	*398.00 FL
48	1		*FRONT NUMBER PLATE GARNISH	Deformed	170.00 F	*170.00 FL
49	1		*RADIATOR GRILLE	Cut	480.00 F	*200.00 FL
50	1		*RADIATOR GRILLE EMBLEM - LOGO	Necessary	92.00 F	*50.00 FL
51	1		*FOG LAMP GARNISH (LH)	Cut	200.00 F	*200.00 FL
52	1		*FOG LAMP GARNISH (RH)	Not Necessary	200.00 F	*- FL
53	1		*FOG LAMP (LH)	Broken	514.00 F	*280.00 FL
54	1		*FOG LAMP (RH)	Not Necessary	514.00 F	*- FL
55	1		*HEAD LAMP (LH)	Cut	1,352.00 F	*1,080.00 FL
56	1		*HEAD LAMP (RH)	Not Necessary	1,352.00 F	*- FL
57	1		*FRONT BUMPER WEATHER STRIP	Deformed	130.00 F	*130.00 FL
58	1		*FRONT SUPPORT PANEL	Not Necessary	665.30 F	*- FL
59	1		*FRONT SUPPORT PANEL TOP GARNISH	Cut	125.60 F	*125.60 FL
60	1		*A/C CONDENSER	Not Necessary	991.00 F	*- FL
61	1		*RADIATOR	Not Necessary	1,027.50 F	*- FL
62	1		*BONNET	Not Necessary	1,312.00 F	*- FL
63	1		*BONNET LOCK	Not Necessary	236.70 F	*- FL
64	1		*FRONT BUMPER UNDER COVER	Not Necessary	137.20 F	*- FL
65	1		*REAR EXHAUST MUFFLER	Bent	720.00 F	*550.00 FL
66	1		*REAR EXHAUST MID PIPE	Not Necessary	622.30 F	*- FL
67	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	190.00 F	*- FL
68	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS
69	1		*REAR NUMBER PLATE & CASING	Not Necessary	45.00 FS	*- FS
70	1		*FRONT NUMBER PLATE & CASING	Deformed	45.00 FS	*45.00 FS
71	1		*SET REAR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
72	1		*SET BOOTLID INSULATOR CLIP	Necessary	45.00 FS	*20.00 FS
73	1		*SET REAR BUMPER UNDERCOVER CLIP	Necessary	30.00 FS	*20.00 FS
74	1		*BOOTLID SPOILER	Not Necessary	700.00 FS	*- FS
75	1		*SET END PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*20.00 FS
76	1		*END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS
77	1		*SPARE TYRE PANEL SEALANT	Not Necessary	50.00 FS	*- FS
78	1		*SPARE TYRE PANEL INSULATOR MATT	Not Necessary	280.00 FS	*- FS
79	1		*SET REAR FENDER INNER TRIM CLIP (LH)	Necessary	45.00 FS	*25.00 FS
80	1		*SET REAR FENDER INNER TRIM CLIP (RH)	Not Necessary	45.00 FS	*- FS
81	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
82	1		*SET FRONT BUMPER UNDERCOVER CLIP	Not Necessary	45.00 FS	*- FS
83	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIP	Necessary	30.00 FS	*20.00 FS
84	1		*ENGINE COOLANT	Not Necessary	120.00 FS	*- FS
85	1		*AUTO TRANSMISSION FLUID 1 LITRE	Not Necessary	80.00 FS	*- FS
86	1		*SET A/C CONDENSER ORING	Not Necessary	30.00 FS	*- FS
87	1		*SET HORN	Not Necessary	160.00 FS	*- FS
88	1		*SET REVERSE SENSOR	Shorted	250.00 FS	*200.00 FS
89	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
90	1		*HEAD LAMP LOWER BRACKET (LH)	Cracked	197.00 F	*197.00 FL
91	1		*FRONT BUMPER LOWER BEAM	Broken	120.00 F	*120.00 FL
92	1		*FRONT SUPPORT AIR GUIDE (LH)	Bent	93.00 F	*93.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
93	1		*FRONT BUMPER QTR FOG LAMP (LH)	Broken	236.00 F	*236.00 FL
94	1		*BOOTLID SENSOR WIRE HARNESS	Cut	380.00 F	*200.00 FL
95	1		*SET TAIL LAMP CLIP	Necessary	30.00 FS	*20.00 FS
				Sub Total (S\$)	25,650.90	11,497.10
				- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	2,203.42
				Total Parts (S\$)	25,650.90	9,293.68

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO R&R REAR BUMPER REVERSE SENSOR	New	80.00	30.00
2	TO CHECK WIRING & LIGHTING SYSTEM	New	100.00	20.00
3	TO CONDUCT HEAD LAMP FOCUS	New	160.00	20.00
4	TO SUPPLY UNDER CODING / PUTTY ON PARTS REPLACED	New	100.00	30.00
5	TO PERFORM ANTI-RUST TREATMENT ON AFFECTED AREAS	New	80.00	20.00
6	TO R&R BOOTLID MECHANISM	New	150.00	50.00
7	TO R&R REAR TRIMS, GARNISH & SEATS ASSY	New	220.00	0.00
8	TO R&R REAR EXHAUST ASSY	New	250.00	70.00
9	TO VACUUM & REFILL 134A REFRIGERANTS	New	160.00	60.00
10	TO R&R A/C CONDENSER, RADIATOR ASSY	New	300.00	60.00
11	TO REPAIR, REPLACE & REALIGN DAMAGED AREAS	New	1,800.00	1,200.00
12	TO SPRAY PAINTING ON AFFECTED AREAS	New	1,600.00	1,000.00
13	TO PERFORM WATER SEEPAGE TEST AFTER REPAIR	New	160.00	30.00
14	TO CAR WASH & POLISH VEHICLE AFTER REPAIR	New	150.00	30.00
Gross Labour Cost (S\$)			5,310.00	2,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >