

TAN CHONG MOTOR SALES PTE. LTD.
911, BUKIT TIMAH ROAD
SINGAPORE 589623

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/ZHR/0197/2019
DATE : 16-APR-2019

AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
S(068811)
TEL : 68804741
FAX : 68804838
ATTN:MOTOR CLAIM MANAGER VALENCIA

OWNER'S NAME : M/S HEALTHBIZ RESOURCE PTE LTD
ADDRESS : 5 ANG MO KIO INDUSTRIAL PARK 2A
#05-21 AMK TECH II
S(567760)
TELEPHONE NO : 91568196

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP -SGL6949C
VEHICLE NO : SME440H
MODEL CODE : TDWARDZE12EDAY520Z
MODEL/YEAR : NISSAN NOTE 1.2 (V) MY 2018
ENGINE NO : HR12200442J
CHASSIS NO : JN1TAAE12Z0982206
MILEAGE : 1 KM
DATE IN : 16/04/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : MUHAMMAD ZUHRI
ACCIDENT DATE : 21/03/2019

DIRECT SETTLEMENT

OWNER CLAIMING LOSS OF USE / RENTAL

~~CAR AT WORKSHOP~~ / CAR NOT AT WORKSHOP

KINDLY REVERT TO ME ASAP

EMAIL : zuhri@tanchong.com

OFFICE : 67038916 FAX : 64697472

16.4.2019

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SME440H

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 FHI	R/INSTALL FRONT H/LAMP & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	✓
2 NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS		
3 RPI	PERFORM RUST PROOFING & TREATMENT FOR 1/2X AFFECTED PANEL	240.00	?
4 RSI	R/INSTALL OR RENEW REVERSE SENSOR, NECESSARY ADJUSTMENT FUNCTION TEST	55.00	✓
5 SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	X
6 ZZ/001	REPAIR REAR END PANEL & FRT UPPER PANEL RENEW REAR & FRT BUMPER	875.00	500
7 ZZ/002	S/PAINT REAR BUMPER, REAR END PANEL, TAILGATE FRT UPPER PANEL & FRT BUMPER	900.00	800
TOTAL LABOUR CHARGES		2218.00	

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SME440H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
		NETT	LIST	S/NETT	
1 SUNDRIES	NPN			50.00	JO
2 REAR LICENCE PLATE X	RLP			60.00	
3 FRT LICENCE PLATE ✓ CNJ	FLP			60.00	
4 ORNAMENT-BACK D ✓ AIEC	90892-3VA0A	73.60			
5 EMBLEM-BACK DOO ✓ AIEC	90890-3VA0A	59.70			
6 BRKT BUMPER RH ?	85220-3VA0C	45.40			
7 BRKT BUMPER LH ?	85221-3VA0C	45.40			
8 ENERGY ABSORBER RR ?	85090-5WJ0A	111.90			
9 FACE-RR BUMPER ✓ DD	85022-5WJ0H	414.00			
10 CLIP(10X1.2) ✓ AIEC	01553-05933	12.00			
11 CLIP(7.4X2) ✓ AIEC	01554-0007U	14.80			
12 EMBLEM RAD GRIL ✓ DR	62890-3VA2A	59.70			
13 CLIP(20X1.2) ✓ AIEC	01553-10501	24.00			
14 GRILLE-RADIATOR ?	62320-3VA1A	194.40			
15 FACE-FR BUMPER ?	62022-5WJ0H	354.90			
SUB TOTAL		1409.80	0.00	170.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		281.96	0.00	0.00	
GRAND TOTAL		1127.84	0.00	170.00	
OVERALL TOTAL		1297.84			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SME440H

TOTAL LABOUR CHARGES	2218.00
TOTAL SPARE PARTS CHARGES	1297.84

GRAND TOTAL	3515.84 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Steve (LKK) 8322 8813
SURVEYED DATE	:	23/4/19 11.15am
AUTHORIZED DATE	:	with invoice
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	P/P Reng before Spring 4 days

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.