Memmeh From (Person	GUO Ctara ASSIGNME	MI (Office)	1)2104 201A
Lo Inspect V	elicle No. SLM 4565	4	Insured: GBD 36161
ii Workshop of	Steuli Flet tro	D # 06-1	Tel 90927279
olicy No. E	32909 6489MKF	Claim No:	518183
ium Insured		Excess	210203
Aske of Vehi			D.O.A 5/12/18
A / REV	/ REP. / REV 24 HRS 1007		12/12-118 -
Inte/Time:_	5:00pm@ II/10/18 Person Conlacted	Alen	Vehicle By OUT
late/Time	Action/Instruction (×) Estimate		
		Sulfred 3	Flog = 33 /06 /20 W
	OBDS&IAL-×		
	Dismantle: 13/12/2018.		
			The District of the Control of the C
	\$2600, 4 Days.		The State of Page 41

RECEIVED 1 9 JUN 2019

Nivitha (LKK Auto)

From:

Accounts (LKKAuto) <account@lkkauto.com>

Sent:

Monday, 15 April 2019 11:09 AM

To:

Admin-D (LKKAuto)

Cc:

assignments

Subject:

Report Send Back Alerts - SLM4565A (TP)

Dear Nivitha,

FYNA Please...

Pending for Survey Report-CS3/MSG18022314/GCD3E2

12 Apr 2019 17:18 Ins Send Back Adj Rpt please conduct paper survey.

[I] Pauline Tham

12 Apr 2019 17:18 Adj Next Rpt Changed Next Rpt:Final Rpt.Due Date:2019/04/16

[I] Merimen Administrator

Thank You

Best Regards,

SuthaShelia (Shelia) | Accounts Dept.

LKK Auto Consultants Pte Ltd

Phone: 6742 9588 | email: account@lkkauto.com | fax: 6844-8805

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]

Sent: Friday, 12 April 2019 5:20 PM

To: account@lkkauto.com

Subject: Report Send Back Alerts - SLM4565A (TP)

Dear Sir / Madam,

Please login to Merimen Online at www.merimen.com.sg for more information.

Thanks,

The Merimen Team

×

This email has been checked for viruses by AVG antivirus software.

www.avg.com

Add Fee:

tide knop 18 Interction 18

Local Local 15

West and 15

Heather Library

10

130

No.

Carrier to State !-

Report Format

Lump Sum / LB !: (S

180-



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 417800 Hotline: 6385 1171

Our reference:

18-12-1285

Date:

19/12/2018

INVOICE NO. 1285

Kiraly Automobile Pte Ltd c/o Team Autopro Pte Ltd 385 Sin Ming Drive #01-02 Voiom Inspection Centre Singapore 575718

Registration No.

SLM4565A

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report,	1	\$ 539.00
	inspection, photographs, transport and miscellaneous.	Total amount	\$ 539.00

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

L.L. Tan (Ms) Principal Consultant

- . Impact Analysis Consulting Pte Ltd. . Impact Analysis Academy Pte Ltd. IA Racking Solutions Pte Ltd
- * IA Accounting & Consultancy Pte Ltd * Infoknights International Services (Philippines) * IABN Pte Ltd



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

Our reference:

18-12-1285

Date:

19/12/2018

c/o Team Autopro Pte Ltd 385 Sin Ming Drive #01-02 Voiom Inspection Centre Singapore 575718

Dear Sirs

RE:

Road Traffic Accident on 5/12/2018

Kiraly Automobile Pte Ltd

In accordance with your instructions received in this office on

12/12/2018

, we made arrangements to

examine the vehicle on

12/12/2018

at above-mentioned address. The following data was

recorded:

Vehicle details


Make	Honda	Registration	SLM4565A
Model	Vezel Hybrid	Chassis	RU31218589
Colour	Brown	Gearbox	Auto
Odometer	158274km	Paintwork	Good
Steering	In order	Brakes	In order
Condition	Good		***

Tyre Depths

Front left	215/60R16	80% Dunlop
Front right	215/60R16	80% Dunlop
Rear left	215/60R16	80% Dunlop
Rear right	215/60R16	80% Dunlop

Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Impact Direction & Area of Damage:



Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$55,600.00 and 6 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Subsidiaries of Impact Analysis Consultant:

- Impact Analysis Consulting Pte Ltd. Impact Analysis Academy Pte Ltd. IA Racking Solutions Pte Ltd.
- IA Accounting & Consultancy Pte Ltd * Infoknights International Services (Philippines) * IABN Pte Ltd

No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

18-12-1285

Date

19/12/2018

Page

2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment	
List Items:					
Front bumper	1	deformed	887.50	88750	1485
Front bumper lower grille	1	deformed	528.30	528/30	1.0
Front bumper reinforcement	1	bent	412.50	412.50	- 321
Front bumper reinforcement moulding	111121	necessary	245.00	245/00)	E N/V
Front bumper side retainer @\$50.40	2 00 2	necessary	100.80	100.80	50.4
Front bumper fog lamp rh	1	damaged	354.90	354.90	2
Front bumper fog lamp cover rh	1	deformed	85.00	85:00	× 45
Headlamp assy rh	1	holder torn	1749.40		1580
Headlamp bracket rh	1	bent	59.60	59.60	V i
Centre grille	1	deformed	328.30	328.30	3 /
Centre grille cover	1	deformed	157.20	157.20	
Centre grille logo	1	necessary	51.20	51.20	X \ ~W
Front engine lower cover	1	deformed	344.00	344.00	2 /
Front bumper tow cover	1	grazed	42.00	42.00	\$ /
Front bumper side outer garnish rh	1	holder torn	134.50	134.50	2/
	Sub-Total	costs	5480.20	5480.20	20/16 2
Percentag	ge discount :	20%	1096.04	1096.04	670717
Su	b-Total costs	for parts	4384.16	4384.16	2271.4
Special Nett Items:					Carrie
Front bumper clips	1 set	necessary	50.00	50.00	30
Front number plate	1	grazed/cut	50.00		40
Su	b-Total costs	for parts	100.00	100.00	-
Parts Repair					Jo.
Front support panel	1	repair	742.10	0.00	
	Sub-Total	costs	742.10	0.00	
2	Total costs fo	r narts	5226.26	4484.16	

Subsidiaries of Impact Analysis Consultant:

Impact Analysis Consulting Pte Ltd. ◆ Impact Analysis Academy Pte Ltd. ◆ IA Racking Solutions Pte Ltd.

[•] IA Accounting & Consultancy Pte Ltd • Infoknights International Services (Philippines) • IABN Pte Ltd



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780

Hotline: 6385 1171

Our reference

18-12-1285

Date

19/12/2018

Page

3

Section B: Labour Cost Calculation

	Но	urly rate	Manhr, Req.	П	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$	50.00	22	\$	1,100.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.		Sub-con	tract work.	\$	900.00
Apply rust proofing on the adjacent panels.		Sub-con	tract work.	\$	30.00
Wiring and bulb checking	\$	50.00	0.5	\$	25.00
*				\$	51
		Total la	bour cost	\$	2,055.00

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

3266.44 20%-2600

778176

Subsidiaries of Impact Analysis Consultant:

Impact Analysis Consulting Pte Ltd. Impact Analysis Academy Pte Ltd. IA Racking Solutions Pte Ltd

. IA Accounting & Consultancy Pte Ltd . Infoknights International Services (Philippines) . IABN Pte Ltd



No.25 Kaki Bukit Road 4 #06-46 Synergy @KB Singapore 41780 Hotline: 6385 1171

Our reference

18-12-1285

Date

19/12/2018

Section C: Summary Table of Total Repair Cost

Des	cription	Cost	5
Damaged Parts Assessment (See section A)		\$4,484.16	
Replace parts			
Further discount	20%	\$896.83	
	nded cost of placement	\$3,587.33	(1)
Labour Cost Calculation (See section B)		\$2,055.00	(2)
	epair Cost to hundred)	\$5,600.00	(1) + (2)

We would recommend a sum of	\$5,600.00	and	6	working days for repair.
No further items will be approved	without our expresse	d written agreement	Any signif	licant additional
items will be subject to a suppleme	ntary report.			

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)

B.Eng. (Hons, NUS)

Diploma.Mechanical Engineering

NTC-2 Automovite Technology

Sr.MIES, Institution of Engineers, Singapore (#20100091)

MATAI, Maryland Association of Traffic Accident Investigators


IAARS, International Association of Accident Reconstruction Specialists

PMC of Singapore Business Advisors & Consultants Council

Subsidiaries of Impact Analysis Consultant:


^{*} IA Accounting & Consultancy Pte Ltd * Infoknights International Services (Philippines) * IABN Pte Ltd














































SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

A STATE OF THE STA	ACCIDENT STATEM	ENI
20 CH 10 CH 20 CH 10 CH		

Date Of Report 05/12/2018 15:45 Date Of Accident 05/12/2018 08:30

Exact Location Of Accident TUAS AVENUE 7 CARPARK

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLM4565A

Insured/Policyholder

Name Of Registered Owner KIRALY AUTOMOBILE PRIVATE LIMITED

Co Reg No 201436970K

Email Address NKF.BEN@GMAIL.COM

Mobile Phone No.

Alternative Phone No. OFFICE-64921785

Vehicle Particulars

Manufacturer HONDA

Model VEZEL 1.5A HYBRID

Exact Purpose for which vehicle was being used at PTE

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY PRIVATE HIRE

Insurance Company

Vehicle Category

Name of Insurance Company CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number Cover Note Number

Driver

Name of Driver LOOK JUN HONG

NRIC No S8384401I Date Of Birth 19/10/1983 Occupation OUTDOOR Date Of Driving Pass 17/12/2008

Driving Experience 9 YEARS AND 11 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-87428028

Fax Number

Contact Number

EMail Address NOEMAIL Address

BLK 817 JURONG WEST STREET 81#06-40

Postcode -

690817

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

OTHER - HIRER

Vehicle Registration Number of Driver's Own

Vehicle

ž

Insurance Company of Driver's Own Vehicle

-

General Information of the Accident

Type Of Accident

COLLIDED INTO PARKED VEHICLE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

2 NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

0

Details of Police Action

Was the accident reported to the police?

If Yes, Please state which Police Station

NO

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

MY CAR SLM4565A WAS PARKED IN A PARKING LOT . UPON COLLECTION OF MY CAR , THE DRIVER'S OF GBD3616J HAD APPROACHED ME AND INFORMED ME THAT HIS VAN HAD COLLIDED ONTO THE FRONT PORTION (RH) OF MY CAR WHILE HE WAS REVERSING.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBD3616J

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

ANPALAGAN A/L PATCHYMUTHU

NRIC/Passport Number

F1412856P

Contact Number

98004382

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please apport gorrectly the recially of the accident in speed on the status britishs
-] . This Form must be completed by the Policyholder and/or the Authorised Driver
- Information preceded must be at probabilized accurate as probable, dry with microproduction in webstoking of reserve facts may allow introduce companies to promise policy cability.
- 4. The note and a centancy of this form his impurity form more south as admission of policy liability on the part of the insulance of imparture.
- Any false reporting may be referred to the Pulice for investigation
- A The report will be forwarded by the animals of the Guk flavor in Association Control attables will by the General Boutance Association of programme (Guk) for an housing and that copies of two report will for a fee by made available upon application by name, and parties.
- If the independ of this issued to the insured, you beauty consent to the outwarp of this report at the centre and to copies of the report being made available of traces.
- 8 Coment under the Personal Data Princetion Act (PDPA)

Funderstand, edinostrope, agree and concretions

- (ii) My expert the workship and the General Holdschip Australian of Segapher ["GM"] may be prevented by policy of Security and Segapher ["GM"] may be prevented by policy of Security and Security an
 - An increase of the current and the control of the current and the
 - (A) monitoring the accident analysis my plants.
 - This servests out and/or coping with my entructions or responding to any enquiries by the
 - By attractioning the classic including the change of correspondence, statements, invoices, separts or notices to me, which should invoke disclosure of correspondence about me to long about delivery of the same as well as on the external count of involvages must packaged, and to
 - (v) a modying with approache few in editional energy programing precising analysis dealing with vey thous furnishment there's "Purposes";
- D. Silversetty arministrational acrecies involved within accident and the laborary seasons/seathern, may are permitted to belief use, excelpts and/or motivo my Personal Silversetty for one or many of the appears and
- (c) His Personal information (stay/far be depleted by any of the separts and/or left tentine third party service provides or appropriately their particular times, which may be letted outside of timpapore, he one or more of the above Purposes.
- (d) The same information will also be consisted and word to complex change for the company of final extension monthly risks and management in present and all finance change.
- the information as collected and orbit above may be shared, absorbed.
 - (i) an advancers and/or are other third parties that excell it eventually, inestituting, controlling or managing fraue, regulators. This principles of and government agreement or controlling requirement for the purposes stated on.

of the company, with requirements made any replacement has a count organ.


Postposter Tareflee Jose & Fore

Transcription to provide

2005,2409,240

Accident Sketch Plan

SKETCH PLAN



DOA: OSTIPLE

A: SLMUSGA

B: GBDZ616J

parted	in a	30 hr, n	lot. Ug	on Col	lection	6
my cor,	the c	lither's	To FIGO	3616 3	had a	rpproc
ellided o	nto the	fort p	ortion (ca

Promoter Signature

Nerve

MECTINE.

Identification Card





Driving Licence

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

DIRECTIVE DATE

Class 3 Motorcycles on 200 ac 17 Dec 200s Motorcycles on 200 ac 17 Dec 200s 17 Dec 200s with class 3 passengers, excusive of grover, and other meter withcles with unlikten weight or 2500kg

NF 426A






Vocational Licence



本田技研工業株式会社 型式 DAA-RU3 車台番号 RU3-1218589 T7BGOH7-YR635M -A-C
























Accident Photo







MSAT18157391 / Sng Ah Tee Motor & Panel Service Pte Ltd - Pioneer ENTRY DATE & TIME: 05/12/2018 14:51 SUBMITTED BY: JOYCE TAN LAI CHIN

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver,
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCIDENT STATEMENT

Date Of Report 05/12/2018 14:51

Date Of Accident 05/12/2018 08:30

Exact Location Of Accident INSIDE WORKERS DORMITORY TUAS AVE 7

Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBD3616J

Insured/Policyholder

Name Of Registered Owner CROWN EQUIPMENT (SINGAPORE) PTE. LTD.

Co Reg No 197800704G

Email Address NOEMAIL

Mobile Phone No.

Alternative Phone No. Office-66901925

Vehicle Particulars

Manufacturer HYUNDAI

Model H-1 STAREX-2.5 D CRDI (A)

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken REPORTING ONLY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.

NO

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number B29096489MKF

Cover Note Number

Driver

Name of Driver ANPALAGAN A/L PATCHYMUTHU

NRIC No F1412856P Date Of Birth 21/10/1970 Occupation

OUTDOOR Date Of Driving Pass 25/07/2017

Driving Experience 1 YEAR AND 4 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-98004382

Fax'Number Contact Number **EMail Address** NOEMAIL Address 15, TUAS AVENUE 8, SINGAPORE 639230 Postcode Was driver an employee of the Insured's Company YES If No. Relationship of the Driver with the Insured Vehicle Registration Number of Driver's Own Vehicle Insurance Company of Driver's Own Vehicle General Information of the Accident Type Of Accident COLLIDED INTO PARKED VEHICLE Weather Conditions CLEAR Road Surface DRY Other Information Was any foreign vehicle involved in this accident? NO Number of vehicles involved in the accident Was any body injured in the Accident? NO Was any injured conveyed to hospital by NO ambulance? Was any other material or property damaged? YES I have been approached by unknown person(s) NO soliciting/offering accident claims assistance. Number of Passengers (Including Driver) **Details of Police Action** Was the accident reported to the police? NO If Yes, Please state which Police Station Was notice of intended Prosecution given? NO If Yes, against whom? Circumstances of Accident ON 05/12/2018 AT ABOUT 0830 HRS. WHILE I WAS REVERSE OUT FROM THE PARKING LOT. MY VEHICLE ACCIDENTALLY Attachment(s) YES NO DETAILS OF OTHER VEHICLE PROPERTY 1

TOUCH ONTO FRT PORTION OF THE VEHICLE B.

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Vehicle Registration Number

SLM4565A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

LOOK JUN HONG

NRIC/Passport Number

S8384401I

Contact Number

Address Postcode Insurance Company Name Nature Of Damage No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims:
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages): and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents[including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time:

Driver's Senature "

(If driver is not the policyholder)


Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

I AM AWARED THAT MY PI SURER MAY HAVE A 14 DAYS TIMEFRAME FOR ME TO SUBMIT AMOWN DAMAGE CLAIM UNDER MY OWN POLICY, I WILL CHECK MY POLICY FOR MORE DETAILS.



A-G803616J B-SLM456SA

Workers Dormitory Tuas Ave 7

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Paker to	circumstances	
		D Claim own policy
	4	☐ Claim third party ☐ Claim OD / TP at other works hop
CLARATION		For record purpose
e declare the foregoing p	articulars are true in every respect.	Palloy No B 2969 6489 MKF Insurer MS! G Ven No GBD 3616
	P. Dradeze	- 1
cyholder's Signature e & Time:	Driver's Signature (If driver is not the policyholder) Date & Time:	Reporting Centre Personnel's Signature Name:



Accident Photo







Accident Photo



...CLAIM SUBFOLDER...(Pending for Survey Report)

AIM SUBF	OLDER TRA	CKING									
Case 1	Notified	Est Submitted	Adj Assigned	Adj Rpt		Adj S	Submitted	Ins Auth'ed	Pending for Survey Report Cancel Case		
Main	05 Dec 2018		11 Dec 2018 16:16 Edit Adj Rpt	S\$2,60 Edit Es	0.00 timates	33.57	,600.00 ew Rpt				ey
	tain	∏R	eference		laim Det	ails		Document	•)	Show	All
CLAIM SUE	FOLDER DE	TAILS					[Created	oy insurer]			
Insured:						7800	704G				
dain Claimant:	KIRALY A	UTOMOBILE PR	IVATE LIMITED,	Co. Reg. N	o.: 20143	6970K					
Vehicle Reg. No.:	SLM456	5A			Date of	Loss:		08:00 - :59 and 5 Days From	n LTA Reg I	Date (Man Y	r)]
Claim Type:	TP / 578	283			Policy/Co Note No			MKF (Comprehen 01/10/2018 - 30/			
Vehicle Reg. No. (Insured):	GBD3616	j.			Policy No (Claimar						
					Excess:						
Repairer:	Team Aut 90927279	opro Pte Ltd (K/	AKI BUKIT) No.8 K	aki Bukit A	venue 4, 4	#06-23	1 Premier®	Kaki Bukit (Gate	2), 415875	Kaki Bukit -	Tel:
Handling Insurer:			ere) Pte. Ltd. (HQ)								
Adjuster:		Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 _	[Handled	by XI	ING GUO Q	IANG] [Fina	Rpt due	16/04/20	19]
Driver/Custo dian (Insured):		N A/L PATCHYMU	THU () , NRIC: F1	412856P,	Tel: +65	98004	1382 Email:				
Adj Asg. Remarks:	SJE DISAG	REE APPOINT LK	LIAB IS CLEAR. P	LS CONTAC	T Mr. Alar	Koh/I	Frederick Lir	n at 9092 7279/9	674 6635		
ASSOCIAT	ED MAIL RE	CEIVED						Vie	rw All C	ompose Case	e Mail
MSIG_SG	(12/04/2019): Report Send	Back Alerts - SLM4	4565A (TP)						
	CIATED TAS	KS ^{EI}				V	/iew All S	earch Tasks	Create New 7	Task Con	mplete
ALL ASSO							ed By	Completed On			Done

Claim Documents

*SLM4565A (578283) [GBD36163] TP

KIRALY AUTOMOBILE PRIVATE LIMITED Dec 5 2018 8:00AM [CROWN EQUIPMENT (SINGAPORE) PTE. LTD.] Team Autopro Pte Ltd

Ass	essment Reports		1 per	page 🔻	V
No:	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/12/18 11:34	Accident Statement From: SC - Reg. No: GBD3616J, Claimant: CROWN EQUIPMENT (SINGAPORE) PTE. LTD.	0	Load HTM	
Pho	tos/Images		3 per	page 🔻	2
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnall	Print
1	17/12/18 13:37	General View	0	Load JPG	V
2	17/12/18 13:37	General View	0	Load JPG	N
3	17/12/18 13:37	General View	0	Load JPG	V
4	17/12/18 13:37	General View	0	Load JPG	N.
5	17/12/18 13:37	General View	0	Load JPG	Ø
6	17/12/18 13:37	General View	0	Load JPG	1
7	17/12/18 13:37	General View	0	Load JPG	V
8	17/12/18 13:37	General View	0	Load 3PG	V
9	17/12/18 13:37	General View	0	Load JPG	120
10	17/12/18 13:37	General View	0	Load JPG	V
11	17/12/18 13:37	General View	0	Load 3PG	2
12	17/12/18 13:37	General View	0	Load JPG	V
13	17/12/18 13:37	General View	0	Load JPG	V
14	17/12/18 13:37	General View	0	Load JPG	V
15	17/12/18 13:37	General View	0	Load JPG	V
16	17/12/18 13:37	General View	0	Load JPG	E21
17	17/12/18 13:37	General View	0	Load JPG	V
18	17/12/18 13:37	General View	0	Load JPG	Ø
19	17/12/18 13:37	General View	0	Load JPG	S
20:	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	V
21	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	V
22	17/12/18 13:38	Photographs of Damaged Parts	0	Load 3PG	V
23	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	Ø
24	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	2
25	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	V
26	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	N.
27	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	V
28	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	₩
29	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	V
30	17/12/18 13:38	Photographs of Damaged Parts	0	Load 3PG	120
31	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	120
32	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	V
33	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	V

Ass	essment Reports		1 per i	page v	2
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
34	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	V
35	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	2
36	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	V
37	17/12/18 13:38	Photographs of Damaged Parts	0	Load JPG	V
38	17/12/18 13:38	Photographs of Damaged Parts	0	Load 3PG	3
	umentation		1 per	page V	
DOC			1 per		_
No.	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
I	10/12/18 11:34	TP SLM4565A E-REPORT From:SC - Rag. Res. (BBD3616), Claimant: CROWN EQUIPMENT (SINGAPORE) PTE. LTD.	0	Load PDF	
2	04/02/19 09:29	survey photos	0	Load PDF	
3	04/02/19 09:29	survey report	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	20/06/19 14:53	Colour Photo	0	Load PDF	
	20/06/19 14:53	PRS Invoice	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
	0
	~
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co. Reg. No.:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG18022314/GSD3E2-1

Date:

20/06/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

B29096489MKF

Claimant Vehicle SLM4565A

Insured Vehicle No:

GBD3616J

No: Date of Loss:

05/12/2018

Nature of Claim:

TP

Claim No: 578283

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SLM4565A

Make & Model:

HONDA VEZEL, 1.5 HYBRID (A) 30/03/2017 (Man. Year: 2016)

Engine No:

LFB5918599

Reg. Date: Colour

Brown

Chassis No: Odometer:

RU31218589 158274 km

Engine Capacity:

1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size:

215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side:

Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side:

Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,226.26	2,441.44	2,784.82	53.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,055.00	825.00	1,230.00	59.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,281.26	3,266.44	4,014.82	55.14
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	7,281.26	2,600.00	4,681.26	64.29

INSPECTION

Date of Assignment:

11/12/2018

Date Inspected:

12/12/2018 Inspected At:

Team Autopro Pte Ltd (KAKI BUKIT)

No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit (Gate 2)

Singapore 415875

Estimated Period of Repair:

4.0 days

Adjuster: XING GUO QIANG

Manager:

Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Referen	ce	
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Jun 2019)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted	no print-code for SLM4565A)
Validity:		tes are valid only if they contain the print code (above) on all estimate pages, running page the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values	not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	887.50 FL	*495.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Deformed	528.30 FL	*118.00 FL
3	1		*FRONT BUMPER REINFORCEMENT	Bent	412.50 FL	*321.00 FL
4	1		*FRONT BUMPER REINFORCEMENT MOULDING	Not Necessary	245.00 FL	*-FL
5	1		*FRONT BUMPER FOG LAMP RH	Damaged	354.90 FL	*354.90 FL
6	1		*FRONT BUMPER FOG LAMP COVER RH	Deformed	85.00 FL	*45.00 FL
7	1		*HEADLAMP ASSY RH	Holder Torn	1,749.40 FL	*1,580.00 FL
8	1		*HEADLAMP BRACKET RH	Not Necessary	59.60 FL	*-FL
9	1		*CENTRE GRILLE	Not Necessary	328.30 FL	*-FL
10	1		*CENTRE GRILLE COVER	Not Necessary	157.20 FL	*-FL
11	1		*CENTRE GRILLE LOGO	Not Necessary	51.20 FL	*-FL
12	1		*FRONT ENGINE LOWER COVER	Not Necessary	344.00 FL	*-FL
13	1		*FRONT BUMPER TOW COVER	Not Necessary	42.00 FL	*-FL
14	1		*FRONT BUMPER SIDE OUTER GARNISH RH	Not Necessary	134.50 FL	*-FL
15	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
16	1		*FRONT NUMBER PLATE	Grazed / Cut	50.00 FS	*40.00 FS
17	1		*FRONT SUPPORT PANEL	Repair	742.10 FS	*-F8
18	1		*FRONT BUMPER SIDE RETAINER	N/S Not Necessary/O/SNecessary	100.80 FL	*50.40 FL
F=Fn	anchise	part. S=1	SpcNett. L=ListItemDisc.	Sub Total (S\$)	6,322.30	3,034.30
			- List Item Discou	int on L Items 20.00/20.00% (S\$)	State of the state	592.86
				Total Parts (S\$)	5,226.26	2,441.44

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Re	commended Labour			AVIOR VIOLEN
No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO DISMANTLE, REPLACE, CUT, WELD, KNOCK OUT DENTS TO STRAIGHTEN ACCIDENT PARTS AS-MENTIONED ON THE PARTS REPAIR COLUMN INCLUSIVE OF REPLACEMENT PARTS	New	1,100.00	400.00
2	PUTTY & SPRAY PAINTING TO ADJACENT PANELS. JOB ALLOWANCE. PAINT / MATERIAL	New	900.00	400.00
3	APPLY RUST PROOFING ON THE ADJACENT PANELS	New	30.00	0.00
4	WIRING AND BULB CHECKING	New	25.00	25.00
	Gross Labou	r Cost (S\$)	2,055.00	825.00
	Report was unsubmitted during	this print-out		

< END OF ESTIMATES >