

新合利服務公司

Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

10 April 2019

Attn: Motor Claim Department
AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

KIN SENG PRINTCRAFT MANUFACTURER PTE LTD
c/o Sin Hup Lee Service Co.
Block 1005 Bukit Merah Lane 2 #01-20
Singapore 159761

Dear Sir/Ms,

Re: Road Traffic on 04 April 2019 at Adam road, involving vehicle SMF8304K/ GBE512H

Quotation for Repair Vehicle No: GBE512H, Nissan NV200 (Third Party Claim)

Quantity	Nett Item		
1	Rear Boot <i>Ben</i>	\$	1,724.60
1	Rear Boot Logo <i>ne</i>	\$	145.60
1	Rear Boot Emblem 'NV200' <i>ne</i>	\$	97.90
1	Rear Boot Emblem 'VANETTE' <i>ne</i>	\$	86.90
1	Rear Boot Sticker '600KG' <i>ne</i>	\$	55.10
1	Rear Boot W/S Moulding <i>ne</i>	\$	110.00
1	Rear Boot Lock <i>bt</i>	\$	261.00
1	Rear Boot Catch <i>MA</i>	\$	43.80
1	Rear Boot Rubber <i>ne</i>	\$	183.80
1	Tail Lamp <i>BH</i>	\$	235.20
1	Rear Panel <i>BT</i>	\$	598.40
1	Rear Panel Inner Member <i>MA</i>	\$	168.60
1	Rear Panel Top Garnish <i>MS</i>	\$	96.90
1	Rear Bumper <i>DE</i>	\$	581.10

1	Rear Bumper Sponge X	\$	84.90
1	Rear Bumper Reinforcement X	\$	182.00
1	Rear Bumper Tow Cover X	\$	27.40
2	Rear Bumper Bracket L+R <i>na</i>	\$	73.20
10	Rear Bumper Clip <i>na</i>	\$	40.00
1	Rear Spare Tyre Bracket X	\$	198.90
1	Rear Spare Tyre Fastener X	\$	45.50
		\$	5,040.80
	Less 10%	\$	504.08
		\$	4,536.72

S/NETT

1	Rear Boot Sticker '600KG' <i>na</i>	\$	10.00
1	Rear Boot Sticker '70km' <i>na</i>	\$	10.00
1	Rear Boot W/S Sealant <i>na</i>	\$	40.00
1	Rear No. Plate X	\$	50.00
1	Rear Bumper Reverses Sensor <i>na</i>	\$	200.00
		\$	310.00

Labour

1	To cut-weld Rear End Panel, Rear Inner Member. To repair Rear Floor Panel, Rear Chassis Member, remove and re-fix damaged parts, straighten and realign affected areas.	\$	1,140.00 <i>900</i>
2	To spray affected areas	\$	1,000.00 <i>800</i>
3	To remove and re-fix Rear W/S Glass	\$	180.00 <i>120</i>
4	To remove and re-fix Rear Boot Mechanism. Check & test Wiper Motor and Centre Locking System	\$	120.00 <i>60</i>
5	To remove and re-fix Rear Spare Tyre, Spare Tyre Carriage and other attachment parts	\$	50.00
6	To install Reverse Sensor and check Water Seepage	\$	60.00 <i>40</i>
7	To rustproof affected areas	\$	90.00 <i>60</i>
Total Amount		\$	7,486.72

Kindly arrange your surveyor to survey my vehicle.

We look forward to hear from you soon.

Thank you.

Yours Faithfully

Mr Wong

81122116

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 2 of 2

Acknowledged by Repairer
Signature: _____
Date: _____

RASUL

Hp 90010068

8 days

4/5

15/04/19 @ 1130

Resurvey after repair