

July

新合利服務公司

Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

10 April 2019

Attn: Motor Claim Department
AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

KIN SENG PRINTCRAFT MANUFACTURER PTE LTD
c/o Sin Hup Lee Service Co.
Block 1005 Bukit Merah Lane 2 #01-20
Singapore 159761

Dear Sir/Ms,

Re: Road Traffic on 04 April 2019 at Adam road, involving vehicle SMF8304K/ GBE512H (VM 20083574) (2015)

Quotation for Repair Vehicle No: GBE512H, Nissan NV200 (Third Party Claim)

Quantity	Nett Item		
1	Rear Boot	\$	1,724.60
1	Rear Boot Logo	\$	145.60
1	Rear Boot Emblem 'NV200'	\$	97.90
1	Rear Boot Emblem 'VANETTE'	\$	86.90
1	Rear Boot Sticker '600KG'	\$	55.10
1	Rear Boot W/S Moulding	\$	110.00
1	Rear Boot Lock	\$	261.00
1	Rear Boot Catch	\$	43.80
1	Rear Boot Rubber	\$	183.80
1	Tail Lamp	\$	235.20
1	Rear Panel	\$	598.40
1	Rear Panel Inner Member	\$	168.60
1	Rear Panel Top Garnish	\$	96.90
1	Rear Bumper	\$	581.10

3655.26

260.00

2030.00

5945.26

20%

4,756.20

L/S-4,750

8 days

1	Rear Bumper Sponge X		\$	X 84.90
1	Rear Bumper Reinforcement X		\$	X 182.00
1	Rear Bumper Tow Cover X	4061.40	\$	X 27.40
2	Rear Bumper Bracket L+R ✓		\$	73.20 ✓
10	Rear Bumper Clip ✓	10%	\$	40.00 ✓
1	Rear Spare Tyre Bracket X		\$	X 198.90
1	Rear Spare Tyre Fastener X	3655.26	\$	X 45.50
			\$	5,040.80
		Less 10%	\$	504.08
			\$	4,536.72

S/NETT

1	Rear Boot Sticker '600KG' ✓		\$	10.00
1	Rear Boot Sticker '70km' ✓		\$	10.00
1	Rear Boot W/S Sealant ✓		\$	40.00
1	Rear No. Plate X	260	\$	X 50.00
1	Rear Bumper Reverses Sensor ✓		\$	200.00
			\$	310.00

Labour

1	To cut-weld Rear End Panel, Rear Inner Member. To repair Rear Floor Panel, Rear Chassis Member, remove and re-fix damaged parts, straighten and realign affected areas.		\$	1,140.00 900
2	To spray affected areas		\$	1,000.00 800
3	To remove and re-fix Rear W/S Glass	2030	\$	180.00 120
4	To remove and re-fix Rear Boot Mechanism. Check & test Wiper Motor and Centre Locking System		\$	120.00 60
5	To remove and re-fix Rear Spare Tyre, Spare Tyre Carriage and other attachment parts		\$	50.00 ✓
6	To install Reverse Sensor and check Water Seepage		\$	50.00 40
7	To rustproof affected areas		\$	90.00 60
			\$	7,486.72

Total Amount

Kindly arrange your surveyor to survey my vehicle.
We look forward to hear from you soon. a
Thank you.

Yours Faithfully
Mr Wong
81122116

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Page 2 of 2

Acknowledged by Repairer
Signature:
Date:

Rasul

Hp 90010068

8 days

4/5

15/04/19 @ 1130

Repair after repair