

Survivor:

UMP

DOI:

ASSIGNMENT

15/4/19

Date / Time:

15/4/19

Registered in Meritmen:

Pre-assign / CCU / FTE

Yp 768M



Insured Vehicle No.:

Name of Insured:

MUA HIN POU TRY PAPER Y/L

Insured Tel No.:

HP:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

Excess Sec II : \$5

D.O.A.:

12/4/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SK888 U



INSRS:

WSP:

Tel:

Liability:

RMKS:

M44



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

DATE / PIC

STAGE

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

25/6/19

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

\$5

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 21/8/19

Confirm with Sukyi

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. : 27

IF NO or B 28, Ass. Lin:

Repair Cost: (w/687)

\$5 49220.00

Loss of Rental (LOR):

\$5

(

days)

Loss of Use (LOU):

\$5

2160.00 (\$ 60 x 36 days)

Loss of Income (LOI):

\$5

(\$ x days)

LOR only ☐ LOU only ☒

\$5 9.45

LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$5

Medical:

\$5

Disbursement:

\$5

(e.g. Tow/ Independent)

Legal Cost

\$5

Total:

\$5 51387.45

Global Sum \$5: 51300.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$5 51300.00

Name 1:

New Hock Teck Motor Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

21/8/19

26/8/19

Adrian

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop n/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 28 days Res.: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Vehicle: IN / OUT  
Person Contacted: \_\_\_\_\_Veh No: SK888U Yr Regn: 2017 1 NovType: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A4 c.c. 1395Colour Blue A/C: Insured / Std / NI / NASp. Reading 14895 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WAUZZZF47JA035848Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: 205/60R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. D.O.I. 15/04/19Survey held at NHTDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Rego.Ls - \$46000 (Red \$47882.40 / 51%)MV: 115KPV: 668KNett: 482K

Date/Time, File Pass to?

Date/Time, File Return to?

Part Prices Check

Survey Fee:

Date:

1)

2)

IN

OUT

Basic &amp; Add.

S + RS, SI

Photos

Others

TOTAL

Pres. Report:

Final Report:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

12/04/2019

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

TP Ergo.

Jis le.

Accident date: 12/04/2019

Estimated repair cost for vehicle no: SK8888U AUDI A4 1.4 A '17

CHASSIS: WAUZZZF47JA035848

S/n	Qty	Items	U/price	Amount
1	1	Rear Windscreen Assy <i>lt</i>		\$1,062.35 ✓
2	1	Rear Boot Lid <i>Distorted</i>		\$1,919.65 ✓
3	2	Rear Boot Lid Hinge <i>Best</i>	\$200.70	\$401.40 ✓
4	2	Rear Boot Lid Shock Absorber <i>Best</i>	\$182.95	\$365.90 <i>182.55</i> ✓
5	1	Rear Boot Lid Emblem Logo		\$93.65 ✓
6	1	Rear Boot Lid A4 Logo <i>new</i>		\$72.30 ✓
7	1	Rear Boot Lid Tfsi Logo		\$72.30 ✓
8	1	Rear Boot Lid Number Plate <i>Best</i>		\$50.00 ✓
9	2	Rear Boot Lid Number Plate Lamp <i>crushed</i>	\$82.90	\$165.80 ✓
10	2	Rear Boot Lid Side Reflector <i>smashed</i>	\$689.05	\$1,378.10 ✓
11	1	Rear Boot Lid Inner Lock <i>damaged</i>		\$133.65 ✓
12	1	Rear Boot Lid Inner Rubber <i>lt</i>		\$144.45 ✓
13	1	Rear Boot Lid Inner Trim Board <i>crushed</i>		\$255.15 ✓
14	10	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$65.00 ✓
15	1	Rear Boot Lid Lock Switch & Camera Assembly <i>damaged</i>		\$926.00 ✓
16	2	Rear Tail Lamp <i>Smashed</i>	\$697.60	\$1,395.20 ✓
17	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 ✓
18	2	Rear Tail Lamp Lower Bracket <i>damaged</i>	\$25.40	\$50.80 ✓
19	2	Rear Tail Lamp Panel <i>Dented</i>	\$181.75	\$363.50 ✓
20	2	Rear Tail Lamp Inner Panel <i>dented</i>	\$152.55	\$305.10 ✓
21	1	Rear Bumper <i>Distorted</i>		\$1,620.55 ✓
22	1	Rear Bumper Lower Lid <i>Distorted</i>		\$476.50 ✓
23	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 <i>50</i> ✓
24	2	Rear Bumper Side Retainer <i>new</i>	\$60.85	\$121.70 ✓
25	2	Rear Bumper Side Reflector <i>crushed</i>	\$69.30	\$138.60 ✓
26	1	Rear Bumper Towing Cover <i>distorted</i>		\$35.60 ✓
27	1	Rear Bumper Reinforcement <i>Best</i>		\$686.65 ✓
28	1	Rear End Panel <i>distorted</i>		\$643.45 ✓

29	1	Rear End Panel Inner	Distorted		\$343.55	✓
30	1	Rear End Panel Top Garnish	distorted		\$203.95	✓
31	2	Rear Fender	Buckled	\$2,093.25	\$4,186.50	✓
32	2	Rear Fender Inner Panel	Buckled	\$713.85	\$1,427.70	✓
33	2	Rear Fender Housing Panel	Buckled	\$470.25	\$940.50	✓
34	2	Rear Fender Housing Inner Panel	Regis	\$892.30	\$1,784.60	+
35	2	Rear Fender Air Duct	new	\$65.45	\$130.90	+
36	2	Rear Fender Cowling	new	\$177.25	\$354.50	+
37	12	Rear Fender Cowling Clip	new	\$6.50	\$78.00	+
38	2	Rear Fender Quarter Glass Assy	new	\$397.35	\$794.70	✓
39	2	Rear Fender Quarter Glass Chrome	new	\$368.95	\$737.90	✓
40	1	Rear R/H Petrol Tank	new		\$4,292.65	+
41	1	Rear R/H Petrol Tank Cover	new		\$229.85	+
42	1	Rear Spare Tyre Panel	Distorted		\$1,734.75	✓
43	2	Rear Spare Tyre Side Panel	Buckled	\$628.45	\$1,256.90	✓
44	1	Rear Spare Tyre Panel Top Cover	Distorted		\$537.80	✓
45	1	Rear Spare Tyre Panel Lower Cover	new		\$265.05	✓
46	1	Rear Spare Tyre Panel Tool Box	new		\$235.95	✓
47	1	Rear Spare Tyre Panel Insulation Pad	new		\$450.00	+
48	1	Rear Exhaust	Bent		\$1,426.55	✓
49	2	Rear Exhaust Mounting	new	\$43.95	\$87.90	+
50	1	Rear Exhaust Aluminium Cover (Small)	crushed		\$152.80	✓
51	1	Rear Exhaust Aluminium Cover (Big)			\$214.80	✓
52	1	Rear Center Exhaust	Bent		\$1,884.55	✓
53	2	Rear Lower Arm	LH Bent	\$858.55	\$1,717.10	858.5
54	2	Rear Upper Arm	LH Bent	\$640.20	\$1,280.40	640.2
55	2	Rear Upper Arm Inner	LH Bent	\$548.15	\$1,096.30	548.1
56	2	Rear Knuckle Arm	LH Dmg	\$1,045.50	\$2,091.00	1045.5
57	2	Rear Knuckle Arm Bearing	LH Dmg	\$477.70	\$955.40	477.7
58	2	Rear Shock Absorber	LH Bent	\$438.25	\$876.50	438.2
59	2	Rear Trailing Arm	LH Bent	\$224.05	\$448.10	+
60	1	Rear Stabilizer Bar	new		\$399.25	+
61	1	Rear Center Crossmember	Bent		\$3,318.35	✓
62	1	Rear L/H Door	Dented		\$1,610.95	✓
63	2	Rear L/H Door Hinge	new	\$67.55	\$135.10	+
64	1	Rear L/H Door Inner Lock	Dented		\$443.75	+
65	1	Rear L/H Door Inner Rubber	new		\$145.85	✓
66	1	Rear L/H Door Inner Trim Board	new		\$1,340.85	+
67	1	Rear L/H Door Top Chrome Moulding	new		\$177.25	+
68	1	Rear L/H Door Lower Chrome Moulding			\$274.40	+
69	1	Rear R/H Door	Dented		\$1,610.95	✓
70	2	Rear R/H Door Hinge	new	\$67.55	\$135.10	+
71	1	Rear R/H Door Inner Lock	Damaged		\$443.75	✓

72	1	Rear R/H Door Inner Rubber	new		\$145.85	✓
73	1	Rear R/H Door Inner Trim Board			\$1,340.85	+
74	1	Rear R/H Door Top Chrome Moulding	3 new		\$177.25	✓
75	1	Rear R/H Door Lower Chrome Moulding			\$274.40	+
76	1	L/H Door Frame Panel	3 Repairs		\$2,593.25	+
77	1	R/H Door Frame Panel			\$2,593.25	+
78	1	Front L/H Car Seat	new		\$2,324.80	+
79	1	Front R/H Car Seat	Bent		\$2,324.80	✓
80	1	Front R/H Car Seat Rear Board	new		\$459.15	+
81	2	Front Seat Belt	Activated	\$829.60	\$1,659.20	✓
82	2	Front Seat Belt Buckle	new	\$287.45	\$574.90	+
83	1	Rear Battery	new		\$856.55	+
84	1	Rear Crash Sensor/Fuse	Activator		\$251.10	✓

Subtotal :- \$70,868.40

45149.25  
4289178

### Labour charges

To remove & refit rear cushion, battery & sensors	<del>\$380.00</del> 280
To remove & refit roof top lining & trim board	<del>\$480.00</del> 160
To remove & refit front car seat, cushion & seat belt	<del>\$480.00</del> 300
To remove & refit rear & centre exhaust	<del>\$380.00</del> 200
To remove & refit petrol tank	<del>\$380.00</del> 100
To remove & refit reverse sensor	<del>\$100.00</del> 60
To remove & refit reverse camera	<del>\$180.00</del> 60
To remove & refit rear windscreen	<del>\$120.00</del> ✓
Gum	<del>\$60.00</del> ✓
To remove & refit rear L/H & R/H fender glass	<del>\$200.00</del> 120
Gum	<del>\$100.00</del> 60
To remove & refit rear L/H & R/H door, lock, rubber, gear motor & trim board	<del>\$480.00</del> + 200

To remove & refit rear L/H & R/H undercarriage & crossmember	<del>\$680.00</del> 600
To reset computer	<del>\$380.00</del> 200
To check wheel alignment	<del>\$150.00</del> 80
To check wiring	<del>\$100.00</del> 30
Tuff kote	\$150.00 ✓
Towing fee	<del>\$150.00</del> 120
Panel Beating	<del>\$8,000.00</del> 3800
Spray painting	<del>\$3,500.00</del> 2600

Subtotal :- \$16,450.00

Total:- \$87,318.40

Supplementary: 5750.56

total 57942.34

L/S AGK

28 days

Chassis 1835  
Trimboard 9225

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:





新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201713370K

26/04/2019

Blk 1 Kaki Bukit Ave 6

# 01-43

Singapore 417883

Accident date: 12/04/2019

Supplementary repair cost for vehicle no: SK8888U AUDI A4 1.4 A '17

CHASSIS: WAUZZZF47JA035848

S/n	Qty	Items	U/price	Amount
1	2	Rear Boot Lid Hinge Cover <i>could</i>	\$58.00	\$116.00 ✓
2	2	Rear Boot Lid Side Reflector Trim <i>at</i>	\$25.00	\$50.00 ✓
3	1	Rear Boot Lid Auto Lock Release Module <i>Done</i>		\$395.00 ✓
4	2	Rear Tail Lamp Side Trim <i>at</i>	\$85.00	\$170.00 ✓
5	1	Rear Bumper Inner Frame <i>could</i>		\$268.00 ✓
6	1	Rear Bumper Security Strip <i>Done</i>		\$206.00 ✓
7	1	Rear Fuel Lid Cover <i>Done Build</i>		\$108.00 ✓
8	1	Rear Fuel Lid Lock <i>Done</i>		\$245.00 ✓
9	2	Rear Fender Inner Trim Board <i>could</i>	\$690.00	\$1,380.00 ✓
10	16	Rear Fender Inner Trim Board Clip <i>in</i>	\$6.50	\$104.00 ✓
11	1	Rear Reverse Sensor Wire Harness <i>snapped</i>		\$618.00 ✓
12	1	Rear Battery Clamp <i>Done</i>		\$88.00 ✓
13	1	Rear Tools Sponge <i>replaced</i>		\$198.00 ✓
14	1	Rear Spare Tyre Panel Inner Garnish Cover <i>could</i>		\$458.00 ✓
15	1	Rear L/H Chassis Frame <i>Best.</i>		\$1,580.00 ✓

5684.80

5400.56

Subtotal :- \$5,984.00

### Labour charges

350

To perform chassis alignment

\$580.00 350

Subtotal :- \$580.00

Total :- \$6,564.00

5841 6715

Supplementary: 5750.56

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Information	
Owner ID Type:	Singapore NRIC
Owner ID:	7517A
Vehicle Details	
Vehicle No.:	SK8888U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	15 Apr 2019
Vehicle Make:	AUDI
Vehicle Model:	A4 1.4 TFSI S TRONIC
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	CVN046663
Chassis No.:	WAUZZZF47JA035848
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$32,726.00
Original Registration Date:	16 Nov 2017
First Registration Date:	16 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$27,817.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Nov 2027
PARF Rebate Amount:	\$20,862.00
Intended COE Registration Details	
COE Expiry Date:	15 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$45,931.00
Total Rebate Amount:	\$66,793.00

The information contained herein is correct as at 15 Apr 2019

OK



## FREE VALUATION

Let us tell you how much your car can sell for!

No obligations and it's FREE!

How much is my car worth?












## Used Car Comparison

— Comparing 3 Vehicles —

Audi A4 1.4A TFSI S-tronic

Audi A4 1.4A TFSI S-tronic

Audi A4 1.4A TFSI S-tronic



Clear All

[Back to search result](#)

## CAR DETAILS

Price	\$112,800	\$115,888	\$118,000	-
Instalment	\$974	\$1,000	\$1,019	-
Registration Date	31-Mar-2017	27-Sep-2017	06-Oct-2017	-
Manufactured	2016	2017	2017	-
Mileage	13,000 km	18,500 km	17,000 km	-
Transmission	Auto	Auto	Auto	-
Engine Cap	1,395 cc	1,395 cc	1,395 cc	-
Road Tax	\$624 /yr	\$624 /yr	\$624 /yr	-
Power	110.0 kW (147 bhp)	110.0 kW (147 bhp)	110.0 kW (147 bhp)	-
Curb Weight	1,450 kg	1,450 kg	1,450 kg	-
Features	Audi 4 Cylinder Inline 16 Valve DOHC Turbocharged, 7-speed S-Tronic, Paddle Shift, Keyless Entry/Start, Auto LED Headlight, Multi Function Steering.	Audi A4 1.4L 4 Cylinders Inline Petrol Engine Turbocharged 150 Bhp 7-Speed S-Tronic, Audi Drive Select.	4 Cylinder Inline 16 Valve DOHC Turbocharged, 7 Speed S-Tronic, Paddle Shift, Keyless Entry/Start, Auto LED Headlight, Multi Function Steering.	-
Accessories	Audi Drive Select, Audi Sound System With Bluetooth, Rear Parking Sensor, Auto Headlights, Rain Sensing Wipers.	Front And Back Audi Car Camera, Sports Foot Pedal, RS Style Grill, 19 Inch Sports Rims And Goodyear F1AZ Tyres.	Audi Drive Select, Audi Sound System With Bluetooth And USB, Audi MMI Infotainment System, Reverse Camera, Front And Rear Cam.	-
Description	Very Beautiful Manhattan Grey Exterior And Black Interior. Fully Serviced And Maintained By Premium Automobiles. Warranty Till March 2022, Free Service By Audi Service Center Till March 2022, Super Low Mileage! View To Believe! Viewing By Appointment Only.	1 Owner, Agent Unit With Agent Warranty Till 2022. Full Documented History With PA, Assured Accident Free, Welcome STA/AA/PA Evaluation. Almost New With 12K KM On The Clock. The New A4 Boasts A Punchy New 1.4L Turbocharged Engine Producing 150Bhp And Excellent Fuel Economy. Upgraded Front Grille (Original Given). New SMC Number Plate For The Next Buyer. Viewing By Appointment.	1 Owner Agent Unit With 5 Years Warranty And 5 Years Free Servicing. 10 Years Engine Warranty Package. S4 BodyKit. Low Mileage Done And In Very Good And Well Maintained Condition, Under Utilized, Always Parked In Basement. Trade In Welcome, Flexible Loan Available, Call Now To View	-
COE	\$54,000	\$49,189	\$48,109	-
OMV	\$32,212	\$32,723	\$32,096	-
ARF	\$27,097	\$27,813	\$26,935	-
Depreciation	\$12,470 /yr	\$12,060 /yr	\$12,330 /yr	-
No. of Owners	1	1	1	-
Type of Vehicle	Luxury	Luxury	Luxury	-
Category	PAIF Car, Low Mileage Car	PAIF Car, Premium Ad Car	PAIF Car	-
Availability	Available	Available	Available	-

## SELLER INFORMATION

## Nivitha (LKK Auto)

---

**From:** Jeannie Cheng <jeannie.cheng@ergo.com.sg>  
**Sent:** Monday, 15 April 2019 2:21 PM  
**To:** admin-d@lkkauto.com  
**Cc:** sur@lkkauto.com  
**Subject:** FW: PRS IRO SK888U | OI : YP768M | DOA: 12/04/2019| ERGO REF: CDMCG19000691/SL/jc  
**Attachments:** SK888U GIA.pdf; YP768M OI.PDF

2:28pm @ 15/4/19  
vehicle in  
person @ suby?  
sur @ Admin

Hi LKK,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company to be the "Single Joint Expert".

Please conduct this survey request on without prejudice basis and try to finalize with the repairer on the repairs. Their client's vehicle can be surveyed at the location as stated in the email below.  
(Note: No repair estimate was provided to us)

Attached are the necessary documents for your further actions.

Kindly acknowledge receipt of this email.

(Please assist to quote our ref as the subject matter, when forwarding the Preliminary Reports / Survey Reports.)

Thank you.

Warmest Regards,  
Jeannie Cheng  
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five  
Singapore 038985  
DID +65 6829 9199 x 194  
[jeannie.cheng@ergo.com.sg](mailto:jeannie.cheng@ergo.com.sg)

# ERGO

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

**From:** Admin nht [<mailto:admin@nhtmotor.com>]  
**Sent:** Monday, April 15, 2019 10:37 AM  
**To:** Jeannie Cheng  
**Cc:** Chloe  
**Subject:** Re: PRS IRO SK888U | OI : YP768M | DOA: 12/04/2019| ERGO REF: YP768M/SL/jc

Without Prejudice

Hi Jeannie

Please arrange for

6	LKK	LKK Auto Consultants Pte Ltd
---	-----	------------------------------

Enclosed GIA for your reference.

Please take note our client vehicle number is SK8888U, there was miss out 1 digit of our client vehicle of your email.

---


Best Regards,

*Sukyi Chong*

New Hock Teck Motor Pte Ltd

1 Kaki Bukit Ave 6 Blk C #01-43 Autobay @ Kaki Bukit S(417883)

Tel : 6747 9241 Fax : 6741 7276



On Mon, Apr 15, 2019 at 10:28 AM Jeannie Cheng <[jeannie.cheng@ergo.com.sg](mailto:jeannie.cheng@ergo.com.sg)> wrote:

**WITHOUT PREJUDICE**

Dear Sir,

We acknowledged receipt of your fax dated 12/04/2019 for the PRS request as below.

In compliance with “**State Courts Practice Directions Amendment No.1 of 2016**”, do select an assessor from the list below.

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd

- Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy
- Your request for inspection does not have your client's GIA report, kindly forward a copy

Kindly let us have your reply on the selection of the surveyor.

Thank you.

Warmest Regards,

Jeannie Cheng

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five

Singapore 038985

DID: +65 6629 9199 x 194

[jeannie.cheng@ergo.com.sg](mailto:jeannie.cheng@ergo.com.sg)

[www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

## EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

**Jia Le (LKK Auto)**

---

**From:** Phoebe Xie <phoebe.xie@ergo.com.sg>  
**Sent:** Friday, 16 August 2019 10:17 AM  
**To:** Jia Le (LKK Auto); Ivy Yong  
**Cc:** ERGO Insurance Pte. Ltd. (Claims Department)  
**Subject:** RE: (SEEK MANDATE) Your Ref: CDMCG19000691/SL/jc\_ACCIDENT INVOLVING VEHICLES YP768M AND SK8888U ON 12/04/2019

Data Classification: Confidential, C3

OK, approved.

Warmest Regards,  
Phoebe Jay Xie  
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five  
Singapore 038985  
DID.: +65 6829 9191  
phoebe.xie@ergo.com.sg

**EMAIL DISCLAIMER**

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.  
Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.  
ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

**From:** ERGO Insurance Pte. Ltd. (Claims Department)  
**Sent:** Friday, 16 August, 2019 10:16 AM  
**To:** Jia Le (LKK Auto); Ivy Yong; Phoebe Xie  
**Subject:** RE: (SEEK MANDATE) Your Ref: CDMCG19000691/SL/jc\_ACCIDENT INVOLVING VEHICLES YP768M AND SK8888U ON 12/04/2019

Dear Ivy and Phoebe

For your kind assistance.

Date Classification : Confidential, C3

Warmest Regards,  
Pauline Soh  
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five  
Singapore 038985  
DID.: +65 6829 9194  
pauline.soh@ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

---



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

---

**From:** Jia Le (LKK Auto) [<mailto:JiaLe@lkkauto.com>]  
**Sent:** Thursday, August 15, 2019 12:19 PM  
**To:** ERGO Insurance Pte. Ltd. (Claims Department)  
**Cc:** Jeannie Cheng; Ivy Yong  
**Subject:** RE: (SEEK MANDATE) Your Ref: CDMCG19000691/SL/jc\_ACCIDENT INVOLVING VEHICLES YP768M AND SK8888U ON 12/04/2019

Dear Sirs/Madam,

We refer to the email dated on 31/07/2019.

Kindly let us have your approval/instruction as third party is chasing.

Thank you.

Best Regards,

**Carlur Chan** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Jia Le (LKK Auto)  
**Sent:** Tuesday, 6 August 2019 10:11 AM  
**To:** ERGO Insurance Pte. Ltd. (Claims Department)  
**Cc:** Jeannie Cheng  
**Subject:** RE: (SEEK MANDATE) Your Ref: CDMCG19000691/SL/jc\_ACCIDENT INVOLVING VEHICLES YP768M AND SK8888U ON 12/04/2019

Dear Sirs/Madam,

We refer to the email dated on 31/07/2019.

Kindly let us have your approval/instruction as third party is chasing.

Thank you.

Best Regards,

**Carlur Chan** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



**From:** Jia Le (LKK Auto)  
**Sent:** Wednesday, 31 July 2019 10:22 AM  
**To:** ERGO Insurance Pte. Ltd. (Claims Department)  
**Cc:** Jeannie Cheng  
**Subject:** (SEEK MANDATE) Your Ref: CDMCG19000691/SL/jc\_ACCIDENT INVOLVING VEHICLES YP768M AND SK8888U ON 12/04/2019

Your ref : **CDMCG19000691/SL/jc**  
Our ref : CC4/EGI19006808/Ada3

Dear Sirs/Madam,

**ACCIDENT INVOLVING YP 768M(OI) & SK 8888U(TP) ON 12/04/2019**

We refer to the above matter.

It is a head-to-rear collision. Liability is not in our driver's favour.

We seek your approval to offer Third Party repairer "NEW HOCK TECK MOTOR PTE LTD" at \$51,387.45(all-in).

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 93,882.40	\$ 49,220.00
2. Loss of Use (37days x \$70.00)	\$ 2,590.00	\$ 2,160.00 (36days x \$60.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 96,479.85	<b>\$ 51,387.45</b>

\*\*28 days recommendation for repair + 5 Sun + 3 PH = 36days

Enclosed here with all the relevant documents for your perusal.

**For your approval/Instruction please.**

Best Regards,

**Carlor Chan** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## NEW HOCK TECK MOTOR PTE LTD

Our Ref : NPLT1906-0059/ SK8888U  
Your Ref : YP768M  
Date : 11<sup>th</sup> June 2019

1 Kaki Bukit Avenue 6  
Blk C #01-43 Autobay@KB  
Singapore 417883

ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard,  
#04-01 Suntec Tower Five,  
Singapore 038985

WITHOUT PREJUDICE

Dear Sirs,

**RE: ACCIDENT INVOLVING SK8888U & YP768M AT BUKIT TIMAH RD ON 12.04.2019, 10:00AM**

We are instructed by **TAN SOON KHOON** to claim damages and losses against you in connection with the above captioned road traffic accident which our client's vehicle **SK8888U** was damaged by vehicle **YP768M** driven by your insured at the material time.

We are instructed that the said accident was caused by your insured's negligent driving and/or management of the vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expenses, particulars of which are as follows:

1) Repair Costs (7% GST)	\$ 49,220.00
2) Loss of Use for 37 days (28 + 6 Weekends + 3 Public Holidays)	\$ 2,590.00
3) LTA Search Fees	\$ 7.45
	<u>\$ 51,817.45</u>

A copy each of the following supporting document is enclosed:

- 1) Final Repair Bill
- 2) LTA Receipt

Please let us have your cheque for the sum **\$51,817.45** made payable to us, **NEW HOCK TECK MOTOR PTE LTD** in the next 14 days.

Yours faithfully,



NEW HOCK TECK MOTOR PTE LTD

## Jia Le (LKK Auto)

---

**From:** Jia Le (LKK Auto)  
**Sent:** Tuesday, 25 June 2019 11:05 AM  
**To:** MAY@HENGGUAN.COM.SG  
**Subject:** ACCIDENT INVOLVING YP 768M & SK 8888U ALONG/AT JUNCTION OF BT.TIMAH RD & FOURTH AVE ON 12/04/2019

Our Ref: CC4/EGI19006808/Ada3

25 JUNE 2019

**MUA HIN POULTRY FARM PTE LTD**  
32 SENOKO CRES  
SINGAPORE 758280

Dear Sir/Madam,

**ACCIDENT INVOLVING YP 768M & SK 8888U ALONG/AT JUNCTION OF BT.TIMAH RD & FOURTH AVE ON 12/04/2019**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, ERGO Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from SK 8888U against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

**Carlton Chan** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6749 5792 | email: [Jiale@lkkauto.com](mailto:Jiale@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

# LETTER OF AUTHORISATION

**New Hock Teck Motor Pte Ltd**  
Kaki Bukit Avenue 6  
Blk 1 #01-43  
Singapore 417883

Dear Sir,

Accident on 12/04/19, 1000  
Involving Vehicles SK88884, YP768M  
Along Bt Timah Rd

I/We, the registered owner/driver of vehicle registration no: SK88884  
have involved in the above accident.

I/We hereby authorize **New Hock Teck Motor Pte Ltd** to commence repairs of the said vehicle forthwith.


I/We agree to assign the whole proceeds of my/our comprehensive/third party claim to you and our solicitor, \_\_\_\_\_, to act on my/our behalf in respect of the above matter. And if applicable, my/our solicitors shall accept this as my/our irrevocable authority to pay the amount as deemed compensated direct to you after deduction of their costs on a Solicitor and client basis.

I/We undertake to co-operate fully with you and our solicitors to ensure that claim is successful.

I/We also authorize you to sign all discharge vouchers/indemnity forms and all necessary papers in relation with the above claim in my/our absence.

Your kind co-operation in this matter will be much appreciated.

Yours truly,



Owner's Signature  
(Company's stamp if applicable)

Name: Tan Soo Khoo  
NRIC No.: S0157517 A  
Date: 15/4/2019

Assignment

To: New Hock Teck Motor Pte Ltd (Workshop)

In consideration for your agreement to repair my motor vehicle registration no. 28988U and to defer demanding for payment of the cost of repair, I/we the undersigned do hereby irrevocably assign absolutely to you all the proceeds of my/our claim(s) including damages, interest, costs and expenses (including legal costs / disbursements payable on a party and party basis which are to be paid to the parties so entitled including solicitors, vehicle appraisers and other experts / consultants).

I/We further confirm that payment to you only or to any person authorised by you to receive payment shall constitute a good and effectual discharge of the obligations by any party of the aforesaid proceeds of my/our claim(s).

I/We authorise you expressly to give notice of this assignment to the party concerned.

I/We confirm that by this assignment, I/we shall not be entitled in law to receive any payment. If a cheque is sent to me/us, I/we shall return same to the sender as I/we am/are precluded from accepting any payment.

Dated this 12 day of 04 20 18.

Signature : [Signature]  
Name : TAN SUI KHOON  
ID No. : S0157517A  
Address : \_\_\_\_\_

Witness Signature : [Signature]  
Witness Name : Chew Yue Yin  
Witness ID : S8826618H  
Witness Address : 1 Kaki Bukit Avenue 6 #01-43  
Singapore 417883

## DISCHARGE VOUCHER

I/We, **TAN SOO KHOON (S0157517A)** hereby agree to accept the sum of **SINGAPORE DOLLARS: FIFTY-ONE THOUSAND THREE HUNDRED ONLY (\$51,300.00)**, in full and final settlement of all claims for damages, costs & disbursements arising out of an accident on **12.04.2019** involving **SK 8888U & YP 768M** at/along **BUKIT TIMAH ROAD**

I /We agree that the said sum is paid without admission of liability and on the part of ERGO Insurance Pte.Ltd./INSURED/INSURED DRIVER, respectively in respect of the said loss and for damage whether now or hereafter to become manifest, and is accepted by me to the intent that the said ERGO Insurance Pte.Ltd./INSURED/INSURED DRIVER, be absolutely and finally discharged from all claims whatsoever which I now or hereafter may have arising out of or connected with or traceable to the said accident. I/We also declare that I/We am/are the person entitled to receive the above compensation.

This discharge is not to be construed as an admission of liability on the part of ERGO Insurance Pte.Ltd./INSURED/INSURED DRIVER, and shall not be used as evidence in any claims/actions which may be lodged by or against them.

I/We hereby authorize you to make payment in favour of: **NEW HOCK TECK MOTOR PTE LTD**

Dated this 21 day of 08 2019.

### CLAIMANT:

Signature:

*Tan Soo Khoon*

Name:

Tan Soo Khoon

(Please endorse with company stamp, if applicable)

NRIC No:

S0157517A

Address:

16 First Avenue  
Singapore 268751

### WITNESS:

Signature:

*Sukji Chong*

Name:

新 福 德 車 廠  
**NEW HOCK TECK MOTOR PTE LTD**

NRIC No:

1 Kaki Bukit Ave 6, Bldg C #01-43  
Autobay@Kaki Bukit Singapore 417883  
Tel: 6747 9241 Fax: 6741 7276  
Email: admin@nhtmotor.com  
UEN: 201718370K

Address:

\_\_\_\_\_



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

## TAX INVOICE

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard,  
#04-01 Suntec Tower Five,  
Singapore 038985

Client: TAN SOO KHOON

Invoice No : NPL1906-0059

Date : 11-Jun-19

Date of Accident : 12-Apr-19

Vehicle No. : SK8888U

Model Type : Audi A4

Descriptions		Amount
Lump Sum Repair Cost		46,000.00
GST 7%		3,220.00
Total		49,220.00

SIN DOLLARS: FORTY NINE THOUSAND TWO HUNDRED AND TWENTY ONLY





[> Back to OneMotoring](#)

Land Transport Authority  
 10 Sin Ming Drive  
 Singapore 575701  
 GST Registration No. : M4-0006529-2

Print Date/Time : 12 Apr 2019 / 12:42:41

Receipt Date/Time : 12 Apr 2019 / 12:42:41

**Tax Invoice/Receipt**

Receipt No. : ITNET-00000-190412-001308

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - YP768M				
As at 12 Apr 2019/11:00:00				
Insurance Co: ERGO INSURANCE PTE. LTD.				
1	Insurance Enquiry - YP768M Enquiry Fee 20190412124144182558	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20190412124151811	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s ERGO INSURANCE PTE LTD

Date: 09/09/2019

**THIRD PARTY DIRECT SETTLEMENT**

Vehicle No.	YP 768M	(Insd Veh)	Your Ref. No. : CDMCG19000691/SL/jc
	SK 8888U	(TP Veh)	Our Ref. No. : CC4/EG19006808/Ada3q2
Date of Accident	12/4/2019		

Liability	100%	
Final Repair Cost	: \$ 49,220.00	
Loss of Use	: \$ 2,160.00	36 days
Rental (If any)	: \$	days
Others:	: \$ 7.45	
	: \$	
	51,387.45	
Final Settlement Sum	: \$ 51,300.00	GLOBAL SUM
Remarks	:	

**Payment Instruction: Payee's Breakdown**

1)	NEW HOCK TECK MOTOR PTE.LTD.	: \$ 51,300.00
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CC4/EG19006808/Ada3q2

5 TEMASEK BOULEVARD  
#04-05 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 09-09-2019



Code : EGI

**1. Policy Particulars :- THIRD PARTY CLAIM**

Insured Veh.	YP 768M	Veh. Inspected	SK 8888U
Policy No.	DMCG19000118	Coverage (\$)	0.00
Claim No.	CDMCG19000691/SL/jc	Excess (\$)	0.00
Assign From	JEANNIE	Assign Date	15/04/2019

**2. Vehicle Particulars & Condition**

Make & Model	AUDI A4	c.c	1395
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	WAUZZZF47JA035848	Colour	BLUE
Odometer	14895	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
R/H Front Tyre	205/60 R16	PIRELLI	6 mm
L/H Front Tyre	205/60 R16	PIRELLI	6 mm
R/H Rear Tyre	205/60 R16	PIRELLI	6 mm
L/H Rear Tyre	205/60 R16	PIRELLI	6 mm

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

**5. General Information**

Accident Date	12/04/2019	Inspection Date	15/04/2019
Survey held at	NEW HOCK TECK MOTOR PTE LTD 1 KAKI BUKIT AVENUE 6 #01-43 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

**5b. Estimate Days of Repair**

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>28 Working Days</b>
-------------------------------------	------------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 1 of 5

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SK 8888U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	REAR WINDSCREEN ASSY	CUT	1,062.35	1,062.35
1	REAR BOOT LID	DISTORTED	1,919.65	1,919.65
2	REAR BOOT LID HINGE @\$200.70	BENT	401.40	401.40
2	REAR BOOT LID SHOCK ABSORBER @\$182.95	BENT	365.90	182.95
1	REAR BOOT LID EMBLEM LOGO	NECESSARY	93.65	93.65
1	REAR BOOT LID A4 LOGO	NECESSARY	72.30	72.30
1	REAR BOOT LID TFSI LOGO	NECESSARY	72.30	72.30
1	REAR BOOT LID NUMBER PLATE	BENT	50.00	50.00
2	REAR BOOT LID NUMBER PLATE LAMP @\$82.90	CRACKED	165.80	165.80
2	REAR BOOT LID SIDE REFLECTOR @\$689.05	SMASHED	1,378.10	1,378.10
1	REAR BOOT LID INNER LOCK	JAMMED	133.65	133.65
1	REAR BOOT LID INNER RUBBER	CUT	144.45	144.45
1	REAR BOOT LID INNER TRIM BOARD	CRUMPLED	255.15	255.15
10	REAR BOOT LID INNER TRIM BOARD CLIP @\$6.50	NECESSARY	65.00	65.00
1	REAR BOOT LID LOCK SWITCH & CAMERA ASSEMBLY	DAMAGED	926.00	926.00
2	REAR TAIL LAMP @\$697.60	SMASHED	1,395.20	1,395.20
4	REAR TAIL LAMP CLIP @\$8.00	NECESSARY	32.00	32.00
2	REAR TAIL LAMP LOWER BRACKET @\$25.40	DAMAGED	50.80	50.80
2	REAR TAIL LAMP PANEL @\$181.75	DENTED	363.50	363.50
2	REAR TAIL LAMP INNER PANEL @\$152.55	DENTED	305.10	305.10
1	REAR BUMPER	DISTORTED	1,620.55	1,620.55
1	REAR BUMPER LOWER LID	DISTORTED	476.50	476.50
10	REAR BUMPER CLIP @\$6.50	NECESSARY	65.00	50.00
2	REAR BUMPER SIDE RETAINER @\$60.85	NECESSARY	121.70	121.70
2	REAR BUMPER SIDE REFLECTOR @\$69.30	CRACKED	138.60	138.60
1	REAR BUMPER TOWING COVER	DISTORTED	35.60	35.60
1	REAR BUMPER REINFORCEMENT	BENT	686.65	686.65
1	REAR END PANEL	DISTORTED	643.45	643.45
1	REAR END PANEL INNER	DISTORTED	343.55	343.55
1	REAR END PANEL TOP GARNISH	DISTORTED	203.95	203.95
2	REAR FENDER @\$2093.25	BUCKLED	4,186.50	4,186.50

Report Ref No. CC4/EG19006808/Ada3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER PANEL @\$713.85	BUCKLED	1,427.70	1,427.70
2	REAR FENDER HOUSING PANEL @\$470.25	BUCKLED	940.50	940.50
2	REAR FENDER HOUSING INNER PANEL @\$892.30	TO REPAIR SEE LABOUR	1,784.60	-
2	REAR FENDER AIR DUCT @\$65.45	NOT NECESSARY	130.90	-
2	REAR FENDER COWLING @\$177.25	NOT NECESSARY	354.50	-
12	REAR FENDER COWLING CLIP @\$6.50	NOT NECESSARY	78.00	-
2	REAR FENDER QUARTER GLASS ASSY @\$397.35	NECESSARY	794.70	794.70
2	REAR FENDER QUARTER GLASS CHROME @\$368.95	NECESSARY	737.90	737.90
1	REAR R/H PETROL TANK	NOT NECESSARY	4,292.65	-
1	REAR R/H PETROL TANK COVER	NOT NECESSARY	229.85	-
1	REAR SPARE TYRE PANEL	DISTORTED	1,734.75	1,734.75
2	REAR SPARE TYRE SIDE PANEL @\$628.45	BUCKLED	1,256.90	1,256.90
1	REAR SPARE TYRE PANEL TOP COVER	DISTORTED	537.80	537.80
1	REAR SPARE TYRE PANEL LOWER COVER	TORN	265.05	265.05
1	REAR SPARE TYRE PANEL TOOL BOX	DEFORMED	235.95	235.95
1	REAR SPARE TYRE PANEL INSULATION PAD	NOT NECESSARY	450.00	-
1	REAR EXHAUST	BENT	1,426.55	1,426.55
2	REAR EXHAUST MOUNTING @\$43.95	NOT NECESSARY	87.90	-
1	REAR EXHAUST ALUMINIUM COVER (SMALL)	CRUMPLED	152.80	152.80
1	REAR EXHAUST ALUMINIUM COVER (BIG)	CRUMPLED	214.80	214.80
1	REAR CENTER EXHAUST	BENT	1,884.55	1,884.55
2	REAR LOWER ARM @\$858.55	N/S BENT	1,717.10	858.55
2	REAR UPPER ARM @\$640.20	N/S BENT	1,280.40	640.20
2	REAR UPPER ARM INNER @\$548.15	N/S BENT	1,096.30	548.15
2	REAR KNUCKLE ARM @\$1045.50	N/S DAMAGED	2,091.00	1,045.50
2	REAR KNUCKLE ARM BEARING @\$477.70	N/S DAMAGED	955.40	477.70
2	REAR SHOCK ABSORBER @\$438.25	N/S BENT	876.50	438.25
2	REAR TRAILING ARM @\$224.05	NOT NECESSARY	448.10	-
1	REAR STABILIZER BAR	NOT NECESSARY	399.25	-
1	REAR CENTER CROSSMEMBER	BENT	3,318.35	3,318.35
1	REAR L/H DOOR	DENTED	1,610.95	1,610.95
2	REAR L/H DOOR HINGE @\$67.55	NOT NECESSARY	135.10	-

Report Ref No. CC4/EGI19006808/Ada3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR L/H DOOR INNER LOCK	DAMAGED	443.75	443.75
1	REAR L/H DOOR INNER RUBBER	NECESSARY	145.85	145.85
1	REAR L/H DOOR INNER TRIM BOARD	NOT NECESSARY	1,340.85	-
1	REAR L/H DOOR TOP CHROME MOULDING	NOT NECESSARY	177.25	-
1	REAR L/H DOOR LOWER CHROME MOULDING	NOT NECESSARY	274.40	-
1	REAR R/H DOOR	DENTED	1,610.95	1,610.95
2	REAR R/H DOOR HINGE @\$67.55	NOT NECESSARY	135.10	-
1	REAR R/H DOOR INNER LOCK	DAMAGED	443.75	443.75
1	REAR R/H DOOR INNER RUBBER	NECESSARY	145.85	145.85
1	REAR R/H DOOR INNER TRIM BOARD	NOT NECESSARY	1,340.85	-
1	REAR R/H DOOR TOP CHROME MOULDING	NOT NECESSARY	177.25	-
1	REAR R/H DOOR LOWER CHROME MOULDING	NOT NECESSARY	274.40	-
1	L/H DOOR FRAME PANEL	TO REPAIR SEE LABOUR	2,593.25	-
1	R/H DOOR FRAME PANEL	TO REPAIR SEE LABOUR	2,593.25	-
1	FRONT L/H CAR SEAT	NOT NECESSARY	2,324.80	-
1	FRONT R/H CAR SEAT	BENT	2,324.80	2,324.80
1	FRONT R/H CAR SEAT REAR BOARD	NOT NECESSARY	459.15	-
2	FRONT SEAT BELT @\$829.60	ACTIVATED	1,659.20	1,659.20
2	FRONT SEAT BELT BUCKLE @\$287.45	NOT NECESSARY	574.90	-
1	REAR BATTERY	NOT NECESSARY	856.55	-
1	REAR CRASH SENSOR /FUSE	ACTIVATED	251.10	251.10
	LESS 5% DISCOUNT		-	-2,257.46
			70,868.40	42,891.79
	<b>NETT ITEMS</b>			
2	REAR BOOT LID HINGE COVER @\$58.00 (ADDITIONAL) (N)	CRACKED	116.00	116.00
2	REAR BOOT LID SIDE REFLECTOR TRIM @\$25.00 (ADDITIONAL) (N)	CUT	50.00	50.00
1	REAR BOOT LID AUTO LOCK RELEASE MODULE (ADDITIONAL) (N)	DAMAGED	395.00	395.00
2	REAR TAIL LAMP SIDE TRIM @\$85.00 (ADDITIONAL) (N)	CUT	170.00	170.00
1	REAR BUMPER INNER FRAME (ADDITIONAL) (N)	CRACKED	268.00	268.00

Report Ref No. CC4/EGI19006808/Ada3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SECURITY STRIP (ADDITIONAL) (N)	DAMAGED	206.00	206.00
1	REAR FUEL LID COVER(ADDITIONAL) (N)	BUCKLED	108.00	108.00
1	REAR FUEL LID LOCK(ADDITIONAL) (N)	DAMAGED	245.00	245.00
2	REAR FENDER INNER TRIM BOARD @\$690.00 (ADDITIONAL) (N)	CRUMPLED	1,380.00	1,380.00
16	REAR FENDER INNER TRIM BOARD CLIP @\$6.50 (ADDITIONAL) (N)	NECESSARY	104.00	104.00
1	REAR REVERSE SENSOR WIRE HARNESS (ADDITIONAL) (N)	SNAPPED	618.00	618.00
1	REAR BATTERY CLAMP (ADDITIONAL) (N)	DAMAGED	88.00	88.00
1	REAR TOOLS SPONGE(ADDITIONAL) (N)	DEFORMED	198.00	198.00
1	REAR SPARE TYRE PANEL INNER GARNISH COVER (ADDITIONAL) (N)	CRACKED	458.00	458.00
1	REAR L/H CHASSIS FRAME (ADDITIONAL) (N)	BENT	1,580.00	1,580.00
	LESS 10% DISCOUNT		-	-598.40
			5,984.00	5,385.60
	<b>LABOUR</b>			
	TO PERFORM CHASSIS ALIGNMENT. (ADDITIONAL)		580.00	350.00
	TO REMOVE & REFIT REAR CUSHION ,BATTERY & SENSORS.		380.00	280.00
	TO REMOVE & REFIT ROOF TOP LINNING & TRIM BOARD .		480.00	160.00
	TO REMOVE & REFIT FRONT CAR SEAT ,CUSHION & SEAT BELT.		480.00	300.00
	TO REMOVE & REFIT REAR & CENTRE EXHAUST .		380.00	200.00
	TO REMOVE & REFIT PETROL TANK.		380.00	100.00
	TO REMOVE & REFIT REVERSE SENSOR .		100.00	60.00
	TO REMOVE & REFIT REVERSE CAMERA.		180.00	60.00
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	GUM.		60.00	60.00
	TO REMOVE & REFIT REAR L/H & R/H FENDER GLASS.		200.00	120.00
	GUM.		100.00	60.00
	TO REMOVE & REFIT REAR L/H & R/H DOOR ,LOCK ,RUBBER ,GEAR MOTOR & TRIM BOARD.		480.00	200.00
	TO REMOVE & REFIT REAR L/H& R/H UNDERCARRIAGE & CROSSMEMBER .		680.00	600.00

Report Ref No. CC4/EG19006808/Ada3q2



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO RESET COMPUTER.		380.00	200.00
	TO CHECK WHEEL ALIGNMENT.		150.00	80.00
	TO CHECK WIRING.		100.00	30.00
	TUFF KOTE.		150.00	150.00
	TOWING FEE.		150.00	120.00
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR FENDER HOUSING INNER PANEL,L/H DOOR FRAME PANEL AND R/H DOOR FRAME PANEL.		8,000.00	3,800.00
	SPRAY PAINTING .		3,500.00	2,600.00
			17,030.00	9,650.00
<b>GRAND TOTAL</b>			<b>93,882.40</b>	<b>57,927.39</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>46,000.00</b>

Report Ref No. CC4/EGI19006808/Ada3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.