



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

12/04/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Eryo.

Jia le.

Accident date: 12/04/2019

Estimated repair cost for vehicle no: SK8888U AUDI A4 1.4 A '17

CHASSIS: WAUZZZF47JA035848

S/n	Qty	Items	U/price	Amount
1	1	Rear Windscreen Assy <i>lt</i>		\$1,062.35 ✓
2	1	Rear Boot Lid <i>Distorted</i>		\$1,919.65 ✓
3	2	Rear Boot Lid Hinge <i>Best</i>	\$200.70	\$401.40 ✓
4	2	Rear Boot Lid Shock Absorber <i>Best</i>	\$182.95	\$365.90 182.55 ✓
5	1	Rear Boot Lid Emblem Logo		\$93.65 ✓
6	1	Rear Boot Lid A4 Logo <i>new</i>		\$72.30 ✓
7	1	Rear Boot Lid Tfsi Logo		\$72.30 ✓
8	1	Rear Boot Lid Number Plate <i>Best</i>		\$50.00 ✓
9	2	Rear Boot Lid Number Plate Lamp <i>crushed</i>	\$82.90	\$165.80 ✓
10	2	Rear Boot Lid Side Reflector <i>smashed</i>	\$689.05	\$1,378.10 ✓
11	1	Rear Boot Lid Inner Lock <i>damaged</i>		\$133.65 ✓
12	1	Rear Boot Lid Inner Rubber <i>lt</i>		\$144.45 ✓
13	1	Rear Boot Lid Inner Trim Board <i>crumpled</i>		\$255.15 ✓
14	10	Rear Boot Lid Inner Trim Board Clip <i>new</i>	\$6.50	\$65.00 ✓
15	1	Rear Boot Lid Lock Switch & Camera Assembly <i>damaged</i>		\$926.00 ✓
16	2	Rear Tail Lamp <i>Smashed</i>	\$697.60	\$1,395.20 ✓
17	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00 ✓
18	2	Rear Tail Lamp Lower Bracket <i>damaged</i>	\$25.40	\$50.80 ✓
19	2	Rear Tail Lamp Panel <i>Dented</i>	\$181.75	\$363.50 ✓
20	2	Rear Tail Lamp Inner Panel <i>dented</i>	\$152.55	\$305.10 ✓
21	1	Rear Bumper <i>Distorted</i>		\$1,620.55 ✓
22	1	Rear Bumper Lower Lid <i>Distorted</i>		\$476.50 ✓
23	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 50. ✓
24	2	Rear Bumper Side Retainer <i>new</i>	\$60.85	\$121.70 ✓
25	2	Rear Bumper Side Reflector <i>crushed</i>	\$69.30	\$138.60 ✓
26	1	Rear Bumper Towing Cover <i>Distorted</i>		\$35.60 ✓
27	1	Rear Bumper Reinforcement <i>Best</i>		\$686.65 ✓
28	1	Rear End Panel <i>Distorted</i>		\$643.45 ✓

29	1	Rear End Panel Inner	Distorted		\$343.55	✓
30	1	Rear End Panel Top Garnish	violated		\$203.95	✓
31	2	Rear Fender	Buckled	\$2,093.25	\$4,186.50	✓
32	2	Rear Fender Inner Panel	Bentled	\$713.85	\$1,427.70	✓
33	2	Rear Fender Housing Panel	Buckled	\$470.25	\$940.50	✓
34	2	Rear Fender Housing Inner Panel	Reps	\$892.30	\$1,784.60	+
35	2	Rear Fender Air Duct	new	\$65.45	\$130.90	+
36	2	Rear Fender Cowling	new	\$177.25	\$354.50	+
37	12	Rear Fender Cowling Clip	new	\$6.50	\$78.00	+
38	2	Rear Fender Quarter Glass Assy	new	\$397.35	\$794.70	✓
39	2	Rear Fender Quarter Glass Chrome	new	\$368.95	\$737.90	✓
40	1	Rear R/H Petrol Tank	new		\$4,292.65	+
41	1	Rear R/H Petrol Tank Cover	new		\$229.85	+
42	1	Rear Spare Tyre Panel	Distorted		\$1,734.75	✓
43	2	Rear Spare Tyre Side Panel	Buckled	\$628.45	\$1,256.90	✓
44	1	Rear Spare Tyre Panel Top Cover	Distorted		\$537.80	✓
45	1	Rear Spare Tyre Panel Lower Cover	new		\$265.05	✓
46	1	Rear Spare Tyre Panel Tool Box	new		\$235.95	✓
47	1	Rear Spare Tyre Panel Insulation Pad	new		\$450.00	+
48	1	Rear Exhaust	Bent		\$1,426.55	✓
49	2	Rear Exhaust Mounting	new	\$43.95	\$87.90	+
50	1	Rear Exhaust Aluminium Cover (Small)	formed		\$152.80	✓
51	1	Rear Exhaust Aluminium Cover (Big)			\$214.80	✓
52	1	Rear Center Exhaust	Bent		\$1,884.55	✓
53	2	Rear Lower Arm	LH Bent	\$858.55	\$1,717.10	858.5
54	2	Rear Upper Arm	LH Bent	\$640.20	\$1,280.40	640.2
55	2	Rear Upper Arm Inner	LH Bent	\$548.15	\$1,096.30	548
56	2	Rear Knuckle Arm	LH Bent	\$1,045.50	\$2,091.00	1045.5
57	2	Rear Knuckle Arm Bearing	LH Bent	\$477.70	\$955.40	477.7
58	2	Rear Shock Absorber	LH Bent	\$438.25	\$876.50	438.25
59	2	Rear Trailing Arm	LH Bent	\$224.05	\$448.10	+
60	1	Rear Stabilizer Bar	new		\$399.25	+
61	1	Rear Center Crossmember	Bent		\$3,318.35	✓
62	1	Rear L/H Door	Dented		\$1,610.95	✓
63	2	Rear L/H Door Hinge	new	\$67.55	\$135.10	+
64	1	Rear L/H Door Inner Lock	Dented		\$443.75	✓
65	1	Rear L/H Door Inner Rubber	new		\$145.85	✓
66	1	Rear L/H Door Inner Trim Board	new		\$1,340.85	+
67	1	Rear L/H Door Top Chrome Moulding	new		\$177.25	+
68	1	Rear L/H Door Lower Chrome Moulding	new		\$274.40	+
69	1	Rear R/H Door	Dented		\$1,610.95	✓
70	2	Rear R/H Door Hinge	new	\$67.55	\$135.10	+
71	1	Rear R/H Door Inner Lock	Damaged		\$443.75	✓

72	1	Rear R/H Door Inner Rubber	new		\$145.85	✓
73	1	Rear R/H Door Inner Trim Board			\$1,340.85	✓
74	1	Rear R/H Door Top Chrome Moulding			\$177.25	✓
75	1	Rear R/H Door Lower Chrome Moulding			\$274.40	✓
76	1	L/H Door Frame Panel	3 Repairs		\$2,593.25	✓
77	1	R/H Door Frame Panel			\$2,593.25	✓
78	1	Front L/H Car Seat	new		\$2,324.80	✓
79	1	Front R/H Car Seat	Bent		\$2,324.80	✓
80	1	Front R/H Car Seat Rear Board	new		\$459.15	✓
81	2	Front Seat Belt	Activated	\$829.60	\$1,659.20	✓
82	2	Front Seat Belt Buckle	new	\$287.45	\$574.90	✓
83	1	Rear Battery	new		\$856.55	✓
84	1	Rear Crash Sensor/Fuse	Activator		\$251.10	✓

Subtotal :- \$70,868.40

45149.25
4289178

Labour charges

To remove & refit rear cushion, battery & sensors	\$380.00 280
To remove & refit roof top lining & trim board	\$480.00 160
To remove & refit front car seat, cushion & seat belt	\$480.00 300
To remove & refit rear & centre exhaust	\$380.00 200
To remove & refit petrol tank	\$380.00 100
To remove & refit reverse sensor	\$100.00 60
To remove & refit reverse camera	\$180.00 60
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$60.00 ✓
To remove & refit rear L/H & R/H fender glass	\$200.00 120
Gum	\$100.00 60
To remove & refit rear L/H & R/H door, lock, rubber, gear motor & trim board	\$480.00 200

To remove & refit rear L/H & R/H undercarriage & crossmember

~~\$680.00~~ 600

To reset computer

~~\$380.00~~ 200

To check wheel alignment

~~\$150.00~~ 80

To check wiring

~~\$100.00~~ 30

Tuff kote

\$150.00 ✓

Towing fee

~~\$150.00~~ 120

Panel Beating

~~\$8,000.00~~ 3800

Spray painting

9300

~~\$3,500.00~~ 3600

Subtotal :- \$16,450.00

Total:- \$87,318.40

Supplementary: 5750.56

total 57542.34

L/S 46.3K

24 Days

chassis 1835
trimboard 9225

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K

26/04/2019

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 12/04/2019

Supplementary repair cost for vehicle no: SK8888U AUDI A4 1.4 A '17

CHASSIS: WAUZZZF47JA035848

S/n	Qty	Items	U/price	Amount
1	2	Rear Boot Lid Hinge Cover <i>could</i>	\$58.00	\$116.00 ✓
2	2	Rear Boot Lid Side Reflector Trim <i>at</i>	\$25.00	\$50.00 ✓
3	1	Rear Boot Lid Auto Lock Release Module <i>Done</i>		\$395.00 ✓
4	2	Rear Tail Lamp Side Trim <i>at</i>	\$85.00	\$170.00 ✓
5	1	Rear Bumper Inner Frame <i>could</i>		\$268.00 ✓
6	1	Rear Bumper Security Strip <i>Done</i>		\$206.00 ✓
7	1	Rear Fuel Lid Cover <i>Done</i>		\$108.00 ✓
8	1	Rear Fuel Lid Lock <i>Done</i>		\$245.00 ✓
9	2	Rear Fender Inner Trim Board <i>could</i>	\$690.00	\$1,380.00 ✓
10	16	Rear Fender Inner Trim Board Clip <i>at</i>	\$6.50	\$104.00 ✓
11	1	Rear Reverse Sensor Wire Harness <i>snapped</i>		\$618.00 ✓
12	1	Rear Battery Clamp <i>and</i>		\$88.00 ✓
13	1	Rear Tools Sponge <i>could</i>		\$198.00 ✓
14	1	Rear Spare Tyre Panel Inner Garnish Cover <i>could</i>		\$458.00 ✓
15	1	Rear L/H Chassis Frame <i>Best.</i>		\$1,580.00 ✓

5684.80

5400.56

Subtotal :- \$5,984.00

Labour charges

To perform chassis alignment

350

~~\$580.00~~ 350

Subtotal :- \$580.00

Total :- \$6,564.00

6841 6715

Supplementary: 5750.56