

ASS. REC. BY:

REF: CS/FC19026815 / P1s d3

Special Instruction:

Survivor: Taufiqh

ASSIGNMENT (Office)

From (Person): Serene

of PIC

Date/Time: 16.4.19 5.47pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHC6495E

Insured: SHD 3159R

at Workshop m/s Premier Automotive

Tel: 62148880

of 23 Changi South Avenue 2 # 01-02

Policy No:

Claim No: D19002553 MP5H

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13.4.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 14.4.2019 10.00am

Person Contacted: Vincent

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SHC 6495E - CC3 / III 18004514 / K129 3xx D.O.A - 04/03/2018
	SHD 3159R - CC3 / AIG 15013217 / M/WA 302 D.O.A - 30/03/2015
22/4@2.24pm	revised preli advise via email


Surveyor

Tanaka

REF: FCS

ASSIGNMENT

From: _____ Date: 17/4/19
 Estimated Cost: _____
 OD / (TP) WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SHC 649SE
 at Workshop m/s: Premier
 of 23 Chongji South Ave 2 #01-02
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS Imp

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 649SE Yr Regn: 2015, Jly
 Type: M.Car / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover /
 Truck / Trailer or
 Make: Lin Upima c.c. 1685
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 46879 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KNA G M 414 MF 5593720
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: (Nil) / S/Rim / STD A/Rim or
 Tyre Size: F: 205/65R15
 R: 205/65R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Michelin
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 17/4/19
 Survey held at Premier
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt N/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>25/7/19</u>	<u>459/200, 3 days email to Lien</u>
	<u>(£ 1,470.70 Red - 55%)</u>

RECEIVED 6 APR 2019

Date/Time, File Pass to? ☐ : Preli. Report

1) 26/04/19 ☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation: _____ \$ + RS. _____ \$

Photos

Others

TOTAL

110
90
90
19
229

Report Format :

Lump Sum / I.B.I: (\$ 1,200/- HS)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D190002553MFSH

Date: 22/4/2019

Our Ref: CS/FCI19006815/T1sd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 6495E

Please be informed that we had conducted the inspection of the abovementioned vehicle 17/4/2019 at the premises of M/s Premier Automotive have the following to report: -

Workshop Estimate Amount	: S\$ 2,670.70
Revised Estimate Amount	: S\$ 1,530.00
"Check" Items Amount	: S\$ 14.40
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the Front n/s portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	16-04-2019	Our Ref No. D19002553MFSH
Accident Date	13-04-2019	Claim Type. Third Party
Insured Vehicle	SHD3159R	Third Party Vehicle. SHC6495E
Survey Location	23 CHANGI SOUTH AVENUE 2 #01-02	
Contact Person.	LIEW HAI LEONG	
Contact No.	62148880/ 0	Fax No. 62141511
Survey Type	WITHOUT PREJUDICE: NO EST. COR PROVIDED	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

V:
E:✓

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PREMIER AUTOMOTIVE SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shirley Hiew (LKK Auto)

From: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Sent: Thursday, 25 April 2019 10:39 AM
To: 'Liew Hai Leong'
Cc: Shirley Hiew (LKK Auto)
Subject: RE: SHC6495E - FINALINATION (SURVEY ON 17.04.2019)

Hi Liew,

COR I/s\$1200 , 3 days.

Regards
Taufikh
Lkk Auto

From: Liew Hai Leong [mailto:haileong.liew@premiertaxi.com]
Sent: Thursday, 25 April 2019 10:15 AM
To: taufikh@lkkauto.com
Subject: SHC6495E - FINALINATION (SURVEY ON 17.04.2019)

Dear Seah,

Please confirm finalize at L/S \$1200 & 3 days.

Regards

Liew Hai Leong
Operation Assistant
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Monday, 22 April 2019 2:24 PM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments; SUR
Cc: 'Serene Ler'
Subject: RE: SURVEY ASSESSMENT - D19002553MFSH/1
Attachments: PRELI ADVISED SHC 6495E.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 6495E**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 17 April 2019 10:14 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Serene Ler' <Sereneler@msfirstcapital.com.sg>
Subject: RE: SURVEY ASSESSMENT - D19002553MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 16 April, 2019 5:47 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Serene Ler <Sereneler@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002553MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	08 Jul 2015 / 08:00:57	Receipt No.:	AACCK001-AX239-150708-000001
Asset Type:	Vehicle	Transaction Amount:	\$75,176.00
Asset ID:	SHC6495E	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01.02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150708080057248232		
Vehicle No.:	SHC6495E		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	08 Jul 2015		
Original Registration Date:	08 Jul 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5593720		
Engine No.:	D4FDEH313565		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2014		
Open Market Value:	\$21,451.00		
Minimum PARF Benefit:	\$13,219.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	08 Jul 2015 08:00:57		
COE No.:	2015070801002828E		
COE Expiry Date:	07 Jul 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$53,004.00		
Lifespan Expiry Date:	07 Jul 2023		

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

16-Apr-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC6495 E

1 pc	Front bumper	\$ 531.00 ^{RY} 531.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	\$ 32.00 ⁿⁿ 32.00 ^{45 x nn}
1 pc	Front n/s wheel cover	\$ 116.00 ^{ad} 116.00
1 pc	Front n/s fender	\$ 384.00 ^{bl} 384.00
1 pc	Front n/s fender inner shield	\$ 120.00 ^X 120.00 ⁿⁿ
		\$ 1,183.00 ⁵⁰⁰
	Less 10%	\$ 118.30
		\$ 1,064.70 ⁴⁵⁰

S/NETT

1 set	Front bumper clips	\$ 48.00 ^X 48.00 ⁿⁿ
1 pc	Front n/s fender sticker	\$ 30.00 ⁿⁿ 30.00
1 set	Front n/s fender inner shield clips	\$ 28.00 ^X 28.00 ⁿⁿ
	Sundry	\$ ²⁰ 50.00
	To check front n/s wheel alignment	\$ 80.00 ^X 80.00 ⁿⁿ
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$ ³⁴⁰⁰ 650.00
	To putty and spray painting on front bumper, front n/s fender, bonnet	\$ [✓] 600.00
	To apply rustproofing on the repaired and replaced panels.	\$ ³⁰ 120.00 ¹⁰⁸⁰
		\$ 2,670.70 ¹⁵³⁰
		\$ 4541.20 ^{4541.20}

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten notes:
17/4/19 @ 23:15
Resurvey after repair
03 days
sure the estimate is correct
Tanglin 92495749
WP
1080
1530
4541.20




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19006815/T1sd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3159R	Veh. Inspected	SHC 6495E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D190002553MFSH	Excess (\$)	0.00	
Assign From	SERENE LER	Assign Date	16/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA OPTIMA	c.c	1685	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	KNAGM414MF5593720	Colour	SILVER	
Odometer	468319	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/65 R15	MAXXIS	6 mm	
L/H Front Tyre	205/65 R15	MAXXIS	6 mm	
R/H Rear Tyre	205/65 R15	MAXXIS	6 mm	
L/H Rear Tyre	205/65 R15	MAXXIS	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/04/2019	Inspection Date	17/04/2019	
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6495E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	531.00	-
2	FRONT BUMPER N/S & O/S SIDE RETAINER @\$16.00	NOT NECESSARY	32.00	-
1	FRONT N/S WHEEL COVER	CUT	116.00	116.00
1	FRONT N/S FENDER	BENT	384.00	384.00
1	FRONT N/S FENDER INNER SHIELD	NOT NECESSARY	120.00	-
	LESS 10% DISCOUNT		-118.30	-50.00
			1,064.70	450.00
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	FRONT N/S FENDER STICKER (SN)	NECESSARY	30.00	30.00
1	SET FRONT N/S FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	28.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			156.00	50.00
<u>LABOUR</u>				
	TO CHECK FRONT N/S WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE SAME, ETC. INCLUSIVE OF THE REPAIR OF FRONT BUMPER.		650.00	400.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER, FRONT N/S FENDER, BONNET.		600.00	600.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		120.00	30.00
	-		-	-
	-		-	-
	-		-	-
			1,450.00	1,030.00
GRAND TOTAL			2,670.70	1,530.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,200.00

Report Ref No. CS/FCI19006815/T1sd3n2



Report Ref No. CS/FCI19006815/T1sd3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.