

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 22 Apr 2019

Preliminary Advice

Insured Vehicle No	: SMJ3582K	Accident Date	: 13/04/2019
TP Vehicle No	: SHB8319Z	Assignment Date	: 17/04/2019
Make	: HYUNDAI I30 GDH	Est. Duration of Repair	: 2.00
Date of Inspection	: 17/04/2019		
Inspection At	: PREMIER AUTOMOTIVE SERVICES PTE LTD (CHANGI) 23 CHANGI SOUTH AVE 2 #01-02 SINGAPORE 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,191.53
Revised Amount	:S\$	1,123.67
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,123.67

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.