

ASS. REC. BY:

REF: CS/MSG 19006816/11v d3 Special Instruction:

Surveyor: TANREN

WIPWIN

ASSIGNMENT (Office)From (Person): Yong Tan Gek Eng of MSIG Date/Time: 17.4.19 9.42a.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHB 83192 Insured: SMJ 3582Kat Workshop m/s Premier Automotive Tel: 65446689of 23 Changi South Avenue 2 #01-20Policy No: 29118443AV2 Claim No: 540729

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13.4.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS "wp" H.O.D. Endorsement: _____

Date/Time: 17.4.2019 Person Contacted: WIPWIN Vehicle (IN) OUT

Date/Time	Action/Instruction (✓) Estimate
	SHB 83192 - X
	SMJ 3582K - X
	6 Smithworth Lane
	10-05
	Zheng Lei 81333672
22/4/19	Send preli revised via merimen
29/4/19	Final fig \$ 1123.67 (Red 67.86, 67.86) confirmed by email

Surveys

Tan

REF: MS16

ASSIGNMENT

From: Date: 17/4/19

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHB 83192

at Workshop m/s premier

of 23 chengj south Ave 2#01-02

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Vincent 65446689

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1up}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SHB.83192 Yr Regn: 2017 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I30 cc 1582

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 119965 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: TMAD 281UV 4312 9247

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 145/65 R15

R: -

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front

Rear

R/Bal: 6 mm R/Bal: 0 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I: 17/4/19

Survey held at Premier

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 16 JUL 2019

RECEIVED 29 APR 2019 29/4/2019

Color/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 16/7 typist

Days Of Repair: 2

Resurvey No. of Trip:

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format : Merimen

Lump Sum / I.B.I: (\$ 1123.67)

150

11

161

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2019		17 Apr 2019 09:42 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ZHANG MANLI, ID: S8576435G								
Main Claimant:	PREMIER TAXIS PTE LTD, Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHB8319Z	Date of Loss:	13/04/2019 00:00 - :59 [20 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 590729	Policy/Cover Note No.:	29118443AV2 Coverage: 28/02/2019 - 27/02/2021						
Vehicle Reg. No. (Insured):	SMJ3582K	Policy No. (Claimant):							
		Excess:							
Repairer:	Premier Automotive Services Pte Ltd (Changi) 23 Changi South Ave 2 #01-02, 486443 Changi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KALVIN ANG WEI KUN] ... [Imm.Advice due 18/04/2019]								
Adj Asg. Remarks:	On WP. (MANUAL ASSIGNED) SURVEY AGREE ON SJE - REQ TO ASSIGN LKK (KALVIN ANG) LIABILITY:DISPUTE (OI NON-REPORTING) CONTACT: VINCENT 6214 8880/6544 6689								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
--	---

Attn: Irene Tan Gek Ing Date: 22 Apr 2019

Preliminary Advice

Insured Vehicle No	: SMJ3582K	Accident Date	: 13/04/2019
TP Vehicle No	: SHB8319Z	Assignment Date	: 17/04/2019
Make	: HYUNDAI I30 GDH	Est. Duration of Repair	: 2.00
Date of Inspection	: 17/04/2019		
Inspection At	PREMIER AUTOMOTIVE SERVICES PTE LTD (CHANGI) 23 CHANGI SOUTH AVE 2 #01-02 SINGAPORE 486443		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,191.53
Revised Amount	:S\$	1,123.67
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,123.67
Lump Sum Repair	:S\$	
Total Loss Consideration		
New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Nivitha (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Wednesday, 17 April 2019 9:13 AM
To: assignments@lkkauto.com; admin-d@lkkauto.com
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned
Attachments: Other.pdf

Pre-inspection/Accident involving between SHB8319Z & SMJ3582K

Manual Assigned

Dear Sir/Mdm,

Please refer to the attachment.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

Crystal Lee

From: Venessa Chan
Sent: Wednesday, 17 April, 2019 9:08 AM
To: Crystal Lee
Subject: Pre-inspection/Accident involving between SHB8319Z & SMJ3582K on 13.04.2019 (nr case)

From: Venessa Chan
Sent: Tuesday, 16 April, 2019 4:54 PM
To: Vincent Chua <vincent.chua@premiertaxi.com>
Cc: Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>; Motor Survey <motorsurvey@sg.msig-asia.com>; Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>
Subject: RE: Pre-inspection/Accident involving between SHB8319Z & SMJ3582K on 13.04.2019 (nr case)

Dear Vincent,

Thank you for your selection of **LKK Auto Consultants – Calvin Ang**.

We will proceed to appoint **LKK Auto Consultants – Calvin Ang** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol

Thank you.

Have A Great Week Ahead!

Venessa Chan

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2470 | Direct fax +65 6225 7402 | venessa_chan@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Vincent Chua [<mailto:vincent.chua@premiertaxi.com>]
Sent: Tuesday, 16 April, 2019 4:45 PM
To: Venessa Chan <venessa_chan@sg.msig-asia.com>
Cc: Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>; Motor Survey <motorsurvey@sg.msig-asia.com>; Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>
Subject: RE: Pre-inspection/Accident involving between SHB8319Z & SMJ3582K on 13.04.2019 (nr case)

Dear all,

We would like to appoint **"Mr Calvin Ang of LKK Auto Consultants"** as the SJE for this PRS.

Please kindly arrange soonest.

Thank you.

Regards

Vincent Chua
Operations Assistant
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION 

From: Venessa Chan [mailto:venessa_chan@sg.msig-asia.com]
Sent: Tuesday, 16 April, 2019 3:46 PM
To: Vincent Chua <vincent.chua@premiertaxi.com>
Cc: Nabilah Rasol <nabilah_rasol@sg.msig-asia.com>
Subject: Pre-inspection/Accident involving between SHB8319Z & SMJ3582K on 13.04.2019 (nr case)

Dear Vincent,

We refer to your email on 16.04.19.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) Automobile Inspection Services Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) **MSIG In-House Surveyors (appointment full on 16.04.19)**

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

- 1 Calvin Ang
- 2 Kenneth Kong
- 3 Marcus Chua
- 4 Henry Ng
- 5 Lau Kwok Kwong
- 6 Frankie Pang
- 7 Ng You Han
- 8 Gary Soon

9 Chow Bo Xiong
10 Axel Lee

NB:

- (a) *Fast-Lane Settlement is not applicable for cases that liability is in dispute*
- (b) If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Thank you.

Have A Great Week Ahead!

Venessa Chan

Admin Officer, Claims Services (Motor)

Direct line +65 6594 2470 | Direct fax +65 6225 7402 | venessa_chan@sg.msig-asia.com



MSIG



Insurer Claims
Team of the Year
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Vincent Chua [<mailto:vincent.chua@premiertaxi.com>]

Sent: Tuesday, 16 April 2019 3:22 PM

To: Motor Survey <motorsurvey@sg.msig-asia.com>

Cc: Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>

Subject: RE: Pre-inspection/Accident involving between SHB8319Z & SMJ3582K on 13.04.2019

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Dear all,

We refer to the vehicles mentioned above.

We have yet to receive a response with regards to the pre-repair inspection.

Vehicle to be Surveyed: SHB8319Z

Insured Vehicle: SMJ3582K

Date of Accident: 13/04/2019

Name of Workshop: Premier Automotive Services Pte Ltd

Address of Survey Location: 23 Changi South Avenue 2, #01-02, S (486443)

Name of Contact Person: Mr Vincent Chua

Contact Number: 65446689

Email Address of Contact Person: vincent.chua@premiertaxi.com

Vehicle available for survey

Kindly arrange for survey soonest.

Kindly send us your panel surveyor list and arrange for survey.

Thank you.

Regards

Vincent Chua
Operations Assistant
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION 

From: Vincent Chua
Sent: Monday, 15 April, 2019 5:44 PM
To: 'motorsurvey@sg.msig-asia.com' <motorsurvey@sg.msig-asia.com>
Cc: Goh Wee Dek <weedek.goh@premiertaxi.com>; Liew Hai Leong <haileong.liew@premiertaxi.com>
Subject: Pre-inspection/Accident involving between SHB8319Z & SMJ3582K on 13.04.2019

Dear all,

We refer to the vehicles mentioned above.

Vehicle to be Surveyed: SHB8319Z
Insured Vehicle: SMJ3582K
Date of Accident: 13/04/2019
Name of Workshop: Premier Automotive Services Pte Ltd
Address of Survey Location: 23 Changi South Avenue 2, #01-02, S (486443)
Name of Contact Person: Mr Vincent Chua
Contact Number: 65446689
Email Address of Contact Person: vincent.chua@premiertaxi.com

Vehicle available for survey

Kindly send us your panel surveyor list and arrange for survey.

Thank you.

Regards

Vincent Chua
Operations Assistant
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 066 | DID: 6544 6689 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION 

Enquire Vehicle Registration Details**Owner Particulars**

NRIC/Passport/Company Cert No.: 200304975H
 Owner ID Type: Company
 Owner Name: PREMIER TAXIS PTE. LTD.
 Registered Address: 23 CHANGI SOUTH AVENUE 2 #04-03 SINGAPORE 486443
 Mailing Address: -
 Birth Date: -

Vehicle Particulars

Vehicle No.: SHB5319Z
 Previous Vehicle No.: -
 Effective Date of Ownership: 19 Jul 2017
 Original Regn Date: 19 Jul 2017
 Registration Date: 19 Jul 2017
 Year of Manufacture: 2016
 Vehicle Type: Public Transport Taxi (Motor Car)
 Vehicle Scheme: Taxi (Company)
 Vehicle Attachment 1: Air-Con (Taxi)
 Vehicle Attachment 2: -
 Vehicle Attachment 3: -
 Vehicle Make: HYUNDAI
 Vehicle Model: I30 GDH 1.6 TCI 5DR DCT
 Primary Colour: Silver
 Secondary Colour: -
 Passenger Capacity: 4
 Chassis No.: TMAD281UVHJ129247
 Engine No.: D4FBGZ125024
 Engine Capacity/Power Rating: 1582 cc / -
 Maximum Power Output: 100.0 kW (134 bhp)
 Propellant: Diesel
 Max Unladen Weight: 1496 kg
 Maximum Laden Weight: 1940 kg
 Open Market Value: \$20,618.00
 PARF Eligibility: Yes
 PARF Eligibility Expiry Date: 18 Jul 2025
 Minimum PARF Benefit: \$8,019.00
 No. of Transfers: 0
 IU Label No.: 1050706416
 COE No.: 2017071901003933R
 COE Expiry Date: 18 Jul 2025
 COE Category: A - Car up to 1600cc & 97kW (130bhp)
 COE Registration Category: A - Car up to 1600cc & 97kW (130bhp)
 Quota Premium (QP) / Prevailing Quota Premium: - / \$48,200.00
 POP Paid: \$38,560.00
 QP (Regn Cat): -
 OPC Cash Rebate Eligibility: No

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/04/2019 15:59
Date Of Accident	13/04/2019 21:00
Exact Location Of Accident	TANJONG KATONG ROAD // DUNMAN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB8319Z
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I30 (FD)-1.6 DOHC (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5107202885
Cover Note Number	

Driver

Name of Driver	YEONG KOK LEONG, WINSTON
NRIC No	S7137676A
Date Of Birth	02/10/1971
Occupation	OUTDOOR
Date Of Driving Pass	17/04/1990
Driving Experience	28 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82234609
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 191B #10-906 RIVERVALE DRIVE
Postcode	542191
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : PAX IN THE REAR SEAT - FOREIGNER GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING , POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEH. A - 1 PAX VEH. B - NO PAX *REFER TO ATTACH POLICE REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMJ3582K
Vehicle Make/Model/Colour	VOLKS
Details Of Properties	VEH. B
Vehicle Category	PRIVATE CAR
Name of Driver	MALE CHINESE
NRIC/Passport Number	
Contact Number	

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

DETAILS OF INJURED PERSON 1

Name

YEONG KOK LEONG, WINSTON - DRIVER OF VEH. A

Approximate Age

Injuries Sustain

WENT CLINIC FOR MEDICAL TREATMENT & HAD 3 DAYS MC

Injured person in which vehicle?

SHB8319Z

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

15 APR 2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

15/4/2019
1610

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: 8168319Z

B: SWJ3582K

* Refer to attached police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 15/4/2019
1610

15 APR 2019

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20190415/2041

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

1 of 3

Report No. T/20190415/2041

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/04/2019 11:49		Vide Report No.:		Station Diary No.: 55	
Informant's Particulars					
Name of Informant: YEONG KOK LEONG, WINSTON			Address: APT BLK 191B RIVERVALE DRIVE #10-906 SINGAPORE 542191		
ID Type / ID No.: NRIC NO / S7137676A			Contact No.: Home/Office: Mobile: 82234609		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 47	Date of Birth: 02/10/1971	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 13/04/2019 21:00	Type of Location: X-Junction
Location: Junction of Road 1 and Road 2 TANJONG KATONG ROAD DUNMAN ROAD				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB8319Z	Car				Slightly Damaged	1
SMJ3582K	Car				Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190415/2041

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

2 of 3

Report No. T/20190415/2041

CONTINUATION OF REPORT

Driver			
Name	YEONG KOK LEONG, WINSTON	ID No.	S7137676A
Related Vehicle	SHB8319Z (Car)	Contact No.	82234609
Hospital/Clinic	GOH MEDICAL CLINIC	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	15/04/2019	Date Discharge	15/04/2019
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 13/04/2019 at about 2100hrs, I was driving my taxi (SHB8319Z) along Tanjong katong Road towards ECP when I met a traffic X-junction with Dunman Road. As the traffic light was red, I waited and my taxi was the first vehicle. All of the sudden, I felt an impact from the back, causing my vehicle to jerk forward. Another car (SMJ3582K) had hit the back of my taxi. I had one passenger at that time and he mentioned that he was not injured. I proceeded to head out, to check what happened. After taking photos of the accident, both of us left scene. There was no agreement between any parties as such I decided to go and make a report to my insurance company to inform of what happened. My vehicle sustained a slightly dislodged rear bumper. On 15/04/2019, I felt pain and sore coming from the back area of my head and body as such I went to the nearest clinic and was given 3 days MC. There is an in car camera installed in my taxi however it only faced the front.



SINGAPORE
POLICE FORCE



T/20190415/2041

3 of 3

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

Report No. T/20190415/2041

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 3 MUHAMMAD FAKHRUDDIN BIN SHAHRI

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

15/04/2019 11:49

Officer In Charge Of Case:

TP / AEIT /

Sgt 2 SHARIFAH NOR FARIZAN BINTE S

MOHD SAID

Contact No.: 65476172

Authentication Stamp

NP188

Classification Of Case:

SN 168

SIGNATURE



POLICE REPORT (NP299)

Report No. G/20190508/7042

Police Station Of Origin
Bedok Division HQ
30 Bedok North Road SINGAPORE 469676
Tel No:1800-2440000

Date/Time Report Made 08/05/2019 19:05	Vide Report No.	Station Diary No.		
Name Of Informant ZHANG MANLI	Address 6 BUTTERWORTH LANE #10-05 SINGAPORE 439422			
ID Type / ID No. NRIC NO / S8576435G	Contact No. Home/Office:	Mobile: 92996686		
Nationality SINGAPORE CITIZEN	Email Address theonlymanli@hotmail.com			
Occupation Operations officer (except transport operations)	Sex Female	Age 33	Date of Birth 08/07/1985	Race Chinese
Institution/School Name	Language English			
Date/Time Of Incident 13/04/2019 22:30 - 13/04/2019 23:00	Location Of Incident TANJONG KATONG ROAD			

Brief details.

Following was what was told by my husband: When the red light was on at traffic junction, both taxi and my car stopped which had about 2 meters distance. As I thought the car was flat, I just put my car at Neutral mode, without stepping on brake or put up handbrake. Then my car gradually sliding forward due to the slight downhill, the movement was suddenly realized by me, then I stepped on the brake immediately and by then two cars were in contact with each other. The contact point was my number plate. (Please take note, I didn't brake due to the reverse force caused by the collision as I didn't feel the bounce back force at all.) Subsequently both taxi driver and I came out of cars. We saw no damage at

Signature Of Officer Recording The Report:	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Not applicable	
Signature Of Interpreter:	Date/Time:
Not applicable	08/05/2019 19:05
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20190508/7042

either taxi or my car. Taxi rear bumper or any part of taxi was in perfect condition. Then taxi driver stood over 1 meter away of the car and took photo of both cars. I felt there's no collision, only a touch, I didn't think there's any damage or whatsoever to either car, so I didn't take photo at all. Then Taxi driver drove forward a little bit, and he came down, we checked again his rear bumper and all over rear side of his car, found there was no scratches caused by my car as my car only had a forward contact with his rear side, no hit, no collision. And found there were already a lot of scratches appeared on taxi which obviously were already existed prior to the incident. There's no scratches or damage to my car either. Therefore, I apologized to taxi driver for my careless, he didn't complain at all as both us saw no damage at all, then we just drove off afterwards. Because there was no collision, no damage, that's the reason why I didn't report to my insurance company nor traffic police at all. I urge if police could help take out the video footage on that night at traffic junction or nearby area to check what was really happened.

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by SingPass. No signature is required.

Date/Time:

08/05/2019 19:05

Classification Of Case:

Premier Automotive Services Pte Ltd
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:
Assessment number: 002707
Version: 1810
Date calculated: 04/17/2019 11:04 AM

Full Report
Registration: SHB8319Z
Printed: 17/04/2019 11:04 AM

Summary Information

Claim Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	WEEDEK GOH	Currency:	SGD
Claim Reference:		Date of Incident:	2019-04-13
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle Manufacturer:	HYUNDAI
Model:	I30 (PD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 82 01
Registration:	SHB8319Z
VIN number:	
Odometer:	
Model Specs	
5-DOOR	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

[Signature]
23/4/19
Tayfun 97495744
WP
17/4/19 @ 230pm
0.2 days
Resurvey before paint
sure@lkkauto.com

**Premier Automotive Services Pte
Ltd**
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:
Assessment number: 002707
Version: 1810
Date calculated: 04/17/2019 11:04 AM

Full Report
Registration: SHB8319Z
Printed: 17/04/2019 11:04 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
86651R00	RENEW REAR BUMPER INCLUDES: REAR BUMPER REAR LIGHTS, REAR LOWER BUMPER AND REQUIRED ATTACHED PARTS R + R		9.0	45.00
2931	BOOTLID/TAILGATE REPAIR		20.0*	100.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		2.90	29.0	145.00
Total of Labour				145.00

Premier Automotive Services Pte Ltd
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:
 Assessment number: 002707

Version: 1810

Date calculated: 04/17/2019 11:04 AM

Full Report
 Registration: SHB8319Z
 Printed: 17/04/2019 11:04 AM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		9.0	
	BOOTLID/TAILGATE REPAIR PAINTING <50%		15.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	35.60
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	20.75

Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			24.0	
	Preparation Main Work Metal		1.70	17.0	85.00
	Preparation Comp. Work Plastic		0.30	3.0	15.00
Total		10 WU/h	4.40	44.0	220.00

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	35.60
Repair Painting	20.75
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	83.45

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
2583	REAR BUMPER	86611G4000		de ✓	811.11
2625	L/R OUT BUMPER BRKT	86613G4000		ny x	52.20
2626	R/R OUT BUMPER BRKT	86614G4000		ny x	52.20
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				915.51
u: Used parts	Subtotal Discount(+35.00%)				-320.43

**Premier Automotive Services Pte
Ltd**
#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:
 Assessment number: 002707
 Version: 1810
 Date calculated: 04/17/2019 11:04 AM

Full Report
 Registration: SHB8319Z
 Printed: 17/04/2019 11:04 AM

Total	595.08
-------	--------

Extras

Code	Description	Price SGD
1000	Rear bumper clips	48.00*
1001	Tailgate stickers	100.00*
	Total Extras	148.00

Final Calculation

	SGD	SGD
Parts	915.51	
Total Discount(+35.00%)	-320.43	
Total Parts		595.08
Labour Time Base 10 WU/h		
Total 29.0 WU X 50.00 SGD/h	145.00 ✓	
Total of Labour		145.00
Total Of Extras		148.00
Paint Work Time Base 10 WU/h		
Labour Cost 44.0 WU X 50.00 SGD/h	220.00 ✓	
Material Cost	83.45 ✓	
Total Paint Including Material		303.45
Repair Cost Excludes GST		1,191.53
GST (+7.0%)		83.41
Repair Cost Included GST		1,274.94

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Workshop Finalised

Claim Reference:

Assessment number: SHB8319Z

Version: 1810

Date calculated: 27/04/2019 9:09 AM

Full Report

Registration: SHB8319Z

Printed: 27/04/2019 9:09 AM

Summary Information

Claim

Location: Singapore (SG)

Work Provider:

MSIG Insurance
(Singapore) Pte Ltd

Printed by: WEEDEK GOH

Currency:

SGD

Claim Reference:

Date of Incident:

13/04/19

Estimated Repair Time:

Hire Car Start:

Actual Repair Days:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

HYUNDAI

Model:

I30 (PD)

Sub Model:

BASE MODEL

Model Sheet Number:

30 82 01

Registration:

SHB8319Z

VIN number:

Odometer:

Model Specs

5-DOOR

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SHB8319Z

Version: 1810

Date calculated: 27/04/2019 9:09 AM

Full Report

Registration: SHB8319Z

Printed: 27/04/2019 9:09 AM

Vehicle Condition


Vehicle Status

Pre-Accident Damage:

Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
86651R00	RENEW REAR BUMPER INCLUDES: REAR BUMPER REAR LIGHTS, REAR LOWER BUMPER AND REQUIRED ATTACHED PARTS R + R		9.0	45.00
2931	BOOTLID/TAILGATE REPAIR		20.0*	100.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		2.90	29.0	145.00
Total of Labour				145.00

Premier Automotive Services Pte Ltd

#01-02, 23 Changi Sth Ave 2
486443

Claim Reference:

Assessment number: SHB8319Z

Version: 1810

Date calculated: 27/04/2019 9:09 AM

Full Report

Registration: SHB8319Z

Printed: 27/04/2019 9:09 AM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		9.0	
	BOOTLID/TAILGATE REPAIR PAINTING <50%		15.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	35.60
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	20.75

Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			24.0	
	Preparation Main Work Metal		1.70	17.0	85.00
	Preparation Comp. Work Plastic		0.30	3.0	15.00
Total		10 WU/h	4.40	44.0	220.00

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	35.60
Repair Painting	20.75
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	83.45

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
2583	REAR BUMPER	86611G4000			811.11
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				811.11
u: Used parts	Subtotal Discount(+35.00%)				-283.89
	Total				527.22

**Premier Automotive Services Pte
Ltd**

#01-02, 23 Changi Sth Ave 2

486443

Claim Reference:

Assessment number: SHB8319Z

Version: 1810

Date calculated: 27/04/2019 9:09 AM

Full Report

Registration: SHB8319Z

Printed: 27/04/2019 9:09 AM

Extras

Code	Description	Price SGD
1000	Rear bumper clips	48.00*
1001	Tailgate stickers	100.00*
Total Extras		148.00

Final Calculation

	SGD	SGD
Parts	811.11	
Total Discount(+35.00%)	-283.89	
Total Parts		527.22
Labour Time Base 10 WU/h		
Total 29.0 WU X 50.00 SGD/h	145.00	
Total of Labour		145.00
Total Of Extras		148.00
Paint Work Time Base 10 WU/h		
Labour Cost 44.0 WU X 50.00 SGD/h	220.00	
Material Cost	83.45	
Total Paint Including Material		303.45
Repair Cost Excludes GST		1,123.67
GST (+7.0%)		78.66
Repair Cost Included GST		1,202.33

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Finalised

Claim Reference:
Assessment number: 002707
Version: 1810
Date calculated: 29/04/2019 11:15 AM

Full Report
Registration: SHB8319Z
Printed: 29/04/2019 11:15 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	MSIG Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	13/04/19
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle	
Manufacturer:	HYUNDAI
Model:	I30 (PD)
Sub Model:	BASE MODEL
Model Sheet Number:	30 82 01
Registration:	SHB8319Z
VIN number:	
Odometer:	
Model Specs	
5-DOOR	

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 002707
 Version: 1810
 Date calculated: 29/04/2019 11:15 AM

Full Report
Registration: SHB8319Z
Printed: 29/04/2019 11:15 AM


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
 Date of Inspection:

Damage Areas

All ☐
 Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 50.00 SGD/h	
			WU	Price SGD
86651R00	RENEW REAR BUMPER INCLUDES: REAR BUMPER REAR LIGHTS, REAR LOWER BUMPER AND REQUIRED ATTACHED PARTS R + R		9.0	45.00
2931	BOOTLID/TAILGATE REPAIR		20.0*	100.00
Labour Cost		Hrs	WU	
Panel / Mechanical Labour		2.90	29.0	145.00
Total of Labour				145.00

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 002707
 Version: 1810
 Date calculated: 29/04/2019 11:15 AM

Full Report
 Registration: SHB8319Z
 Printed: 29/04/2019 11:15 AM

Paint

Paint Work		SYSTEM AZT	Time Basis 10WU/h	
Code	Description		WU	Price SGD
	REAR BUMPER NEW PART PAINT K1R		9.0	
	BOOTLID/TAILGATE REPAIR PAINTING <50%		15.0	

Paint Material Per Part

Code	Description	Price SGD
2583	REAR BUMPER NEW PART PAINT K1R	35.60
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	20.75

Labour Cost - Paint

	Factor	50.00 SGD/h	Hrs	WU	Price SGD
	Time Paint			24.0	
	Preparation Main Work Metal		1.70	17.0	85.00
	Preparation Comp. Work Plastic		0.30	3.0	15.00
Total		10 WU/h	4.40	44.0	220.00

Material Cost - Paint

	Price SGD
New Part Painting - Plastic K1R	35.60
Repair Painting	20.75
Material-constant Metal	18.10
Material-constant Plastic	9.00
Total	83.45

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
2583	REAR BUMPER	86611G4000			811.11
f: OEM Parts	Savings				0.00
n: Non-OEM Parts	Subtotal				811.11
u: Used parts	Subtotal Discount(+35.00%)				-283.89
	Total				527.22

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park,
51 Ubi Avenue 1
408933

Claim Reference:
 Assessment number: 002707
 Version: 1810
 Date calculated: 29/04/2019 11:15 AM

Full Report
Registration: SHB8319Z
Printed: 29/04/2019 11:15 AM

Extras

Code	Description	Price SGD
1000	Rear bumper clips	48.00*
1001	Tailgate stickers	100.00*
	Total Extras	148.00

Final Calculation

	SGD	SGD
Parts	811.11	
Total Discount(+35.00%)	-283.89	
Total Parts		527.22
Labour Time Base 10 WU/h		
Total 29.0 WU X 50.00 SGD/h	145.00	
Total of Labour		145.00
Total Of Extras		148.00
Paint Work Time Base 10 WU/h		
Labour Cost 44.0 WU X 50.00 SGD/h	220.00	
Material Cost	83.45	
Total Paint Including Material		303.45
Repair Cost Excludes GST		1,123.67
GST (+7.0%)		78.66
Repair Cost Included GST		1,202.33

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 29 April 2019 11:29 AM
To: Goh Wee Dek; SUR
Subject: RE: SHB 8319Z-DOA: 13/4/2019

Dear Wee Dek,

WITHOUT PREJUDICE

Confirm PxP \$1,123.67 & 2days.

Kindly send Final invoice and all supporting documents directly to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh Wee Dek <weedek.goh@premiertaxi.com>
Sent: Saturday, 27 April 2019 9:11 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>
Subject: RE: SHB 8319Z-DOA: 13/4/2019

Dear Veron

Please confirm PxP \$1,123.67 & 2days.

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION 

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]
Sent: Friday, 26 April, 2019 3:48 PM
To: Gary Shi; Goh Wee Dek
Subject: SHB 8319Z-DOA: 13/4/2019

Dear Wee Dek/Gary,

Kindly advise vehicle status.

If vehicle has been repaired, please finalize with us.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2019		17 Apr 2019 09:42 Edit Adj Rpt	S\$1,123.67 Edit Estimates	S\$1,123.67 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	ZHANG MANLI , ID: S8576435G								
Main Claimant:	PREMIER TAXIS PTE LTD , Co. Reg. No.: 200304975H								
Vehicle Reg. No.:	SHB8319Z	Date of Loss:	13/04/2019 00:00 - :59 [20 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 590729	Policy/Cover Note No.:	29118443AV2 Coverage: 28/02/2019 - 27/02/2021						
Vehicle Reg. No. (Insured):	SMJ3582K	Policy No. (Claimant):							
		Excess:							
Repairer:	Premier Automotive Services Pte Ltd (Changi) 23 Changi South Ave 2 #01-02, 486443 Changi - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 17/05/2019]								
Adj Asg. Remarks:	On WP. (MANUAL ASSIGNED) SURVEY AGREE ON SJE - REQ TO ASSIGN LKK (KALVIN ANG) LIABILITY:DISPUTE (OI NON-REPORTING) CONTACT: VINCENT 6214 8880/6544 6689								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB8319Z (590729)
[SMJ3582K]
TP
PREMIER TAXIS PTE LTD
Apr 13 2019 12:00AM
[ZHANG MANLI]
Premier Automotive Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	22/04/19 14:49	Adjuster Immediate Advice						Load HTM			
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
2	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
3	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
4	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
5	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
6	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
7	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
8	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
9	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
10	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
11	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
12	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
13	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
14	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
15	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
16	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
17	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
18	29/04/19 10:56	General View						Load JPG	<input checked="" type="checkbox"/>		
19	29/04/19 11:01	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>		
20	29/04/19 11:01	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>		
21	29/04/19 11:01	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>		
22	29/04/19 11:01	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>		
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print		
1	17/04/19 09:13	SHB8319Z GIA Rpt						Load PDF			
2	17/04/19 09:28	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK (KALVIN ANG)						Load PDF			
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)						Thumbnail	Print		
1	17/04/19 09:39	email - manual assign						Load PDF			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	16/07/19 11:22	INVESTIGATION REPORT						Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
----------------------------	-------	------	-------

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19006816/T1VD3E2

Date: 16/07/2019

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29118443AV2

Claimant Vehicle No: SHB8319Z

Insured Vehicle No: SMJ3582K

Date of Loss: 13/04/2019

Nature of Claim: TP

Claim No: 590729

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB8319Z

Make & Model: HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)

Engine No: D4FBGZ125024

Reg. Date: 19/07/2017 (Man. Year: 2016)

Chassis No: TMAD281UVHJ129247

Colour: Silver

Odometer: 119963 km

Engine Capacity: 1582 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	743.08	675.22	67.86	9.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	448.45	448.45	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,191.53	1,123.67	67.86	5.70
+ GST 7.00/7.00% (S\$)	83.41	78.66	4.75	5.69
Nett Amount (S\$)	1,274.94	1,202.33	72.61	5.70

INSPECTION

Date of Assignment: 17/04/2019

Date Inspected: 17/04/2019 Inspected At:

Premier Automotive Services Pte Ltd
(Changi)
23 Changi South Ave 2 #01-02
Singapore 486443

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Jul 2019)	
Parts:	N/A	HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB8319Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	811.11 FL	*811.11 FL
2	1		*L/R OUT BUMPER BRKT	Not Necessary	52.20 FL	*- FL
3	1		*R/R OUT BUMPER BRKT	Not Necessary	52.20 FL	*- FL
4	1		*REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS
5	1		*TAILGATE STICKERS	Necessary	100.00 FS	*100.00 FS
					Sub Total (S\$)	1,063.51
					- List Item Discount on L Items 35.00/35.00% (S\$)	320.43
					Total Parts (S\$)	743.08
						959.11
						283.89
						675.22

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	29.0 WU X 50.00 SGD/H	New	145.00	145.00
2	LABOUR COST 44.0 WU X 50.00 SGD/H	New	220.00	220.00
3	MATERIAL COST	New	83.45	83.45
Gross Labour Cost (S\$)			448.45	448.45

Report was unsubmitted during this print-out.

< END OF ESTIMATES >