



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 33971

Customer :

EQ INSURANCE COMPANY LIMITED
22 GEMMILL LANE
SINGAPORE 069257

MOTOR CLAIMS DEPT

DATE : 08/04/2019
CLAIM NO. : 11313
POLICY NO. : AVFMSB0000651800

FROM : RAYMOND

VEHICLE NO. : FBN1669S
MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALANCER P/N: 55166	REPLACE	1.00	\$12.00	12.00
2	BELLY PAN P/N: 58094	REPLACE	1.00	\$35.00	35.00
3	BOARD FOOTREST RH P/N: 59589	REPLACE	1.00	\$52.00	52.00
4	BOX FILTER AIR OUTER P/N: 58141	REPLACE	1.00	\$18.00	18.00
5	BOX FILTER AIR REAR P/N: 58189	REPLACE	1.00	\$28.00	28.00
6	BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT P/N: 27220	REPLACE	1.00	\$208.00	208.00
7	BRACKET MASTER CYLINDER RH P/N: 60166	REPLACE	1.00	\$10.00	10.00
8	CLIP	REPLACE	1.00	\$1.50	1.50
9	COVER CLUTCH OUTER P/N: 58147	REPLACE	1.00	\$68.00	68.00
10	COVER SIDE CENTRE RH (WHITE) P/N: 58117	REPLACE	1.00	\$30.00	30.00
11	COWLING FRONT RH (WHITE) P/N: 59594	REPLACE	1.00	\$38.00	38.00
12	EMBLEM (YAMAHA) LOGO P/N: 57069	REPLACE	1.00	\$12.00	12.00
13	GASKET FILTER AIR	REPLACE	2.00	\$4.50	9.00



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg
Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0383
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
14	GRIP HANDLE	REPLACE	1.00	\$7.00	7.00 X
15	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	3.00	\$35.00	105.00
16	LEVER BRAKE RH P/N: 58185	REPLACE	1.00	\$18.00	18.00
17	MIRROR RH P/N: 58187	REPLACE	1.00	\$38.00	38.00
18	PANEL 2 P/N: 58081	REPLACE	1.00	\$22.00	22.00 ?
19	PIPE DRAIN FILTER AIR	REPLACE	1.00	\$1.50	1.50 ?
20	PROTECTOR EXHAUST P/N: 58086	REPLACE	1.00	\$38.00	38.00
21	SCREW (VISOR) P/N: 62053	REPLACE	1.00	\$4.50	4.50
22	SPRAY PAINT COWLING FRONT RH (LACQUER)	Spray	1.00	\$90.00	90.00
23	STICKER (CERTIS CISCO) WINDSHIELD NEW MODEL P/N: 61182	REPLACE	1.00	\$60.00	60.00
24	STICKER (CISCO) COWLING FRONT RH P/N: 58617	REPLACE	1.00	\$38.00	38.00
25	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$18.00	18.00 ¹⁰
26	TRANSPORT CHARGES P/N: 07169 - FOR COLLECTION OF ACCIDENT BIKE AND DELIVER BIKE BACK TO BASE ONCE REPAIR DONE.		1.00	\$35.00	35.00
27	WINDSHIELD P/N: 58073	REPLACE	1.00	\$60.00	60.00

SUB TOTAL

\$1,056.50

GST @ 7 %

\$73.96

GRAND TOTAL

\$1,130.46

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



LRK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Acknowledge & Accepted By



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

