

ASS. REC. BY:

REF: 7M1/CC3/TM119006821/KSD302


Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s Trans Cab  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 02 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SHC 5915S Yr Regn: 12, 14  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Renault Latitude c.c 1995  
 Colour M. White Red AC: Insured / Std / NI / NA  
 Sp. Reading 635892 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: VFIABL15AHC 280981  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 215/60R16  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Citi  
 Front R/Bal. 8 mm Rear R/Bal. 8 mm  
 L/Bal. 8 mm L/Bal. 8 mm  
 D.O.A. 14/4/19 D.O.I. 16/4/19  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or  
Rear N/S  
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	File pass to LISA @ Pool
	SHC 5915 S - (04/A1907003437) LD M D.O.A - 10/11/2017
	SG 70403 - (03/LR 17009647) NIP 0392 D.O.A - 4/09/2017
	Book Value - R 48,206.05 X

RECEIVED 25 MAY 2019

Date/Time, File Pass to: 29/05/19  
 : Prell. Report  
 : Final Report  
 Date/Time, File Return to: \_\_\_\_\_

Days Of Repair: 2  
 Resurvey No. of Trip: 1

Add Fee:  : Site Insp (\$ )  
 : Interview (\$ )  
 : Tech Invs (\$ )  
 : Weekend (\$ )

Survey Fee:  
 Transportation: 250  
 S - RS \$ 10  
 Fuel: \_\_\_\_\_  
 Others: \_\_\_\_\_

250
10
TOTAL
260

Report Format :

Lump Sum / I.B.I: (\$ 1,900/- / 1/5 )

## Shirley Hiew (LKK Auto)

---

**From:** Ng Wai Yin <waiyin.ng@transcab.com.sg>  
**Sent:** Wednesday, 29 May 2019 4:25 PM  
**To:** 'Shirley Hiew (LKK Auto)'  
**Subject:** FW: TCS REF: AAD1904-151--Accident involving SHC 5915S & SLG 7040D on 14.04.2019  
**Attachments:** ESTIMATE MARKED.pdf; DSCN3871.JPG; DSCN3873.JPG; DSCN3866.JPG

Hi Shirley

We confirmed COR amount \$ 1,900.00(before GST).

Thank You  
Best Regards,  
*Ng Wai Yin*  
Finance Department  
TEL: 6603 1265 Ext.308

**\*\*\* Please be reminded that all claims correspondence to be send to [claims@transcab.com.sg](mailto:claims@transcab.com.sg)**



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: [www.transcab.com.sg](http://www.transcab.com.sg)

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Shirley Hiew (LKK Auto) [<mailto:ShirleyHiew@lkkauto.com>]  
**Sent:** Thursday, 18 April, 2019 9:17 AM  
**To:** 'Ng Wai Yin' <[waiyin.ng@transcab.com.sg](mailto:waiyin.ng@transcab.com.sg)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** TCS REF: AAD1904-151--Accident involving SHC 5915S & SLG 7040D on 14.04.2019

Dear Wai Yin,

Please confirm final fig \$ 1,900.00 (lump sum) @ 2 days of repairs before GST.

Thank you.  
Best Regards,  
Shirley Hiew | Case Handler  
**LKK Auto Consultants Pte Ltd**  
Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



---

This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

**Shirley Hiew (LKK Auto)**

---

**From:** weichunkong <weichunkong@transcab.com.sg>  
**Sent:** Wednesday, 17 April 2019 7:17 PM  
**To:** 'Candy Kong'  
**Cc:** 'Kenneth Kong (LKKAuto)'  
**Subject:** RE: BOOK VALUE REQUIRE FOR CLOSURE

Hi all,

SHC5915S Net book value is \$48,206.05  
SHC5278Y Net book value is \$41,767.95  
SHD9794S Net book value is \$44,920.44  
SHC5368X Net book value is \$45,753.42

Thanks  
Best regards

CK



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line: (65) 6287 6666 Fax Line: (65) 6287 7764  
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet.

---

**From:** Candy Kong [mailto:candy.kong@transcab.com.sg]  
**Sent:** Wednesday, 17 April, 2019 2:15 PM  
**To:** 'weichunkong' <weichunkong@transcab.com.sg>  
**Cc:** 'Kenneth Kong (LKKAuto)' <KennethKong@lkkauto.com>  
**Subject:** BOOK VALUE REQUIRE FOR CLOSURE

Hi CK

Kindly assist to forward below vehicles net book value,

SHC5915S DOA: 14/4/2019 7:10 PM  
SHC5278Y DOA : 15/4/2019 12:55 PM  
SHD9794S DOA : 15/4/2019 8:00 AM  
SHC5368X DOA : 15/4/2019 1:50 PM

*Thks & Rdgs*  
*Candy Kong*  
*Claims Service Assistant*



**TRANS-CAB SERVICES PTE LTD**  
No. 2 Ang Mo Kio Street 63, Singapore 569111  
Main Line :(65) 6287 6666 Fax Line: (65) 6257 1330  
Website: www.transcab.com.sg

This message is confidential. It may also be privileged or otherwise protected by work product immunity or other legal rules. If you have received it by mistake, please let us know by e-mail reply and delete it from your system; you may not copy this message or disclose its contents to anyone. Please send us by fax any message containing deadlines as incoming e-mails are not screened for response deadlines. The integrity and security of this message cannot be guaranteed on the Internet

---



This email has been checked for viruses by AVG antivirus software.  
[www.avg.com](http://www.avg.com)

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Wednesday, 17 April 2019 1:35 PM  
**To:** 'Motor Claims'  
**Cc:** SUR  
**Subject:** DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD, DOA: 14/04/2019 , SHC 5915S (TP Vehicle), SLG 7040J (OI Vehicle)  
**Attachments:** TP GIA REPORT.pdf; ESTIMATE.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SHC 5915S at M/s: TRANS-CAB AUTO SERVICES PTE LTD, NO.2 ANG MO KIO ST 63 SINGAPORE 569111 on 16/04/2019.

Enclosed herewith a copy of TP's GIA report and estimated cost of repair .

Meanwhile, kindly create claim in merimen for our necessary action.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type: Company  
 Owner ID: 3878K

#### Vehicle Details

Vehicle No.: SHC59155  
 Vehicle to be Exported: Yes  
 Intended Deregistration Date: 15 Apr 2019  
 Vehicle Make: RENAULT  
 Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR  
 Primary Colour: Red  
 Manufacturing Year: 2014  
 Engine No.: M9R8839C002159  
 Chassis No.: VF1ABL15AUC280981  
 Maximum Power Output: 127.0 kW (170 bhp)  
 Open Market Value: \$19,998.00  
 Original Registration Date: 18 Dec 2014  
 First Registration Date: 18 Dec 2014  
 Transfer Count: 0  
 Actual ARF Paid: \$12,498.00

#### Intended PARF Rebate Details

PARF Eligibility: Yes  
 PARF Eligibility Expiry Date: 17 Dec 2022  
 PARF Rebate Amount: \$9,373.00

#### Intended COE Rebate Details

COE Expiry Date: 17 Dec 2022  
 COE Category: A - Car up to 1600cc & 97kW (130bhp)  
 COE Period(Years): B  
 PQP Paid: \$51,668.00  
 COE Rebate Amount: \$23,715.00  
**Total Rebate Amount: \$33,088.00**

#### Message

Please note that the B-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 15 Apr 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	15/04/2019 14:23
Date Of Accident	14/04/2019 19:10
Exact Location Of Accident	CTE SLIP ROAD TOWARDS ANG MO KIO AVENUE 5
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC5915S
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

### Vehicle Particulars

Manufacturer	RENAULT
Model	LATITUDE-2.0 L (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

### Driver

Name of Driver	MAH KIN HUAT
NRIC No	S0220916J
Date Of Birth	20/07/1954
Occupation	OUTDOOR
Date Of Driving Pass	01/02/1990
Driving Experience	29 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92268812
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 172 WOODLANDS ST13 #11-307
Postcode	730172
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - RELIEF
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

On 14.04.2019 at about 1910hours, I was stationary straight on the third lane along CTE slip road towards Ang Mo Kio Avenue 5 when the traffic light was red. Whiled stationary, suddenly I felt an impact. Vehicle B (SLG7040J) hit onto my taxi's rear portion.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLG7040J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	91000928
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/PIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

plz see attach OA Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 59155**

AAD1904-151

*Not Authored  
11 Sep 8 1900*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

**SHC 59155**

VF1ABL15AUC280981

RENAULT

LATITUDE

14.4.2019

**TOKIO MARINE**

18/12/2014

**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>CM</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Not/low</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	✓
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	} X
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	
13	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56	
15	1 BOOT REAR	\$	<i>R</i> 2,872.68	
16	1 TAILLAMP RH	\$	<i>Sn</i> 552.55	
17	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70	
18	1 TAILLAMP LH	\$	<i>Sn</i> 552.55	
19	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	
		\$	<b>11,496.85</b>	
		10% \$	<b>1,149.69</b>	
		\$	<b>10,347.17</b>	

**Special Nett**

1	1SET PARKING AID	\$	<i>Sn</i> 700.00	X
2	1SET REAR BUMPER CLIP	\$	<i>nc</i> 66.00	✓
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>nc</i> 33.00	✓

**Trans-cab Auto Services Pte Ltd**

AAD1904-151

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 59155**

4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	<
6	1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	<
7	1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	<
8	1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	na	17.82	} X
11	2 REAR WINDSCREEN SELANT	\$	na	80.00	
12	1 WINDSCREEN MOULDING	\$	na	100.00	
13	1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	
14	1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	
15	1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	
<b>TOTAL</b>		<b>\$</b>		<b>605.82</b>	
<b>TOTAL PARTS</b>		<b>\$</b>		<b>10,952.99</b>	

**LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	na	170.00 X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00 X
To repair and realign rear exhaust pipe.	\$	na	170.00 X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na	170.00 X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	170.00 X

**Trans-cab Auto Services Pte Ltd**

**AAD1904-151**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 59155**

To transfer of rear windscreen fittings and conduct water seepage test. \$ *nn* 170.00 X

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

**TOTAL \$ 7,410.00**

**Over All Total \$ 28,710.15**

**(LUMP SUM)**

**Repair Days**

*19161.98*  
~~**10 DAYS**~~

*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts using resurvey
- Parts prices are subject to confirmation
- This policy works on the "Without Prejudice" basis
- No. of claimants/claim(s) is allowed
- Supplemental claim(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledges by Repairer  
Signature:  
Date:

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI19006821/KSD3N2

Date: 03/06/2019

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MK000205
Claimant Vehicle No :	SHC5915S	Insured Vehicle No :	SLG7040J
Date of Loss:	14/04/2019	Nature of Claim:	TP
		Claim No:	M1902628

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5915S	Engine No:	M9R8839C002159
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC280981
Reg. Date:	18/12/2014 (Man. Year: 2014)	Odometer:	635892 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Giti 8 mm	Rear Left Side:	Giti 8 mm
Front Right Side:	Giti 8 mm	Rear Right Side:	Giti 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %	
Parts	11,751.98	1,893.82	9,858.16	83.89	
Miscellaneous Items	0.00	0.00	0.00		
Labour	7,410.00	480.00	6,930.00	93.52	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>19,161.98</b>	<b>2,373.82</b>	<b>16,788.16</b>	<b>87.61</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>1,900.00</b>			
	(S\$)	19,161.98	1,900.00	17,261.98	90.08
+ GST 7.00/7.00% (S\$)	1,341.34	133.00	1,208.34	90.08	
<b>Nett Amount (S\$)</b>	<b>20,503.32</b>	<b>2,033.00</b>	<b>18,470.32</b>	<b>90.08</b>	

INSPECTION

Date of Assignment:	17/04/2019		
Date Inspected:	16/04/2019	Inspected At:	Trans-Cab Services Pte Ltd (HQ) 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

<b>Reference</b>	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 03 Jun 2019)
<b>Parts:</b> 143	RENAULT LATITUDE 2.0 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHC5915S)	
<b>Validity:</b> These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Cracked	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented/Cut	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	113.47 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Cracked	43.61 FL	*43.61 FL
10	1		*BUMPER BEAM REAR	Repair	777.52 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	225.95 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	1,471.77 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL
15	1		*BOOT REAR	Repair	2,872.68 FL	*- FL
16	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
17	1		*TAILLAMP PANEL RH	Repair	986.70 FL	*- FL
18	1		*TAILLAMP LH	Serviceable	552.55 FL	*- FL
19	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
20	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
21	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
22	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
23	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
24	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
25	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
26	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
27	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
28	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
29	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
30	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
31	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
32	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
33	1		*REAR BOOT STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
34	1		*REAR BOOT STICKER 6555-3333	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>12,901.66</b>	<b>2,085.91</b>
- List Item Discount on L Items 10.00/10.00% (S\$)	1,149.68	192.09
<b>Total Parts (S\$)</b>	<b>11,751.98</b>	<b>1,893.82</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	220.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	3,000.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
9	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
10	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>7,410.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

&lt; END OF ESTIMATES &gt;