

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9794S**AAD1904-150***Not Autharised
11 Sep @ 1750h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9794S

VF1ABL15AUC277283

RENAULT

LATITUDE

15.4.2019

TOKIO MARINE

14/4/2014

PART**LIST**

1	DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66 <i>X</i>
1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13 <i>X</i>
1	FENDER PANEL INNER TRIM REAR	\$	<i>SL</i> 671.45 <i>X</i>
1	WHEELARCH REAR LH	\$	<i>SL</i> 543.47 <i>X</i>
1	BUMPER COVER REAR	\$	<i>R</i> 1,108.46 ✓
1	BUMPER LOWER REAR	\$	<i>SL</i> 768.84
1	BUMPER BRACKET CTR REAR	\$	<i>SL</i> 113.47
1	BUMPER RETAINER LH REAR	\$	<i>SL</i> 44.99
1	BUMPER BEAM REAR	\$	<i>R</i> 777.52
1	BUMPER BEAM BRACKET LH REAR	\$	<i>SL</i> 225.95
1	TAILLAMP LH	\$	<i>SL</i> 552.55
1	ROCKER PANEL INNER GARNISH LH	\$	<i>SL</i> 466.51
1	ROCKER PANEL INNER LH	\$	<i>R</i> 1,024.79
1	ROCKER PANEL CENTER LH	\$	<i>R</i> 990.25
1	KUCKLE ARM REAR LH L70Y	\$	<i>SL</i> 736.67
1	BRAKE DISC REAR L70Y	\$	<i>SL</i> 525.91
1	ABS SENSOR REAR LH L70Y	\$	<i>SL</i> 375.93
1	LOWER ARM REAR LH L70Y	\$	<i>SL</i> 905.99
2	ABSORBER REAR	\$	<i>SL</i> 389.75
1	STABILIZER BAR REAR L70Y	\$	<i>SL</i> 604.65

\$	16,970.94
10% \$	1,697.09
\$	15,273.85

Specical Nett

1SET	BUMPER CLIP FRT	\$	<i>R</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT LH	\$	<i>na</i> 12.00 <i>X</i>
1	BUMPER SUPPORT CLIP FRT LH	\$	<i>na</i> 10.50 <i>X</i>

Trans-cab Auto Services Pte Ltd

AAD1904-150

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9794S

1SET	BUMPER GRILLE LOWER CLIP	\$	nn 69.00 X
1	REAR DOOR STICKER '6555 3333'	\$	nn 80.00 605n
1	DOOR CHECK BOLT	\$	nn 22.69
1	DOOR GUIDE SCREW	\$	nn 10.85
1	DOOR HINGE BOLT	\$	nn 10.85
1	DOOR HINGE NUT RH	\$	nn 14.60
1	DOOR CHECK BOLT	\$	nn 22.69
1	DOOR CHECK NUT	\$	nn 3.75
1	DOOR LOCK SCREW L70Y	\$	nn 6.12
1	DOOR CATCH SCREW L70Y	\$	nn 10.06
1	LEFT REAR TYRE RIM	\$	sn 380.00
1	LEFT REAR TYRE	\$	sn 330.00

TOTAL \$ 1,049.13**TOTAL PARTS \$ 16,322.98****LABOUR**

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 3,000.00 400l

To apply paint protection system (PPS) maintain and enhancement

\$ nn 380.00 X

Putty and spray painting of the affected portion.

\$ 3,000.00 660l

To rust-proofing of the affected areas.

\$ nn 170.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

Trans-cab Auto Services Pte Ltd**AAD1904-150**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9794S

To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00 X
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 X

TOTAL	\$	8,210.00
--------------	-----------	-----------------

Over All Total	\$	24,532.98
-----------------------	-----------	------------------

LUMP SUM(REPAIR DAY)~~10 DAYS~~
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: