

ASS. REC. BY:

REF:

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SCY88934 Yr Regn: 2012 AprilType: Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Lexus GS350 cc 3456Colour: Grey A/C: Insured / Std / Nil / NASp. Reading 157310 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: JTHBE1BL405006344Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rigi / STD A/Rim orTyre Size: F: 235/45R18R: 235/45R18BS / DUN / EXNOVA / BYTFS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 16/04/19Survey held at 96 MotorsportDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Check.

15/07/19 Confirmed LS \$10,600/- @ 7 days with Advan.
(\$18,528.33 Red - 64%?)

MV: 78K

PV: 62.5K

Nett: 15.5K

RECEIVED 18 JUL 2019

Resurvey No. of TP - 2

Date/Time, File Pass to?

Date/Time, File Return to?

1) <u>15/07/19</u>	2) <u>Tyast</u>
3)	4)
5)	6)

Prel. Report

Final Report: LS \$10,600/-

Part Prices Check:

IN

OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

220

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Apr 2019		17 Apr 2019 11:40 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant: NG KIM LAN , ID: S1605886F									
Vehicle Reg. No.: SCY8893U		Date of Loss: 12/04/2019 17:00 - :59							
Claim Type: TP / SNM19D201657C02		Policy/Cover Note No.: DMPCSN3079551801							
Vehicle Reg. No. (Insured): SLN8880H		Policy No. (Claimant): S104512937 CLASSIC							
		Excess: S\$1,500.00							
Repairer: 96 Motorsports Pte Ltd (HQ) 62/64 Kaki Bukit Avenue 6, 417893 Kaki Bukit - Tel: 6702 6996									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ong Chin Kiat]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 29/04/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
☐ ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

FOR SALE BY OWNER


Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

 [Post an Ad](#)  [Advertiser Login](#)  [Ways of Selling](#)

Proton Saga 1.3M M-Line.

Cheapest Car In Singapore!
\$20/Day!

Don't Miss Out! StarAd



Think One Automobile

NEW & USED
COMMERCIAL VEHICLES

[Browse by Category](#)
[Save Search](#)
[Print](#)
[Sort by Date Posted](#)
[20 results/page](#)

[illegible]

 **Lexus GS350 Luxury** \$80,800 \$16,450 /yr 28-Mar-2012 3,456 cc 97,000 km Luxury Available
Looking For A Sporty, Reliable, Powerful Yet Elegant Daily Driver! Passionate And Car Enthusiast Owned. Look No Further. This GS350 Is Fully Loaded. Why Buy A GS250 When You Could Get This Fully Loaded...
Sweet Seng Motors
Product: 11-Apr-2015 | Page: 2012 Lexus GS350, 2012 Lexus GS350, Lexus GS350, 2012 Lexus GS350, Lexus GS350


 **Lexus GS350 Luxury** | \$88,888 | \$17,710 /yr | 26-Jun-2012 | 3,456 cc | 110,000 km | Luxury | Available
 \$1300 Monthly, Fierce And Luxury Looks With Customized Bodykit, Full Soundproof, Tip Top Condition, Luxury Model And Perfect Colour Combination Of Exterior And Interior. As Good As New, Consignment Ur... [\[Finance\]](#)

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view [Expired ads](#)

20 results/page



[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5886F
Vehicle Details	
Vehicle No.:	SCY8893U
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS GS350 LUXURY AUTO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	2GR8747884
Chassis No.:	JTHBE1BL405006344
Maximum Power Output:	233.0 kW (312 bhp)
Open Market Value:	\$64,609.00
Original Registration Date:	13 Apr 2012
First Registration Date:	13 Apr 2012
Transfer Count:	1
Actual ARF Paid:	\$64,609.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2022
PARF Rebate Amount:	\$38,765.00
Intended COE Rebate Details	
COE Expiry Date:	12 Apr 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$79,304.00
COE Rebate Amount:	\$23,735.00
Total Rebate Amount:	\$62,500.00

The information contained herein is correct as at 15 Apr 2019

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5886F
Vehicle Details	
Vehicle No.:	SCY8893U
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS GS350 LUXURY AUTO
Primary Colour:	Blue
Manufacturing Year:	2012
Engine No.:	2GR8747884
Chassis No.:	JTHBE1BL405006344
Maximum Power Output:	233.0 kW (312 bhp)
Open Market Value:	\$64,609.00
Original Registration Date:	13 Apr 2012
First Registration Date:	13 Apr 2012
Transfer Count:	1
Actual ARF Paid:	\$64,609.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Apr 2022
PARF Rebate Amount:	\$38,765.00
Intended COE Details	
COE Expiry Date:	12 Apr 2022
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$79,304.00
COE Rebate Amount:	\$23,714.00
Total Rebate Amount:	\$62,479.00

The information contained herein is correct as at 16 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	13/04/2019 11:02
Date Of Accident	12/04/2019 17:30
Exact Location Of Accident	SLE TOWARDS CTE (BEFORE CAMERA)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCY8893U
Insured/Policyholder	
Name Of Registered Owner	NG KIM LAN
NRIC No	S1605886F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96708893
Alternative Phone No	OFFICE-96708893
Vehicle Particulars	
Manufacturer	LEXUS
Model	LEXUS GS350 LUXURY AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104512937 CLASSIC
Cover Note Number	

Driver

Name of Driver	LEOW CHUN KIAT
NRIC No	S98034571
Date Of Birth	25/01/1998
Occupation	INDOOR
Date Of Driving Pass	23/03/2019
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-87678893
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLK 825 #08-412 JURONG WEST STREET 81
Postcode	640825
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : NG KIM LAN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLN8880H
Vehicle Make/Model/Colour	LEXUS IS250 AUTO
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg
Reporting Centre's Stamp & Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Along SLE > CTE




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time, I vehicle A 'SCY8893U' was travelling along stated venue. As the front vehicle stopped, I stopped as well. Suddenly I felt an impact from behind and realise vehicle B 'SLN8880H' had hit onto the rear portion of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC KAKI BUKIT (VAC)
 23 Kaki Bukit Ave 4
 Singapore 415933
 Tel: 67416697 Fax: 67492305
 Email: vac@singnet.com.sg
 Name:
 NRIC/IN No.:

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 12 Apr 2019 / 19:25:17

Receipt Date/Time : 12 Apr 2019 / 19:25:17

Tax Invoice/Receipt

Receipt No. : ITNET-00000-190412-003005

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLN8880H				
As at 12 Apr 2019/18:00:00				
Insurance Co: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD				
1	Insurance Enquiry - SLN8880H Enquiry Fee 20190412192420107706	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx8982	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

TPChine.

Shirley.

JTHBE1BL405006344

VEHICLE NUM:

SCY 8893 U

MAKE & MODEL:

LGS350

MILEAGE:

TYRE: FRONT

TYRE: REAR

CHASSIS NUM:

ATTN:

NO.	DESCRIPTION - PARTS	QTY	PRICE	ADJUSTED PRICE
1	BOOT LID <i>Buckled</i> ✓	1	1612.40	1612.40
2	BOOT LID CAMERA <i>Not in</i> x.	1	1538.50	
3	BOOT LID BADGE <i>Not in</i>	1	92.70	92.70
4	BOOT LID EMBLEM (LEXUS) <i>Not in</i> ✓	1	89.40	89.40
5	BOOT LID EMBLEM LGS350 <i>Not in</i> ✓	1	87.50	87.50
6	BOOT LID OUTER CHROME MOULDING <i>Not in</i> +	1	262.70	
7	BOOT LID OUTER CHROME MOULDING CLIP <i>Not in</i> +	1set	60	
8	BOOT LID NUMBER PLATE LAMP L+R <i>Not in</i> +.	2	285.40	
9	BOOT LID OPENER SWITCH <i>Not in</i> +	1	258.40	
10	BOOT LID LAMP L+R <i>Not in</i> x.	2	991.20	
11	BOOT LID LAMP INNER SEAL L+R <i>Not in</i> +	2	150.20	
12	BOOT LID LAMP CLIP <i>Not in</i> +	1set	20	
13	BOOT LID STOPPER <i>Not in</i> +	1	37.10	
14	BOOT LID INNER TRIM <i>Not in</i> +	1	597.30	
15	BOOT LID INNER TRIM CLIP <i>Not in</i> +	1set	50	
16	BOOT LID INNER LOCK <i>Damaged</i> ✓	1	982.30	982.30 804
17	BOOT LID LOCK CATCH <i>Not in</i> +	1	57.20	
18	BOOT LID WEATHERSTRIP <i>Not in</i> ✓	1	295.60	295.60
19	BOOT LID HINGE L+R <i>Not in</i> +	2	330.4	
20	BOOT LID HINGE COVER GARNISH L+R <i>Not in</i> +	2	175.20	
21	BOOT LID HINGE SPRING L+R <i>Not in</i> +	2	394.60	
22	TAIL LAMP L+R <i>Not in</i> ✓	2	1193.40	1193.40
23	TAIL LAMP INNER SEAL L+R <i>Not in</i> ✓	2	150.40	150.40
24	TAIL LAMP CLIP <i>Not in</i> ✓	1set	20	20
25	TAIL LAMP PANEL L+R <i>Not in</i> x.	2	571.20	
26	REAR BUMPER <i>Disturbed</i> ✓	1	1332.50	1332.50 1056
27	REAR BUMPER LOWER <i>Disturbed</i> ✓	1	568.30	568.30
28	REAR BUMPER LOWER CHROME L+R <i>Best</i> ✓	2	585.40	585.40
29	REAR BUMPER SIDE RETAINER L+R <i>Not in</i> ✓	2	179.20	179.20
30	REAR BUMPER ATTACHMENT RETAINER L+R <i>Not in</i> ✓	2	152.40	152.40
31	REAR BUMPER CLIP <i>Not in</i> ✓	1set	60	60
32	REAR BUMPER REINFORCEMENT <i>Best</i> ✓	1	495.20	495.20

[illegible]

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119006828/ASD3N2

Date: 19/07/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3079551801		
Claimant Vehicle No :	SCY8893U	Insured Vehicle No :	SLN8880H		
Date of Loss:	12/04/2019	Nature of Claim:	TP	Claim No:	SNM19D201657C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCY8893U	Engine No:	2GR8747884
Make & Model:	LEXUS GS350, 3.5 LUXURY (L10) (A)	Chassis No:	JTHBE1BL405006344
Reg. Date:	13/04/2012 (Man. Year: 2012)	Odometer:	157310 km
Colour:	Grey		
Engine Capacity:	3456 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45R18	Rear Tyre Size:	235/45R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	24,168.33	10,730.96	13,437.37	55.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,960.00	2,520.00	2,440.00	49.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	29,128.33	13,250.96	15,877.37	54.51
Approved Total (Overridden) (\$\$)		10,600.00		
(\$\$)	29,128.33	10,600.00	18,528.33	63.61
+ GST 7.00/7.00% (\$\$)	2,038.98	742.00	1,296.98	63.61
Nett Amount (\$\$)	31,167.31	11,342.00	19,825.31	63.61

INSPECTION

Date of Assignment:	17/04/2019	
Date Inspected:	16/04/2019	Inspected At: 96 Motorsports Pte Ltd (HQ) 62 Kaki Bukit Avenue 6, The Ark@KB Singapore 417893
Estimated Period of Repair:	7.0 days	

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jul 2019)
Parts:	143	LEXUS GS350 3.5 LUXURY (L10) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCY8893U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Buckled	1,612.40 FL	*1,612.40 FL
2	1		*BOOT LID CAMERA	Not Necessary	1,538.50 FL	*- FL
3	1		*BOOT LID BADGE	Necessary	92.70 FL	*92.70 FL
4	1		*BOOT LID EMBLEM (LEXUS)	Necessary	89.40 FL	*89.40 FL
5	1		*BOOT LID EMBLEM GS350	Necessary	87.50 FL	*87.50 FL
6	1		*BOOT LID OUTER CHROME MOULDING	Not Necessary	262.70 FL	*- FL
7	1		*SET BOOT LID OUTER CHROME MOULDING CLIP	Not Necessary	60.00 FL	*- FL
8	2		*BOOT LID NUMBER PLATE LAMP L+R	Not Necessary	285.40 FL	*- FL
9	1		*BOOT LID OPENER SWITCH	Not Necessary	258.40 FL	*- FL
10	2		*BOOT LID LAMP L+R	Not Necessary	991.20 FL	*- FL
11	2		*BOOT LID LAMP INNER SEAL L+R	Not Necessary	150.40 FL	*- FL
12	1		*SET BOOT LID LAMP CLIP	Not Necessary	20.00 FL	*- FL
13	1		*BOOT LID STOPPER	Not Necessary	37.10 FL	*- FL
14	1		*BOOT LID INNER TRIM	Not Necessary	597.30 FL	*- FL
15	1		*SET BOOT LID INNER TRIM CLIP	Not Necessary	50.00 FL	*- FL
16	1		*BOOT LID INNER LOCK	Damaged	982.30 FL	*804.00 FL
17	1		*BOOT LID LOCK CATCH	Not Necessary	57.20 FL	*- FL
18	1		*BOOT LID WEATHERSTRIP	Cut	295.60 FL	*295.60 FL
19	2		*BOOT LID HINGE L+R	Not Necessary	330.40 FL	*- FL
20	2		*BOOT LID HINGE COVER GARNISH L+R	Not Necessary	175.20 FL	*- FL
21	2		*BOOT LID HINGE SPRING L+R	Not Necessary	394.60 FL	*- FL
22	2		*TAIL LAMP L+R	Cracked	1,183.40 FL	*1,183.40 FL
23	2		*TAIL LAMP INNER SEAL L+R	Necessary	150.40 FL	*150.40 FL
24	1		*SET TAIL LAMP CLIP	Necessary	20.00 FL	*20.00 FL
25	2		*TAIL LAMP PANEL L+R	Repair	571.20 FL	*- FL
26	1		*REAR BUMPER	Distorted	1,332.50 FL	*1,056.00 FL
27	1		*REAR BUMPER LOWER	Distorted	568.30 FL	*568.30 FL
28	2		*REAR BUMPER LOWER CHROME L+R	Bent	585.40 FL	*585.40 FL
29	2		*REAR BUMPER SIDE RETAINER L+R	Necessary	179.20 FL	*179.20 FL
30	2		*REAR BUMPER ATTACHMENT RETAINER L+R	Necessary	152.40 FL	*152.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
31	1		*SET REAR BUMPER CLIP	Necessary	60.00 FL	*60.00 FL
32	1		*REAR BUMPER REINFORCEMENT	Bent	495.20 FL	*495.20 FL
33	1		*REAR BUMPER SPONGE	Distorted	161.20 FL	*161.20 FL
34	2		*REAR BUMPER SIDE BOTTOM GARNISH BRACKET L+R	Not Necessary	151.60 FL	*- FL
35	2		*REAR BUMPER REFLECTOR L+R	Cracked	251.40 FL	*251.40 FL
36	1		*REAR BUMPER REVERSE SENSOR HOLDER	Necessary	57.80 FL	*57.80 FL
37	1		*REAR BUMPER UNDER COVER	Deformed	468.10 FL	*468.10 FL
38	1		*SET REAR BUMPER UNDER COVER CLIP	Necessary	50.00 FL	*50.00 FL
39	2		*REAR FENDER L+R (NPA)	Repair	0.00 FL	*- FL
40	2		*REAR FENDER INNER TRIM L+R	Not Necessary	1,243.40 FL	*- FL
41	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	100.00 FL	*- FL
42	1		*END PANEL	Dented	798.40 FL	*798.40 FL
43	1		*END PANEL TOP TRIM	Deformed	365.80 FL	*365.80 FL
44	1		*SET END PANEL TOP TRIM CLIP	Necessary	20.00 FL	*20.00 FL
45	1		*REAR KEY ANTERNE SENSOR	Damaged	198.40 FL	*198.40 FL
46	1		*SPARE TYRE PANEL	Repair	995.40 FL	*- FL
47	1		*SPARE TYRE PANEL TOP BOARD	Deformed	468.70 FL	*468.70 FL
48	1		*SPARE TYRE PANEL TOP SIDE TOOL SPONGE	Not Necessary	397.90 FL	*- FL
49	1		*SPARE TYRE PANEL TOP CENTER SPONGE	Not Necessary	455.60 FL	*- FL
50	1		*REAR EXHAUST SILENCER L+R	N/s Bent	2,325.40 FL	*1,162.70 FL
51	2		*REAR EXHAUST MOUNTING BRACKET L+R }	Not Necessary	370.40 FL	*- FL
52	2		*REAR EXHAUST MOUNTING L+R }	Not Necessary	0.00 FL	*- FL
53	2		*REAR EXHAUST GASKET L+R	Not Necessary	125.40 FL	*- FL
54	2		*REAR EXHAUST HEAT PLATE L+R	Not Necessary	239.00 FL	*- FL
55	1		*CENTER EXHAUST PIPE	Not Necessary	2,595.60 FL	*- FL
56	1		*CENTER EXHAUST PIPE MOUNTING }	Not Necessary	185.20 FL	*- FL
57	1		*CENTER EXHAUST PIPE MOUNTING BRACKET }	Not Necessary	0.00 FL	*- FL
58	1		*CENTER EXHAUST PIPE GASKET	Not Necessary	62.70 FL	*- FL
59	1		*REAR NUMBER PLATE WITH COVER	Not Necessary	60.00 FS	*- FS
60	1		*REVERSE CAMERA	Not Necessary	350.00 FS	*- FS
61	1		*BODY PANEL JOINT SEALANT	Necessary	40.00 FS	*40.00 FS
62	1		*REAR BUMPER SENSOR	Damaged	400.00 FS	*400.00 FS
63	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	40.00 FS	*- FS
64	1		*SPARE WHEEL PANEL INSULATOR	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,743.70	11,874.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,575.37	1,143.44
Total Parts (\$\$)	24,168.33	10,730.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK, STRAIGHTEN AND REALIGN ACCIDENT AFFECTED AREA	New	1,800.00	1,100.00
2	TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA	New	1,500.00	1,000.00
3	TO RUST PROOF ACCIDENT AFFECTED AREA	New	150.00	60.00
4	TO R&R BOOT & MECH	New	150.00	80.00
5	TO CHECK REVERSE CAMERA FUNCTION	New	120.00	60.00
6	TO R&R REVERSE SENSOR AND FUNCTION	New	120.00	60.00
7	TO CHECK WATER SEEPAGE	New	120.00	0.00
8	TO CHECK WIRING AND RESET SYSTEM	New	400.00	60.00
9	TO R&R BOOT COMPARTMENT	New	120.00	0.00
10	TO R&R EXHAUST PIPE SYSTEM	New	180.00	100.00
11	TO CHECK CHASSIS ALIGNMENT	New	300.00	0.00
Gross Labour Cost (S\$)			4,960.00	2,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >