



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684567 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info	
MR TAY CHUAN LEE (DAI CHUANLI) BLK 57 GEYLANG BAHRU #14-3521 SINGAPORE 330057 Contact No Mobile: 97432887	Cust No/Name	/MR TAY CHUAN LEE (DAI CHUANLI)
	Reg No/Reg Date	SME400Z / 05/04/201
	Date In/Mileage	/ 0
	Chassis No	KNAFZ411MF5538366
	Engine No	G4FGFH600857
	Make/Model	KIA/FORTE K3 1.6 A SX ADR BROWN
	Colour/Trim	ABP / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	15/04/2019/ 14:39		261 / Edwin Caina	48413		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
I	WWCV						X 23.00
	Wash, Wax, Clean & Vacuum						550 1650.00
E	PNT88000						
	RENEW & RE-ALIGN RR DAMAGED PORTION:						
	-RENEW RR BUMPER						X
	-REPAIR RR END & BOOTLID						
E	PNT98000						420 1400.00
	RESPRAY RR BUMPER , RR END PNL & BOOTLID						80 120.00
E	PNT88000						30 50.00
	REMOVE & REFIT RR FLR BOARD,TRIM & CARPET						200.00
A	54900099						
	CHECK WIRING ELECTRICAL SYSTEM						
A	10028901						
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST						
	USING HI-SCAN PRO TEST						
M	SUNDRY						X 80.00
	APPLY ANTI CORROSION ON AFFECTED AREAS						80 100.00
E	PNT88000						
	REMOVE & REFIT REVERSE SENSOR						X 50.00
M	SUNDRY						20 50.00
	SUPPLY C&C BADGE						
M	SUNDRY						
	Sundries						
R	COVER-RR BUMPER				1.00	791.00 00.00	791.00
M	COVER-RR BUMPER,UPR				1.00	245.00 00.00	245.00
M	BEAM-RR BUMPER				1.00	365.00 00.00	365.00
M	WIRING HARNESS-BWS EXT				1.00	173.00 00.00	173.00
M	ULTRASONIC SENSOR ASSY-FBWS				4.00	172.00 00.00	688.00
M	STAY-RR BUMPER LH				1.00	75.00 00.00	75.00
M	STAY-RR BUMPER RH				1.00	75.00 00.00	75.00
M	LOGO ASSY-KIA SUB				1.00	37.00 00.00	37.00
M	FORTE EMBLEM				1.00	40.00 00.00	40.00
M	EMBLEM K3				1.00	15.00 00.00	15.00

Confirm & accepted by

SURVEYOR NAME: Rahul - Hp 90010068SURVEYOR SIGNATURE: RDATE: 16/05/19 @ 1610REMARKS: 4 days

Authorized signatory and company stamp

Net 6,227.00
 7% GST on 6227.00 435.89
Total Payable 6,662.89

Revised before print

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.