

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: INDIA INTERNATIONAL INS	DATE	: 15-Apr-19
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SJS 6698D
ADDRESS	:	MODEL	: NISSAN SYPHY
<u>ACCIDENT DETAILS</u>		DATE	: 13-Apr-19
		TIME	: 10:10HRS
THIRD PARTY REQUESTOR / CONTACT : DEON			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	BONNET <i>Here Repair</i>	1	\$ 1,433.00	\$ 1,433.00
2	BONNET CHROME GARNISH <i>Cracked</i>	1	\$ 98.80	\$ 98.80
3	BONNET LOCK <i>3 new</i>	1	\$ 159.00	\$ 159.00
4	BONNET LOCK CATCH <i>1 new</i>	1	\$ 60.00	\$ 60.00
5	FRONT BUMPER <i>Distorted</i>	1	\$ 755.30	\$ 755.30
6	FRONT BUMPER SIDE RETAINER <i>new RH</i>	2	\$ 52.30	\$ 104.60
7	FRONT BUMPER GRILLE <i>new missing</i>	1	\$ 397.60	\$ 397.60
8	FRONT BUMPER GRILLE LOGO <i>new</i>	1	\$ 67.60	\$ 67.60
9	FRONT BUMPER TOWING COVER <i>new</i>	1	\$ 52.00	\$ 52.00
10	FRONT BUMPER REINFORCEMENT <i>Beut</i>	1	\$ 661.80	\$ 661.80
11	FRONT BUMPER REINFORCEMENT SUPPORT B <i>new Beut</i>	2	\$ 108.40	\$ 216.80
12	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 366.80	\$ 366.80
13	FRONT BUMPER SPONGE <i>Cracked</i>	1	\$ 296.50	\$ 296.50
14	HEAD LAMP RH <i>Cracked</i>	1	\$ 640.00	\$ 640.00
15	HEADLAMP LOWER BRACKET RH <i>new</i>	1	\$ 70.00	\$ 70.00
16	SUPPORT PANEL (UPPER) <i>3 new</i>	1	\$ 296.30	\$ 296.30
17	SUPPORT PANEL (LOWER) <i>3 Repair</i>	1	\$ 443.80	\$ 443.80
18	SUPPORT PANEL (SIDE)	2	\$ 293.10	\$ 586.20
19	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 363.10	\$ 363.10
20	WIPER TANK <i>3 new Delid</i>	1	\$ 60.00	\$ 60.00
21	WIPER TANK MOTOR <i>new</i>	1	\$ 270.00	\$ 270.00
22	RADIATOR <i>3 new</i>	1	\$ 1,138.20	\$ 1,138.20
23	AIR CON CONDENSER	1	\$ 877.30	\$ 877.30

TOTAL PRICE \$ 9,414.70

318.3
2842.47

LESS 10% \$ 941.47

SUB TOTAL PRICE \$ 8,473.23

SPECIAL NETT PRICE

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	FRONT BUMPER GRILLE CLIPS(SET) <i>new</i>	1	\$ 22.00	\$ 22.00
4	FRONT BUMPER LOWER GRILLE CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
5	FRONT SUPPORT PANEL COVER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
6	RADIATOR COOLANT <i>new</i>	1	\$ 120.00	\$ 120.00
7	HEADLAMP CLIP <i>new</i>	1	\$ 20.00	\$ 20.00

TOTAL \$ 272.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$1,600.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$1,600.00	600	
3	TUFF COAT	\$150.00	x	
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$120.00	x	
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$80.00	x	
6	WIRING CHECK	\$50.00	30	

TOTAL \$ 3,600.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 2,000.00		
2	SPRAY PAINTING TO AFFECTED AREA	\$ 2,000.00		
3	TUFF COAT	\$ 250.00		
4	TO CONDUCT WATER LEAKAGE TEST	\$ 200.00		
5	TRANSFER BOOTLID MECHANISM	\$ 60.00		
6	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 250.00		
7	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 80.00		

8	WIRING CHECK	\$ 180.00		
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00		

TOTAL

\$5,140.00

TOTAL PARTS COST : \$ 8,745.23

TOTAL LABOUR COST : \$ 8,740.00

TOTAL REPAIR COST : \$ 17,485.23

APPROVED DETAILS

EXCESS :

NO. OF WORKING DAYS :

RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

Adrian Lj
L/s 17/04/19.

05 days.

total: 4034.47

L/s: 28K

sls.

L/s: 2.81c
#.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: