

INS. CASE OWNER:

W CC4 / Asm 1900 6838, K2a3s2

LKK:

IDAC:

111142

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

GBC 1396L



INSRS:

WSP:

Tel:

Liability:

RMKS:

Cheng Hoe



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

GBC 1396L - X

XD 8097M - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI: (WMA) [initials]

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

38

If NO or B 28, Ass. Lia: 100%

Repair Cost:

S\$

14766.00

3 VET CC O/D LOST

Loss of Rental (LOR):

S\$

-

(

days)

Loss of Use (LOU):

S\$

1422.00

x

24

days)

Loss of Income (LOI):

S\$

-

(

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

8.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

Total:

S\$

16214.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

16214.00

Name 1:

Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

350.00

COPY SENT

ASS. REC. BY:

REF:

AXA/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: B15K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 24 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBC 1396L Yr Regn: 09, 09

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Dyno c.c. 2982Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 513991 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTIFAT 35470K 200932Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm orTyre Size: F: B.S 195R15X8R: Falken 155R12X8(10)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 9 mmL/Bal. 9 mmD.O.A. 15/4/19

Survey held at

Rear

R/Bal. 33 mmL/Bal. 33 mmD.O.I. 17/4/19Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1/ File pass to
EH not readyUS \$ 138W CR ~~at~~ 16478.60/5474
24 + 2PH + 25m = 28

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee:

Transportation:

S - RS, SI

Parking

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S: AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288
 ATTN: Motor Claim Department

WS Ref: TP-AXA
 Claim Type: Third Party

Accident Date: 15/04/2019

TP Veh Reg No: XD8097M

FAX: 68804739

Estimate No: ES1991424/WS

Date: 17 Apr 2019

Policy No: D-18091716MFCV/3

Veh Reg No: GBC1396L

Make/Model: TOYOTA DYNA 150 D

Chassis No: JTFAT35Y70K200932

Engine No: 1KD1952401

Reg. Date: 30/09/2009

Estimate Repair Cost to Vehicle No :GBC1396L

Description	U/Price	Quantity	List Price	Amount
List Price			SS	SS
1 REAR TAILGATE	1,065.20	1 PC	By 1,065.20	—
2 REAR TAILGATE LOWER STICKER "DYNA"	23.90	1 PCS	M 23.90	—
3 REARTAILGATE SAFETY LOCK HANDLE	165.80	1 PC	By 165.80	—
4 LH SIDE GATE	1,989.80	1 PC	By 1,989.80	—
5 LH SIDE GATEHINGE PIN	18.10	6 PCS	Di 108.60	—
6 REAR NUMBER PLATE PANEL	172.85	1 PC	By 172.85	—
7 REAR NUMBER PLATE LAMP	29.20	1 PC	By 29.20	7 X
8 FRONT BUMPER	398.57	1 PC	By 398.57	—
9 FRONT GRILLE	424.15	1 PCS	mi 424.15	—
10 FRONT GRILLE LOGO	70.35	1 PC	mi 70.35	—
11 FRONT GRILLE CLIPS	4.50	3 PCS	me 13.50	—
12 HEAD LAMP	795.20	2 PCS	1,590.40	—
13 HEAD LAMP LOWER RUBBER	29.50	2 PCS	59.00	4 + 29.50 ✓
14 FRONT PANEL	1,126.00	1 PC	By 1,126.00	—
15 FRONT WIPER PANEL	256.70	1 PC	By 256.70	—
16 FRONT CENTRE SIDE GARNISH	115.10	2 PCS	230.20	4 + 115.10 ✓
17 FRONT CENTRE GARNISH	285.10	1 PC	By 285.10	—
18 FRONT WINDSCREEN GLASS	1,390.90	1 PC	CM 1,390.90	—
19 FRONT WINDSCREEN GLASS RUBBER	288.61	1 PC	By 288.61	50 is a #144.306 ✓
20 FRONT RH WIPER NOZZLES	39.90	1 PC	CM 39.90	—
21 FRONT WIPER BLADE	74.48	1 SET	By 74.48	—
22 FRONT LH SIDE MIRROR	538.10	1 PC	CM 538.10	—
23 FRONT LH SIDE MIRROR STAY COVER	38.90	1 PC	mi 38.90	—
24 FRONT CORNAL PANEL	265.58	1 PC	By 265.58	—
25 AIR-CON BLOWER Condenser	490.10	1 PC	By 490.10	—
26 AIR-CON GAS DISCHARGE HOSE	321.80	1 PC	By 321.80	7 X
27 AIR-CON CONDENSER WITH FAN	698.90	1 PC	By 698.90	7 X
28 RADIATOR	1,596.70	1 PC	By 1,596.70	7 X
29 RADIATOR FAN COWLING	221.80	1 PC	CM 221.80	7 X
30 FRONT LH DOOR	1,310.80	1 PC	By 1,310.80	—
31 FRONT LH DOOR GLASS	525.10	1 PC	Shorten 525.10	—
32 FRONT LH DOOR GLASS OUTER MOULDING	110.70	1 PC	By 110.70	—
33 FRONT LH DOOR GLASS REGULATOR	295.65	1 PC	By 295.65	—

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 15/04/2019

TP Veh Reg No: XD8097M

Estimate No: ES1991424/WS

Date: 17 Apr 2019

Policy No: D-18091716MFCV/3

Veh Reg No: GBC1396L

Make/Model: TOYOTA DYNA 150 D

Chassis No: JTFAT35Y70K200932

Engine No: 1KD1952401

Reg. Date: 30/09/2009

Estimate Repair Cost to Vehicle No :GBC1396L

Description	U/Price	Quantity	List Price	Amount
34 FRONT LH DOOR GLASS CHANNEL	219.87	1 PC	<i>Di</i> 219.87 ^{SS} ✓	^{SS}
35 FRONT LH DOOR GLASS INNER LOCK	262.90	1 PC	<i>Im</i> 262.90 ✓	
36 FRONT LH DOOR GLASS INNER RUBBER	180.80	1 PC	<i>Del</i> 180.80 ✓	
37 FRONT LH DOOR GLASS TRIM BOARD	560.56	1 PC	<i>Bu</i> 560.56 ✓	
38 FRONT LH DOOR GLASS HINGES	85.10	2 PCS	<i>Ry</i> 170.20 ✓	
39 FRONT DOOR REAR PILLAR OUTER	620.00	1 PC	<i>Ry</i> 620.00 ✓	
40 FRONT DOOR REAR INNER	301.15	1 PC	<i>R</i> 301.15 <i>XX</i>	
41 FRONT LH DOOR REAR EMBLEM 'D4'D	46.90	1 PC	<i>Me</i> 46.90 ✓	
42 REAR WINDSCREEN RUBBER	99.85	1 PC	<i>Me</i> 99.85 <i>50% \$49.92 SN</i>	
43 CABIN FRONT CROSS BAR	720.00	1 PC	<i>Ry</i> 720.00 ✓	
44 CABIN FRONT CROSS BAR MOUNTING	491.80	2 PCS	<i>CM</i> 983.60 ✓	
45 FRONT CHASSISS CROSS MEMBER	191.80	1 PC	<i>Di</i> 191.80 ✓	
46 RADIATOR SPARE TANK	140.85	1 PC	<i>Sm</i> 140.85 <i>XX</i>	
47 CABIN REAR CROSS BAR	855.10	1 PS	<i>Sm</i> 855.10 <i>XX</i>	
48 CABIN REAR LH HANDLE OPENER	449.70	1 PS	<i>Sm</i> 449.70 <i>XX</i>	
49 CABIN REAR RH DOOR PANEL OUTER	620.00	1 PC	<i>Ry</i> 620.00 ✓	
50 DASHBOARD	658.12	1 PC	<i>Bu</i> 658.12 ✓	
51 DASHBOARD HOUSING <i>reinforcement</i>	494.12	1 PC	<i>Di</i> 494.12 ✓	
52 GLOVER BOX	299.30	1 PC	<i>CM</i> 299.30 ✓	
53 DASH BOX TOP GARNISH	393.30	1 PC	<i>Sm</i> 393.30 <i>XX</i>	
54 FRONT WINDSCREEN PILLAR	580.85	1 PC	<i>Ry</i> 580.85 ✓	
55 FRONT WHEEL ARP GARNISH	157.15	1 PC	<i>Di</i> 157.15 ✓	
			25,223.46	
Less 25%			6,305.87	18,917.60
Special Net				
56 FRONT NUMBER PLATE	15.00	1 PC	<i>Ry</i> 15.00 ✓	
57 REAR NUMBER PLATE	15.00	1 PC	<i>Del</i> 15.00 ✓	
58 STICKER - 70KM/H	10.00	1 PC	<i>Me</i> 10.00 ✓	
59 STICKER - 13 PAX	10.00	1 PC	<i>Bu</i> 10.00 ✓	
60 TAILGATE INNER PROTECTOR	350.00	1 PC	<i>Bu</i> 350.00 ✓	
61 REAR TRUCK FLOOR PROTECTOR	900.00	1 PC	<i>Bu</i> 900.00 ✓	
62 REVERSE SENSOR	200.00	1 PC	<i>Short</i> 200.00 ✓	
63 FRONT LH COY STICKER	20.00	1 PC	<i>Me</i> 20.00 ✓	

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBC1396L
78/AXA
2018-15/4/19

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 15/04/2019

TP Veh Reg No: XD8097M

Estimate No: ES1991424/WS

Date: 17 Apr 2019

Policy No: D-18091716MFCV/3

Veh Reg No: GBC1396L

Make/Model: TOYOTA DYNA 150 D

Chassis No: JTFAT35Y70K200932

Engine No: 1KD1952401

Reg. Date: 30/09/2009

Estimate Repair Cost to Vehicle No :GBC1396L

Description	U/Price	Quantity	List Price	SS
Labour				
64 TOWING	50.00	1 LA	50.00	✓
65 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓
66 REMOVE AND REFIX DASH BOARD, METER ASSY AND CHECK WIRING	250.00	1 LA	250.00	✓
67 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
68 REMOVE AND REFIX REAR WINDSCREEN GLASS	60.00	1 LA	60.00	✓
69 REMOVE AND REFIX CARPET, GARNISH, TOP ROOF LINING, SAFETY BELT, ETC	120.00	1 LA	120.00	✓
70 -PANEL BEATING ON FRONT PORTION	2,000.00	1 LA	2,000.00	1600
71 PUTTY AND RESPRAY BY FRONT PORTION	1,600.00	1 LA	1,600.00	1300
72 PANEL BEATING ON REAR PORTION	1,400.00	1 LA	1,400.00	1100
73 PUTTY AND RESPRAY ON REAR PORTION	900.00	1 LA	900.00	800
74 REMOVE AND REFIX CANOPY ASSY, TRUCK PROTECTOR AND REALIGN THE SAME	1,000.00	1 LA	1,000.00	800
75 TO REWRITE ADVERTISEMENT	500.00	1 LA (8/11)	500.00	280
76 RUSTPROOFING	100.00	1 LA	100.00	✓
			8,140.00	8,140.00

Total S\$ 28,577.60

Add GST @ 7% 2,000.43

Total Amount Payable S\$ 30,578.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

30278.69

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Supp 1
GBC1396L

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 15/04/2019

TP Veh Reg No: XD8097M

Estimate No: ES1991424/WS

Date: 23 Apr 2019

Policy No: D-18091716MFCV/3

Veh Reg No: GBC1396L

Make/Model: TOYOTA DYNA 150 D

Chassis No: JTFAT35Y70K200932

Engine No: 1KD1952401

Reg. Date: 30/09/2009

Estimate Repair Cost to Vehicle No :GBC1396L

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
Net Price				
1 ENGINE INTERCOOLER	1,890.10	1 PC	1,890.10	
			1,890.10	
		Less 10%	189.01	1,701.09
Total				S\$ 1,701.09
GST Amount				S\$ 119.08
Total Amount Payable				S\$ 1,820.17

The above vehicle was surveyed by LKK - KENNETH on 17/04/2019

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

30278.69

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 15/04/2019

TP Veh Reg No: XD8097M

Estimate No: ES1991424/WS

Date: 17 Apr 2019

Policy No: D-18091716MFCV/3

Veh Reg No: GBC1396L

Make/Model: TOYOTA DYNA 150 D

Chassis No: JTFAT35Y70K200932

Engine No: 1KD1952401

Reg. Date: 30/09/2009

Estimate Repair Cost to Vehicle No :GBC1396L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR TAILGATE	1,065.20	1 PC	1,065.20	✓
2 REAR TAILGATE LOWER STICKER "DYNA"	23.90	1 PCS	23.90	✓
3 REAR TAILGATE SAFETY LOCK HANDLE	165.80	1 PC	165.80	✓
4 LH SIDE GATE	1,989.80	1 PC	1,989.80	✓
5 LH SIDE GATE HINGE PIN	18.10	6 PCS	108.60	✓
6 REAR NUMBER PLATE PANEL	172.85	1 PC	172.85	✓
7 REAR NUMBER PLATE LAMP	29.20	1 PC	29.20	✓
8 FRONT BUMPER	398.57	1 PC	398.57	✓
9 FRONT GRILLE	424.15	1 PCS	424.15	✓
10 FRONT GRILLE LOGO	70.35	1 PC	70.35	✓
11 FRONT GRILLE CLIPS	4.50	3 PCS	13.50	✓
12 HEAD LAMP	795.20	2 PCS	1,590.40	✓
13 HEAD LAMP LOWER RUBBER	29.50	2 PCS	59.00	✓
14 FRONT PANEL	1,126.00	1 PC	1,126.00	✓
15 FRONT WIPER PANEL	256.70	1 PC	256.70	✓
16 FRONT CENTRE SIDE GARNISH	115.10	2 PCS	230.20	✓
17 FRONT CENTRE GARNISH	285.10	1 PC	285.10	✓
18 FRONT WINDSCREEN GLASS	1,390.90	1 PC	1,390.90	✓
19 FRONT WINDSCREEN GLASS RUBBER	288.61	1 PC	288.61	✓
20 FRONT RH WIPER NOZZLES	39.90	1 PC	39.90	✓
21 FRONT WIPER BLADE	74.48	1 SET	74.48	✓
22 FRONT LH SIDE MIRROR	538.10	1 PC	538.10	✓
23 FRONT LH SIDE MIRROR STAY COVER	38.90	1 PC	38.90	✓
24 FRONT CORNAL PANEL	265.58	1 PC	265.58	✓
25 AIR-CON BLOWER	490.10	1 PC	490.10	?
26 AIR-CON GAS DISCHARGE HOSE	321.80	1 PC	321.80	?
27 AIR-CON CONDENSER WITH FAN	698.90	1 PC	698.90	?
28 RADIATOR	1,596.70	1 PC	1,596.70	?
29 RADIATOR FAN COWLING	221.80	1 PC	221.80	?
30 FRONT LH DOOR	1,310.80	1 PC	1,310.80	✓
31 FRONT LH DOOR GLASS	525.10	1 PC	525.10	✓
32 FRONT LH DOOR GLASS OUTER MOULDING	110.70	1 PC	110.70	✓
33 FRONT LH DOOR GLASS REGULATOR	295.65	1 PC	295.65	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 15/04/2019

TP Veh Reg No: XD8097M

Estimate No: ES1991424/WS

Date: 17 Apr 2019

Policy No: D-18091716MFCV/3

Veh Reg No: GBC1396L

Make/Model: TOYOTA DYNA 150 D

Chassis No: JTFAT35Y70K200932

Engine No: 1KD1952401

Reg. Date: 30/09/2009

Estimate Repair Cost to Vehicle No :GBC1396L

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
34 FRONT LH DOOR GLASS CHANNEL	219.87	1 PC	<i>D17</i> 219.87 ✓	
35 FRONT LH DOOR GLASS INNER LOCK	262.90	1 PC	<i>7m</i> 262.90 ✓	
36 FRONT LH DOOR GLASS INNER RUBBER	180.80	1 PC	<i>Dd</i> 180.80 ✓	
37 FRONT LH DOOR GLASS TRIM BOARD	560.56	1 PC	<i>Bu</i> 560.56 ✓	
38 FRONT LH DOOR GLASS HINGES	85.10	2 PCS	<i>R1</i> 170.20 ✓	
39 FRONT DOOR REAR PILLAR OUTER	620.00	1 PC	<i>R1</i> 620.00 ✓	
40 FRONT DOOR REAR INNER	301.15	1 PC	301.15 ?	
41 FRONT LH DOOR REAR EMBLEM 'D4' D	46.90	1 PC	<i>me</i> 46.90 ✓	
42 REAR WINDSCREEN RUBBER	99.85	1 PC	<i>me</i> 99.85 <i>50% on</i>	
43 CABIN FRONT CROSS BAR	720.00	1 PC	720.00 ?	
44 CABIN FRONT CROSS BAR MOUNTING	491.80	2 PCS	983.60 ?	
45 FRONT CHASSIS CROSS MEMBER	191.80	1 PC	191.80 ?	
46 RADIATOR SPARE TANK	140.85	1 PC	140.85 ?	
47 CABIN REAR CROSS BAR	855.10	1 PS	855.10 ?	
48 CABIN REAR LH HANDLE OPENNER	449.70	1 PS	449.70 ?	
49 CABIN REAR RH DOOR PANEL OUTER	620.00	1 PC	<i>R1</i> 620.00 ✓	
50 DASHBOARD	658.12	1 PC	<i>Bu</i> 658.12 ✓	
51 DASHBOARD HOUSING	494.12	1 PC	494.12 ?	
52 GLOVER BOX	299.30	1 PC	<i>CM</i> 299.30 ✓	
53 DASH BOX TOP GARNISH	393.30	1 PC	393.30 ?	
54 FRONT WINDSCREEN PILLAR	580.85	1 PC	<i>R1</i> 580.85 ✓	
55 FRONT WHEEL ARP GARNISH	157.15	1 PC	<i>D17</i> 157.15 ✓	
			25,223.46	
		Less 25%	6,305.87	18,917.60

Special Net

56 FRONT NUMBER PLATE	15.00	1 PC	<i>R1</i> 15.00 ✓
57 REAR NUMBER PLATE	15.00	1 PC	<i>RC1</i> 15.00 ✓
58 STICKER - 70KM/H	10.00	1 PC	<i>me</i> 10.00 ✓
59 STICKER - 13 PAX	10.00	1 PC	<i>me</i> 10.00 ✓
60 TAILGATE INNER PROTECTOR	350.00	1 PC	<i>Bu</i> 350.00 ✓
61 REAR TRUCK FLOOR PROTECTOR	900.00	1 PC	<i>Bu</i> 900.00 ✓
62 REVERSE SENSOR	200.00	1 PC	<i>Photo</i> 200.00 ✓
63 FRONT LH COY STICKER	20.00	1 PC	<i>me</i> 20.00 ✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBC1396L

70/AXA

2018-15/4/19

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 15/04/2019

TP Veh Reg No: XD8097M

Estimate No: ES1991424/WS

Date: 17 Apr 2019

Policy No: D-18091716MFCV/3

Veh Reg No: GBC1396L

Make/Model: TOYOTA DYNA 150 D

Chassis No: JTFAT35Y70K200932

Engine No: 1KD1952401

Reg. Date: 30/09/2009

Estimate Repair Cost to Vehicle No :GBC1396L

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
			1,520.00	1,520.00
Labour				
64 TOWING	50.00	1 LA	50.00	✓
65 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓
66 REMOVE AND REFIX DASH BOARD, METER ASSY AND CHECK WIRING	250.00	1 LA	250.00	✓
67 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
68 REMOVE AND REFIX REAR WINDSCREEN GLASS	60.00	1 LA	60.00	✓
69 REMOVE AND REFIX CARPET, GARNISH, TOP ROOF LINING, SAFETY BELT, ETC	120.00	1 LA	120.00	✓
70 -PANEL BEATING ON FRONT PORTION	2,000.00	1 LA	2,000.00	1600
71 PUTTY AND RESPRAY BY FRONT PORTION	1,600.00	1 LA	1,600.00	1300
72 PANEL BEATING ON REAR PORTION	1,400.00	1 LA	1,400.00	1100
73 PUTTY AND RESPRAY ON REAR PORTION	900.00	1 LA	900.00	800
74 REMOVE AND REFIX CANOPY ASSY, TRUCK PROTECTOR AND REALIGN THE SAME	1,000.00	1 LA	1,000.00	?
75 TO REWRITE ADVERTISEMENT	500.00	1 LA (B:11)	500.00	?
76 RUSTPROOFING	100.00	1 LA	100.00	✓
			8,140.00	8,140.00

Total S\$ 28,577.60

Add GST @ 7% 2,000.43

Total Amount Payable S\$ 30,578.03

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 9/5/2019

Survey Details:

Date of loss	15-Apr-19
Date of appointment	17-Apr-19
Date of survey	17-Apr-19
Location of survey	Cheng Hoe Motor Pte Ltd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	GBC 1396L
Make and Model	TOYOTA DYNA 150 (M)
Date of registration	30-Sep-19
Parf Rebate	
Market Value	\$ 15,000.00
Parf Rebate	\$ 793.00
Nett Loss	\$ 14,207.00

Repair details:

Initial Estimate	\$ 28,577.60
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 13,941.57
Check items (estimate)	\$ 7,116.09
Labour	\$ 5,540.00
Total	\$ 26,597.66
Lump Sum(if applicable)	\$ 13,800.00

Number of days for repair	24DAYS
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Liability: Insured involved in 3 vehicle chain collision insured was the last vehicle. Will submit the revised Mandate IA once our surveyor verify the check item.

Mandate:

Liability(TP)	100%	
Proposed repair cost	TBA	
Loss of use	TBA	no. of days
Loss of rental	TBA	no. of days
Loss of income	TBA	no. of days
LTA search fees	TBA	
Others	TBA	
Proposed Total	TBA	

check items

LABOUR		S/N PARTS	PARTS
	\$1,000.00		\$29.20
	\$500.00		\$90.10
			\$321.80
			\$698.90
			\$1,596.70
			\$221.80
			\$301.15
			\$720.00
			\$983.60
			\$191.80
			\$140.85
			\$855.10
			\$449.70
			\$494.12
			\$393.30

\$0.00	\$1,500.00	\$0.00	\$7,488.12
			\$1,872.03
			\$5,616.09

Total: \$7,116.09

Lump Sum:

Lump Sum: **\$15,585.26**



ANNOUNCING Think One Automobile & Trading as sgCarMart Premium Dealer for the 8th Consecutive Year



Think One

Automobile & Trading Pte Ltd
Trading Buy/Sell Pte Ltd
Credit Pte Ltd
Leasing Pte Ltd
Autocare Pte Ltd

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mercedes-Benz GLC-Class GLC250 4MATIC.



Super Low Mileage, One Owner
Car, Great Condition, Warranty
Until Sept 2019,
Direct Owner StarAd

PRIME MOTOR & LEASING
(CHENG YONG CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES)
With over 200 units of vehicles
to choose from, ranging from
all European to Japanese Makes.

Browse by Category

« Back (1 2) Next »

Sort by Date Posted

20 results/page

28 vehicles

Toyota Dyna

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Toyota Dyna		Any	Any	2009	Any	Any	Any	Available
	Toyota Dyna	150 3.0M (New 5-yr COE)	\$31,800	\$6,350 /yr	05-Jun-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel Most Reliable Model In The Market, New Cushion And Print, Previous Owner Was Meticulous And Kept Vehicle In Good Condition. High Trade In Available. 100% Loan Available. Call Our Friendly Sale. Net Link Partners Pte Ltd Posted: 17-Apr-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M (New 5-yr COE)	\$32,800	\$6,550 /yr	27-Jul-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel Most Reliable Model In The Market, Sexy White Color, New Cushion, Previous Owner Was Meticulous And Kept Vehicle In Good Condition, High Trade In Available. 100% Loan Available. Call Our Friendly Sale... ABWIN (1994) Pte Ltd Posted: 16-Apr-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	100 3.0M (COE till 03/2024)	\$31,800	\$6,510 /yr	05-Mar-2009	2,982 cc	155,000 km	Truck	Available
Fuel Type: Diesel 100% Loan Available! Flexible Loan Scheme, Full Cash Welcome! Excellent Condition With Low Mileage For A 10 Years Workhorse! No Repairs Needed! Drive For The Next 5 Years Without Any Worries! Toyota D... Car (S) Pte Ltd Posted: 16-Apr-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	100 3.0M (New 5-yr COE)	\$29,800	\$5,950 /yr	28-Oct-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel Cheapest Toyota Lorry In The Market. 2 Owner Only. Engine In Tip-Top Condition, Comes With Checker Plate & Half Canopy. Best Selling Lorry In The Market. Price Inclusive Of 5-Year COE. Call For Us For... Posted: 16-Apr-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
GET YOUR COE RENEWAL LOAN Is your COE expiring? Let us help you renew it! Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Enquire today.									
	Toyota Dyna	150 3.0M	\$17,888	\$29,680 /yr	25-Nov-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel 1 Owner, Guaranteed Buy Back At \$10,000. Reliable Toyota Dyna 10ft Truck With Silent Powerful 1KD Euro 4 Turbo Engine. New 5 Years COE Just Renew. Clean And Pristine Interior. Call Us Now For Test Dr... Net Link Partners Pte Ltd Posted: 16-Apr-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota									
	Toyota Dyna	150 3.0M (New 5-yr COE)	\$30,800	\$6,150 /yr	04-Feb-2009	2,982 cc	-	Truck	Available
Fuel Type: Diesel Your Company Logo On This Reliable Working Horse. Full Canopy And Full Checked Plate, Expensive Wooden Plank Available For Ferrying Of s. Viewing And Test Drive Available. Call In For Appo... Compare									

Posted: 09-Apr-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M (New 5-yr COE)	\$33,800	\$6,750 /yr	16-Jul-2009	2,982 cc	-	Truck	Available
--	-----------------	--------------------	--------------------	-----------------	----------	--------------	------------------

Fuel Type: Diesel

Good Condition. New Paint. Servicing Done. No Repairs Needed. Loan Available. Price Negotiable. Call Now For View And Test Drive!

ABWIN (1994) Pte Ltd

Posted: 05-Apr-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M (COE till 03/2024)	\$33,800	\$6,850 /yr	23-Mar-2009	2,982 cc	-	Truck	Available
--	-----------------	--------------------	--------------------	-----------------	----------	--------------	------------------

Fuel Type: Diesel

ABWIN (1994) Pte Ltd

Posted: 05-Apr-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M (New 5-yr COE)	\$33,800	\$6,750 /yr	29-Sep-2009	2,982 cc	-	Truck	Available
--	-----------------	--------------------	--------------------	-----------------	----------	--------------	------------------

Fuel Type: Diesel

Including Of New 5 Years COE And Lifespan Expiry Until 28 Sep 2029! New Paint Work! New Leather Seat Cover! Interest Rate From 3.39%! Tip Top Engine Condition! Fast And Easy Approval For Your In-House...

ABWIN (1994) Pte Ltd

Posted: 04-Apr-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M (COE till 01/2024)	\$31,800	\$6,680 /yr	20-Jan-2009	2,982 cc	-	Truck	Available
--	-----------------	--------------------	--------------------	-----------------	----------	--------------	------------------

Fuel Type: Diesel

ABWIN (1994) Pte Ltd

Posted: 04-Apr-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota



Toyota Dyna 150 3.0M (COE till 03/2024)	\$33,800	\$6,840 /yr	26-Mar-2009	2,982 cc	-	Truck	Available
--	-----------------	--------------------	--------------------	-----------------	----------	--------------	------------------

Fuel Type: Diesel

Beautiful Blue And Powerful 1KD Euro 4 Turbo Engine. Reliable Toyota Dyna 10ft Truck With New 5 Years COE Just Renew. Clean And Pristine Interior. Call Us Now For Test Drive.

ABWIN (1994) Pte Ltd

Posted: 03-Apr-2019 Tags: 2009 Toyota Dyna, 2009 toyota dyna, Toyota Dyna, toyota dyna, Toyota, Dyna, dyna, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
------	-------	-------	--------------	----------	---------	---------	----------	--------

For old advertisements, view Expired ads

« Back (1 2) Next »

20 results/page

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to CDE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Toyota Dyna, Toyota Dyna Singapore, used Toyota Dyna Singapore, used Toyota Dyna, used vehicles Singapore or even buy used Toyota Dyna Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com
[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5981G
Vehicle Details	
Vehicle No.:	GBC1396L
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 MANUAL 3SEATER
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	1KD1952401
Chassis No.:	JTFAT35Y70K200932
Maximum Power Output:	-
Open Market Value:	\$24,970.00
Original Registration Date:	30 Sep 2009
First Registration Date:	30 Sep 2009
Transfer Count:	0
Actual ARF Paid:	\$1,249.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$17,410.00
COE Rebate Amount:	\$793.00
Total Rebate Amount:	\$793.00

The information contained herein is correct as at 15 Apr 2019

OK

FREE VALUATION
Let us tell you how much your car can sell for!
No obligations and it's FREE!

How much is my car worth?



toyota dyna

Price Range

Depreciation

2009

Vehicle Type

Submit

Advanced Search

Home » Used Cars » Net Link Partners Pte Ltd » Toyota Dyna 150 3.0M

Toyota Dyna 150 3.0M

Overview Financial Accessories Similar Research Photos Map

NETLINK

Your Commercial Specialist

Specialized in New & Used Commercial Vehicles, Insurance, Hire Purchase, Scrap/Export

Price	\$17,888	Lifespan	24-Nov-2029
Depreciation	\$29,280 /yr View models with similar depre	Reg Date	25-Nov-2009 (7mths 9days COE left)
Mileage	N.A.	Manufactured	2009
Road Tax	N.A.	Transmission	Manual
Dereg Value	N.A.	OMV	\$24,970
COE	N.A.	ARF	\$1,249
Engine Cap	2,982 cc	No. of Owners	1
Curb Weight	2,160 kg		
Type of Vehicle	Truck		

Features

View specs of the Toyota Dyna 150 (2014)

Description

1 Owner. Guaranteed Buy Back At \$10,000. Reliable Toyota Dyna 10ft Truck With Silent Powerful 1KD Euro 4 Turbo Engine. New 5 Years COE Just Renew. Clean And Pristine Interior. Call Us Now For Test Drive.

Category

Premium Ad Car

Status

Available

Resources



Car Valuation - Free

Find out the market value of your existing car for free. Get started



Vehicle Evaluation

Afraid of lemons? Request to have this car evaluated professionally. Find out more

Posted on: 08-Apr-2019 | Last Updated on: 15-Apr-2019

Upfront Payment

[» more Financial info](#)

Transfer Fee	\$25	
Down Payment	\$1,789 (change)	Maximum 90% Loan
1st Instalment	\$2,345	Based on 3.4% interest rate
Total Upfront Payment	\$4,159 (Without insurance)	Check with seller for exact figure


Products and Services

[» View All](#)

Compare [1]



Price Chart



Shortlist Compare Add note
Report Error More Actions

Seller Information

Company	Net Link Partners Pte Ltd = dealer's pricelist = 94 vehs sold 129 vehs available	
Address	71 Woodlands Industrial Park E9 #07-01, #08-08 Search cars nearby this location	
Location	Wave9	
Office No	67531661	
Contact Person	Ivan Huang	91870392
(s)	Pearlyn	87002017
	Johnson	92722208



Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email: efficienttowing.sg@gmail.com

Business Reg. No.: 53349344K

NO. 28668

CASH SALE / JOB ORDER

Date: 15/4/19

Messrs: Cash
车牌 GBC 1396L 车型 Toyota Ryna
Vehicle No. GBC 1396L Model No: Toyota Ryna
时间 (日/夜) Day 联络号码 93705992
Time (day/night): Day Contact No: 93705992
由 1003 Yoa Panyoh 2nd Park
Location: 1003 Yoa Panyoh 2nd Park
到 Autopoint #01-04
To: Autopoint #01-04
银额 50 其他
Cash \$ 50 Others:
经手人 Di Tow Truck R. Nao
Authorised By: Di Driver Name: R. Nao

- ☐ Jump Start/Changing of battery
- ☐ Tyre Replacement
- ☒ Accident/Breakdown
- ☐ Multi/Basement
- ☐ With Load/Cargo Box
- ☐ King Dolly
- ☐ Transport Charge
- ☐ Low Body Kit
- ☐ Door Opening Service
- ☐ Crane Up/Winch Out
- ☐ Collect Doc/Key
- ☐ Repo
- ☐ Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在进行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Wednesday, 17 April 2019 11:08 AM
To: assignments
Subject: FW: Repair Survey (Single Joint Expert) - GBC1396L (DOA: 15/04/2019) // S9M01KIR // 111142 // OH Vale // VIRTUAL CASE-VO
Attachments: XD8097M INSD GIA.PDF; P2103083_EN_00002_1.pdf; P2103083_CI_00002_1.pdf

Tp smart.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

11.42am @ 17/4/19

Dunlop.
vehicle in

17/4/19 11:03 AM

OH Vale

*** VIRTUAL CASE-

VO -

From: Cheng Hoe Motor Pte Ltd (AMK) <chmamk@singnet.com.sg>
Sent: Tuesday, 16 April, 2019 2:12 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>; chmotor@singnet.com.sg
Subject: Repair Survey (Single Joint Expert) - GBC1396L (DOA: 15/04/2019)

Dear Sir,

OUR CLIENT – GBC1396L

DOA : 15/04/2019

YOUR INSURED : XD8097M (TRISAAI ENGINEERING PTE LTD)

We refer to the above.

Under Protocol - SJE, pls provide list of surveyors for our selection.

Thank you.

Regards
Dorlyn Li

Cheng Hoe Motor Pte Ltd
Tel :64812001

Fax : 64821296



Auto
Consultants
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 9/5/2019

Survey Details:

Date of loss	15-Apr-19
Date of appointment	17-Apr-19
Date of survey	17-Apr-19
Location of survey	Cheng Hoe Motor Pte Ltd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	GBC 1396L
Make and Model	TOYOTA DYNA 150 (M)
Date of registration	30-Sep-19
Parf Rebate	
Market Value	\$ 15,000.00
Parf Rebate	\$ 793.00
Nett Loss	\$ 14,207.00

Repair details:

Initial Estimate	\$ 28,577.60
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 17,839.52
Check items (estimate)	NIL
Labour	\$ 6,620.00
Supplementary	\$ 1,701.09
Total	\$ 26,160.61
Lump Sum(if applicable)	\$ 13,800.00

Number of days for repair	24DAYS
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Liability: Insured involved in 3 vehicle chain collision insured was the last vehicle.

**Recommended 24 repair days + 2PH + 2Sunday = 28days*

Mandate:

Liability(TP)	100%	
Proposed repair cost (w/GST)	\$	14,766.00
Loss of use	\$	1,680.00 (28days x \$60.00)
Loss of rental		NIL no. of days
Loss of income		NIL no. of days
LTA search fees	\$	8.00
Others		NIL
Proposed Total	\$	16,454.00



<TP - Mandate IA> - S9M01KIR [ACCIDENT INVOLVING
XD 8097M(OI-Virtual)/ GBC 1396L (TP) / OTHERS ON
15/04/2019]

Type

🔍 Question

Message

Liability: 100%. Insured involved in 3 vehicle chain collision whereby insured was the last vehicle. We seek your mandate at \$16,454.00(all-in). TP-Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction. Hsiao Tong - 11-Oct-19

Reply



RE: Re:RE: Re:<TP - Mandate IA> - S9M01KIR [ACCIDENT INVOLVING XD 8097M(OI-Virtual)/ GBC 1396L (TP) / OTHERS ON 15/04/2019]

Type

🔔 Question

Message

Hi Vale, we have uploaded a copy of TP-Mandate IA dd 06012020 in SC for your easy reference. Kindly advise the mid-way amount for our necessary action. Thank you. Hsiao Tong - 06 Jan 2020

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 3/1/2020

Survey Details:

Date of loss	15-Apr-19
Date of appointment	17-Apr-19
Date of survey	17-Apr-19
Location of survey	Cheng Hoe Motor Pte Ltd

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	GBC 1396L
Make and Model	TOYOTA DYNA 150 (M)
Date of registration	30-Sep-19
Parf Rebate	
Market Value	\$ 15,000.00
Parf Rebate	\$ 793.00
Nett Loss	\$ 14,207.00

Repair details:

Initial Estimate	\$ 28,577.60
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 17,839.52
Check items (estimate)	NIL
Labour	\$ 6,620.00
Supplementary	\$ 1,701.09
Total	\$ 26,160.61
Lump Sum(if applicable)	\$ 13,800.00

Number of days for repair	24DAYS
---------------------------	--------



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

Liability: Insured involved in 3 vehicle chain collision insured was the last vehicle.

**Recommended 24 repair days + 2PH + 2Sunday = 28days*

Mandate:

Liability(TP)	100%	
	Our Last Offer	TP proposed
Proposed repair cost (w/GST)	\$ 12,840.00	\$ 14,766.00
Loss of use (28days x \$60.00)	\$ 1,680.00	\$ 1,680.00
Loss of rental	NIL	NIL
Loss of income	NIL	NIL
LTA search fees	\$ 8.00	\$ 8.00
Others	NIL	NIL
Proposed Total	\$ 14,528.00	\$ 16,454.00

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Friday, 11 October 2019 2:31 PM
To: Hsiao Tong (LKKAUTO)
Subject: FW: New message for service request 111142, vehicle number GBC1396L

11/10/19 12:59 PM *** MessageHI Pls reduce further on COR if possible. We are looking at LS \$11-12K-VO - OH
Vale

-----Original Message-----

From: vale.oh@axa.com.sg <vale.oh@axa.com.sg>
Sent: Friday, 11 October, 2019 1:00 PM
To: admin-d@lkkauto.com
Subject: New message for service request 111142, vehicle number GBC1396L

AXA Insurance has sent you a message for claim number S9M01KIR.
Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.
This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.



RE: Re:<TP - Mandate IA> - S9M01KIR [ACCIDENT INVOLVING XD 8097M(OI-Virtual)/ GBC 1396L (TP) / OTHERS ON 15/04/2019]

Type

🔗 Question

Message

Hi, For COR, third party rejected our offer at \$12K. Kindly let us have your further mandate (COR with GST + LOU). Thank you. Hsiao Tong. 05 Dec 2019

Reply

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Friday, 20 December 2019 4:45 PM
To: Hsiao Tong (LKKAUTO)
Subject: FW: New message for service request 111142, vehicle number GBC1396L

20/12/19 2:33 PM *** MessageHi Hsiao Tong Pls offer mid way-VO - OH Vale

-----Original Message-----

From: vale.oh@axa.com.sg <vale.oh@axa.com.sg>
Sent: Friday, 20 December, 2019 2:34 PM
To: admin-d@lkkauto.com
Subject: New message for service request 111142, vehicle number GBC1396L

AXA Insurance has sent you a message for claim number S9M01KIR.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Tuesday, 7 January 2020 2:59 PM
To: Hsiao Tong (LKKAUTO)
Subject: FW: New message for service request 111142, vehicle number GBC1396L

7/1/20 8:52 AM *** Message - Hi Hsiao Tong Pls counter offer COR at S\$12500/- to S\$12900/--VO - OH
Vale

-----Original Message-----

From: vale.oh@axa.com.sg <vale.oh@axa.com.sg>
Sent: Tuesday, 7 January, 2020 8:53 AM
To: admin-d@lkkauto.com
Subject: New message for service request 111142, vehicle number GBC1396L

AXA Insurance has sent you a message for claim number S9M01KIR.

Please click here <https://vp.smartclaims.axa.com.sg/claim-portal/> to view the message in Vendor Portal.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Hsiao Tong (LKKAUTO)

From: Cheng Hoe Motor Pte Ltd (June-Yishun) <chmotor@singnet.com.sg>
Sent: Tuesday, 11 February 2020 10:52 AM
To: CHIONH Hock San Christopher
Cc: Hsiao Tong (LKKAUTO)
Subject: DV- ACCEPTANCE - Your ref: GBC1396L Our ref: S9M01KIR (XD8097M)
Attachments: 1396.jpg

Hi Christopher,

Signed DV is attached.

Pls assist to process payment to be made payable to "CHENG HOE MOTOR PTE LTD"

Thank you.

Rgds
June
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: CHIONH Hock San Christopher
Sent: Monday, February 10, 2020 4:01 PM
To: Cheng Hoe Motor Pte Ltd (June-Yishun)
Cc: Hsiao Tong (LKKAUTO)
Subject: RE: [EXTERNAL] ACCEPTANCE - Your ref: GBC1396L Our ref: S9M01KIR (XD8097M)

Dear June,

Please see attached DV.



Warmest Regards,

Christopher Chionh | Senior Manager, Claims Services

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: <mailto:cheekeong.pan@axa.com.sg>

DID: (65) 6880 5594

HP: (65) 8189 3051

axa.com.sg



From: Cheng Hoe Motor Pte Ltd (June-Yishun) <chmotor@singnet.com.sg>
Sent: Monday, February 10, 2020 3:52 PM
To: CHIONH Hock San Christopher <chris.chionhhs@axa.com.sg>
Cc: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Subject: [EXTERNAL] ACCEPTANCE - Your ref: GBC1396L Our ref: S9M01KIR (XD8097M)

Dear Sir,

Your offer as below is accepted.

Pls forward DV.

Thank you.

Rgds
June
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: CHIONH Hock San Christopher
Sent: Monday, February 10, 2020 3:08 PM
To: chmotor@singnet.com.sg
Cc: Hsiao Tong (LKKAUTO)
Subject: Your ref: GBC1396L Our ref: S9M01KIR (XD8097M)

Without Prejudice

Dear June,

We are prepared to revised our offer as follows:

COR:	\$14,766
LOU:	\$1440 (\$60 x 24)
LTA:	\$8
Total	\$16,214

Please advise acceptance



Warmest Regards,

Christopher Chionh | Senior Manager, Claims Services

AXA Insurance Pte Ltd | 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 | www.axa.com.sg

Email: chris.chionhhs@axa.com.sg

DID: (65) 6880 5594

HP: (65) 8189 3051

axa.com.sg



-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Insurance Pte Ltd or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

This message is confidential; its contents do not constitute a commitment by AXA except where provided for in a written agreement between you and AXA. Any unauthorized disclosure, use or dissemination, either whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TAX INVOICE

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP-AXA

Claim Type: Third Party

Accident Date: 15/04/2019

TP Veh Reg No: XD8097M

NO: **CL8190924**
Date: 29 Aug 2019
Policy No: D-18091716MFCV/3
Veh Reg No: **GBC1396L**
Make/Model: TOYOTA DYNA 150 D
Job No: JC1600399

Description	Quantity	List Price	PAGE:1
			Amount
To Supply all replaced parts, all necessary and agreed labour & miscellaneous charges. (As recommended by your appointed surveyor)	1 PC	<u>S\$</u> 13,800.00	<u>S\$</u> 13,800.00


Total	S\$ 13,800.00
Add GST @ 7%	966.00
Total Amount payable	S\$ 14,766.00

For Cheng Hoe Motor Pte Ltd

E. & O. E.

AUTHORISED SIGNATURE





CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

Date: 01 OCT 2019

AXA Insurance (S) Pte Ltd
C/O LKK Auto Consultants

Attn : THE MOTOR CLAIMS DEPT

Dear Sir / Madam

**ACCIDENT INVOLVING VEHICLE NO. GBC1396L & XD8097M ON 15/04/2019
PIE 19KM MARK.**

We are authorized by GBC1396L for their above matter.

Record reveals that you are the insurer of XD8097M. We therefore wish to seek compensation from you as below:-

1. Cost of Repairs	S\$ 14766.00
2. Loss of Use (22+6 x \$60/Day)	S\$ 1680.00
3. Hire of Vehicle	S\$ 0.00
4. LTA Search Fee/GIA Reports	S\$ 8.00
TOTAL	S\$ 16454.00

Please let us have your reply soonest possible.

Thank you.

Yours faithfully

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19006838/Kpa3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: VALE OH		Date : 20-02-2020 Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XD 8097M	Veh. Inspected	GBC 1396L
Policy No.	VCA/P2103083	Coverage (\$)	0.00
Claim No.	S9M01KIR	Excess (\$)	0.00
Assign From	VALE OH	Assign Date	17/04/2019
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA DYNA (M)	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JTFAT35Y70K200932	Colour	BLUE
Odometer	513991	Steering	JAMMED
Brakes	JAMMED	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
L/H Front Tyre	195 R15X8	BRIDGESTONE	9 mm
R/H Rear Tyre	155 R12X8 (D)	FALKEN	3/3 mm
L/H Rear Tyre	155 R12X8 (D)	FALKEN	3/3 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/04/2019	Inspection Date	17/04/2019
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		24 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBC 1396L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE (CONSISTENT)	BENT	1,065.20	1,065.20
1	REAR TAILGATE LOWER STICKER "DYNA" (CONSISTENT)	NECESSARY	23.90	23.90
1	REAR TAILGATE SAFETY LOCK HANDLE (CONSISTENT)	BENT	165.80	165.80
1	LH SIDE GATE (CONSISTENT)	BENT	1,989.80	1,989.80
6	LH SIDE GATHERING PIN @ \$18.10 (CONSISTENT)	DISTORTED	108.60	108.60
1	REAR NUMBER PLATE PANEL (CONSISTENT)	BENT	172.85	172.85
1	REAR NUMBER PLATE LAMP (CONSISTENT)	SERVICEABLE	29.20	-
1	FRONT BUMPER (CONSISTENT)	BENT	398.57	398.57
1	FRONT GRILLE (CONSISTENT)	MISSING	424.15	424.15
1	FRONT GRILLE LOGO (CONSISTENT)	MISSING	70.35	70.35
3	FRONT GRILLE CLIPS @ \$4.50 (CONSISTENT)	NECESSARY	13.50	13.50
2	HEAD LAMP @ \$795.20 (CONSISTENT)	O/S MTG CRACKED / N/S BROKEN	1,590.40	1,590.40
2	HEAD LAMP LOWER RUBBER @ \$29.50 (CONSISTENT)	N/S MISSING	59.00	29.50
1	FRONT PANEL (CONSISTENT)	BENT	1,126.00	1,126.00
1	FRONT WIPER PANEL (CONSISTENT)	BENT	256.70	256.70
2	FRONT CENTRE SIDE GARNISH @ \$115.10 (CONSISTENT)	N/S MISSING / O/S SERVICEABLE	230.20	115.10
1	FRONT CENTRE GARNISH (CONSISTENT)	BUCKLED	285.10	285.10
1	FRONT WINDSCREEN GLASS (CONSISTENT)	CRACKED	1,390.90	1,390.90
1	FRONT RH WIPER NOZZLES (CONSISTENT)	CRACKED	39.90	39.90
1	SET FRONT WIPER BLADE (CONSISTENT)	CUT	74.48	74.48
1	FRONT LH SIDE MIRROR (CONSISTENT)	CRACKED	538.10	538.10
1	FRONT LH SIDE MIRROR STAY COVER (CONSISTENT)	MISSING	38.90	38.90
1	FRONT CORNAL PANEL (CONSISTENT)	BENT	265.58	265.58
1	AIR-CON CONDENSER (CONSISTENT)	BENT	490.10	490.10
1	AIR-CON GAS DISCHARGE HOSE (CONSISTENT)	SERVICEABLE	321.80	-
1	AIR-CON CONDENSER WITH FAN (CONSISTENT)	SERVICEABLE	698.90	-
1	RADIATOR (CONSISTENT)	PUNCTURE	1,596.70	1,596.70
1	RADIATOR FAN COWLING (CONSISTENT)	CRACKED	221.80	221.80

Report Ref No. CC4/ASM19006838/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LH DOOR (CONSISTENT)	BUCKLED	1,310.80	1,310.80
1	FRONT LH DOOR GLASS (CONSISTENT)	SHATTERED	525.10	525.10
1	FRONT LH DOOR GLASS OUTER MOULDING (CONSISTENT)	BUCKLED	110.70	110.70
1	FRONT LH DOOR GLASS REGULATOR (CONSISTENT)	BENT	295.65	295.65
1	FRONT LH DOOR GLAS CHANNEL (CONSISTENT)	DISTORTED	219.87	219.87
1	FRONT LH DOOR GLASS INNER LOCK (CONSISTENT)	JAMMED	262.90	262.90
1	FRONT LH DOOR GLASS INNER RUBBER (CONSISTENT)	DENTED	180.80	180.80
1	FRONT LH DOOR GLASS TRIM BOARD (CONSISTENT)	BUCKLED	560.56	560.56
2	FRONT LH DOOR GLASS HINGES @ \$85.10 (CONSISTENT)	BENT	170.20	170.20
1	FRONT DOOR REAR PILLAR OUTER (CONSISTENT)	BENT	620.00	620.00
1	FRONT DOOR REAR INNER (CONSISTENT)	TO REPAIR SEE LABOUR	301.15	-
1	FRONT LH DOOR REAR EMBLEM 'D4' D (CONSISTENT)	NECESSARY	46.90	46.90
1	CABIN FRONT CROSS BAR (CONSISTENT)	BENT	720.00	720.00
2	CABIN FRONT CROSS BAR MOUNTING @ \$491.80 (CONSISTENT)	CRACKED	983.60	983.60
1	FRONT CHASSIS CROSS MEMBER (CONSISTENT)	DISTORTED	191.80	191.80
1	RADIATOR SPARE TANK (CONSISTENT)	SERVICEABLE	140.85	-
1	CABIN REAR CROSS BAR (CONSISTENT)	SERVICEABLE	855.10	-
1	CABIN REAR LH HANDLE OPENER (CONSISTENT)	SERVICEABLE	449.70	-
1	CABIN REAR RH DOOR PANEL OUTER (CONSISTENT)	BENT	620.00	620.00
1	DASHBOARD (CONSISTENT)	BUCKLED	658.12	658.12
1	DASHBOARD REINFORCEMENT (CONSISTENT)	DISTORTED	494.12	494.12
1	GLOVER BOX (CONSISTENT)	CRACKED	299.30	299.30
1	DASH BOX TOP GARNISH (CONSISTENT)	SERVICEABLE	393.30	-
1	FRONT WINDSCREEN PILLAR (CONSISTENT)	BENT	580.85	580.85
1	FRONT WHEEL ARP GARNISH (CONSISTENT)	DISTORTED	157.15	157.15
	LESS 25% DISCOUNT		-6,208.74	-5,375.10
			18,626.26	16,125.30
1	FRONT WINDSCREEN GLASS RUBBER (@ \$288.61 DISC 50%) (SN) (CONSISTENT)	DENTED	288.61	144.30

Report Ref No. CC4/ASM19006838/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WINDSCREEN RUBBER (@ \$99.85 DISC 50%) (SN) (CONSISTENT)	NECESSARY	99.85	49.92
	LESS 25% DISCOUNT		-97.12	-
			291.34	194.22
	NETT ITEMS			
1	ENGINE INTERCOOLER (N) (CONSISTENT) (ADDITIONAL)		1,890.10	1,890.10
	LESS 10% DISCOUNT		-189.01	-189.01
			1,701.09	1,701.09
	SPECIAL NETT ITEMS			
1	FRONT NUMBER PLATE (SN) (CONSISTENT)	BENT	15.00	15.00
1	REAR NUMBER PLATE (SN) (CONSISTENT)	DENTED	15.00	15.00
1	STICKER - 70KM/H (SN) (CONSISTENT)	NECESSARY	10.00	10.00
1	STICKER - 13 PAX (SN) (CONSISTENT)	NECESSARY	10.00	10.00
1	TAILGATE INNER PROTECTOR (SN) (CONSISTENT)	BUCKLED	350.00	350.00
1	REAR TRUCK FLOOR PROTECTOR (SN) (CONSISTENT)	BUCKLED	900.00	900.00
1	REVERSE SENSOR (SN) (CONSISTENT)	SHORTED	200.00	200.00
1	FRONT LH COY STICKER (SN) (CONSISTENT)	NECESSARY	20.00	20.00
			1,520.00	1,520.00
	LABOUR			
	TOWING.		50.00	50.00
	REMOVE AND REFIX FRONT WINDSCREEN GLASS.		60.00	60.00
	REMOVE AND REFIX DASH BOARD, METER ASSY AND CHECK WIRING.		250.00	250.00
	REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL GAS.		100.00	100.00
	REMOVE AND REFIX REAR WINDSCREEN GLASS.		60.00	60.00
	REMOVE AND REFIX CARPET, GARNISH, TOP ROOF LINING, SAFETY BELT, ETC.		120.00	120.00
	PANEL BEATING ON FRONT PORTION. INCLUSIVE OF THE REPAIR OF FRONT DOOR REAR INNER.		2,000.00	1,600.00
	PUTTY AND RESPRAY BY FRONT PORTION.		1,600.00	1,300.00
	PANEL BEATING ON REAR PORTION.		1,400.00	1,100.00
	PUTTY AND RESPRAY ON REAR PORTION.		900.00	800.00

Report Ref No. CC4/ASM19006838/Kpa3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE AND REFIX CANOPY ASSY, TRUCK PROTECTOR AND REALIGN THE SAME.		1,000.00	800.00
	TO REWRITE ADVERTISEMENT.		500.00	280.00
	RUSTPROOFING.		100.00	100.00
			8,140.00	6,620.00
GRAND TOTAL			30,278.69	26,160.61
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				13,800.00

Report Ref No. CC4/ASM19006838/Kpa3s2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.