



TRANS EUROKARS PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN : MOTOR CLAIMS FAX :		NAME : MR NARASIMALU SRIKANTH ADDRESS : 19 TAMAN SIREH SINGAPORE 535206 TEL : 96496140		WIP : 39504 EXCESS : DATE: 16-Apr-19	
VEH NO :	SFN7170B	DATE IN :		CONTACT PERSON :	JOBI THOMAS 6331 0682
CHASSIS NO :	JM6DJ2HAA01300143	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA 2	DATE REG.:	23-Nov-18	POLICY NO. :	
NATURE OF WORKS					
S/NO	Parts Description				
		QTY		REVISED	PRICES
1	REAR BUMPER	1	MDC3R-50-221BBB	de	\$ 893.40
2	REAR BUMPER RETAINER LH	1	MD09H-50-2J1A	neu	\$ 27.20
3	REAR BUMPER RETAINER RH	1	MD09H-50-2H1A	X	\$ 27.20
4	REAR BUMPER STAY BRACKET	2	MD09W-50-271A	neu	\$ 22.80
5	REAR BUMPER BRACKET CENTER	1	MKD53-50-251	?	\$ 5.40
6	REAR BUMPER SHIELD LH	1	MD09H-50-350	neu	\$ 62.30
7	REAR BUMPER CAP	1	MD09W-50-705	neu	\$ 39.60
8	REAR BUMPER FASTENER	7	MB45A-56-146A	neu	\$ 21.00
9	REAR BUMPER GROMMET	4	MBHN1-50-021A	neu	\$ 10.80
10	TAILGATE	1	MD0Y0-62-02XB	bt	\$ 956.70
11	TAILGATE TRIM FASTENER	9	MGJ21-68-885B02	neu	\$ 27.00
12	TAILGATE WEATHERSTRIP	1	MD09H-62-761A	?	\$ 168.60
13	TAILGATE VALVE ONEWAY	2	MGHP9-58-867	neu	\$ 24.00
14	TAILGATE RUBBER STOP	2	ML206-62-877	?	\$ 22.80
15	TAILGATE TAPE PROTECTOR	2	MG043-62-864A	X	\$ 7.00
16	TAILGATE SPOILER GARNISH CLIP	4	MD09W-50-M38A	neu	\$ 20.80
17	TAILGATE SPOILER GARNISH TAPE	1	MD10V-50-898	neu	\$ 18.40
18	TAILGATE SPOILER GARNISH TAPE	1	MD10T-50-898	neu	\$ 13.30
19	TAILGATE SPOILER GARNISH TAPE	1	MD09T-50-898	neu	\$ 13.30
20	TAILGATE SPOILER GARNISH TAPE	1	MD09V-50-898	neu	\$ 18.40
21	TAILGATE MAZDA LOGO	1	MD09W-51-730	neu	\$ 61.20
22	TAILGATE MAZDA 2 EMBLEM	1	MD09W-51-771	neu	\$ 68.00
23	TAILGATE SKYACTIV EMBLEM	1	MDB2M-51-721	neu	\$ 58.30
24	LICENSE PLATE LAMP - photo	12	MD09H-51-270B	?	\$ 111.60
25	TAILGATE LAMP GASKET RH	1	MDA6A-51-3H8	neu	\$ 54.30
26	TAILGATE LAMP GASKET LH	1	MDA6A-51-3J8	neu	\$ 54.30
27	TAILLAMP LH	1	MD09L-51-160D	?	\$ 764.40
28	REAR END PANEL - photo	1	MDJYS-70-75Z	bt	\$ 477.10
29	REAR BUMPER AIR-COWL PANEL	1	MD09T-56-351A	?	\$ 70.40
30	AIR-COWL PANEL FASTENER	8	MB45A-56-146A	?	\$ 24.00
TOTAL PARTS					\$ 4,143.60
LESS 10%					\$ 414.36
TOTAL PARTS COST					\$ 3,729.24

	Labour Description		
1	TO REPLACE REAR BUMPER, REAR END PANEL AND TAILGATE. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 660	2310	\$ 2,640.00
2	TO RESPRAY REAR BUMPER, REAR END PANEL AND TAILGATE. 630	1890	\$ 2,100.00
3	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING AREAS.	250	\$ 350.00
4	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
5	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.	330	\$ 400.00
6	TO TRANSFER THE TAILGATE MECHANISM.	330	\$ 400.00
7	TO REMOVE & REFIT THE REAR WINDSCREEN GLASS.	NETT ✓	\$ 560.00
8	TO SUPPLY SEALER ON THE REAR WINDSCREEN GLASS.	NETT ✓	\$ 120.00
9	TO TRANSFER REVERSE SENSORS.	330	\$ 400.00
10	TO SUPPLY 1 PC NUMBER PLATE WITH CASING.	NETT <i>ent</i> ✓	\$ 70.00
11	TO TRANSFER REVERSE CAMERA.	NETT 330	\$ 400.00
12	TO SUPPLY BRILA PREMIUM COATING. => *sales agreement	NETT ✓	\$ 500.00
13	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
14	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	180	\$ 350.00
15	SUNDRIES.	NETT 50	\$ 100.00

Tayfik 97495749
 'wp'
 18/4/19 0935
 8 days
 Resurvey before paint
 surellkauto.com

TOTAL LABOUR	\$ -	\$ 8,890.00
TOTAL PARTS	\$ -	\$ 3,729.24
TOTAL	\$ -	\$ 12,619.24
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: