

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18  
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

**TP INSURER:** FWD Singapore Pte. Ltd. (HQ)  
N/A

Singapore

**Claimant Insurer:** Auto & General Insurance (Singapore) Pte. Limited.

**PARTICULARS OF CLAIM**

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	13/04/2019
Vehicle Reg. No.:	SJE6683U	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHOW OEI KHENG		
Make/Model:	NISSAN LATIO, 1.5 (A)	Vehicle Reg. Date:	02/05/2008
Vehicle Colour:	GOLD		
Engine No:	HR15259903A	Chassis No:	JN1BAAC11Z0009685
Odometer:	5 KM		
Paint Type:			
List Item Discount:	30.00 %	Nett Item Discount:	10.00 %
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	6		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

<b>COST OF CLAIMS</b>	<b>Amount</b>
Parts	5,018.97
Miscellaneous Items	0.00
Labour	2,030.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>7,048.97</b>
<b>+ GST 7.00% (S\$)</b>	<b>493.43</b>
<b>Nett Amount (S\$)</b>	<b>7,542.40</b>

This claim is handled by: SAMANTHA TAN YONG SING

# REPAIR DETAILS

## Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 17 Apr 2019)  
**Parts:** 144      NISSAN LATIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** (Unsubmitted, no print-code for SJE6683U)  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR NUMBER PLATE X	30.00	0.00	*35.00 FL
2	1		*REAR BUMPER DE	10.00	0.00	✓ *532.40 FN
3	2		*REAR BUMPER SIDE RETAINER N	10.00	0.00	✓ *73.20 FN
4	10		*REAR BUMPER CLIP N	10.00	0.00	✓ *44.00 FN
5	1		*REAR BUMPER REVERSE SENSOR NW	0	0.00	200 / <del>*280.00</del> FS
6	2		*REAR BUMPER DAMPER X	10.00	0.00	*99.60 FN
7	2		*REAR BUMPER SPONGE DE	10.00	0.00	*74.00 FN
8	2		*REAR FENDER repair	10.00	0.00	*2,009.40 FN
9	2		*REAR FENDER INNER SHIELD X	10.00	0.00	*38.80 FN
10	16		*REAR FENDER INNER SHIELD CLIP X	10.00	0.00	*70.40 FN
11	2		*REAR TAILLAMP CR	10.00	0.00	*558.00 FN
12	1		*REAR BOOT BT	10.00	0.00	*787.50 FN
13	2		*REAR BOOT HINGE X	10.00	0.00	*116.80 FN
14	1		*REAR BOOT LATIO STICKER N	10.00	0.00	*80.90 FN
15	1		*REAR BOOT EMBLEM N	10.00	0.00	*59.70 FN
16	1		*REAR BOOT LOCK BT	10.00	0.00	*123.20 FN
17	1		*REAR END PANEL BT	10.00	0.00	*434.40 FN
18	1		*REAR END PANEL TOP GARNISH CR	10.00	0.00	*92.00 FN
19	10		*REAR END PANEL TOP GARNISH CLIP N	10.00	0.00	✓ *44.00 FN

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (S\$)	5,553.30
- List Item Discount on L Items (S\$)	10.50
- Nett Item Discount on N Items (S\$)	523.83
Total Parts (S\$)	5,018.97

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

# Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO CKEC WIRING	New	30.00
2	TO REMOVE & REFIX TRIM	New	60 <del>100.00</del>
3	TO KNOCK,WELD,REMOVE & FIX ON ABOVE PARTS	New	800 <del>900.00</del>
4	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	900 <del>1,000.00</del>
<b>Gross Labour Cost (S\$)</b>			<b>2,030.00</b>

Report was unsubmitted during this print-out.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Resue*  
*Hp 90010068*  
*7 days*  
*43*  
*17/04/19 @ 1145*  
*Resurvey after repair*

LKK Auto Consultants hence notify the Repairer of the following:  
 • To resurvey before/after spray painting  
 • To display damaged part(s) during resurvey  
 • Parts prices are subject to confirmation  
 • Third party survey is on a "Without Prejudice" basis  
 • No illegal modification(s) is allowed  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company  
 Acknowledged by Repairer  
 Signature:  
 Date: