



南方摩哆
SOUTHERN MOTOR

Block 10
Singapore

6614

Repair & Dealing in New & Second-hand Motor-cycles, Scooters & Insurance Agent

Date: 15th April 2019
Motor Claims Department
MSIG Insurance (Singapore) Pte Ltd
4 Renton Way #21-01
S.G. Centre 2
Singapore 06880

Dear Sirs

Re: Cost of repair to Yamaha C2500A/Ken300 - P371544A

1 pc of	Body cover CRA ✓	JK	480.00	
"	Body cover bracket ? X SVC		225.00	
"	Mirror SCA ✓		85.00	1954
"	Front spoke light SCA ✓		190.00	
"	Brake lever SCA ✓		65.00	10%
"	Handle bar ? X SVC		185.00	
"	Side box SCA ✓		195.00	1758.60
"	Body sliders SCA ✓		100.00	
"	Kappa box + 8 SCA ✓		80.00	
			2364.00	
			236.40	
			2127.60	

Less 10%

Nett

Transport	40.00 ✓	} 300
Alignment fork	100.00	
Alignment fork bracket	90.00 } 60	
Labour	200.00	200
Resue	25/4/19	JK 2637.60
HP 90010068		1758.60
3 days		300.00
4/3		2058.60
18/04/19 @ 1630		20%
		1646.88
		45-1,650
		<u>3 days</u>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,
SOUTHERN MOTOR

Resue after repair

Tel 62277888

Fax 62257402