

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Adress : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacufic Insurance Pte Ltd
Motor Claims Dept

Date : 22 Apr 19

Dear Sirs :

Fax : 64193727

RE : ESTIMATE COST FOR TOYOTA CAMRY 2.4 MR053 - WSB7228 ACCIDENT INVOLVING WSB7228 & GBC6081L ON 11/04/2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear door n/s.	1pc	\$ 2,417.18
2	Rear door hinge n/s @\$89.2ea.	1pc	\$ 378.98
3	Rear door lock n/s.	1pc	\$ 2,169.64
4	Rear door outer handle n/s.	1pc	\$ 238.01
5	Rear door inner trim n/s.	1pc	\$ 1,534.70
6	Rear mudguard n/s.	1pc	\$ 759.60
7	Rear fuel tank cover n/s.	1pc	\$ 162.30
8	Rear door outer moulding n/s.	1pc	\$ 145.70
			\$ 7,806.11
	Less 25%		\$ (1,951.52)
			\$ 5,854.59
9	Rear windscreen sealant.	2pcs	\$ 40.00
	Sum Carried Forward		\$ 5,894.59

Sum Carried Forward		\$ 5,894.59
----------------------------	--	--------------------

Labour Charge & Misc

To remove, repair, replace & install damaged parts.	} }	\$ 1,200.00
--	--------	-------------

To R & R wiring.		\$ 100.00
------------------	--	-----------

To remove & install mechansim & check for function.	} }	\$ 100.00
--	--------	-----------

To R & R rear windscreen glass.		\$ 150.00
---------------------------------	--	-----------

To putty & spray painting.		\$ 750.00
----------------------------	--	-----------

Total		\$ 8,194.59
--------------	--	--------------------

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.