

Jia Le

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
(Email Adress : woonmeng @singnet.com.sg)
Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Date : 22 Apr 19

Dear Sirs :

Fax : 64193727

RE : ESTIMATE COST FOR TOYOTA CAMRY 2.4 MR053 - WSB7228 ACCIDENT INVOLVING WSB7228 & GBC6081L ON 11/04/2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear door n/s. <i>buc ✓</i>	1pc	\$ 1,055.70
2	Rear door hinge n/s @\$89.2ea. <i>X suc</i>	1pc	\$ 178.40
3	Rear door lock n/s. <i>bt ✓</i>	1pc	\$ 357.89
4	Rear door outer handle n/s. <i>repair</i>	1pc	\$ 123.50
5	Rear door inner trim n/s. <i>X suc</i>	1pc	\$ 1,534.70
6	Rear mudguard n/s. <i>buc ✓</i>	1pc	\$ 759.60
7	Rear fuel tank cover n/s. <i>bt ✓</i>	1pc	\$ 162.30
8	Rear door outer moulding n/s. <i>rec ✓</i>	1pc	\$ 145.70
			\$ 4,317.79
	Less 25%		\$ (1,079.44)
			\$ 3,238.35
9	Rear windscreen sealant. <i>rec ✓</i>	2pcs	\$ 40.00
Sum Carried Forward			\$ 3,278.35

2481.19
252
1860.89
40

Sum Carried Forward**\$ 3,278.35****Labour Charge & Misc**To remove, repair, replace & install
damaged parts.} }
}\$ ~~1,200.00~~ 800

To R & R wiring.

\$ ~~100.00~~ 80To remove & install mechanism & check
for function.} }
}\$ ~~100.00~~ 80

To R & R rear windscreen glass.

\$ ~~150.00~~ 120

1450

To putty & spray painting.

\$ ~~750.00~~ 450**Total****\$ 5,578.35**

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1860.89

40.00

1450.00

3350.89

20%

2,680.71

43-2,650

Paul
Hp 900100 68

6 days

H/S

22/04/19 @ 1630

Revy after repair

6 days