

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Express Sec II :SS

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A.:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call CE:

After call ltr to CE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to CE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 19/9/19

Confirm with Admin

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No. 21111

If NO or B 28, Ass: Lia:

Repair Cost: (w/ GST)

S\$ 2835.50

Loss of Rental (LOR):

S\$ -

(

days)

Loss of Use (LOU):

S\$ 700.00

(\$ 100 x 7 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒

S\$ -

LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

Total:

S\$ 3535.50

Global Sum S\$: 3500.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 3500.00

Name 1:

Woon Meng Motor Pte Ltd

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

COPY SENT 19/9/19

1) Claim status: Normal/Reject/Private Settle

2) Report Format: GP

3) Survey fee: \$320

19/9/19

Jia Le

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578
 Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050
 42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523
 (Email Address : woonmeng @singnet.com.sg)
 Co Reg No. 200603678M GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
 Motor Claims Dept

Date : 22 Apr 19

Dear Sirs :

Fax : 64193727

RE : ESTIMATE COST FOR TOYOTA CAMRY 2.4 MR053 - WSB7228
ACCIDENT INVOLVING WSB7228 & GBC6081L ON 11/04/2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear door n/s. <i>buc /</i>	1pc	\$ 1,055.70
2	Rear door hinge n/s @\$89.2ea. <i>X suc</i>	1pc	\$ 178.40
3	Rear door lock n/s. <i>bt /</i>	1pc	\$ 357.89
4	Rear door outer handle n/s. <i>repair</i>	1pc	\$ 123.50
5	Rear door inner trim n/s. <i>X suc</i>	1pc	\$ 1,534.70
6	Rear mudguard n/s. <i>buc /</i>	1pc	\$ 759.60
7	Rear fuel tank cover n/s. <i>bt /</i>	1pc	\$ 162.30
8	Rear door outer moulding n/s. <i>rec /</i>	1pc	\$ 145.70
			\$ 4,317.79
	Less 25%		\$ (1,079.44)
			\$ 3,238.35
9	Rear windscreen sealant. <i>rec /</i>	2pcs	\$ 40.00
Sum Carried Forward			\$ 3,278.35

2481.19

252

1860.89

40

Sum Carried Forward

\$ 3,278.35

Labour Charge & Misc

To remove, repair, replace & install
damaged parts.

}
}

\$ ~~1,200.00~~ 800

To R & R wiring.

\$ ~~100.00~~ } 80

To remove & install mechanism & check
for function.

}
}

\$ ~~100.00~~ }

To R & R rear windscreen glass.

\$ ~~150.00~~ 120

1450

To putty & spray painting.

\$ ~~750.00~~ 450

Total

\$ 5,578.35

All prices quoted are subjected to 7% GST

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1860.89

40.00

1450.00

3350.89

20%

2,680.71

43,216.50

Repair

Hp 900100 68

6 days

H/S

22/04/19 @ 1630

Rem after repair

6 days

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : AIG Asia Pacific Insurance Pte Ltd
Motor Claims Dept

Date : 22 Apr 19

Dear Sirs :

Fax : 64193727

RE : ESTIMATE COST FOR TOYOTA CAMRY 2.4 MR053 - WSB7228
ACCIDENT INVOLVING WSB7228 & GBC6081L ON 11/04/2019

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear door n/s.	1pc	\$ 2,417.18
2	Rear door hinge n/s @\$89.2ea.	1pc	\$ 378.98
3	Rear door lock n/s.	1pc	\$ 2,169.64
4	Rear door outer handle n/s.	1pc	\$ 238.01
5	Rear door inner trim n/s.	1pc	\$ 1,534.70
6	Rear mudguard n/s.	1pc	\$ 759.60
7	Rear fuel tank cover n/s.	1pc	\$ 162.30
8	Rear door outer moulding n/s.	1pc	\$ 145.70
			<hr/>
			\$ 7,806.11
			<hr/>
	Less 25%		\$ (1,951.52)
			<hr/>
			\$ 5,854.59
9	Rear windscreen sealant.	2pcs	\$ 40.00
			<hr/>
	Sum Carried Forward		\$ 5,894.59

Sum Carried Forward		\$ 5,894.59
----------------------------	--	--------------------

Labour Charge & Misc

To remove, repair, replace & install damaged parts.	} }	\$ 1,200.00
--	--------	-------------

To R & R wiring.		\$ 100.00
------------------	--	-----------

To remove & install mechansim & check for function.	} }	\$ 100.00
--	--------	-----------

To R & R rear windscreen glass.		\$ 150.00
---------------------------------	--	-----------

To putty & spray painting.		\$ 750.00
----------------------------	--	-----------

Total		<u>\$ 8,194.59</u>
--------------	--	---------------------------

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.



Woon Meng Motor Pte Ltd

Address: 50 Bukit Batok Street 23 #01-06 Midview Building, Singapore 659578
Tel: +6563161131 / +6563161151 FAX: +6563167050
Workshop: 42, Sungai Kadut Ave Singapore 729666 Tel: +6563628523
Email: woonmeng@singnet.com.sg
Co Reg No 200603678M GST Reg No. 20-0603678M

AIG Asia Pacific Insurance Pte Ltd
Chartis Building
78 Shenton Way
07- 16
Singapore 079120

20 Jun 2019

Attn: Motor Claim Dept.

Dear Sirs

DIRECT SETTLEMENT FOR REPAIR OF TOYOTA CAMRY MR053 2.4 - WSB7228

RE : ACCIDENT INVOLVING WSB7228 & GBC6081L
ALONG WEST COAST ROAD ON 11/04/2019

We have been given the full authority to act on behalf of Siew Chooi Mee, registered owner of motor vehicle no : WSB7228, which was involved and damaged in the above accident.

We were told that the said accident was caused solely due to the negligence of your insured driver. Therefore, we are compelled to claim against you for the losses incurred as follows:-

1)	Cost of repairs.	\$ 2,835.50
2)	Loss of use for 7days @120.00perday.	\$ 840.00
TOTAL AMOUNT:-		<u>\$ 3,675.50</u>

We have told our client that this matter is strictly on a DIRECT SETTLEMENT basis. If you do not dispute liability, please arrange to let us have your payment for the sum of S/D: THREE THOUSAND SIX HUNDRED SEVENTY FIVE AND CENTS FIFTY ONLY in full and final settlement for our client's claim.

We enclose herewith the GIA report, Surveyor's report and the invoices for your attention.

We look forward to your early favourable reply.

Yours faithfully

Chong Han Woon



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC6/AIG19006872/R1da3

28 AUGUST 2019

FEDERAL EXPRESS (SINGAPORE) PTE LTD
90 ALPS AVE
SINGAPORE 498746
Attn: The Management

Dear Sir/Madam,

ACCIDENT INVOLVING GBC 6081L & WSB 7228 ALONG/AT 517 WEST COAST ROAD ON 11/04/2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AIG Asia Pacific Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from WSB 7228 against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour as your vehicle reversing out of parking lot and collided onto Third Party vehicle. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

CHAN JIA LE
Case Handler
DID: 6749 5792
FAX: 6741 4108
Email: jiaLe@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Grew Chai Mee ("the third party claimant")
of No. 42 Jalan Baktari 28/2 Taman Baktari Indah 81800 Ulu Tiram, Johor. (address),
owner of WGB 7228 (vehicle no.) hereby authorize
Woon Meng Motor Pte Ltd
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. WGB 7228 that was
damaged pursuant to the accident which occurred on 11/4/19 (date) along
West Coast Road (location)
involving vehicle no/s GBC 6021 L ("the accident").


I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 20 day of Jun (month) 20 19 (year)

MEE

Signed by "the third party claimant"




Signed by "the workshop"

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, WOON MENG MOTOR PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$3,500.00 (Global Sum) for vehicle no. WSB 7228 that was damaged pursuant to the accident which occurred on 11/04/2019 (date) along WEST COAST ROAD involving vehicle no/s GBC 6081L.

This is pursuant to the inspection conducted on 22/04/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SIEW CHOOI MEE ("the third party claimant") of vehicle no. WSB 7228 make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to WSB 7228 (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 19th (day) of SEPTEMBER (month) 2019 (year)



Signed by appointed surveyor



Signed by "the workshop" (with chop)



Woon Meng Motor Pte Ltd

Address: 50 Bukit Batok Street 23 #01-06 Midview Building, Singapore 659578
Tel: +6563161131 / +6563161151 FAX: +6563167050
Workshop 42, Sungei Kadut Ave Singapore 729668 Tel: +6563628523
Email: woonmeng@singnet.com.sg
Co Reg No.200603678M GST Reg No. 20-0603678M

TAX INVOICE NO: WM2019/C04306/jun/TP

Date : 20 Jun 2019

AIG Asia Pacific Insurance Pte Ltd
Chartis Building
78 Shenton Way
07- 16
Singapore 079120

Attn Motor Claims Department

Dear Sirs

RE : REPAIR COST FOR TOYOTA CAMRY 2.4 MR053 - WSB7228
ACCIDENT INVOLVING WSB7228 & GBC6081L ON 11.04.2019

<u>ITEM</u>	<u>DESCRIPTION</u>	<u>PRICE</u>
1	Lump sum repair cost	\$ 2,650.00
		<hr/>
		\$ 2,650.00
	ADD GST 7%	\$ 185.50
	TOTAL AMOUNT S\$	<hr/> \$ 2,835.50

S/D : Two Thousand Eight Hundred Thirty Five And Cents Fifty Only.

This is a computer-generated document. No signature is required.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Apr 2019 Edit Reg		22 Apr 2019 00:00 Edit Adj Rpt	S\$2,650.00 Edit Estimates	S\$2,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by adjuster]					
Insured:	FEDERAL EXPRESS (SINGAPORE) PTE LTD, Co. Reg. No.: 198402740W							
Main Claimant:	SIEW CHOOI MEE, ID: 680404085568							
Vehicle Reg. No.:	WSB7228	Date of Loss:	11/04/2019 11:00 - :59 [124 Months and 15 Days From LTA Reg Date (Man Yr)]					
Claim Type:	TP / 2748869510SG	Policy/Cover Note No.:	(Third Party Only)					
Vehicle Reg. No. (Insured):	GBC6081L	Policy No. (Claimant):						
		Excess:						
Repairer:	Woon Meng Motor Pte Ltd (Bukit Batok) 50 Bukit Batok Street 23,, #01-06 Midview Building, 659578 Bukit Batok - Tel: 6316 1131							
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 29/04/2019]							
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail				
<ul style="list-style-type: none"> AIG_SG (18/04/2019): Request to upload TP GIA REPORT 								
ALL ASSOCIATED TASKS			View All	Search Tasks	Create New Task			
Due Date	Priority	Type	Task Group	Subject	Handler			
				Assigned By	Completed On			
					Created On			
					Done?			
No results.								

Claim Documents

*WSB7228 (27488695105G)
[GBC6081L]

TP

SIEW CHOOI MEE

Apr 11 2019 11:00AM




[FEDERAL EXPRESS (SINGAPORE) PTE LTD]
Woon Meng Motor Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	19/09/19 15:54	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
2	19/09/19 15:54	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
3	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
4	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
5	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
6	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
7	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
8	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
9	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
10	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
11	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
12	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
13	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
14	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
15	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
16	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
17	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
18	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
19	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
20	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
21	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
22	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
23	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
24	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
25	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
26	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
27	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
28	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
29	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
30	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
31	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>
32	19/09/19 15:54	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	17/04/19 19:52	TP POLICE REPORT		Load PDF	
2	18/04/19 11:11	TP LOG CARD + CI		Load PDF	
3	26/04/19 10:05	TP ESTIMATE		Load PDF	
4	08/10/19 09:45	WORKSHOP INVOICE		Load PDF	
5	08/10/19 09:45	AUTHORISATION TO ACT FORM		Load PDF	
6	08/10/19 09:45	Release Voucher		Load PDF	

Letters/Correspondences				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
7	08/10/19 09:45	LKK Auto Consultants Pte Ltd (HQ)			Load PDF
8	08/10/19 09:45	LETTER TO OI			Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	18/04/19 09:04	OI GIA REPORT			Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	GBC6081L (Insd veh)	Model:	TOYOTA CAMRY 2.4 (A)
	WSB7228 (TP veh)		
Date of Accident:	11/04/2019		

Global Sum Settlement	:	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> No
Repair Estimate	:	\$	5,968.82
Final Repair Cost	:	\$	3,500.00
Loss of Use	:	\$	7.00 days at \$100.00 per day
Rental (if any)	:	\$	days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	3,500.00
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability ____ 100 ____ (%)			
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: ____			
BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)			
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Woon Meng Motor Pte Ltd	:	\$ 3,500.00
2)		:	\$

JOANNE LEE KHANG MIN

08 Oct
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19006872/R1DA3Q2

Date: 08/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : WSB7228

Insured Vehicle No : GBC6081L

Date of Loss: 11/04/2019

Nature of Claim: TP

Claim No: 2748869510SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **WSB7228**

Make & Model: TOYOTA CAMRY, 2.4 (A)

Engine No: 2AZE113973

Reg. Date: 27/11/2008 (Man. Year: 2008)

Chassis No: MR053BK4007030422

Colour: Grey

Odometer: 133395 km

Engine Capacity: 2362 cc

Market Value/New Car

N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17

Rear Tyre Size:

215/55 R17

Front Left Side: Toyo 6 mm

Rear Left Side:

Toyo 6 mm

Front Right Side: Toyo 6 mm

Rear Right Side:

Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,278.34	1,900.89	1,377.45	42.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,450.00	850.00	36.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,578.34	3,350.89	2,227.45	39.93
Approved Total (Overridden) (S\$)		2,650.00		
(S\$)	5,578.34	2,650.00	2,928.34	52.49
+ GST 7.00/7.00% (S\$)	390.48	185.50	204.98	52.49
Nett Amount (S\$)	5,968.82	2,835.50	3,133.32	52.49
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
Nett Liability (S\$)		3,535.50		
Global Sum Settlement (S\$)		3,500.00		

INSPECTION

Date of Assignment: 22/04/2019

Date Inspected: 22/04/2019 Inspected At:

Woon Meng Motor Pte Ltd (Bukit Batok)
50 Bukit Batok Street 23., #01-06
Midview Building
Singapore 659578

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR N/S	Buckled	1,055.70 FL	*1,055.70 FL
2	1		*REAR DOOR HINGE N/S	Serviceable	178.40 FL	*- FL
3	1		*REAR DOOR LOCK N/S	Bent	357.89 FL	*357.89 FL
4	1		*REAR DOOR OUTER HANDLE N/S	Repair	123.50 FL	*- FL
5	1		*REAR DOOR INNER TRIM N/S	Serviceable	1,534.70 FL	*- FL
6	1		*REAR MUDGUARD N/S	Buckled	759.60 FL	*759.60 FL
7	1		*REAR FUEL TANK COVER N/S	Bent	162.30 FL	*162.30 FL
8	1		*REAR DOOR OUTER MOULDING N/S	Necessary	145.70 FL	*145.70 FL
9	2		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,357.79	2,521.19
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,079.45	620.30
Total Parts (\$\$)	3,278.34	1,900.89

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REPAIR ,REPLACE & INSTALL DAMAGED PARTS	New	1,200.00	800.00
2	TO R&R WIRING }	New	100.00	80.00
3	TO REMOVE & INSTALL MECHANISM & CHECK FOR FUNCTION }	New	100.00	0.00
4	TO R&R REAR WINDSCREEN GLASS	New	150.00	120.00
5	TO PUTTY & SPRAY PAINTING	New	750.00	450.00
Gross Labour Cost (S\$)			2,300.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >