

27/03/2012

ASS. REC. BY:

REF: CS/SPF 190069001 Jv d3d Special Instruction:

Surveyor: ASSIGNMENT (Office)From (Person): Abdul Rahman of SPF Date/Time: 18.4.19 8.35a.m

Estimated Cost: _____ Bill to: _____

OD ~~TP~~ WS+TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SL 5229U Insured: QX FOHat Workshop m/s Kah motor Tel: 82886302of 6 A mandai estatePolicy No: _____ Claim No: AGMD / 105 / 009 / 2019 / 040

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 3.4.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS "wp" H.O.D. Endorsement: _____

Date/Time: 18.4.19 10.46a.m Person Contacted: Anikka Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SL 5229U - x
	QX FOH - x
17/19	@ 343pm Anikka said vehicle has not send in for repair
17/19	@ 557pm check with Hwee Jie range \$3k - \$4k
18/19	Submit \$ 1619.16, 3 days

Upper range \$ 1600 - \$ 2000

1/8/19 To re-open and submit final report. - PLS pass to typist

5/8/19 1st Dec 19/1/19, reopen ref only ↓

Alvin 5/8/19

Hwee Jie

REF: SPF

ASSIGNMENT

From:

Date:

21/5/2019

Veh No:

SLL S229U

In Resp: 22 Feb 2017

Estimated Cost:

Type: ☒ M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime MoverOD: ☒ TP / RES / OD RES / EVA / INV / MV

Truck / Trailer or

To report/Vehicle No:

SLL 52294

Make:

Honda Civic

G: 1597

at Workshop m/s:

Kah Motor

Colour:

white

A/C: Insured / Std / NI / NA

of:

GA Mendai Estate

Sp/Reading:

35381

T/Cable: Insured / Std / NI / NA

Insured:

Log/No:

Policy No:

C/No:

MRHFC5650GT00116

Claim No:

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Sign Insured:

Excess:

Steering: ☒ In order / Jammed / Leaked / Burnt or

(Client's Record)

Brake: ☒ In order / Jammed / Leaked / Burnt or

Make of Veh:

10-30cm (waiting)

Mod: Nil / S/R / STD AIR / or

(Policy Condition)

Tyre Size:

F: 205/55 R16

R:

Remark: The veh had commenced its repair at the time of inspection

☒ BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Report

Consistent? Yes or No

R/Dial:

6

mm

R/Dial:

6

mm

GIA / PR Seen:

Consistent? Yes or No

L/Dial:

6

mm

L/Dial:

6

mm

Est. Repairs:

days Res: Yes or No

D.O.A:

3/4/19

D.O.A:

21/5/19

Lump Sum:

% 3 Val: Yes or No

Survey held at

Kah motor

CA / REV / REP. / 24 HRS ^{rep}Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

mv-#75000

RECEIVED 3 JUL 2019

Do Not Finalise

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 3/7 - typist

Report Format:

TP

Lump Sum / L.B.I. (\$) :

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Insp (\$)



Weekend (\$)

Survey Fee:

Transportation:

) 5 x 45.00

) Photo:

) Other:

TOTAL

220

220

Fax: 64784848

Attn: Mr Frankie

Fr: Anikka (Kah Motor)

QUOTATION



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Mobile: 82886302

GST Reg No.: M200050223

Fr: 63625015

Company Ref. No.: S60FC1380G

21/5 - 10:30am Survey

Customer : SINGAPORE POLICE
TANGLIN POST OFFICE
PO BOX 60
SINGAPORE 912402

Registration No : SLL5229U

Chassis No : MRHFC5650GT001116

Model : CIVIC 1.6 VTI YM2016

Owner's Name : TOH GUO WEI

Ins Policy No. :

Date of Accident : 3/4/2019

Document No. : SQT19001524 Page 1

Date : 4. Apr 2019

Customer No. : SP0000001

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : R16B21601420

Date | Time : 4. Apr 2019 4:46:01 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: TOH GUO WEI						
	OWNER INSURER : FWD						
	ACC DATE: 03/04/2019						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: SPF						
	TP VEH: QX701H						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>DD /</i>	1	617.20	25	462.90	✓ 32.40	495.30
71593-TEA-T01	SPACERR,RR.BUMPER SIDE <i>rec /</i>	1	11.50	25	8.62	✓ 0.60	9.22
71598-TEA-T01	SPACERL,RR.BUMPER SIDE <i>rec /</i>	1	11.50	25	8.62	✓ 0.60	9.22
91505-TM8-003	CLIP,BUMPER <i>rec /</i>	1	2.30	25	1.72	✓ 0.12	1.84
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER <i>scr /</i>	1	36.40	25	27.30	✓ 1.91	29.21
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER <i>? X NN</i>	1	164.70	25	123.52	8.65	132.17
Sum Item					<u>632.68</u>	<u>44.28</u>	<u>676.96</u>
BKBU02R	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON	1	1000.00	✓ 560	1000.00	70.00	1070.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)	1	800.00	✓ 450	800.00	56.00	856.00
BOSUN	SUNDRIES <i>install</i>	1	100.00	✓ 20	100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00	✓ 80	120.00	8.40	128.40
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	100.00		100.00	X 7.00	107.00
Sum Labor					<u>2120.00</u>	<u>148.40</u>	<u>2,268.40</u>

Survey By

Hwa Jit - Lck

Date & Time

21/5/19

Excess

-

Total Amount 2,752.68 192.68 2,945.36

Total (Inclusive of GST) 2,945.36

Printed on 4/4/2019 5:42:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn Bhd, it will be refunded



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : SINGAPORE POLICE
TANGLIN POST OFFICE
PO BOX 60
SINGAPORE 912402
Registration No : SLL5229U
Chassis No : MRHFC5650GT001116
Model : CIVIC 1.6 VTI YM2016
Owner's Name : TOH GUO WEI
Ins Policy No. :
Date of Accident : 3/4/2019


Document No. : SQT19001524 Page 2
Date : 4. Apr 2019
Customer No. : SP0000001
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : R16B21601420
Date | Time : 4. Apr 2019 4:46:01 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
Status	P/P						
Signature							

Huaz Jia-LKK

3days





64784840

Printed on 4/4/2019 5:42:30 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: SP0000001 / SINGAPORE
Chassis No: MRHFC5650GT001116
License No: SLL5229U
Mileage: 37806
Engine No: R16B21601420

Document No: SVO19046857
Printed By: ANIKKALAI
Order Date: 22. July 2019
Order Time: 10:26:22 AM
Service Advisor: ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TOH GUO WEI OWNER INSURER : FWD ACC DATE: 03/04/2019 SURVEYED BY: HWEE JIE DATE: 21/05/2019 REF NO: TP INSURER: SPF TP VEH: QX701H						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	1	2.30	25	1.72	0.12	1.84
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	36.40	25	27.30	1.91	29.21
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	0	164.70	25	0.00	0.00	0.00
	SUM PARTS:				509.16	35.63	544.79
BKBU02R	1466 REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON ATTACHMENT ITEMS	1	560.00		560.00	39.20	599.20
BP01R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(1P)	1	450.00		450.00	31.50	481.50
BOSUN	1718 SUNDRIES	1	20.00		20.00	1.40	21.40
BA02R	1466 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	80.00		80.00	5.60	85.60
	SUM LABOUR:				1,110.00	77.70	1,187.70
	TOTAL SGD				1,619.16	113.33	1,732.49

Total Payable (SGD)

1,732.49

GST Amount is calculated from individual line(s)

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 1 August 2019 11:06 AM
To: Anikka Lai; SUR
Cc: Mei Kwan (LKKAUTO)
Subject: RE: SLL5229U - FINALIZATION
Attachments: MARK EST_0001.pdf

Dear Anikka,

WITHOUT PREJUDICE

For claims against Singapore Police Force, we have instruction Not to finalise any COR.

However, please be informed that we will submit our recommendation as per our surveyor marking in the estimate.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Anikka Lai <anikkalai@honda.com.sg>
Sent: Wednesday, 31 July 2019 6:19 PM
To: SUR <sur@lkkauto.com>
Cc: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Subject: SLL5229U - FINALIZATION
Importance: High

Dear Sir / Madam,

We enclosed the total final repair costs for,

Vehicle No.	SLL5229U
Final Repair Costs (exclude GST)	\$1619.16
Repair Period* (Days)	3 days

***Note: Repair period does include Sunday and Public Holiday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

In addition, I have attached photos of before paint, '?' items and supplementary parts (if any) for your records.

Thank you.

Warmest regards
Anikka Lai
6A Mandai Estate
Singapore 729903
DID : 65145248 HP: 82886302
Email add: anikkalai@honda.com.sg

From: Printer Service <printservice@honda.com.sg>
Sent: Wednesday, 31 July 2019 6:16 PM
To: Anikka Lai <anikkalai@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 5229U

INSPECTION








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLL 5229U

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19006900/Jvd3e2		
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333		Date : 19-07-2019		
ATTN : ABDUL RAHMAN		Code : SPF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 701H	Veh. Inspected	SLL 5229U	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/040	Excess (\$)	0.00	
Assign From	ABDUL RAHMAN	Assign Date	18/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	MRHFC5650GT001116	Colour	WHITE	
Odometer	35381	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm	
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/04/2019	Inspection Date	21/05/2019	
Survey held at	KAH MOTOR.CO.SDN.BHD 6A MANDAI ESTATE SINGAPORE 729903			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 5229U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FACE ASSY, RR.BUMPER (SN)	DENTED	462.90	462.90
1	SPACERR.RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62
1	SPACERL.RR.BUMPER SIDE (SN)	NECESSARY	8.62	8.62
1	CLIP, BUMPER (SN)	NECESSARY	1.72	1.72
1	GARNISH, RR.BUMPER LOWER (SN)	SCRATCHED	27.30	27.30
1	BEAM COMPRR.BUMPER (SN)	NOT NECESSARY	123.52	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			732.68	529.16
<u>LABOUR</u>				
	REMOVE & RENEW RR BUMPER INCLUDING FITTINGS ON.		1,000.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (1P)		800.00	450.00
	REMOVE & INSTALL REVERSE SENSORS - 4PCS (N).		120.00	80.00
	APPLY BODY UNDERSIDE COATING (N).	NOT NECESSARY	100.00	-
			2,020.00	1,090.00
GRAND TOTAL			2,752.68	1,619.16
RECOMMENDED COST OF REPAIRS				1,619.16

Report Ref No. CS/SPF19006900/Jvd3e2

NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,600-\$2,000

ONG HWEE JIE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.