

ASS. REC. BY:

REF: CS/MSG 19006916/Dtd312

Special Instruction:

Surveyor: Bryan

ASSIGNMENT (Office)

M/M/M

From (Person): Kathrine Wong

of MSI

Date/Time: 18.4.2019 11:30A.M

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHA 1917Z

Insured: GBH 9713B

at Workshop m/s Chunni Motor

Tel:

of BK 10 Ang mo kio Industrial Park 2A A03-19

Policy No: 29097289MKF

Claim No: 590844

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 15.4.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 18.4.19 11:39A.M

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SHA 1917Z - CC372CR17024451 / K1P6392 D.O.A - 22/12/2017
	GBH 9713B - X
<u>25/4-</u>	<u>Revised via preli advise manimen</u>

08/11/19

REF:

Surveyor


ASSIGNMENT

CR 2023 Sept.

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SHA 1917Z Yr Regn: Sept 2015
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
 Make: Hyundai I40 c.c 1685
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 669698 T/Radio: Insured / Std / NI / NA
 Eng/No: D4FDEU496607
 C/No: KMHLB41UMGU077245
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 205/60 R16
 R: — " —

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: 12 Consistent? : Yes or No
 Est. Repairs: 12 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Davanti
 Front Rear
 R/Bal. 5 mm R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 15/04/2019 D.O.I. 18/04/2019
 Survey held at Omni AMK
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S Body & N/S Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	MSIG. GBH 97133
15/05/19	Insured 2/5 12500/- with 12 days of rev (Red. 9167.52, 42%)

RECEIVED 10 MAY 2019

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 16/5 Typist
 Date/Time, File Return to?

Days Of Repair: 12
 Resurvey No. of Trip: 2

2)
 Report Format :
 Lump Sum / I.B.I: (\$) 12,500/-

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))

Survey Fee:	
Transportation:	<u>200</u>
S + RS, SI	<u>10</u>
Photos	
Others	
TOTAL	<u>210</u>

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong Chew Shong

Date: 25 Apr 2019

Preliminary Advice

Insured Vehicle No	: GBH9713B	Accident Date	: 15/04/2019
TP Vehicle No	: SHA1917Z	Assignment Date	: 18/04/2019
Make	: HYUNDAI I40	Est. Duration of Repair	: 9.00
Date of Inspection	: 18/04/2019		
Inspection At	: CHUNNI MOTOR WORK PTE LTD (HQ) BLK 10 ANG MO KIO INDUSTRIAL PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and n/s rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,667.52
Revised Amount	:S\$	15,780.32
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,780.32
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2019		18 Apr 2019 11:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [\[Created by insurer\]](#)

Insured:	GROCERY LOGISTICS OF SINGAPORE PTE LTD , Co. Reg. No.: 199300545M		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA1917Z	Date of Loss:	15/04/2019 00:00 - :59 [43 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 590848	Policy/Cover Note No.:	29097289MKF Coverage: 25/09/2018 - 24/09/2019
Vehicle Reg. No. (Insured):	GBH9713B	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint, 568047 Ang Mo Kio - Tel: 6542 7162		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong Chew Shong - 6594 2544]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/04/2019]		
Adj Asg. Remarks:	TP REQ IHS TO SURVEY VEHICLE. LIABILITY:DISPUTE (OI NON-REPORTING) CONTACT: LYNN/IRENE 6542 5119/6542 7162		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

MCD619049484 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 16/04/2019 12:14
 SUBMITTED BY: Janel Lim Siang Oek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/04/2019 12:14
Date Of Accident	15/04/2019 19:50
Exact Location Of Accident	CHANGI BUSINESS PARK >CHANGI BUSINESS PARK CTRL 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA1917Z
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own Insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18088936MFSH
Cover Note Number	
Driver	
Name of Driver	TAN KONG CHUAN
NRIC No	S1685048I
Date Of Birth	15/05/1965
Occupation	OUTDOOR
Date Of Driving Pass	26/01/1985
Driving Experience	34 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97628460
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 631 ANG MO KIO AVENUE 4 #03-922
Postcode	560631
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED * TYPE OF ACCIDENT :- HEAD TO SIDE

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH9713B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	UNKNOWN
NRIC/Passport Number	
Contact Number	90071351
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	FRONT RH
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	TAN KONG CHUAN
Approximate Age	
Injuries Sustain	NECK
Injured person in which vehicle?	SHA1917Z
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver.**
3. Information provided must be as **truthful and accurate as possible.** Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability.**
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(Including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

陳光全

✓

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)

Date & Time: 16.04.2019 @ 1130HRS

Reporting Centre Personnel's Signature
Name:

NRIC/FIN No.: June

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1917Z

DATE : 16.04.2019

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper N/A			\$ 553.00	X
	Rear Bumper Clip 10 pcs N/A			\$ 22.00	X
	Rear Bumper Bracket, LH N/A			\$ 35.60	X
	Rear Fender With Housing (LH) <i>Distorted</i>			\$ 4,736.80	✓
	Rear Fender Inner Lining (LH) N/A			\$ 169.30	X
	Rear Windscreen Moulding N/A			\$ 28.30	✓
	Rear Door (LH) <i>3pc</i>			\$ 2,201.10	✓
	Rear Door Hinge Upper (LH) N/A			\$ 45.90	X
	Rear Door Hinge Lower (LH) N/A			\$ 45.90	X
	Rear Door Check (LH) N/A			\$ 62.90	X
	Front Door (LH) <i>3pc</i>			\$ 2,256.40	✓
	Front Door Glass (LH) <i>Scratched</i>			\$ 228.20	✓
	Front Door Gear / Regulator (LH) <i>broken</i>			\$ 250.60	✓
	Front Door Outer Handle (LH) <i>broken</i>			\$ 36.30	✓
	Front Door Outer Moulding (LH) <i>6t</i>			\$ 47.10	✓
	Front Door Mirror Assy (LH) <i>broken</i>			\$ 670.00	✓
	Front Door Power Motor, LH N/A			\$ 172.70	X
	Door Centre Pillar Outer (LH) <i>Distorted</i>			\$ 2,527.80	✓
	Rocker Panel Outer Garnish (LH) N/A			\$ 341.40	X
	Rear Tyre Rim (LH) <i>distorted</i>			\$ 325.30	✓
	Rear Wheel Hup-Cap (LH) <i>cut</i>			\$ 107.10	✓
	Rear Wheelbearing ING & Hub <i>2 Dam</i>			\$ 362.00	✓
	Rear Trailing Arm (LH) <i>2 distorted</i>			\$ 192.00	✓
	Rear Assist (LH) <i>2 distorted</i>			\$ 145.70	✓
	Rear Shock Absorber (LH) <i>2 distorted</i>			\$ 276.30	✓
	Rear Shock Absorber Mounting (LH) N/A			\$ 81.30	X
	Rear Crossmember <i>2 N/A</i>			\$ 1,021.50	X
	Stabilizer Bar <i>2 distorted</i>			\$ 199.60	✓
	Stabilizer Link <i>2 distorted</i>			\$ 85.90	✓
	Rear Upper Arm (LH) <i>2 distorted</i>			\$ 335.75	✓
	Rear Lower Arm (LH) <i>2 distorted</i>			\$ 353.80	✓
	Rear Knuckle Arm (LH) <i>2 distorted</i>			\$ 545.60	✓
			15911.65		
			12729.32		
				\$ 18,463.15	
				\$ 3,692.63	
				\$ 14,770.52	
				\$ 50.00	Nett ✓
	Rear Bumper Advertisement Logo N/A			\$ 50.00	Nett ✓
	Rear Bumper Rubber Mat N/A			\$ 200.00	Nett ✓
	Rear Fender Advertisement Logo (LH/RH) N/A		\$ 100.00	\$ 46.00	Nett ✓
	Rear Windscreen Sealant N/A			\$ 100.00	Nett ✓
	Rear Door Advertisement Logo (LH) N/A			\$ 80.00	Nett ✓
	Rear Door Comfortdelgro & Apps Sticker (LH) N/A		701.00	\$ 75.00	Nett ✓
	Front Door Coloured Comfort Logo (LH) N/A			\$ 100.00	Nett ✓
	Front Door Advertisement Logo (LH) N/A			\$ 216.00	Nett X
	Rear Tyre (LH) N/A			\$ 917.00	

SHA 1917Z

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 2,000.00 800/-
	Spray Painting Charge			\$ 1,500.00 800/-
	Wiring Charge			\$ 100.00 114
	Tuff Kote			\$ 150.00 40/-
	Towing Charge			\$ 50.00 114
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00 80/-
	Remove/Refix Rear Windscreen Glass			\$ 120.00 80/-
	Remove/Refix Reverse Sensor			\$ 120.00 114
	Remove/Refix Fuel Tank			\$ 150.00 114
	Transfer of Door	\$	120.00	\$ 240.00 120/-
	Remove/Refix Undercarriage (RR)			\$ 200.00 150/-
	Rear Wheel Alignment			\$ 120.00 60/-
	Re-set Rear ABS System			\$ 200.00
	Re-set Frt & Rear Power Window System	\$	200.00	\$ 400.00 } 150/-
	Diagnostic & Resetting To Erase Fault Code			\$ 480.00
	TOTAL LABOUR			\$ 5,980.00
	ESTIMATE TOTAL			\$ 21,667.52
	<p>18/04/2019 @ 1530m</p> <p>KK Auto</p> <p>2/Smw @ 12 dys.</p> <p>Man</p> <p>KK Auto</p>		<p>2280.00</p> <p>15710.32</p> <p>1/12500/-</p>	

LKK Auto Consultants hence notify the Reparer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company
 Acknowledged by Reparer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

NAME
ADDRESS

Home Tel.:
VIN:
Registration: SHA 1917 Z
Technician:
Mileage: 669698
Time Printed 18.4.19 3:53 PM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
-1°05'		-3°00' 3°00'
4°01'		-0°19' 5°41'
-1°05'		-1°30' 1°30'
17°34'		
16°29'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
-0°18'		-3°00' 3°00'
4°14'		-0°19' 5°41'
1°09'		-1°30' 1°30'
13°46'		
13°28'		

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	BEFORE	Specified Range
-0°47'		-3°00' 3°00'
-0°13'		-3°00' 3°00'
3°48'		-3°00' 3°00'
0°04'		-3°00' 3°00'

Rear : Left

Actual	BEFORE	Specified Range
-0°22'		-3°30' 2°30'
2°03'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°54'		-3°30' 2°30'
0°16'		-1°30' 1°30'

Rear

Cross Camber
Total Toe
Thrust Angle

Actual	BEFORE	Specified Range
0°32'		-3°00' 3°00'
2°19'		-3°00' 3°00'
0°53'		-3°00' 3°00'

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG19006916/DTD3N2

Date: 22/05/2019

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29097289MKF
Claimant Vehicle No :	SHA1917Z	Insured Vehicle No :	GBH9713B
Date of Loss:	15/04/2019	Nature of Claim:	TP Claim No: 590848

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA1917Z		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDEU496607
Reg. Date:	03/09/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMGU077245
Colour:	Blue	Odometer:	669698 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Davanti 5 mm	Rear Left Side:	Davanti 5 mm
Front Right Side:	Davanti 5 mm	Rear Right Side:	Davanti 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,687.52	13,430.32	2,257.20	14.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,980.00	2,280.00	3,700.00	61.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,667.52	15,710.32	5,957.20	27.49
Approved Total (Overridden) (S\$)		12,500.00		
(S\$)	21,667.52	12,500.00	9,167.52	42.31
+ GST 7.00/7.00% (S\$)	1,516.73	875.00	641.73	42.31
Nett Amount (S\$)	23,184.25	13,375.00	9,809.25	42.31

INSPECTION

Date of Assignment:	18/04/2019	
Date Inspected:	18/04/2019 Inspected At:	Chunni Motor Work Pte Ltd (HQ) Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint Singapore 568047

Estimated Period of Repair: 12.0 days

Adjuster: BRYAN TANI

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2019)
Parts: 143	HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA1917Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Not Necessary	553.00 FL	*- FL
2	10		*REAR BUMPER CLIP	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER BRACKET LH	Not Necessary	35.60 FL	*- FL
4	1		*REAR FENDER WITH HOUSING (LH)	Dented	4,736.80 FL	*4,736.80 FL
5	1		*REAR FENDER INNER LINING (LH)	Not Necessary	169.30 FL	*- FL
6	1		*REAR WINDSCREEN MOULDING	Necessary	28.30 FL	*28.30 FL
7	1		*REAR DOOR (LH)	Buckled	2,201.10 FL	*2,201.10 FL
8	1		*REAR DOOR HINGE UPPER (LH)	Not Necessary	45.90 FL	*- FL
9	1		*REAR DOOR HINGE LOWER (LH)	Not Necessary	45.90 FL	*- FL
10	1		*REAR DOOR CHECK (LH)	Not Necessary	62.90 FL	*- FL
11	1		*FRONT DOOR (LH)	Buckled	2,256.40 FL	*2,256.40 FL
12	1		*FRONT DOOR GLASS (LH)	Scratched	228.20 FL	*228.20 FL
13	1		*FRONT DOOR GEAR/REGULATOR (LH)	Broken	250.60 FL	*250.60 FL
14	1		*FRONT DOOR OUTER HANDLE (LH)	Broken	36.30 FL	*36.30 FL
15	1		*FRONT DOOR OUTER MOULDING (LH)	Bent	47.10 FL	*47.10 FL
16	1		*FRONT DOOR MIRROR ASSY (LH)	Broken	670.00 FL	*670.00 FL
17	1		*FRONT DOOR POWER MOTOR,LH	Not Necessary	172.70 FL	*- FL
18	1		*DOOR CENTRE PILLAR OUTER (LH)	Dented	2,527.80 FL	*2,527.80 FL
19	1		*ROCKER PANEL OUTER GARNISH (LH)	Not Necessary	341.40 FL	*- FL
20	1		*REAR TYRE RIM (LH)	Distorted	325.30 FL	*325.30 FL
21	1		*REAR WHEEL HUP-CAP (LH)	Cut	107.10 FL	*107.10 FL
22	1		*REAR WHEELBEARING ING & HUB	Damaged	362.00 FL	*362.00 FL
23	1		*REAR TRAILING ARM (LH)	Distorted	192.00 FL	*192.00 FL
24	1		*REAR ASSIST (LH)	Distorted	145.70 FL	*145.70 FL
25	1		*REAR SHOCK ABSORBER (LH)	Distorted	276.30 FL	*276.30 FL
26	1		*REAR SHOCK ABSORBER MOUNTING (LH)	Not Necessary	81.30 FL	*- FL
27	1		*REAR CROSSMEMBER	Not Necessary	1,021.50 FL	*- FL
28	1		*STABILIZER BAR	Distorted	199.60 FL	*199.60 FL
29	1		*STABILIZER LINK	Distorted	85.90 FL	*85.90 FL
30	1		*REAR UPPER ARM (LH)	Distorted	335.75 FL	*335.75 FL
31	1		*REAR LOWER ARM (LH)	Distorted	353.80 FL	*353.80 FL
32	1		*REAR KNUCKLE ARM (LH)	Distorted	545.60 FL	*545.60 FL
33	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
34	1		*REAR BUMPER RUBBER MAT	Necessary	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
35	2		*REAR FENDER ADVERTISEMENT LOGO (LH/RH)	Necessary	200.00 FS	*200.00 FS
36	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
37	1		*REAR DOOR ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
38	1		*REAR DOOR COMFORTDELGRO & APPS STICKER (LH)	Necessary	80.00 FS	*80.00 FS
39	1		*FRONT DOOR COLOURED COMFORT LOGO (LH)	Necessary	75.00 FS	*75.00 FS
40	1		*FRONT DOOR ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
41	1		*REAR TYRE (LH)	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	19,380.15	16,612.65
- List Item Discount on L Items 20.00/20.00% (S\$)	3,692.63	3,182.33
Total Parts (S\$)	15,687.52	13,430.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	2,000.00	800.00
2	SPRAY PAINTING CHARGE	New	1,500.00	800.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	150.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX CUSHION & UPHOLSTERY REAR	New	150.00	80.00
7	REMOVE/REFIX REAR WINDSCREEN GLASS	New	120.00	80.00
8	REMOVE/REFIX REVERSE SENSOR	New	120.00	0.00
9	REMOVE/REFIX FUEL TANK	New	150.00	0.00
10	TRANSFER OF DOOR	New	240.00	120.00
11	REMOVE/REFIX UNDERCARRIAGE (RR)	New	200.00	150.00
12	REAR WHEEL ALIGNMENT	New	120.00	60.00
13	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE }	New	480.00	150.00
14	RE-SET REAR ABS SYSTEM }	New	200.00	0.00
15	RE-SET FRT & REAR POWER WINDOW SYSTEM }	New	400.00	0.00
Gross Labour Cost (S\$)			5,980.00	2,280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >