

A14

stytech

3

Cecilia

Vehicle: PC7489Y

Make & Model: Toyota Hiace

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Bumper			\$ 874.70	no/re ✓
2	Rear Bumper Retainer	2 Pcs	\$ 88.00	\$ 176.00	11 X
3	Rear Bumper Clip			\$ 30.00	re —
4	Rear End Panel 1064.13			\$ 1,275.00	DD —
5	Rear End Panel Stricker			\$ 95.00	11 X
6	Rear Tailgate			\$ 2,621.50	3.5m —
7	"70KM/H" Sticker			\$ 10.00	re — S.N
8	"Hiace" Sticker			\$ 56.00	ref X
9	"GL" Plate			\$ 62.00	VF X
10	Toyota Emblem			\$ 58.00	re —
11	Tailgate Glass Inner Seal			\$60 SN	re — S.N
12	Glass Sealant			\$60 SN	re 40 S.N
13	Panel Joint Sealant			\$60 SN	re 50 S.N
14	Rear Tailgate Lock			\$ 289.50	no/ya —
15	Rear Bumper Garnish	25w		\$200.00 SN	re ✓ S.N
16	Reverse Sencer			\$200.00 SN	end

P- 4937.80
 252
 P- 3703.35
 S.N- 500.00
 1.6m - 1720.00
5983.35

Labour					
2	Transfer Door Fitting & Sound System			\$ 200.00	120
3	Transfer Glass			\$ 120.00	✓
6	Anti Rust Proofing			\$ 80.00	60
7	Check Wiring			\$ 100.00	20
8	Panel Beaing			\$ 800.00	600
9	Paint Work			\$ 900.00	800

1720

Not Done

4 days

22/4/18

4/5 \$4750

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date: