

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Ergo Insurance Pte Ltd
 5 Temasek Boulevard
 #04-01 Suntec Tower Five
 Singapore 038985
 Tel : 6829 - 9170
 Fax : 6829 - 9247

Asher

Quotation
 DATE : 17.04.2019
 VEH NO : SMA3344D
 MODEL : BMW 316i
 D O A : 13.04.2019
 YR REF : SKW5456J

WBA3A16050NS38644

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SMA3344D (BMW 316i)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Front Bumper <i>Repair</i>	1	1,078.00 *
2	Front Bumper Clips <i>new</i>	1	30.00 ✓
3	Front Bumper Bracket - LH & RH <i>new</i>	2	42.00 +
4	Front Bumper Side Retainer - LH & RH <i>new</i>	2	42.00 +
5	Head Lamp - RH <i>cut</i>	1	2,226.00 ✓
6	Head Lamp Panel - RH <i>new</i>	1	138.00 +
7	Front Fender - RH <i>Dented</i>	1	735.00 ✓
8	Front Fender Inner Panel - RH <i>Repair</i>	1	1,758.00 *
9	Front Fender Inner Shield - RH (Lower) <i>new</i>	1	59.00 +
10	Front Fender Inner Shield - RH (Front) <i>new</i>	1	122.00 +
11	Front Fender Inner Shield - RH (Rear) <i>new</i>	1	122.00 +
12	Front Fender Inner Shield Clips - RH <i>new</i>	1 set	30.00 ✓
13	Front Door - RH <i>Repair</i>	1	1,331.00 +
14	Front Door Glass Outer Moulding - RH <i>new</i>	1	89.00 +
15	Front Door Lock - RH <i>new</i>	1	302.00 +
16	Front Door Weatherstripe - RH <i>new</i>	1	148.00 +
17	Front Door Hinges - RH (upper & Lower) <i>new</i>	2	118.00 +
18	Front Door Checker - RH <i>new</i>	1	81.00 +
19	Front Wheel Bearing - RH <i>new</i>	1	489.00 +
20	Front Suspension - RH <i>new</i>	1	589.00 +
21	Front Knuckle Arm - RH <i>new</i>	1	484.00 +
22	Front Lower Arm - RH <i>new</i>	1	282.00 *
			\$ 10,295.00
Less 10%			(1,029.50)
			\$ 9,265.50

SI/ NET ITEMS

1 Front Wheel Rim - RH *new* 1

1500
1000

1000

RE : ESTIMATE FOR ACCIDENT REPAIR SMA3344D (BMW 316i)

\$ 580.00

Total

\$ 9,845.50

LABOUR CHARGE

1	To knocking & pull out RH side portion & renew above parts	\$	1,000.00	400
2	To putty & spray up paint works	\$	1,000.00	750
3	To check wiring system	\$	30.00	✓
4	To underseal	\$	3.00	✗
5	To transfer door fittings	\$	150.00	✗
6	To remove undercarriage for checking	\$	180.00	✗
7	4 wheel computer alignment	\$	120.00	80
		\$	2,483.00	

Grand Total

\$ 12,328.50

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repaire of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repaire

Signature:

Date:

total: 4978.90
(P/P)
05Days.