

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5368X**AAD1904-167***Not Authorized*
1/1/2019

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5368X

VF1ABL15AUC279576

RENAULT

LATITUDE

15.4.2019

TOKIO MARINE

21/10/2014

PART**LIST**

1	1 BUMPER COVER REAR	\$	<i>Per</i> 1,108.46 ✓
2	1 BUMPER LOWER REAR	\$	<i>Per</i> 768.84 X
3	1 BUMPER BRACKET CTR REAR	\$	<i>Per</i> 113.47 X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Per</i> 135.97 X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Per</i> 44.99 X
6	1 BUMPER REFLECTOR RH	\$	<i>Per</i> 43.61 X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Per</i> 135.97 X
8	1 BUMPER RETAINER LH REAR	\$	<i>Per</i> 44.99 X
9	1 BUMPER REFLECTOR LH	\$	<i>Per</i> 43.61 X
10	1 BUMPER BEAM REAR	\$	777.52 ?
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>Per</i> 225.95 X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>Per</i> 225.95 X
13	1 OUTER PANEL REAR (End Panel)	\$	<i>Per</i> 1,471.77 X
14	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Per</i> 404.56 X
15	1 BOOT REAR	\$	<i>Per</i> 2,872.68 X
16	1 TAILLAMP RH	\$	<i>Per</i> 552.55 X
17	1 TAILLAMP PANEL RH	\$	<i>Per</i> 986.70 X
18	1 TAILLAMP LH	\$	<i>Per</i> 552.55 X
19	1 TAILLAMP PANEL LH	\$	<i>Per</i> 986.70 X

\$ 11,496.85

10% \$ 1,149.69

\$ 10,347.17**Specical Nett**

1	1SET PARKING AID	\$	<i>Per</i> 700.00 X
2	1SET REAR BUMPER CLIP	\$	<i>Per</i> 66.00 —
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>Per</i> 33.00 ✓

Trans-cab Auto Services Pte Ltd**AAD1904-167**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5368X

4	1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	}	X	
5	1SET	BUMPER RETAINER RH CLIP RR	\$	na	20.00			
6	1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00			
7	1SET	BUMPER RETAINER CLIP LH RR	\$	na	20.00			
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00			
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00			
10	1	EXHAUST MOUNTING REAR	\$	na	17.82			
11	2	REAR WINDSCREEN SELANT	\$	na	80.00			
12	1	WINDSCREEN MOULDING	\$	na	100.00			
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00			
14	1	REAR BOOT STICKER 'Trans-cab'	\$	na	80.00			
15	1	REAR BOOT STICKER '6555-3333'	\$	na	80.00			
TOTAL			\$		605.82			
TOTAL PARTS			\$		10,952.99			

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	2001
To Rust-Proofing Of The Affected Areas.	\$	na 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na 170.00	X
To repair and realign rear exhaust pipe.	\$	na 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	na 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na 170.00	X

Trans-cab Auto Services Pte Ltd**AAD1904-167**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5368X

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ *na* 170.00 *X*

To check steering geometry and computer wheel
alignment

\$ *na* 220.00 *X***TOTAL \$ 7,410.00****Over All Total \$ 28,710.15****(LUMP SUM)****Repair Days***10 DAYS**2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: