

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

18/04/2019 11:26

JOB-NO: 50111576

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHA8689K

TRANS: AUTO

CHASSIS: KMHLB41UMFU068395

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDEU440388

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,600.00	0.00	1,600.00		Y	1000.
2 REMOVE & REFIT WHEEL CAP & CHECK UNDERCARRIAGE NECESSARY ADJUSTMENT	1.00	120.00	0.00	120.00		Y	30
3 CONDUCT 4 WHEEL ALIGNMENT	1.00	120.00	0.00	120.00		Y	60.
4 REMOVE & RE-FIX REAR DOOR MECHANISM LHS	1.00	120.00	0.00	120.00		Y	60.
5 DIAGNOSTIC & RESETTING ABS & BRAKE & DOOR MECHANISM	1.00	250.00	0.00	250.00		Y	100.
6 SUNDRIES	1.00	80.00	0.00	80.00		Y	50
7 REMOVE & REPLACE REAR SUSPENSION SYSTEM	1.00	250.00	0.00	250.00		Y	120.
8 REMOVE & RE-FIX SUSPENSION CROSS MEMBER	1.00	250.00	0.00	250.00		Y	150? plus
9 REMOVE & RE-FIX FUEL TANK & FUEL GARNISH & FUEL NECK	1.00	180.00	0.00	180.00		Y	100 plus
10 RESPRAY FRONT DOOR & REAR DOOR	1.00	450.00	0.00	450.00		Y	400.
11 RESPRAY SIDE SKIRT & REAR FENDER	1.00	450.00	0.00	450.00		Y	300.
12 RESPRAY REAR BUMPER & WHEEL HOUSE PANEL	1.00	450.00	0.00	450.00		Y	300
13 REMOVE & REFIT REAR WINDSCREEN	1.00	180.00	0.00	180.00		Y	120.
14 REMOVE & REFIT ROOF LINING	1.00	250.00	0.00	250.00		Y	60.
TOTAL:		4,750.00	0.00	4,750.00			

MATERIALS

1 REAR DOOR LHS	1.00	2,201.00	440.20	1,760.80	L	Y	bt
2 REAR DOOR WEATHERSTRIP 831303Z300	1.00	223.88	44.78	179.10	L	Y	?
3 REAR DOOR BOODY WEATHERSTRIP LHS	1.00	237.12	47.42	189.70	L	Y	?
4 REAR DOOR GLASS RUNNING LHS	1.00	113.52	22.70	90.82	L	Y	?
5 REAR DOOR LOCK ASSY LHS	1.00	359.40	71.88	287.52	L	Y	?
6 REAR DOOR LOCK CATCH LHS	1.00	22.00	4.40	17.60	L	Y	?
7 REAR DOOR HINGE TOP LHS	1.00	39.00	7.80	31.20	L	Y	Ry
8 REAR DOOR HINGE BOTTOM LHS	1.00	36.40	7.28	29.12	L	Y	Ry
9 SIDE MOULDING (SIDE SKIRT) LHS	1.00	341.40	68.28	273.12	L	Y	de
10 REPAIR ROCKER PANEL LHS	1.00	0.00	0.00	0.00	L	Y	Ry
11 REAR FENDER PANEL LHS	1.00	2,171.49	434.30	1,737.19	L	Y	bt
12 REAR FENDER INNER PANEL LHS	1.00	1,374.40	274.88	1,099.52	L	Y	Ry
13 FUEL LID HOUSING LHS	1.00	134.00	26.80	107.20	L	Y	Ry
14 REAR BUMPER	1.00	698.33	139.67	558.66	L	Y	de

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
15 REAR BUMPER RETAINER LHS	1.00	49.14	9.83	39.31	L	Y	<u>rev</u>
16 TAIL LAMP LHS	1.00	659.88	131.98	527.90	L	Y	<u>X</u>
17 REAR WHEEL CAP LHS	1.00	265.88	53.18	212.70	L	Y	<u>aut</u>
18 REAR WHEEL RIM LHS	1.00	359.55	71.91	287.64	L	Y	<u>?</u>
19 REAR SHOCK ABOSRBER 553113Z510	1.00	276.60	55.32	221.28	L	Y	<u>?</u>
20 REAR STABILIZER BAR 555103Q111	1.00	358.51	71.70	286.81	L	Y	<u>?</u>
21 REAR STABILIZER LINK	1.00	67.80	13.56	54.24	L	Y	<u>?</u>
22 REAR UPPER ARM 551003Z000	1.00	338.45	67.69	270.76	L	Y	<u>?</u>
23 REAR LOWER ARM 552103Z055	1.00	323.29	64.66	258.63	L	Y	<u>?</u>
24 REAR KNUCKLE ARM 527203Z010	1.00	543.60	108.72	434.88	L	Y	<u>?</u>
25 REAR KNUCKLE BEARING & HUB 527303S200	1.00	362.00	72.40	289.60	L	Y	<u>?</u>
26 REAR TRAILING CONTROL ARM 552703Z000	1.00	612.53	122.51	490.02	L	Y	<u>?</u>
27 REAR SUSPENSION CONTROL ARM 552503Z000	1.00	2,094.40	418.88	1,675.52	L	Y	<u>?</u>
28 REAR ABS SENSOR	1.00	234.00	46.80	187.20	L	Y	<u>X</u>
29 REAR BRAKE HOSE	1.00	80.70	16.14	64.56	L	Y	<u>X</u>
30 FRONT DOOR STICKER-COMFORTDELGRO LHS	1.00	120.00	0.00	120.00	S	Y	<u>rev</u>
31 REAR DOOR STICKER-BOOK NOW&APPS STORE LHS	1.00	120.00	0.00	120.00	S	Y	<u>rev</u>
32 REAR DOOR TRIM BOARD CLIP SET LHS	1.00	35.00	0.00	35.00	S	Y	<u>rev</u>
33 REAR FENDER SEALANT LHS	1.00	50.00	0.00	50.00	S	Y	<u>rev</u>
34 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	<u>rev</u>
35 REAR TYRE LHS	1.00	200.00	0.00	200.00	S	80% Y	<u>aut</u>
TOTAL:		15,138.27	915.67	12,222.60			

TOTAL PARTS & LABOUR : 19,888.27 2,915.67 16,972.60

EXCESS/LOADING:\$ 0.00

No. Of Day: 8

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: \$

DATE OF SURVEY: 18 / 4 / 19

SURVEYED BY: Tanpin

CONTACT NO: 97495749

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED
DAuto002

Ding Auto User 2

ESTIMATOR
STA AUTOCENTRE
TEL: _____ FAX: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

G-STAR-WI-ET-001-02-Rev00