

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 39Z**AAD1904-168***Not Authored
1/1/2015*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 39Z

VF1ABL15AUC281532

RENAULT

LATITUDE

14.4.2019

QBE

23/3/2015

PART**LIST**

1	1	BUMPER COVER FRT	\$	<i>As</i>	1,259.42	—
2	1	BUMPER SPOILER FRT	\$	<i>DIR</i>	181.75	—
3	1	BUMPER ABSORBER FRT	\$	<i>CM</i>	394.68	—
4	1	BUMPER RETAINER FRT LH	\$	<i>CM</i>	151.41	—
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i>	123.88	X
6	1	BUMPER RETAINER FRT RH	\$	<i>DIR</i>	150.77	—
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i>	123.88	X
8	1	BUMPER UNDERTRAY FRT	\$	<i>CM</i>	472.83	—
9	1	BUMPER GRILLE LOWER FRT	\$	<i>DIR</i>	266.80	—
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>CM</i>	207.21	—
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i>	207.21	X
12	1	BUMPER BEAM FRT	\$	<i>As</i>	914.08	—
13	1	TOW COVER FRT	\$	<i>SL</i>	28.61	X
14	1	RADIATOR GRILLE	\$	<i>My CM</i>	1,707.78	—
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i>	225.36	—
16	1	RADIATOR GRILLE FRAME	\$	<i>CM</i>	1,353.75	—
17	1	FRAME FULL SUPPORT PANEL	\$	<i>CM</i>	615.90	—
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i>	89.79	X
19	1	FRONT BRACE PANEL	\$	<i>R</i>	177.22	X
20	1	HORN	\$	<i>SL</i>	314.17	X
21	1	HORN BRACKET	\$	<i>R</i>	40.45	X
22	1	HEADLAMP LH	\$	<i>My Br</i>	1,184.43	—
23	1	HEADLAMP HARNESS	\$	<i>SL</i>	928.29	X
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i>	152.15	X
25	1	BONNET	\$	<i>R</i>	1,941.63	X
26	1	BONNET INSULATOR	\$	<i>SL</i>	405.73	X
27	1	BONNET STRUT LH	\$	<i>SL</i>	88.61	X
28	1	BONNET STRUT RH	\$	<i>SL</i>	88.61	X

Trans-cab Auto Services Pte Ltd**AAD1904-168**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 39Z

29	1	BONNET HINGE LH	\$	R	348.31	}	X
30	1	BONNET HINGE RH	\$	R	348.31		
31	1	BONNET LOCK	\$	R	305.48		
32	1	BONNET CABLE	\$	SL	119.19		
33	1	BONNET CABLE COVER	\$	R	161.03		
34	1	BONNET SEAL OUTER	\$	SL	92.36		
35	1	BONNET SEAL INNER	\$	SL	157.28	}	✓
36	1	FENDER PANEL FRT LH	\$	R	783.83		
37	1	WHEELARCH FRT LH	\$	CM	278.84	}	✓
38	1	FENDER BRACKET LOWER LH	\$	SL	15.79		
39	1	FENDER INSULATOR LH	\$	SL	130.84	}	X
40	1	FENDER PANEL INNER FRT LH	\$	R	1,693.77		
41	1	FENDER PANEL REINFORCEMENT FRT LH	\$	R	1,096.22		
42	1	TURBO DUCT	\$	SL	1,027.80		
43	1	A/C HEATER VALVE	\$	SL	484.50		
44	1	SUBFRAME OUTER FRT	\$	SL	2,652.45		
45	1	SUBFRAME BRACKET OUTER LH	\$	SL	92.36		
46	1	SUBFRAME BRACKET OUTER RH	\$	SL	92.36		
47	1	ENGINE UNDERTRAY	\$	SL	564.98		
48	1	A/C CONDENSER	\$	SL	2,020.37		
49	1	A/C CONDENSER GARNISH LH UPPER	\$	SL	39.67	}	X
50	1	A/C CONDENSER GARNISH RH UPPER	\$	SL	39.67		
51	1	A/C CONDENSER GARNISH LH	\$	SL	58.81		
52	1	A/C CONDENSER GARNISH RH	\$	SL	59.60		
53	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	SL	208.39		
54	1	A/C PIPE CONDENSER TO EXPENSION VALVE	\$	SL	658.72		
55	1	A/C PIPE COMPRESSOR	\$	SL	334.29		
56	1	A/C PIPE	\$	SL	658.72		
57	1	A/C COMRPESSOR	\$	SL	2,684.61		
58	1	AIR COOLER	\$	SL	792.60		
59	1	AIR INTERCOOLER HOSE (LONG)	\$	SL	1,014.13	}	
60	1	AIR INTERCOOLER HOSE (Short)	\$	SL	375.14		
61	1	TRANSMISSION COOLER	\$	SL	1,219.30		
62	1	TRANSMISSION COOLER PAD	\$	SL	17.96		
63	1	RADIATOR	\$	SL	1,202.20		
64	2	RADIATOR STUD UPPER	\$	SL	14.41		
65	2	RADIATOR BUSH UPPER	\$	SL	50.12		
66	2	RADIATOR MTG LOWER	\$	SL	55.85		

Trans-cab Auto Services Pte Ltd**AAD1904-168**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 39Z

67	1	RADIATOR FAN COWLING	\$	820.54	} X
68	1	RADIATOR FAN MOTOR LH	\$	967.36	
69	1	RADIATOR FAN MOTOR RH	\$	1,479.46	
70	1	RADIATOR TANK	\$	324.62	
71	1	RADIATOR HOSE UPPER	\$	240.56	
72	1	RADIATOR HOSE LOWER	\$	491.18	
73	1	RADIATOR TANK HOSE	\$	61.18	
74	1	LOWER ARM LH	\$	685.76	
75	1	KUNCKLE ARM LH	\$	846.98	
76	1	ABSORBER FRT LH	\$	360.54	
77	1	STABILIZER BAR FRT	\$	604.65	
78	1	DRIVESHAFT LH	\$	1,747.45	
79	1	AUTO COMPUTER	\$	5,032.17	
80	1	INJECTION COMPUTER	\$	4,706.30	
81	1	RHD HYDRAULIC POWER(ROCK&PINION)	\$	5,154.52	
82	1	STEERING PUMP ELECTRIC	\$	2,306.90	?
83	1	STEERING PINION RACK	\$	4,413.11	X
84	1	ENGINE HARNESS WIRE	\$	4,084.54	X

TOTAL	\$	70,074.47
10%	\$	7,007.45
	\$	63,067.02

Specical Nett

1	1SET	RADIATOR GRILLE FRAME CLIP	\$	52.00	} X
2	1SET	BUMPER CLIP FRT	\$	66.00	
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00	
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50	
7	1	TOW COVER FRT	\$	14.50	
8	1SET	RADIATOR GRILLE SCREW	\$	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00	

Trans-cab Auto Services Pte Ltd

AAD1904-168

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 39Z

13	1	Windscreen moulding	\$	<i>nn</i> 100.00 X
14	1	FRONT NUMBER PLATE WITH HOLDER	\$	<i>nn</i> 200.00 X

TOTAL	\$	682.50
--------------	-----------	---------------

TOTAL PARTS	\$	63,749.52
--------------------	-----------	------------------

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	<i>nn</i> 4,000.00
---	----	--------------------

Towing Fees.	\$	120.00 <i>501</i>
--------------	----	-------------------

To apply paint protection system (PPS) maintain and enhancement	\$	<i>nn</i> 380.00 X
---	----	--------------------

Putty and spray painting of the affected portion.	\$	4,000.00 <i>6601</i>
---	----	----------------------

To rust-proofing of the affected areas.	\$	170.00 <i>301</i>
---	----	-------------------

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00 X
---	----	--------------------

To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 X
---	----	--------------------

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00 <i>7</i>
---	----	-----------------

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i> 380.00 X
---	----	--------------------

To lift-up engine with gear box and refit.	\$	<i>nn</i> 440.00 X
--	----	--------------------

Trans-cab Auto Services Pte Ltd

AAD1904-168

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 39Z

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	na 440.00 X
To remove and refit air bag system and reset.	\$	na 480.00 X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	na 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	380.00 100/
To replace, refix and top up coolant for radiator	\$	170.00 50/
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00 50/
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	na 170.00 X
To Transfer Of Bonnet Fittings, Attachments And Perform Water Seepage Test.	\$	na 170.00 X

TOTAL	\$	12,830.00
--------------	-----------	------------------

Over All Total	\$	76,579.52
-----------------------	-----------	------------------

Repair Days (Lump Sum)**20 days**
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: