

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO : AIG INSURANCE
ATTENTION : MOTOR CLAIMS DEPT
ESTIMATE REPORT :
DATE : 16-Apr-19
JOB TYPE : TP CLAIM

VEHICLE DETAILS

VEHICLE NO : SMF 3791 U
MODEL : HONDA FREED 1.5G A
CHASSIS NO

ACCIDENT DETAILS
DATE : 14-Apr-19
TIME : 15:00HRS

THIRD PARTY REQUESTOR / CONTACT : DEON

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 1,460.30	\$ 1,460.30 1280
2	TAIL GATE LOGO <i>re</i>	1	\$ 72.30	\$ 72.30
3	TAIL GATE EMBLEM 'FREED' <i>re</i>	1	\$ 76.40	\$ 76.40
4	TAIL GATE EMBLEM 'HYBRID' <i>re</i>	1	\$ 76.40	\$ 76.40
5	TAIL GATE INNER HOLDER <i>re</i>	1	\$ 80.00	\$ 80.00
6	TAIL GATE INNER TRIM <i>re</i>	1	\$ 460.00	\$ 460.00
7	TAIL GATE TOP LOCK <i>Dented</i>	1	\$ 255.90	\$ 255.90
8	TAIL GATE WEATHERSTRIP <i>re</i>	1	\$ 241.70	\$ 241.70
9	TAIL GATE WINDSCREEN MOULDING <i>re</i>	1	\$ 194.20	\$ 194.20
10	NUMBER PLATE LAMP(SET) <i>re</i>	1	\$ 168.50	\$ 168.50
11	REAR BUMPER <i>Dented</i>	1	\$ 1,155.60	\$ 1,155.60 76
12	REAR BUMPER SIDE RETAINER <i>re</i>	2	\$ 69.70	\$ 139.40
13	REAR BUMPER TOW HOOK COVER <i>re</i>	1	\$ 55.90	\$ 55.90
14	REAR BUMPER INNER HOLDER <i>re</i>	2	\$ 80.50	\$ 161.00
15	REAR END PANEL (OUTER) <i>Repr</i>	1	\$ 655.50	\$ 655.50
16	REAR END PANEL (INNER) <i>Repr</i>	1	\$ 530.80	\$ 530.80
17	REAR END PANEL TOP GARNISH <i>could</i>	1	\$ 190.00	\$ 190.00

TOTAL PRICE \$ 5,973.90

36250
2890

LESS 20% \$ 1,194.78

SUB TOTAL PRICE \$ 4,779.12

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	TAIL GATE INNER TRIM CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	TAIL GATE WINDSCREEN INNER SEAL <i>3m</i>	1	\$ 100.00	\$ 100.00
4	TAIL GATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00
5	REAR BUMPER CLIP(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
6	REAR END PANEL INSULATOR SEAL(OUTER) <i>3m</i>	1	\$ 120.00	\$ 120.00
7	REAR END PANEL INSULATOR SEAL(INNER) <i>3m</i>	1	\$ 120.00	\$ 120.00
8	REAR END PANEL TOP GARNISH CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
9	REAR REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00
10	REAR REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00

TOTAL \$ 1,200.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, WELDING, CUTTING, GRAZING ADJUST, KNOCK STRAIGHTEN	\$ 1,400.00	600
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,400.00	600
3	TO APPLY RUST PROOFING/ UNDER COAT	\$ 250.00	x
4	WIRNING, BULB CHECKING	\$ 80.00	x
5	REMOVE AND REFIX UPHOLSTERY, CUSHION, SEAT TO FACILITATE REPAIR	\$ 250.00	60
6	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
7	TO TRANSFER TAIL GATE MECHANISM	\$ 80.00	✓
8	CONDUCT WATER LEAKAGE TEST	\$ 100.00	x
9	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
10	REMOVE AND REFIX REAR REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	x

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

APPROVED DETAILS

SURVEYOR

TOTAL

\$3,840.00

ESTIMATE REPORT

TOTAL PARTS COST

5,979.12

TOTAL LABOUR COST

3,840.00

TOTAL REPAIR COST

9,819.12

Adrian Lj
H/S 17/04/19.

04 days

total: 4710

L/S: 3750