



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower, Singapore 068811 Attn: Motor Claims Contact No 63387288	Cust No/Name /Mr Chai Yew Thong Reg No/Reg Date SJW3213T / 17/03/2010 Date In/Mileage 18/04/2019/ 0 Chassis No KNAFW411MA5178390 Engine No G4FC9H345497 Make/Model KIA/CERATO 1.6 A SX (2010) Colour/Trim HO / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
F0000008	Credit	18/04/2019/ 09:40	DS	303 / Renemer	22876			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
S	MIPNT88088							✓ 250.00
	DAIGNOSTIC/SCANNING							80 100.00
S	MIPNT88088							+ 600.00
	TO CHECK LIGHTING/WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS							x 200.00
S	MIPNT88088							600 1800.00
	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS							x 200.00
S	MIPNT88088							600 1800.00
	TO APPLY SEALANT KIT ON NEW & REPAIRED PANELS							x 200.00
S	MIPNT88088							420 1680.00
	TO REPLACE REAR BUMPER UPR & LWR, REINFORCEMENT, ETC							x 50.00
	TO REPAIR REAR END PANEL							
	STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS							
S	MIPNT98088							x 50.00
	SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS							
M	SUNDRY							
	C & C LOGO							
M	KS 86611 1M 010	COVER-RR BUMPER	Red d		1.00	698.00	0.00	✓ 698.00
M	KS 86695 1M 010	CTR COVER-RR BUMPER	Red d		1.00	128.00	0.00	✓ 128.00
M	KS 86613 1M 000	LH BRKT ASSY-RR BUMP	Free		1.00	26.00	0.00	✓ 26.00
M	KS 86614 1M 000	RH BRKT ASSY-RR BUMP	Free		1.00	26.00	0.00	✓ 26.00
M	KS 86620 1M 010	RR BUMPER ENERGY	?		1.00	179.00	0.00	✓ 179.00
M	KS 95420 3K 100	ANTENNA ASSY-SMARTKE	new		1.00	79.00	0.00	✓ 79.00
M	KS 86630 1M 010	RAIL ASSY-RR BUMPER	?		1.00	385.00	0.00	✓ 385.00
M	KS 86686 1M 000	LWR BRKT REAM BEAM M	?		2.00	25.00	0.00	✓ 50.00
M	KS 86685 1M 000	LWR BRKT RR BUMPER M	?		1.00	5.00	0.00	✓ 5.00
M	KS 06032 50 037A	CLIP- BUMPER	new		10.00	2.00	0.00	✓ 20.00
M	KS 95720 1M 010	SENSOR ASSY-ULTRASON	new		3.00	204.00	0.00	✓ 612.00
M	KS 86310 1M 100	EMBLEM-CERATO	?		1.00	32.00	0.00	✓ 32.00
M	KS 86310 1M 000	EMBLEM-FORTE	Free		1.00	32.00	0.00	✓ 32.00
M	KS 86318 2G 000	ORNAMENT-KIA			1.00	55.00	0.00	✓ 55.00

Confirm & accepted by

Adrian
P/P 23/04/19. 96893735.
03 Days.

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

Invoice Name & Address	Owner Name & Vehicle Info	
AXA Insurance Singapore Pte Ltd 8 Shenton Way #27-01 AXA Tower, Singapore 068811 Attn: Motor Claims Contact No 63387288	Cust No/Name	/Mr Chai Yew Thong
	Reg No/Reg Date	SJW3213T / 17/03/2010
	Date In/Mileage	18/04/2019/ 0
	Chassis No	KNAFW411MA5178390
	Engine No	G4FC9H345497
	Make/Model	KIA/CERATO 1.6 A SX (2010)
	Colour/Trim	HO / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000008	Credit	18/04/2019/ 09:40	DS	303 / Renemer	22876
Description of Goods / Services					Qty Unit Price Disc% Amount

Z NOTES
 ACCIDENT ON 17/04/2019 ALONG CTE TOWARDS PIE
 OWNER CLAIMING THIRD PARTY
 REQUIRED REPLACEMENT CAR
 TP#: SGK7575X TP INS: AXA

Estimate

Confirm & accepted by	Parts	2,327.00
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	4,630.00
	Others(Lub,etc)	0.00
	Sundry	50.00
	Total(w/o GST)	7,007.00
Authorized signatory and company stamp		

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.