

22/03/2002

ASS. REC. BY:

REF: CS/FC1 19006956/Dtd3

Special Instruction:

72

Supervisor: Bryan

ASSIGNMENT (Office)

(CWS) From (Person): Henry Kao

of PC1

Date/Time: 18.4.19 3.36p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SL 580J

Insured: SHC 0256T

at Workshop m/s Tan Lim Moto

Tel: 68585151

of 1 Detu Lane 6

Policy No:

Claim No: D19002610 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 16.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

nwp

H.O.D. Endorsement:

Date/Time: 18.4.19

Person Contacted:

William

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SL 580J - X
	SHC 0256T - X
22/4/2019 2:30pm	Revised preli advise via email

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC 580J

Yr Regn:

2016 April

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Kia Forte

c.c.

1591

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading:

35157

T/Radio:

Insured / Std / NI / NA

Eng/No:

G4F GG+612275

C/No:

KNAFX411MG5596007

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ STD A/Rim or

Tyre Size:

F:

205/55R16

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Toyo

Front

Rear

P/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

16/24/2019

D.O.I.

18/04/2019

Survey held at

Ten Lim MAW Deputee

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

First report SLC 256T

21/05/19

Invoice PIP 6777-60 - 7 bags gran
(Red: 3517.84 / 34%)

RECEIVED 22 MAY 2019

Date/Time, File Pass to?

22/05/2019



: Preli. Report



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

2

Add Fee:



: Site Insp (\$)



: Interview (\$)



: Tech. Insp (\$)



: Weekend (\$)

Survey Fee:

Transportation:

) S + RS, \$

) Photos

) Others

) 21/5/19

TOTAL

Report Format :

TP

Lump Sum / I.B.I. (\$) 6777-60

170

50

50+50

105

425



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002610MFSH

Date: 22/4/2019

Our Ref: CS/FCI19006956/Dtd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLC 580J

Please be informed that we had conducted the inspection of the abovementioned vehicle
18/4/2019 at the premises of M/s Tan Lim Automotive have the following to report: -

Workshop Estimate Amount	: S\$ 4,575.04
Revised Estimate Amount	: S\$ 3,032.40
"Check" Items Amount	: S\$ 518.40
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
n/s front portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Bryan

Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	18-04-2019	Our Ref No. D19002610MFSH
Accident Date	16-04-2019	Claim Type. Third Party
Insured Vehicle	SHC0256T	Third Party Vehicle. SLC580J
Survey Location	1 DEFU LANE 6	
Contact Person.	WILLIAM	
Contact No.	68585151/ 0	Fax No. 68580877
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN LIM MOTOR PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	HENRY KAO	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Monday, 22 April 2019 2:30 PM
To: Admin-D (LKKAuto); 'CWS Motor Claims'; assignments
Cc: 'Henry Kao Cai Jie'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002610MFSH/1
Attachments: PRELI ADVISED SLC 580J.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SHC 580J**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Thursday, 18 April 2019 4:41 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Henry Kao Cai Jie' <HenryKao@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002610MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 18 April 2019 3:36 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Henry Kao Cai Jie <HenryKao@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002610MFSH/1

Dear Sir/Mdm,

 > Back to OneMotoring**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Business
Owner ID:	2085A

Vehicle Details

Vehicle No.:	SLC580J
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Apr 2019
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A EX
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	G4FGGH612275
Chassis No.:	KNAFX411MG5596007
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$14,010.00
Original Registration Date:	29 Apr 2016
First Registration Date:	29 Apr 2016
Transfer Count:	1
Actual ARF Paid:	\$14,010.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Apr 2026
PARF Rebate Amount:	\$10,507.00

Intended COE Rebate Details

COE Expiry Date:	28 Apr 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,300.00
COE Rebate Amount:	\$33,254.00
Total Rebate Amount:	\$43,761.00

The information contained herein is correct as at 17 Apr 2019

OK



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

MS FCIL Insured's Veh No : SHC256T

Date of Accident : 16 April 2019

Messrs M Conceptz

Date : 21 May 2019

Estimate To Repair SLC580J - KIA FORTE K3 1.6A

Chassis No : KNAFX411MG5596007

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	2 pc	front bumper side retainers @ \$40.00 N/S broken o/s NW	\$ 40.00 80.00
02	1 pc	front bumper lower grille NW	\$ 65.00 X
03	1 pc	front bumper lower splashield centre NW	\$ 88.00 X
04	1 pc	front fender inner cowl LH deformed	\$ 116.00 ✓
05	1 pc	front shock absorber LH distorted	\$ 326.00 ✓
06	1 pc	front lower arm LH distorted	\$ 352.00 ✓
07	1 pc	front bumper cut / mounting broken	\$ 637.00 ✓
08	8 ps	front bumper clips @ \$4.50 Nec	\$ 36.00 ✓
09	1 pc	front bumper fog lamp LH mounting broken	\$ 263.00 ✓
10	1 pc	front bumper fog lamp trim LH deformed	\$ 35.00 ✓
11	1 pc	headlamp left broken	\$ 1,870.00 ✓
12	1 pc	headlamp bracket vt	\$ 30.00 ✓
13	1 pc	headlamp bracket panel HS	\$ 99.80 X
14	1 pc	front left fender Dent	\$ 425.00 ✓
15	4 pc	front left fender cowl clips @ \$4.50 Nec	\$ 18.00 ✓
16	1 pc	front left fender inner cowl extension NW	\$ 45.00 X
17	1 pc	front left knuckle arm distorted	\$ 310.00 ✓
18	1 pc	front left bearing Dem	\$ 108.00 ✓
19	1 pc	front left bearing hub NW	\$ 151.00 X
20	1 pc	front left lower arm vapour	\$ 352.00 X
21	1 pc	front left anti roll bar linkage NW	\$ 79.00 X
22	1 pc	front support panel broken	\$ 1,256.00 ✓
23	1 pc	front left fender inner panel NW	\$ 587.00 X
24	1 pc	fuse box assy NW	\$ 1,778.00 X
			\$ 9,106.80
Less 20 %			\$ 1,821.36
			\$ 7,285.44
<u>SPECIAL NETT ITEMS</u>			
25	1 pc	front left wheel rim cut	\$ 500.00 ✓
26	1 pc	front left wheel tyre cut 60% depreciation 650.00	\$ 250.00 150/-
			\$ 750.00
<u>LABOUR & MISC. CHARGES</u>			
01		To check steering geometry and computer wheel alignment.	\$ 80.00 60/-



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

MS FCIL Insured's Veh No : SHC256T

Date of Accident : 16 April 2019

Messrs M Conceptz

Date : 21 May 2019

Estimate To Repair SLC580J - KIA FORTE K3 1.6A
Chassis No : KNAFX411MG5596007

S/No	Quantity	Description	Amount
02		LABOUR & MISC. CHARGES	
		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 100.00
03		To check electrical lighting concerned.	\$ 80.00
04		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,200.00
05		Putty and spray painting of the affected portion. 1470.00	\$ 800.00
			\$ 2,260.00
		Total	\$ 10,295.44

80/-
30/-
700/-
600/-

18/04/2019 @ 1730hrs
NA Antenna
7/7A. 6 days.

Photo 54 spray
with damaged parts.
LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19006956/Dtd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 23-05-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 256T	Veh. Inspected	SLC 580J	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002610MFSH	Excess (\$)	0.00	
Assign From	HENRY KAO	Assign Date	18/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	KIA FORTE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	KNAFX411MG5596007	Colour	BLUE	
Odometer	35157	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	TOYO	6 mm	
L/H Front Tyre	205/55 R16	TOYO	6 mm	
R/H Rear Tyre	205/55 R16	TOYO	6 mm	
L/H Rear Tyre	205/55 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/04/2019	Inspection Date	18/04/2019	
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 580J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
2	FRONT BUMPER SIDE RETAINERS @\$40.00	N/S BROKEN / O/S NOT NECESSARY	80.00	40.00
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	65.00	-
1	FRONT BUMPER LOWER SPLASHIELD CENTRE	NOT NECESSARY	88.00	-
1	FRONT FENDER INNER COWLING LH	DEFORMED	116.00	116.00
1	FRONT SHOCK ABSORBER LH	DISTORTED	326.00	326.00
1	FRONT LOWER ARM LH	DISTORTED	352.00	352.00
1	FRONT BUMPER	CUT / MOUNTING BROKEN	637.00	637.00
8	FRONT BUMPER CLIPS @\$4.50	NECESSARY	36.00	36.00
1	FRONT BUMPER FOG LAMP LH	MOUNTING BROKEN	263.00	263.00
1	FRONT BUMPER FOG LAMP TRIM LH	DEFORMED	35.00	35.00
1	HEADLAMP LEFT	BROKEN	1,870.00	1,870.00
1	HEADLAMP BRACKET	BENT	30.00	30.00
1	HEADLAMP BRACKET PANEL	NO SUCH PARTS	99.80	-
1	FRONT LEFT FENDER	DENTED	425.00	425.00
4	FRONT LEFT FENDER COWLING CLIPS @\$4.50	NECESSARY	18.00	18.00
1	FRONT LEFT FENDER INNER COWLING EXTENSION	NOT NECESSARY	45.00	-
1	FRONT LEFT KNUCKLE ARM	DISTORTED	310.00	310.00
1	FRONT LEFT BEARING	DAMAGED	108.00	108.00
1	FRONT LEFT BEARING HUB	NOT NECESSARY	151.00	-
1	FRONT LEFT LOWER ARM	REPEATED	352.00	-
1	FRONT LEFT ANTI ROLL BAR LINKAGE	NOT NECESSARY	79.00	-
1	FRONT SUPPORT PANEL	BROKEN	1,256.00	1,256.00
1	FRONT LEFT FENDER INNER PANEL	NOT NECESSARY	587.00	-
1	FUSE BOX ASSY	NOT NECESSARY	1,778.00	-
	LESS 20% DISCOUNT		-1,821.36	-1,164.40
			7,285.44	4,657.60
SPECIAL NETT ITEMS				
1	FRONT LEFT WHEEL RIM (SN)	CUT	500.00	500.00

Report Ref No. CS/FC119006956/Dtd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LEFT WHEEL TYRE (60%)(DEPRECIATION)(SN)	CUT	250.00	150.00
			750.00	650.00
	LABOUR			
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		80.00	60.00
	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS,REMOVE AND RENEWAL OF THE NECESSARY PARTS,TO PERFORM FINAL CHECKING AND TESTING.		100.00	80.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		80.00	30.00
	PANEL BEATING,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.		1,200.00	700.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		800.00	600.00
			2,260.00	1,470.00
	GRAND TOTAL		10,295.44	6,777.60
RECOMMENDED COST OF REPAIRS				6,777.60

Report Ref No. CS/FCI19006956/Dtd3n2

ANG BRYAN TANI

Automotive Assessor / Investigator

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.