

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

LKK
Kenneth

17, APR 2019

AXA Insurance PL
143 Cecil Street #01-01
GB Building
S 069542

Not Authorized
L1 Surp 8?
Resurvey After Painting
4-5 days

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: GBD9757X
Accident involving vehicle no: SMJ8573D/GBD9757X
DOA: 13/04/2019 AT TPE Exit Loyang Ave

Re: Estimate cost of repair for vehicle no: SMJ8573D

To Supply—

Description	Qty	Amount
Lid	1	597.50 ✓
Lid hinge @60.20	2	120.40 X
Lid lock	1	96.50 ✓
Lid chrome handle	1	221.10 ✓
Lid-Corolla emblem	1	42.35 —
Lid-Altis emblem	1	44.10 —
Lid-TOYOTA logo	1	52.50 —
Lid reflector @147	2	294.00 4
Rear bumper	1	459.70 ✓
Rear bumper enforcement/sponge	1	117.50 ?
Rear bumper retainer-long @66.70	2	133.40 X
Rear bumper retainer-small @29.40	2	58.80 X
End panel	1	552.25 ?
End panel top garnish	1	185.20 ?
Boot weatherstrip	1	175.30 X
Spare tyre panel	1	494.70 X
Spare tyre board	1	348.10 X
Taillamp @409.90	2	819.80
Parts		4,813.20
Parts less 25%		1,203.30
		3,609.90

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle no: SMJ8573D

Reverse sensor

220.00 ?

To remove damaged parts and attachments.

Cut n weld damaged panel.

Repair/reshape damaged panel/dented areas.

Straighten rear chassis where necessary.

Replace all parts into position.

To spray paint

1,200.00 500

1,000.00 600

6,029.90