

威利摩多
WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

LKK
Kenneth

17, APR 2019

AXA Insurance PL
143 Cecil Street #01-01
GB Building
S 069542

Not Authorized
61 Sm @ 1850/
Passing After Paint
4-5 days

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: GBD9757X
Accident involving vehicle no: SMJ8573D/GBD9757X
DOA: 13/04/2019 AT TPE Exit Loyang Ave

Re: Estimate cost of repair for vehicle no: SMJ8573D

To Supply—

Description	Qty	Amount	
Lid	1	597.50	✓
Lid hinge @60.20	2	120.40	X
Lid lock	1	96.50	✓
Lid chrome handle	1	221.10	✓
Lid-Corolla emblem	1	42.35	✓
Lid-Altis emblem	1	44.10	✓
Lid-TOYOTA logo	1	52.50	✓
Lid reflector @147	2	294.00	✓
Rear bumper	1	459.70	✓
Rear bumper enforcement/sponge	1	117.50	X
Rear bumper retainer-long @66.70	2	133.40	X
Rear bumper retainer-small @29.40	2	58.80	X
End panel	1	552.25	X
End panel top garnish	1	185.20	X
Boot weatherstrip	1	175.30	X
Spare tyre panel	1	494.70	X
Spare tyre board	1	348.10	X
Taillamp @409.90	2	819.80	X
Parts		4,813.20	
Parts less 25%		1,203.30	
		3,609.90	

Vehicle no: SMJ8573D

Reverse sensor
To remove damaged parts and attachments.
Cut n weld damaged panel.
Repair/reshape damaged panel/dented areas.
Straighten rear chassis where necessary.
Replace all parts into position.
To spray paint

Sn 220.00 X

1,200.00 500
1,000.00 600

6,029.90

Parts
less 258 1660.75
1402.75
1245.57
1100.57
2345.57
469.11
1876.46
laf
sum