



Name: SOH CHIEN SIONG SEBASTIAN
Address: Blk 322 Jurong East Street 31 #10-224
Singapore 600322
Policy Number: AVPPSB0551571800
Quotation for Reinstste / Repairs for Vehicle

Date: 25/4/19
Vehicle No: SLP328D

Parts Replacement-Cost Price		Cost Price		
1 Pc	Rear R/H Tyre 225/60R17 Yokohama RV02	\$	168.22	puncture
1 Pc	Front R/H Low Door Hinge	\$	45.00	bt
1 Pc	Front R/H Fender Mudflap	\$	55.00	nec
1 Pc	Front R/H Fender Garnish	\$	45.00	nec
	Cost + 10%	\$	313.22	

1 job


To remove and replace all the parts mentioned above and knocking
and straighten up the necessary affected areas

1 job

To spray painting on affected areas

\$ ~~626.44~~ 344.54

Labour's Total :
Sub-Total : \$ 626.44
GST 7% : \$ 43.85
Grand Total : \$ 670.29




Michael Tee
Wah Hong Motors & Credit Pte Ltd
Tel: 67737377
Fax: 68966321
Email: michael@wahhong.sg

WAH HONG

38 Toh Guan Road East, #03-57 Enterprise Hub, Singapore 608581 Tel: 6515 5988 Fax: 6896 6321 Email: enquiry@wahhong.sg