

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 22 Apr 2019

Preliminary Advice

Vehicle No	: SLV6957S	Accident Date	: 18/04/2019
Make	: KIA SORENTO	Policy No.	: D19MTPV01000361
Assignment Date	: 18/04/2019	Excess	: S\$400.00
Date of Inspection	: 22/04/2019	Est. Duration of Repair	: 4 days
Inspection At	: Lai Huat (Meng Kee) Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #04-01, Sin Ming AutoCity Singapore 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,378.20
Revised Amount	:S\$	2,117.70
Check Items (Estimated)	:S\$	60.50
Total	:S\$	2,178.20
Lump Sum Repair		:S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	138,000.00
COE / PARF Rebate	:S\$	66,907.00
Salvage Value	:S\$	
Margin for Repair	:S\$	71,093.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :