

22/03/2002

ASS. REC. BY:

REF: CS/CTI19006997/Ktd 302 Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

main

From (Person): Elaine chiong of CTI Date/Time: 22.4.2019 11:55 a.m

Estimated Cost: Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: S94 6080P Insured: GBD 85454

at Workshop m/s Siong Lu motor Tel: 64531255

of 160 sin ming Drive #02-07

Policy No: DM CVSV K07321900 Claim No: SNM 19D 2017 0102

Sum Insured: Excess: \$45-00

Make of Veh: D.O.A. 15.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"top"

H.O.D. Endorsement:

Date/Time: 22-4-2019 1:19 p.m Person Contacted: KWEE Pin Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	S94 6080P - X
	GBD 85454 - X
23/5	1/1 Ly \$16,300 email
	Confirm \$10,350 - email. (Red: 13449.26', 56%)

ASS. REC. BY:

REF: CT21

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Sion Lee

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SGY 6080P Yr Regn: 01, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A)

Make: M E250 c.c. 1991

Colour: N.L Blue A/C: Insured / Std / NI / NA

Sp. Reading: 117338 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: W00 21203828 089397

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 6 mm

L/Bal. 7 mm L/Bal. 6 mm

D.O.A. 15/4/19 D.O.I. 22/4/19

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or R/O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

RECEIVED 26 AUG 2019

Date/Time, File Pass to?

11/26/18 Typast

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / I.B.I: (\$ W.3500)

: Prell. Report

: Final Report

Days Of Repair: 5

Resurvey No. of Trlp: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee: 270

Transportation: _____

S - R.S. \$ _____

Photos _____

Others _____

TOTAL

270

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2019		22 Apr 2019 11:55 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
Insured:			
Main Claimant:	YEO CHENG CHUAN, ID: S1219749G		
Vehicle Reg. No.:	SGY6080P	Date of Loss:	15/04/2019 19:00 - :59
Claim Type:	TP / SNM19D201701C02	Policy/Cover Note No.:	DMCVSN1907321900
Vehicle Reg. No. (Insured):	GBD8545Y	Policy No. (Claimant):	GA299239/1
		Excess:	S\$450.00
Repairer:	- Not Applicable - (-)		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/05/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			
ALL ASSOCIATED TASKS		View All	Search Tasks
		Create New Task	Complete
Due Date	Priority	Type	Task Group
			Subject
			Handler
			Assigned By
			Completed On
			Created On
			Done?
No results.			

Nivitha (LKK Auto)

From: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Sent: Monday, 22 April 2019 11:47 AM
To: Cheonghoh Law; 'assignments'
Subject: RE: PRS for SGY 6080 P accident involving vehicle GBD 8545 Y ON 15 April 2019 at Blk 310 Shunfu Road - Open Car Park (Our ref: LCH.lg/SMSL-90296.9) - CLAIM REF: SNM19D201701C02/5
Attachments: Fwd: PRS for SGY 6080 P accident involving vehicle GBD 8545 Y ON 15 Ap....9) (288 KB)

WITHOUT PREJUDICE

Dear Catherine,

We refer to your email of 18.04.19.

We will be assigning M/s LKK Auto Consultants Pte Ltd to survey your client's vehicle.

Aside to LKK,

Please refer email below and proceed to survey the third party vehicle.

Thank you.

Regards,

Elaine Cheong
Executive (Motor Claims)
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389 6530
Fax: 6224 7478 / 6224 7175
Email: elaine.cheong@sg.cntaiping.com
Website: www.sg.cntaiping.com

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Thursday, 18 April, 2019 9:32 AM
To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>
Subject: Re: PRS for SGY 6080 P accident involving vehicle GBD 8545 Y ON 15 April 2019 at Blk 310 Shunfu Road - Open Car Park (Our ref: LCH.lg/SMSL-90296.9) - CLAIM REF: SNM19D201701C02/5

Dear Sirs,

We refer to the above matter and to your email of 17 April 2019.

Our client hereby nominate Xing Quo Qiang of LKK Auto Consultants Pte Ltd named in paragraph 1 of your said email to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be contact our client's workshop, Siong Lee Motor, 160 Sing Ming Drive #02-07 AutoCity Singapore 575722 for the survey of SGY 6080 P.

Contact Person : Mr Tan / Ms Kwee Pin
Telephone : 6453 1255

Kindly proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 17 Apr 2019, at 6:12 PM, Elaine Cheong <elaine.cheong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Catherine,

We refer to your email of 16.04.19.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Elaine Cheong

Executive (Motor Claims)

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6224 7478 / 6224 7175

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com

From: Cheonghoh Law [<mailto:mail@cheonghoh.sg>]

Sent: Wednesday, 17 April, 2019 9:16 AM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Elaine Cheong

<elaine.cheong@sg.cntaiping.com>

Subject: Fwd: PRS for SGY 6080 P accident involving vehicle GBD 8545 Y ON 15 April 2019 at Blk 310 Shunfu Road - Open Car Park (Our ref: LCH.lg/SMSL-90296.9)

REMINDER!

re-send

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: Cheonghoh Law <mail@cheonghoh.sg>

Subject: Re: PRS for SGY 6080 P accident involving vehicle GBD 8545 Y ON 15 April 2019 at Blk 310 Shunfu Road - Open Car Park (Our ref: LCH.lg/SMSL-90296.9)

Date: 16 April 2019 at 10:07:29 AM SGT

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Dear Sirs,

We enclosed herewith our letter of PRS and await your urgent reply.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: roaming26@singtel.com.sg

Subject: Attached Image

Date: 16 April 2019 at 9:51:10 AM SGT

To: "mail@cheonghoh"

<mail@cheonghoh.sg>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

Denise Tay (LKKAuto)

From: twinauto@singnet.com.sg
Sent: Monday, 26 August 2019 1:42 PM
To: Denise Tay (LKKAuto)
Subject: RE: SGY6080P - ALIGNMENT

Dear Denise

Accepted amount @ lumpsum \$10,350.00 .

Thank you
Regards

Siong Lee Motor
Tel: 6457 0410
Fax: 6552 0692

On Mon Aug 26 2019 13:37:18 GMT+0800 (Singapore Standard Time) Denise Tay (LKKAuto) <denisetay@lkkauto.com> wrote:

----- Original Message -----

Dear Sir,

Kindly confirm \$10,350

Best Regards,
Denise Tay
| Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email:
sur@lkkauto.com
| fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Denise Tay (LKKAuto)
Sent: Monday, 26 August 2019 11:14 AM
To: twinauto@singnet.com.sg
Subject: RE: SGY6080P - ALIGNMENT

Dear Sir/Madam,

Enclosed estimate

Best Regards,
Denise Tay
| Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email:
sur@lkkauto.com
| fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From:

Work Order: R031202
 VIN: SGY6080P
 Year: 10
 Date: 16.4.19 16:03



SGY6080P

Mercedes-Benz : 212 (E Class 2009-16) : Rear Wheel Drive : Sedan Steel Spring Suspension Europe version/USA : Standard Suspension (Code 485)

Front : Left

Actual	Before	Specified Range
-0°23'	-0°23'	-0°45' -0°02'
6°57'	6°57'	
0°07'	0°07'	0°00' 0°10'
13°37'	13°37'	
13°14'	13°14'	
		-2°24' -1°24'

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-3°06'	-3°05'	-0°45' -0°02'
6°57'	6°57'	
0°20'	0°24'	0°00' 0°10'
16°11'	16°10'	
13°05'	13°05'	
		-2°24' -1°24'

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
2°44'	2°43'	-0°24' 0°24'
0°00'	0°00'	-0°30' 0°30'
-2°34'	-2°33'	
0°27'	0°31'	0°00' 0°20'

Rear : Left

Actual	Before	Specified Range
-1°32'	-1°33'	-1°33' -0°33'
-0°02'	-0°02'	0°04' 0°18'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°21'	-1°22'	-1°33' -0°33'
0°08'	0°08'	0°04' 0°18'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°11'	-0°11'	-0°30' 0°30'
0°06'	0°06'	0°14' 0°29'
-0°05'	-0°05'	-0°15' 0°15'

Siong Lee

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/04/2019 18:47
Date Of Accident	15/04/2019 19:55
Exact Location Of Accident	BLK 310 SHUNFU ROAD OPEN CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGY6080P
Insured/Policyholder	
Name Of Registered Owner	YEO CHENG CHUAN
NRIC No	S1219749G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96600880
Alternative Phone No	OFFICE-96600880

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200 (R17)-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA299239/1
Cover Note Number	

Driver

Name of Driver	YEO CHENG CHUAN
NRIC No	S1219749G
Date Of Birth	25/05/1957
Occupation	INDOOR
Date Of Driving Pass	24/11/1976
Driving Experience	42 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96600880
Fax Number	
Contact Number	OFFICE-96600880
Email Address	NOEMAIL

Address	BLK 310 SHUNFU ROAD #09-219
Postcode	570310
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBD8545Y
Vehicle Make/Model/Colour	MINICAB
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	ANG MUN TIO
NRIC/Passport Number	S2001923I
Contact Number	94521570
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the Insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time: 16/4/19
9.20 am



Driver's Signature
(If driver is not the policyholder)
Date & Time: 16/4/19
9.20 am




Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

15/4/19 . I parked my car (PSY 6080 P) in front of my Block 210 SAMPAN ROAD LOT NO. 248. About 7.55 pm , my neighbour informed me that my car had damaged.

I check and found that one paper slip with phone number on the front windscreen wiper.


* Repair other workshop *

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 16/4/19
 9.20 am


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 16/4/19
 9.20 am


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No:





松 利 摩 哆
SIONG LEE MOTOR

Compar Reg No: 100838/00J

Sin Ming AutoCity
160 Sin Ming Drive #02-07 Singapore 575722
Tel: 6457 0410, 6453 1255 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

16 April 2019

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: YEO CHENG CHUAN
H/P: 9660 0880

Dear Sirs / Madam,

Accident Claim for Vehicle No.SGY 6080 P , Involving Vehicle No.GBD 8545 Y.
A ident on 15 APRIL 2019, AT BLK 310 SHUNFU ROAD - FRONT OPEN AIR
CARPARK.

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

Not Authorised
11 Lap 810,300
Primary After Paint
Selanj

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	FRONT BUMPER	1PC	\$ <i>Mjcm</i> 1,435.00
2	FRONT BUMPER SIDE BRACKET - RH	1PC	\$ <i>cm</i> 80.00
3	FRONT BUMPER SPORT LAMP COVER - RH	1PC	\$ <i>cm</i> 88.90
4	REAR BUMPER SPONGE - RH	1PC	\$ <i>sm</i> 167.10
5	FRONT BUMPER INNER RETIANER	1PC	\$ <i>cm</i> 45.00
6	HEADLAMP - RH	1PC	\$ <i>cm</i> 3,150.00
7	FRONT HEADLAMP PANEL - RH	1PC	\$ <i>R</i> 299.90
8	BONNET	1PC	\$ <i>R</i> 2,160.00
9	BONNET LOCK CATCH	1PC	\$ <i>R</i> 90.00
10	FRONT FENDER - RH	1PC	\$ <i>R</i> 1,050.00
11	FRONT FENDER COWLING - RH	1PC	\$ <i>bit</i> 350.00
12	FRONT WHEEL BEARING - RH	<i>Nu</i> 1PC	\$ <i>2</i> 720.20
13	FRONT KNUCKLE - RH	<i>R</i> 1PC	\$ <i>?</i> 1,265.00
14	FRONT LOWER ARM - RH	<i>diy</i> 1PC	\$ <i>2</i> 565.00
15	FRONT SIDE ARM - RH	1PC	\$ <i>sm</i> <i>x</i> 580.00
16	FRONT SHOCK ABSORBER - RH	<i>R</i> 1PC	\$ <i>2</i> 975.30
17	FRONT STEERING RACK	1PC	\$ <i>R</i> 8,900.00
	TOTAL LIST PRICE		\$ 21,921.40
	LESS 10%		\$ (2,192.14)
	TOTAL AMOUNT		\$ 19,729.26

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	FRONT BUMPER SENSOR		
2	FRONT SPORT RIM - RH	2PCS	\$ <i>Sm</i> 380.0
		1PC	\$ <i>nu</i> 680.0
TOTAL SPECIAL NETT PRICE			\$ 1,060.0

LABOUR :			
1	LABOUR TO SPRAY PAINT		
2	LABOUR TO PANEL BEATING	\$	<i>7501</i> 950.0
3	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS	\$	<i>5401</i> 900.0
4	LABOUR TO RESET HEADLAMP LIGHT.	\$	<i>nn</i> 150.0
5	LABOUR TO FOCUS HEADLAMP.	\$	<i>1001</i> 380.0
6	LABOUR TO DISMANTLE AND REFIX UNDER CARRIAGE PARTS.	\$	<i>201</i> 50.0
7	COMPUTERISED WHEEL ALIGNMENT	\$	<i>2001</i> 500.0
		\$	<i>601</i> 80.0
TOTAL LABOUR		\$	3,010.0
TOTAL AMOUNT		\$	23,799.26

THANK YOU

FROM:
SIONG LEE MOTOR
 Mr Tan Leng Huat

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
 Signature:
 Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Apr 2019		22 Apr 2019 11:55 Edit Adj Rpt	S\$10,350.00 Edit Estimates	S\$10,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS		[Created by Insurer]		
Insured:	-, Co. Reg. No.: -			
Main Claimant:	YEO CHENG CHUAN , ID: S1219749G			
Vehicle Reg. No.:	SGY6080P	Date of Loss:	15/04/2019 19:00 - :59 [50 Months and 24 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / SNM19D201701C02	Policy/Cover Note No.:	DMCVSN1907321900	
Vehicle Reg. No. (Insured):	GBD8545Y	Policy No. (Claimant):	GA299239/1	
		Excess:	S\$450.00	
Repairer:	Siong Li Motor (HQ) SIONG LI MOTOR, 575722 Sin Ming - Tel:			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]			
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 02/05/2019]			
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS			View All	Search Tasks
			Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

*SGY6080P (SNM19D201701C02)
[GBD8545Y]
TP
YEO CHENG CHUAN
Apr 15 2019 7:00PM
[-]
Siong Li Motor

Upload Documents | Upload Photos | Compose New Letter

View View in Browser

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	16/04/19 22:58	Accident Statement	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	16/04/19 20:24	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
2	16/04/19 20:24	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
3	16/04/19 20:24	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
4	16/04/19 20:24	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
5	16/04/19 20:24	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
6	16/04/19 20:24	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
7	16/04/19 20:24	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
8	16/04/19 22:57	Accident Photo <small>[Linked Accident Report Documents]</small>	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
2	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
3	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
4	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
5	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
6	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
7	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
8	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
9	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
10	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
11	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
12	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
13	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
14	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
15	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
16	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
17	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
18	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
19	25/07/19 15:22	General View	Load JPG	<input checked="" type="checkbox"/>
20	26/08/19 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
21	26/08/19 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
22	26/08/19 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
23	26/08/19 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
24	26/08/19 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
25	26/08/19 13:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/04/19 11:58	PRS - SGY6080P	Load PDF	<input type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	16/04/19 20:24	Sketch Plan [Linked Accident Report Documents]	Load TIF	
2	16/04/19 20:24	Sketch Plan #2 [Linked Accident Report Documents]	Load TIF	

Linked Accident Report Documents

View

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	16/04/19 22:58	Accident Statement	Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	16/04/19 20:24	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
2	16/04/19 20:24	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
3	16/04/19 20:24	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
4	16/04/19 20:24	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
5	16/04/19 20:24	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
6	16/04/19 20:24	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
7	16/04/19 20:24	Accident Photo	Load JPG <input checked="" type="checkbox"/>	
8	16/04/19 22:57	Accident Photo	Load JPG <input checked="" type="checkbox"/>	

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	16/04/19 20:24	Sketch Plan	Load TIF	
2	16/04/19 20:24	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19006997/KTD3E2

Date: 11/09/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN1907321900	
Claimant Vehicle No : SGY6080P	Insured Vehicle No : GBD8545Y	
Date of Loss: 15/04/2019	Nature of Claim: TP	Claim No: SNM19D201701C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGY6080P		
Make & Model:	MERCEDES-BENZ E250, 2.0 SEDAN (R17) (A)	Engine No:	27492030203663
Reg. Date:	22/01/2015 (Man. Year: 2014)	Chassis No:	WDD2120362B089397
Colour:	Metallic Light Blue	Odometer:	117338 km
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R17	Rear Tyre Size:	245/45 R17
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,789.26	11,255.45	9,533.81	45.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,010.00	1,670.00	1,340.00	44.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,799.26	12,925.45	10,873.81	45.69
Approved Total (Overridden) (S\$)		10,350.00		
	(S\$) 23,799.26	10,350.00	13,449.26	56.51
+ GST 7.00/7.00% (S\$)	1,665.95	724.50	941.45	56.51
Nett Amount (S\$)	25,465.21	11,074.50	14,390.71	56.51

INSPECTION

Date of Assignment:	22/04/2019		
Date Inspected:	22/04/2019	Inspected At:	160 SIN MING DRIVE #02-07 Repairer : Siong Lee Motor (HQ)
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 11 Sep 2019)
Parts: 143	MERCEDES-BENZ E250 2.0 SEDAN (R17) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SGY6080P)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	1,435.00 FL	*1,435.00 FL
2	1		*FRONT BUMPER SIDE BRACKET - RH	Cracked	80.00 FL	*80.00 FL
3	1		*FRONT BUMPER SPORT LAMP COVER - RH	Serviceable	88.90 FL	*- FL
4	1		*REAR BUMPER SPONGE - RH	Serviceable	167.10 FL	*- FL
5	1		*FRONT BUMPER INNER RETAINER	Serviceable	45.00 FL	*- FL
6	1		*HEADLAMP - RH	Cracked	3,150.00 FL	*3,150.00 FL
7	1		*FRONT HEADLAMP PANEL - RH	Repair	299.90 FL	*- FL
8	1		*BONNET	Bent	2,160.00 FL	*2,160.00 FL
9	1		*BONNET LOCK CATCH	Repair	90.00 FL	*- FL
10	1		*FRONT FENDER - RH	Bent	1,050.00 FL	*1,050.00 FL
11	1		*FRONT FENDER COWLING - RH	Distorted	350.00 FL	*350.00 FL
12	1		*FRONT WHEEL BEARING - RH	Necessary	720.20 FL	*720.20 FL
13	1		*FRONT KNUCKLE - RH	Bent	1,265.00 FL	*1,265.00 FL
14	1		*FRONT LOWER ARM - RH	Distorted	565.00 FL	*565.00 FL
15	1		*FRONT SIDE ARM - RH	Serviceable	580.00 FL	*- FL
16	1		*FRONT SHOCK ABSORBER - RH	Bent	975.30 FL	*975.30 FL
17	1		*FRONT STEERING RACK	Repair	8,900.00 FL	*- FL
18	2		*FRONT BUMPER SENSOR	Serviceable	380.00 FS	*- FS
19	1		*FRONT SPORT RIM - RH	Dented	680.00 FS	*680.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	22,981.40	12,430.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,192.14	1,175.05
Total Parts (\$\$)	20,789.26	11,255.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO SPRAY PAINT	New	950.00	750.00
2	LABOUR TO PANEL BEATING	New	900.00	540.00
3	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS	New	150.00	0.00
4	LABOUR TO RESET HEADLAMP LIGHT	New	380.00	100.00
5	LABOUR TO FOCUS HEADLAMP	New	50.00	20.00
6	LABOUR TO DISMANTLE AND REFIX UNDER CARRIAGE PARTS	New	500.00	200.00
7	COMPUTERISED WHEEL ALIGNMENT	New	80.00	60.00
Gross Labour Cost (S\$)			3,010.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >