

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0490/2019/DY/  
**Date** : 16-Apr-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

**Your insured vehicle** : SJZ 2169 E

## AXA Insurance Singapore Pte Ltd

8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

**Attn: Motor Claims Dept**

**Tel: 6880 4602 - Fax 6880 4838**

**Owner's Name** : Dr Lum Hon Kit Raymond  
**Address** : 138 Hillview Avenue  
#10-08  
Singapore 669599  
**Telephone** : HP +65 97706906  
**Type of Claim** : Third Party Claim  
**Policy No.** : 1700030916-01  
**Vehicle No** : **SLQ 7672 H** ✓  
**Model Code** : Audi A4 SEDAN 1.4 TFSI  
**Model / Year** : Jul-17  
**Engine No** : CVN 040519  
**Chassis No** : WAUZZZF4XHA177248  
**Mileage** : -  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 14-Apr-19  
**Place of Accident** : Decathlon Carpark at Kallang

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle. SLQ 7672 H.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	✓
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ <del>800.00</del>	600
3	To respray rear bumper and lhs rear fender.	\$ <del>1,500.00</del>	1200.
4	To renew lhs rear rim and carry out wheel alignment.	S/N \$ 280.00	✗
5	To carry out diagnostic check.	S/N \$ 192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 3,132.00</b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SLQ 7672 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>Reband</i>	\$ 1,844.00	✓
2	REAR BUMPER FIXING PARTS	\$ 61.00	X
3	REAR PARKING SENSOR SECURING STRIP	\$ 203.00	X
4	REAR BUMPER SPOILER	\$ 203.00	X
5	REAR BUMPER LIGHT REFLECTOR - LH	\$ 33.00	X
6	REAR BUMPER GUIDE - LH LOWER	\$ 36.00	X
7	REAR BUMPER GUIDE - LH UPPER	\$ 18.00	X
8	REAR BUMPER GUIDE LOCK PIN	\$ 6.00	X
9	REAR PARKING SENSOR O-RING	\$ 14.00	X
10	ALUMINIUM RIM - LH REAR <i>not new</i>	\$ 465.00	X
11	TYRE VALVE <i>not new</i>	\$ 11.00	X
12	SUNDRIES ?	\$ 500.00	?
<b>TOTAL SPARE PARTS</b>		<b>\$ 3,394.00</b>	
<b>TOTAL LABOUR</b>		<b>\$ 3,132.00</b>	
<b>GRAND TOTAL</b>		<b>\$ 6,526.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : *Adrian King*  
Surveyed Date : *23/04/19.*  
Authorised Date :  
Excess Cost :  
Liability :  
Remarks : *not authorised, 03 days*

**Please Note** : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant