

ASS. REC. BY:

REF: CS/SMD19007008/Jgd367

Special Instruction:

Surveyor: Hwe Jie

ASSIGNMENT (Office)

From (Person): Gnoh Pau Loong

of SMO

Date/Time: 22.4.19 10.46a.m

Estimated Cost:

Bill to:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: SHD 6264A

Insured: SGR 3388J

at Workshop m/s SMRT Automotive Services

Tel:

of NO 61 Woodlands Industrial Park E9, #04-04

Policy No: DIBMTPO1013708

Claim No: CM7D1901957

Sum Insured:

Excess:

Make of Veh:

D.O.A. 18.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 22.4.19 10.56a.m

Person Contacted:

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 6264A - CC3/AXA14006611/KIWA 3w2 D.O.A-05/04/2014
	SGR 3388J - CC6/AIG14006654/GHG 3w2 D.O.A-07/04/2014
24/4/19 @ 1.42pm	revised to Gnoh Pau Loong via Messenger.
	US \$ 1650, 4 days (Red \$ 4449.31, 73%)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Apr 2019		22 Apr 2019 10:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LAI EE LIN FIONA, ID: S6829604H, Tel: +6592788818, Email: leo3818@live.com								
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHD6264A	Date of Loss:	18/04/2019 10:00 - :59						
Claim Type:	TP / CMTD1901957	Policy/Cover Note No.:	D18MTPV01013708 (Comprehensive)						
Vehicle Reg. No. (Insured):	SGR3388J	Policy No. (Claimant):							
		Excess:							
Repairer:	Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building, 757047 Woodlands - Tel:								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 02/05/2019]								
Driver/Custodian (Insured):	LAI EE LIN FIONA (50 / Female), NRIC: S6829604H, Tel: +6592788818 Email: leo3818@live.com								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: GNOH PAU LOONG

Date: 24 Apr 2019

Preliminary Advice

Insured Vehicle No	: SGR3388J	Accident Date	: 18/04/2019
TP Vehicle No	: SHD6264A	Assignment Date	: 22/04/2019
Make	: TOYOTA PRIUS	Est. Duration of Repair	: 4.00
Date of Inspection	: 22/04/2019		
Inspection At	: SMRT AUTOMOTIVE SERVICES PTE LTD (HQ) NO. 61 WOODLANDS INDUSTRIAL PARK E9, #04-04 PREMIUM BUILDING SINGAPORE 757047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,475.87
Revised Amount	:S\$	1,647.45
Check Items (Estimated)	:S\$	1,032.32
Total	:S\$	2,679.77

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHD6264A
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6521874
Chassis No.:	JTDKN36U105765954
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	05 Oct 2015
First Registration Date:	05 Oct 2015
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Oct 2023
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	04 Oct 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$45,439.00
COE Rebate Amount:	\$25,257.00
Total Rebate Amount:	\$29,007.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 23 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/04/2019 11:24
Date Of Accident	18/04/2019 10:15
Exact Location Of Accident	GRAND HOTEL LOBBY DRIVEWAY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD6264A
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-19093197MFSH
Cover Note Number	

Driver

Name of Driver	TAN YANG JOO
NRIC No	S1736382D
Date Of Birth	17/04/1966
Occupation	OUTDOOR
Date Of Driving Pass	23/02/1988
Driving Experience	31 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG THE DRIVEWAY OF GRAND HYATT HOTEL AS I WAS WAITING FOR THE FRONT VEHICLE TO MOVE. SUDDENLY I FELT AN IMPACT AT THE REAR PORTION OF MY TAXI. A VEHICLE SGR3388J AHD COLLIDED ONTO THE REAR RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGR3388J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LAI EE LIN FIONA
NRIC/Passport Number	S6829604H
Contact Number	
Address	
Postcode	
Insurance Company Name	

Address	11
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY ALONG THE DRIVEWAY OF GRAND HYATT HOTEL AS I WAS WAITING FOR THE FRONT VEHICLE TO MOVE. SUDDENLY I FELT AN IMPACT AT THE REAR PORTION OF MY TAXI. A VEHICLE SGR3388J AHD COLLIDED ONTO THE REAR RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGR3388J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LAI EE LIN FIONA
NRIC/Passport Number	S6829604H
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

Grand Hyatt Hotel Lobby



A - SHD 6264A

B- SGR 3388 J

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____

Date & Time:



Driver's Signature
(If driver is not the policyholder)

Date & Time:

15/4/19

18/4/2019

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 3/1/19

Driver's Signature
(If driver is not the policyholder)
Date & Time: 13/4/19

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Case Details

Case Reference Number :

TAX/04/19/2073

Type of Repair : Accident Repair

Vehicle Registration Number :

SHD6264A

Company Type : SMRT Taxis Pte Ltd

Estimation ID : EST-6541-ID

Assigned By : Taxi Claims Manager
Team

Insurance Company Name : Sompo Insurance Singapore Pte.
Ltd

Accident Date and Time : 18/04/2019 02:17 AM

Vehicle Age(In Months) : 42

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation				Repair/ Replace	Surveyor Approval			Remarks
						List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			DUCT ASSY, QUARTER	1	70.40	70.40	25.00	52.80	Replace	0	0	Check	
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check	
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace	DEF
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	nec
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace	nec
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Check	
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Check	
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Check	

Total Spare Part Cost 2,794.87

Surveyor Total 1,007.45

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 2,235.90

Final Sur Total 805.96

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	1	502.02	Replace	CRA
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0	Check	
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	1	0	Repair	
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	hec
One Time Key In	Main			STICKER DECAL SMRT	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	hec
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	0	0	Check	
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Check	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	hu
Total Spare Part Cost									2,794.87	Surveyor Total		1,007.45		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									2,235.90	Final Sur Total		805.96		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR RH PORTION REAR	845.00	400	
Total:			845.00	400.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR FENDER RH	378.00	200	
3	Main	TO RESPRAY REAR PANEL	180.00	0	
Total:			1,116.00	400.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
4	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			1,116.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0	
2	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	120.00	20	
3	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0	
4	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0	
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	20	
6	Main	TO REPLACE SUNDRY PARTS	100.00	0	
7	Main	TO WASH AND VACUUM	60.00	0	
Total:			720.00	40.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	2,235.90	805.96
Total Labour Cost	845.00	400.00
Total Spray Painting	1,116.00	400.00
Other	720.00	40.00
Overall Total	4,916.90	1,645.96
Lump Sum Repair Option	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
Lump Sum Total	4,900.00	1,650.00
Surveyor Approved Amount		1,650.00
No of Repair Days*	6	4
Remarks	-	L/S REPAIR, PHOTO AFTER REPAIR.
Surveyor Name		Hwee jie

Estimator Assessment(\$)

Surveyor Assessment(\$)

Signature


24/4/19

Save

Clear

Survey Date

22/04/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer



Signature:

Date:

Shiwei Chan

Section A - Accident Details



Registration Number	SHD6264A
Case Reference Number	TAX/04/19/2073
Registration Date	5/10/2015
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	TAN YANG JOO
Type of Accident	Head to Rear
Accident Date and Time	18/4/2019 10:17 AM
Accident Reported Date and Time	18/4/2019 11:33 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24101119
Special Instruction to ARC, if any	TP
Prepared Date and Time	20/4/2019 7:18 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Toyota

L/S \$1650/- 4days

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$400.00
Total Spray Cost	\$1,116.00	\$400.00
Total Spare Part Cost	\$2,235.90	\$805.96
Total Other Cost	\$720.00	\$40.00
TOTAL COST	\$4,916.90	\$1,645.96
Lump Sum Total	\$4,900.00	\$1,650.00 (L/S)
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Kim Ming Chin	Hwee Jie (LKK) / Somp
ARC / Surveyor Sign Off Date	22/04/2019 2:21 PM	22/04/2019 1:55 PM
Signature		
Remarks	L/S REPAIR, PHOTO AFTER REPAIR.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0456	Invoice Number	
Quotation Date	29.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION REAR	\$845.00	\$400.00
Total Labour	\$845.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$0.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$1,116.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$120.00	\$20.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	\$120.00	\$0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$720.00	\$40.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		62940-16060	DUCT ASSY, QUARTER	0.00	\$70.40	0.00	\$0.00	Replace	Check X
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check X
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check X
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Check X
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Check X
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$118.10	0.00	\$0.00	Replace	Check X
		81551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace
		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	0.00	\$0.00	Replace	Check X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63655592
Estimator Telephone Number : 68662023
Accident Reporting Number : 68662072

Date Generated : 29/04/2019

User ID : PehSuan

	61604-47090	FENDER RR/RH	1.00	\$766.80	100.00	\$0.00	Replace	Repair	✓
		STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
		STICKER DECAL SMRT	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
	58307-47060	END PANEL	0.00	\$602.10	0.00	\$0.00	Replace	Check	X
		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Check	X
		SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given	X
Total				\$3,418.31		\$1,007.45			

nee
nee
nn
nn
nn

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1007.45

- 202

805.96

+ 400.00

+ 440.00

1645.96

US \$1650/-

6099.31

6173.80

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Apr 2019		22 Apr 2019 10:44 Edit Adj Rpt	S\$1,650.00 Edit Estimates	S\$1,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]					
Insured:	LAI EE LIN FIONA, ID: S6829604H, Tel: +6592788818, Email: leo3818@live.com						
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K						
Vehicle Reg. No.:	SHD6264A	Date of Loss:	18/04/2019 10:00 - :59 [42 Months and 13 Days From LTA Reg Date (Man Yr)]				
Claim Type:	TP / CMTD1901957	Policy/Cover Note No.:	D18MTPV01013708 (Comprehensive)				
Vehicle Reg. No. (Insured):	SGR3388J	Policy No. (Claimant):					
		Excess:					
Repairer:	Smrt Automotive Services Pte Ltd (HQ) No. 61 Woodlands Industrial Park E9, #04-04 Premium Building, 757047 Woodlands - Tel:						
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]						
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 02/05/2019]						
Driver/Custodian (Insured):	LAI EE LIN FIONA (50 / Female) , NRIC: S6829604H, Tel: +6592788818 Email: leo3818@live.com						

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHD6264A (CMTD1901957)**
[SGR3388J]

TP
SMRT TAXIS PTE LTD
Apr 18 2019 10:00AM
[LAI EE LIN FIONA]
Smrt Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Print
1	22/04/19 10:45	Accident Statement From: OD - Reg. No: SGR3388J, Claimant: LAI EE LIN FIONA		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	24/04/19 13:42	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
2	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
3	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
4	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
5	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
6	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
7	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
8	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
9	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
10	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
11	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
12	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
13	25/04/19 08:42	General View		Load JPG <input checked="" type="checkbox"/>
14	02/05/19 13:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
15	02/05/19 13:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
16	02/05/19 13:56	Photo After Spray		Load JPG <input checked="" type="checkbox"/>
Documentation			1 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>	
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)		Thumbnail Print
1	22/04/19 10:41	Third Party E-filed GIA report		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset Save Print
There are no document checklists configured.		
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; width: 100%; height: 100%;"></div>		
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>		

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19007008/JQD3E2

Date: 09/05/2019

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTPV01013708

Claimant Vehicle No : SHD6264A

Insured Vehicle No : SGR3388J

Date of Loss: 18/04/2019

Nature of Claim: TP

Claim No: CMTD1901957

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD6264A

Make & Model: TOYOTA PRIUS, 1.8 (A)

Engine No: 2ZR6521874

Reg. Date: 05/10/2015 (Man. Year: 2015)

Chassis No: JTDKN36U105765954

Colour: Maroon

Odometer: 410600 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,492.80	1,007.45	2,485.35	71.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,681.00	840.00	1,841.00	68.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,173.80	1,847.45	4,326.35	70.08
Approved Total (Overridden) (S\$)		1,650.00		
Nett Amount (S\$)	6,173.80	1,650.00	4,523.80	73.27

INSPECTION

Date of Assignment: 22/04/2019

Date Inspected: 22/04/2019 Inspected At:

Smrt Automotive Services Pte Ltd (HQ)
No. 61 Woodlands Industrial Park E9, #04-04 Premium Building
Singapore 757047

Estimated Period of Repair: 4.0 days

Adjuster: ONG HWEE JIE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 09 May 2019)
Parts: 144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD6264A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER REAR (DISC 25%)	Deformed	458.60 F	*343.95 F
2	1		*BUMPER CLIPS (DISC 25%) (10PCS)	Necessary	16.10 F	*12.08 F
3	1		*TAIL LAMP RH (DISC 10%)	Cracked	557.80 F	*502.02 F
4	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
5	1		*STICKER DECAL 6555 8888 (SN)	Necessary	21.60 F	*21.60 F
6	1		*STICKER DECAL SMRT (SN)	Necessary	7.80 F	*7.80 F
7	1		*DUCT ASSY, QUARTER	Not Necessary	70.40 F	*- F
8	1		*BUMPER REINFORCEMENT REAR	Not Necessary	205.70 F	*- F
9	1		*ARM SUB-ASSY, RR BUMPER RH	Not Necessary	139.60 F	*- F
10	1		*BUMPER SIDE RETAINER RR/RH	Not Necessary	94.80 F	*- F
11	1		*BUMPER SEAL, RR RH	Not Necessary	65.70 F	*- F
12	1		*BUMPER LIP COVER RR/RH	Not Necessary	118.10 F	*- F
13	1		*TAIL LAMP BRACKET, RH	Not Necessary	30.70 F	*- F
14	1		*END PANEL	Not Necessary	602.10 F	*- F
15	1		*SEALANT SIKAFLEX	Not Necessary	37.00 F	*- F
16	1		*SENSOR REVERSE	Not Necessary	180.00 F	*- F
17	1		*FENDER RR/RH	Repair	766.80 F	*- F
F=Franchise part.						
					Total Parts (S\$)	3,492.80 1,007.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	845.00	400.00
2	SPRAY PAINT	New	1,116.00	400.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	0.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA	New	120.00	20.00
5	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR	New	120.00	0.00
6	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	New	120.00	0.00
7	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
8	TO REPLACE SUNDRY PARTS	New	100.00	0.00
9	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			2,681.00	840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >