

INS. CASE OWNER:

cc 4, upc 1900 7018, P10352

LKK:
IDAC:

Surveyor:

DOI:

Date / Time:

18/04/2019

Registered in Merimen:

Pre-assign / CCU / FTS



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SFZ 8778D



INSRS:

WSP:

Tel:

Liability:

RMKS:

Borneo.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

(in 1/31)

S\$ 24464.05

OI TH TP PACKED YES.

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$ 700.00

(\$ 100 x 7 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$ 25166.05

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 25166.05

Name 1:

Borneo Motors (Singapore) Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$450

COPY SENT
19/12/19

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

-

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SFZ 8718D

Yr Regn: 2013 / Jan

Type: ☒ M. Car /

M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA LEXUS GS350

c.c. 3456

Colour:

GREY

A/C: Insured / Std / NI / NA

Sp. Reading:

57351

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTH861BL105024218

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ Inorder / ☐ Jammed / ☐ Leaked / ☐ Burnt orModi: Nil ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

235/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

16/04/19

D.O.I.

18/04/19

Survey held at

BORNEO MOTOR

Des. of Damages ☒ Fr / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

P/P - \$22863.60 (Red \$3870 / 14%)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

TOTAL

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Attn: Sustainability Check.

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH	L1	GRL10R	21/06/2013	SFZ8778D	0	17077 4TP/SFZ8778D/16041

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019 4.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN:16.04.19 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:		n/c		50 80.00
2	Z	BP-SUNDRY TOWING IN CHARGE.				380.00
3	B	BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT)				216.50
4	B	BP-LAB3 REMOVE/REFIX FRONT PARKING SENSORS. (NETT)				216.50
5	B	BP-MECH3 REMOVE/REFIX AIR-CON CONDENSER, RECEIVER DRYER, GAS PIPES TO ENABLE REPAIRING, REFIT AND REGAS.				Xm? 866.00
6	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS AND FIT NEW PARTS.				2598 3464.00
7	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1835 2597.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2019

TIME 10:55

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MP 8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETON L1	GRL10R	21/06/2013	SFZ8778D	0	17077	4TP/SFZ8778D/16041

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019 4.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
8	2	BP-SLANT SUPPLY SEALANT (NETT)				100.00
9	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)				216.50
10	L	BP-LPO SUPPLY REGN PLATE (PG# FRONT (NETT))				96.00
11	1	L53301-30491 HOOD SUB-ASSY	1.00	2754.60		2754.60
12	2	T90467-09050 CLIP	11.00	2.40		26.40
13	3	L11293-31120 LABEL, ENGINE	1.00	4.20		4.20
14	4	T88723-42070 LABEL, COOLER	1.00	3.60		3.60
15	5	L53805-30203 SHIELD SUB-ASSY, 7x8	1.00	336.80		336.80
16	6	L53806-30203 SHIELD SUB-ASSY, LH	1.00	349.50		349.50
17	7	L53879-50010 RETAINER, FR FENDER	12.00	2.90		34.80
18	8	T90467-07214 CLIP	10.00	2.20		22.00
19	9	L81145-30F60 UNIT, HEADLAMP RH	1.00	3735.30		3735.30
20	0	L81185-30F60 UNIT, HEADLAMP LH	1.00	3735.30		3735.30
21	1	L53119-30260 PROTECTOR RADIATOR	1.00	66.10		66.10
22	2	L53111-30D90 GRILLE, RADIATOR	1.00	981.30		981.30
23	3	L53115-30070 BRACKET, GRILLE	1.00	24.70		24.70
24	4	T53149-46010 PROTECTOR, RADIATOR	1.00	3.10		3.10
25	5	L90975-02125 EMBLEM, SYMBOL	1.00	472.10		472.10
26	6	L52711-30270 MOULDING, RADIATOR GR	1.00	379.20		379.20

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 17/04/2019
TIME 10:55

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

**TAX INVOICE**Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE****Borneo Motors (Singapore) Pte Ltd**www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH	L1	GRL10R	21/06/2013	SFZ8778D	0	17077 :4TP/SFZ8778D/16041'

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019	4.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
27	7	S52161-OK040 BUMPER CLIPS <i>acc</i>	9.00	4.00		36.00 ✓
28	8	L52535-30230 RETAINER, FR BUMPER <i>acc</i>	1.00	74.20		74.20 ✓
29	9	L52536-30220 RETAINER, FR BUMPER <i>acc</i>	1.00	74.20		74.20 ✓
30	0	L52115-30150 SUPPORT, FR BUMPER <i>acc</i>	1.00	63.80		63.80 ✓
31	1	L52116-30100 SUPPORT, FR BUMPER <i>acc</i>	1.00	63.80		63.80 ✓
32	2	L52115-30140 SUPPORT, FR BUMPER <i>acc</i>	1.00	35.50		35.50 ✓
33	3	L52116-30090 SUPPORT, FR BUMPER <i>acc</i>	1.00	35.50		35.50 ✓
34	4	L52611-30420 ABSORBER, FR BUMPER <i>acc</i>	1.00	126.00		126.00 ✓
35	5	L52119-3A932 COVER, FR BUMPER <i>acc</i>	1.00	965.40		965.40 ✓
36	6	L52421-30110 PAD, FR BUMPER <i>acc</i>	1.00	5.90		5.90 ✓
37	7	L52129-30907 COVER, FR BUMPER <i>acc</i>	1.00	20.90		20.90 ✓
38	8	L53112-30240 GRILLE, RADIATOR LWR <i>acc</i>	1.00	183.50		183.50 ✓
39	9	L52114-30230 BRACKET, EXTENTION <i>acc</i>	1.00	159.20		159.20 ✓
40	0	L53141-30160 GARNISH, RADIATOR <i>acc</i>	1.00	69.60		69.60 ✓
41	1	L53142-30060 GARNISH, RADIATOR <i>acc</i>	1.00	79.60		79.60 ✓
42	2	L81481-30110 COVER, FOG LAMP RH <i>acc</i>	1.00	90.80		90.80 ✓
43	3	L81482-30150 COVER, FOG LAMP LH <i>acc</i>	1.00	90.80		90.80 ✓
44	4	L52535-50060 FRT BUMPER RETAINER, <i>acc</i>	2.00	8.70		17.40 ✓
45	5	L53879-30050 RETAINER, FR FENDER <i>acc</i>	4.00	16.80		67.20 ✓
46	6	L47749-50090 CLIP <i>acc</i>	4.00	1.50		6.00 ✓

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 17/04/2019
TIME 10:55

VEHICLE NO SF28778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Inchcape

Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MP 8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH	L1	21/06/2013	SFZ8778D	0	17077	4TP/SFZ8778D/16041
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019	4.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
47	7	T81210-0D042 R/FRT FOG LAMP ASSY <i>3x7.5x1</i>	1.00	306.30		306.30
48	8	T81220-0D042 L/FRT FOG LAMP ASSY <i>3x5x1</i>	1.00	306.30		306.30
49	9	L85353-30090 B1 COVER, HEADLAMP <i>3x5x1</i>	1.00	14.10		14.10
50	0	L85207-30060 ACTUATOR SUB-ASSY <i>3x5x1</i>	1.00	586.00		586.00
51	1	L89341-76010 B3 SENSOR, ULTRASONIC <i>3x5x1</i>	2.00	490.80		981.60
52	2	L89348-30030 B1 RETAINER, ULTRASONIC <i>3x5x1</i>	4.00	21.70		86.80
53	3	L89348-35030 CLIP, ULTRASONIC <i>3x5x1</i>	2.00	3.70		7.40
54	4	L82114-30200 WIRE, ENGINE ROOM <i>3x5x1</i>	1.00	122.80		122.80
55	5	L53217-30903 BRACE, HOOD LOCK <i>3x5x1</i>	1.00	79.60		79.60
56	6	L53153-30200 GUIDE RADIATOR <i>3x5x1</i>	1.00	106.40		106.40
57	7	L53154-30190 GUIDE RADIATOR <i>3x5x1</i>	1.00	99.70		99.70
58	8	L53289-30180 COVER RADIATOR <i>3x5x1</i>	1.00	586.70		586.70
59	9	T90467-07217 CLIP <i>3x5x1</i>	11.00	2.10		23.10

LKK Auto Consultants hence notify the Repairer of the following:

- To reserve before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	26,733.60
Acknowledged by Customer	Please acknowledge receipt of vehicle	Parts 18,501.10	GST 7.00%	1,871.35
Signature:		Labour 8,136.50	Less	0.00
Date:		Materials 96.00		
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	28,604.95

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

27,439.80

Asher



Attn: Rasul
*Final Bill

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9
ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007/ICLPI1	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 15/05/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH	L1	GRL10R	21/06/2013	SFZ8778D	57351	17077 :4DS/SFZ8778D/16041'
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019	4.00	15/05/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P ins.:LONPAC ACC DATE:16.04.19 T/P VEHICLE NO.:SLF9224M TOW-IN:16.04.19 DATE SURVEY:18.04.19 NO OF REPAIR DAYS:7 DAYS BY:RASUL (LKK) *DIRECT SETTLEMENT*				50.00 ✓
2	Z	BP-SUNDRY TOWING IN CHARGE.				380.00 ✓
3	B	BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT)	*			216.50 ✓
4	B	BP-LAB3 REMOVE/REFIX FRONT PARKING SENSORS. (NETT)	*			216.50 ✓
5	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS AND FIT NEW PARTS.	*			2598.00 ✓
6	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.	*			1855.00 ✓
7	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00 ✓
8	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)	*			216.50 ✓
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/05/2019
TIME 15:23

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchcape

Borneo Motors

**TAX INVOICE**

Co Reg No : 196700086Z
 GST Reg No : MR-8500000-9
ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
 No.2 Pandan Crescent
 Singapore 128462
 Tel no.: 6631 1388

Account Detail		Account No S1000007/ICLPI1		Customer Detail																	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		Document No 0		Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050																	
		Document Date 15/05/2019																			
		<table border="1"> <thead> <tr> <th>Year</th> <th>Make</th> <th>Model</th> <th>Reg Date</th> <th>Veh Reg No</th> <th>Kilometers</th> <th>WIP No</th> <th>Order No/Remarks</th> </tr> </thead> <tbody> <tr> <td>13</td> <td>BETQH</td> <td>L1</td> <td>21/06/2013</td> <td>SFZ8778D</td> <td>57351</td> <td>17077</td> <td>4DS/SFZ8778D/16041</td> </tr> </tbody> </table>						Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	13	BETQH	L1	21/06/2013	SFZ8778D	57351
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks														
13	BETQH	L1	21/06/2013	SFZ8778D	57351	17077	4DS/SFZ8778D/16041														
Chassis No		Engine No		Terms		Lexus Consultant		Vehicle In		Collected On											
JTHBE1BL105024218		2GR8804191		60		Wally Tan G H		16/04/2019		4.00 15/05/2019 18.00											
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount												
9	L	BP-LPO SUPPLY REGN PLATE (PO#4183) E33							96.00 ✓												
		FRONT (NETT)																			
10	1	L11293-31120 LABEL, ENGINE				1.00	4.20		4.20 ✓												
11	2	T88723-42070 LABEL, COOLER				1.00	3.60		3.60 ✓												
12	3	L53301-30491 HOOD SUB-ASSY				1.00	2754.60		2754.60 ✓												
13	4	T90467-09050 CLIP				11.00	2.40		26.40 ✓												
14	5	L81145-30F60 UNIT, HEADLAMP RH**				1.00	3735.30		3735.30 ✓												
15	6	L81185-30F60 UNIT, HEADLAMP LH**				1.00	3735.30		3735.30 ✓												
16	7	L53111-30D90 GRILLE, RADIATOR				1.00	981.30		981.30 ✓												
17	8	L53115-30070 BRACKET, GRILLE				1.00	24.70		24.70 ✓												
18	9	L90975-02125 EMBLEM, SYMBOL				1.00	472.10		472.10 ✓												
19	0	L52711-30270 MOULDING, RADIATOR GR				1.00	379.20		379.20 ✓												
20	1	S52161-OK040 PIECE, RR BUMPER				9.00	4.00		36.00 ✓												
21	2	L52535-30230 RETAINER, FR BUMPER				1.00	74.20		74.20 ✓												
22	3	L52536-30220 RETAINER, FR BUMPER				1.00	74.20		74.20 ✓												
23	4	L52115-30150 SUPPORT, FR BUMPER				1.00	63.80		63.80 ✓												
24	5	L52116-30100 SUPPORT, FR BUMPER				1.00	63.80		63.80 ✓												
25	6	L52115-30140 SUPPORT, FR BUMPER				1.00	35.50		35.50 ✓												
26	7	L52116-30090 SUPPORT, FR BUMPER				1.00	35.50		35.50 ✓												
27	8	L52611-30420 ABSORBER, FR BUMPER				1.00	126.00		126.00 ✓												
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.																					
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total															
		Please acknowledge receipt of vehicle		Parts Labour Materials Lubrication/Fluid Others		Less															
						Amount Due															

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
 VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/05/2019
 TIME 15:23

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
 FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Inchape

Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : M8500000-9

ESTIMATE



Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail		Account No S1000007 / ICLPI1		Customer Detail	
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia		Document No 0		Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050	
		Document Date 15/05/2019			

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH	L1	GRL10R	21/06/2013	SFZ8778D	57351	17077 4DS/SFZ8778D/16041

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019	4.00 15/05/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
28	9	L52119-3A932 COVER, FR BUMPER	1.00	965.40		965.40 ✓
29	0	L52421-30110 FRONT BUMPER PAD,	1.00	5.90		5.90 ✓
30	1	L53112-30240 GRILLE, RADIATOR LWR	1.00	183.50		183.50 ✓
31	2	L52535-50060 RETAINER, FR BUMPER2	2.00	8.70		17.40 ✓
32	3	L89341-76010 B3 SENSOR, ULTRASONIC	2.00	490.80		981.60 ✓
33	4	L89348-30030 B1 RETAINER, ULTRASONIC	4.00	21.70		86.80 ✓
34	5	L89348-35030 CLIP, ULTRASONIC	2.00	3.70		7.40 ✓
35	6	L53217-30903 BRACE, HOOD LOCK	1.00	79.60		79.60 ✓
36	7	L52129-30907 COVER, FR BUMPER	1.00	20.90		20.90 ✓
37	8	L52114-30230 BRACKET, EXTENTION	1.00	159.20		159.20 ✓
38	9	L85207-30060 ACTUATOR SUB-ASSY	1.00	586.00		586.00 ✓
39	0	L82114-30200 WIRE, ENGINE ROOM	1.00	122.80		122.80 ✓
40	1	L53289-30180 COVER RADIATOR	1.00	586.70		586.70 ✓
41	2	L51410-30090 COVER, ENGINE	1.00	670.70		670.70 (1)
42	3	T90981-13075 BULB2	1.00	35.50		35.50 (1)
						22,863.60
For & on behalf of Borneo Motors		Customer's Signature	Change Summary		Total	22,863.60
		Please acknowledge receipt of vehicle 	17,135.10		GST 7.00%	1,600.45
			5,632.50		Less	0.00
			96.00			
			0.00			
			0.00			

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 15/05/2019
TIME 15:23

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Attn: Rasul
* Supplementary *

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007 / ICLPI1	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 15/05/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH	L1	GRL10R	21/06/2013	SFZ8778D	0	17194 SFZ8778D
Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On		
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUPPLEMENTARY T/P INS.: LONPAC ACC DATE: 16.04.19 T/P VEHICLE NO.: SLF9224M TOW-IN: 16.04.19 DATE SURVEY: 18.04.19 NO OF REPAIR DAYS: 7 DAYS BY: RASUL (LKK) *DIRECT SETTLEMENT*				
2	1	L51410-30090 COVER, ENGINE	1.00	670.70		670.70
3	2	T90981-13075 BULB	1.00	35.50		35.50
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	706.20
	Please acknowledge receipt of vehicle	Parts	GST 7.00%	49.43
		Labour	Less	0.00
		Materials		
		Lubrication/Fluid		
		Others	Amount Due	755.63

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SFZ8778D

CUSTOMER

DATE 15/05/2019
TIME 17:36

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



After Serviceability Check.

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH	L1	GRL10R	21/06/2013	SFZ8778D	0	17077 :4TP/SFZ8778D/16041

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019 4.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN:16.04.19 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 88.00
2	Z	BP-SUNDRY TOWING IN CHARGE.				380.00
3	B	BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT)				216.50
4	B	BP-LAB3 REMOVE/REFIX FRONT PARKING SENSORS. (NETT)				216.50
5	B	BP-MECH3 REMOVE/REFIX AIR-CON CONDENSER, RECEIVER DRYER, GAS PIPES TO ENABLE REPAIRING, REFIT AND REGAS.				? 866.00
6	B	BP-LAB3 REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS AND FIT NEW PARTS.				2598 3464.00
7	B	BP-RES3 SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.				1855 2597.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2019
TIME 10:55

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MP-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No S1000020 / TPCLAIM	Customer Detail
THIRD PARTY CLAIM	Document No 0	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH L1	GRL10R	21/06/2013	SFZ8778D	0	17077	4TP/SFZ8778D/16041

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019 4.00	--/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
8	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00
9	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)				216.50
10	L	BP-LPO SUPPLY REGN PLATE (PO#)				96.00
		FRONT (NETT)				
11	1	L53301-30491 HOOD SUB-ASSY	1.00	2754.60		2754.60
12	2	T90467-09050 CLIP	11.00	2.40		26.40
13	3	L11293-31120 LABEL, ENGINE	1.00	4.20		4.20
14	4	T88723-42070 LABEL, COOLER	1.00	3.60		3.60
15	5	L53805-30203 SHIELD SUB-ASSY, ?	1.00	336.80		336.80
16	6	L53806-30203 SHIELD SUB-ASSY, LH	1.00	349.50		349.50
17	7	L53879-50010 RETAINER, FR FENDER	12.00	2.90		34.80
18	8	T90467-07214 CLIP	10.00	2.20		22.00
19	9	L81145-30F60 UNIT, HEADLAMP RH	1.00	3735.30		3735.30
20	0	L81185-30F60 UNIT, HEADLAMP LH	1.00	3735.30		3735.30
21	1	L53119-30260 PROTECTOR RADIATOR	1.00	66.10		66.10
22	2	L53111-30D90 GRILLE, RADIATOR	1.00	981.30		981.30
23	3	L53115-30070 BRACKET, GRILLE	1.00	24.70		24.70
24	4	T53149-46010 PROTECTOR, RADIATOR	1.00	3.10		3.10
25	5	L90975-02125 EMBLEM, SYMBOL	1.00	472.10		472.10
26	6	L52711-30270 MOULDING, RADIATOR GR	1.00	379.20		379.20

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2019
TIME 10:55

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETQH	L1	GRL10R	21/06/2013	SFZ8778D	0	17077 4TP/SFZ8778D/16041

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019	4.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
27	7	S52161-0K040 BUMPER CLIPS <i>acc</i>	9.00	4.00		36.00
28	8	L52535-30230 RETAINER, FR BUMPER <i>acc</i>	1.00	74.20		74.20
29	9	L52536-30220 RETAINER, FR BUMPER <i>acc</i>	1.00	74.20		74.20
30	0	L52115-30150 SUPPORT, FR BUMPER <i>acc</i>	1.00	63.80		63.80
31	1	L52116-30100 SUPPORT, FR BUMPER <i>acc</i>	1.00	63.80		63.80
32	2	L52115-30140 SUPPORT, FR BUMPER <i>acc</i>	1.00	35.50		35.50
33	3	L52116-30090 SUPPORT, FR BUMPER <i>acc</i>	1.00	35.50		35.50
34	4	L52611-30420 ABSORBER, FR BUMPER <i>acc</i>	1.00	126.00		126.00
35	5	L52119-3A932 COVER, FR BUMPER <i>acc</i>	1.00	965.40		965.40
36	6	L52421-30110 PAD, FR BUMPER <i>acc</i>	1.00	5.90		5.90
37	7	L52129-30907 COVER, FR BUMPER <i>acc</i>	1.00	20.90		20.90
38	8	L53112-30240 GRILLE, RADIATOR LWR <i>acc</i>	1.00	183.50		183.50
39	9	L52114-30230 BRACKET, EXTENTION <i>acc</i>	1.00	159.20		159.20
40	0	L53141-30160 GARNISH, RADIATOR <i>acc</i>	1.00	69.60		69.60
41	1	L53142-30060 GARNISH, RADIATOR <i>acc</i>	1.00	79.60		79.60
42	2	L81481-30110 COVER, FOG LAMP RH <i>acc</i>	1.00	90.80		90.80
43	3	L81482-30150 COVER, FOG LAMP LH <i>acc</i>	1.00	90.80		90.80
44	4	L52535-50060 FRT BUMPER RETAINER, <i>acc</i>	2.00	8.70		17.40
45	5	L53879-30050 RETAINER, FR FENDER <i>acc</i>	4.00	16.80		67.20
46	6	L47749-50090 CLIP <i>acc</i>	4.00	1.50		6.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2019
TIME 10:55

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : 85900000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD-PARTY CLAIM	S1000020 / TPCLAIM	Mr Mitesh Kumar 116 Pasir Ris Street 11 #03-553 Singapore 510116 Mobile: 90263050
	Document No 0	
	Document Date 17/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
13	BETOH	L1	21/06/2013	SFZ8778D	0	17077	4TP/SFZ8778D/16041

Chassis No	Engine No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBE1BL105024218	2GR8804191	60	Wally Tan G H	16/04/2019	4.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
47	7	T81210-0D042 R/FRT FOG LAMP ASSY <i>347?</i>	1.00	306.30		306.30
48	8	T81220-0D042 L/FRT FOG LAMP ASSY <i>X</i>	1.00	306.30		306.30
49	9	L85353-30090 B1 COVER, HEADLAMP <i>?</i>	1.00	14.10		14.10
50	0	L85207-30060 ACTUATOR SUB-ASSY <i>?</i>	1.00	586.00		586.00
51	1	L89341-76010 B3 SENSOR, ULTRASONIC <i>mis</i>	2.00	490.80		981.60
52	2	L89348-30030 B1 RETAINER, ULTRASONIC <i>ne</i>	4.00	21.70		86.80
53	3	L89348-35030 CLIP, ULTRASONIC <i>ne</i>	2.00	3.70		7.40
54	4	L82114-30200 WIRE, ENGINE ROOM, <i>?</i>	1.00	122.80		122.80
55	5	L53217-30903 BRACE, HOOD LOCK <i>?</i>	1.00	79.60		79.60
56	6	L53153-30200 GUIDE RADIATOR <i>?</i>	1.00	106.40		106.40
57	7	L53154-30190 GUIDE RADIATOR <i>?</i>	1.00	99.70		99.70
58	8	L53289-30180 COVER RADIATOR <i>?</i>	1.00	586.70		586.70
59	9	T90467-07217 CLIP <i>?</i>	11.00	2.10		23.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis.

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	26,733.60
Acknowledged by Borneo Motors Signature: <i>[Signature]</i> Date: <i>18/04/19</i>	Please acknowledge receipt of vehicle	Parts 18,501.10 Labour 8,136.50 Materials 96.00 Lubrication/Fluid 0.00 Others 0.00	GST 7.00%	1,871.35
			Less	0.00
			Amount Due	28,604.95

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 17/04/2019
TIME 10:56

VEHICLE NO SFZ8778D

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/19/19VP05/021688
Our ref: CC4/LPC19007018/R1ea3

Date: 30/04/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SFZ 8778D


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 18/04/2019 at the premises of M/s Borneo Motors (S) Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	26,733.60
Revised Estimate Amount	: S\$	20,684.90
"Check" Items Amount	: S\$	3,883.60
Total (Including Check Items)	: S\$	24,568.50
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 6~7 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Thursday, 18 April, 2019 12:56 PM
To: Suraidah B Saidi PTCBC; assignments@lkkauto.com; Admin-D (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: Our Ref: 18/19/19VP05/021688 Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M DOA 16.04.2019 [External General]
Attachments: SFZ8778D_GIA Rpt_Est Inv_Damaged Photos.pdf

Lonpac External - General

person: wally

Time: 1.13 p.m

v: In .

E: ✓

Without Prejudice


Dear Suraidah

Please liaise with LKK Auto Consultants Pte Ltd for survey.

Dear Nivitha

FYA

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Suraidah B Saidi PTCBC [mailto:SuraidahB.Saidi@inchcape.com.sg]
Sent: Thursday, 18 April, 2019 11:23 AM
To: MT_Claim_SG
Cc: GERALD POH WEE BIN; ONG LI LI
Subject: Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M DOA 16.04.2019

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured **SLF9224M** thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with **Car Rental of @ \$150/day x no. of days** as recommended by your appointed surveyor.

Kindly have your surveyor contact our Motor Claim Accessor, **Wally Tan @ 9847 6178 / 6631 1506** located at **2 Pandan Crescent, Level 4** for an appointment to inspect our client's vehicle (currently vehicle is NOT in the workshop).

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you.

Warmest Regards,

SURAIDAH

TPR TEAM, CLAIMS DEPT

D: 6631 1887 | F: 6872 7260 | E: suraidahb.saidi@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

Mei Kwan (LKKAuto)

From: Mei Kwan (LKKAuto)
Sent: Friday, 3 May, 2019 1:38 PM
To: ONG LI LI
Cc: MT_Claim_SG; CS A Team; Admin A; Asher Sng (LKKAuto)
Subject: RE: Our Ref: 18/19/19VP05/021688 Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M DOA 16.04.2019 [External General]
Attachments: TP ESTIMATE - MARKED.pdf; Preliminary Advice.pdf
Categories: HMK

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

LPC ref: 18/19/19VP05/021688
LKK REF: CC4/LPC19007018/R1ea3

Dear Sir / Madam,

We refer to the above matter.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

We have not authorized repairs.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 22 April, 2019 5:23 PM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>
Subject: RE: Our Ref: 18/19/19VP05/021688 Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M DOA 16.04.2019 [External General]


Lonpac External - General

Dear Mei Kwan

Please see attached.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: ONG LI LI
Sent: Thursday, 18 April, 2019 3:33 PM
To: 'Suraidah B Saidi PTCBC'; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: MT_Claim_SG
Subject: RE: Our Ref: 18/19/19VP05/021688 Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M
DOA 16.04.2019 [External General]

Lonpac External - General

Without Prejudice

Dear Suraidah


Please liaise with LKK Auto Consultants Pte Ltd for assessment of liability as well.

All correspondences should be forward to them for handling.

Dear Nivitha

Fya

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Suraidah B Saidi PTCBC [<mailto:SuraidahB.Saidi@inchcape.com.sg>]
Sent: Thursday, 18 April, 2019 3:29 PM
To: ONG LI LI
Subject: RE: Our Ref: 18/19/19VP05/021688 Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M
DOA 16.04.2019 [External General]

Dear Li Li,

Please be inform that our client vehicle has been survey by LKK today.
Hence, appreciate if you could revert on the liability the soonest.

Thank you.

Warmest Regards,

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured **SLF9224M** thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with **Car Rental of @ \$150/day x no. of days** as recommended by your appointed surveyor.

Kindly have your surveyor contact our Motor Claim Accessor, **Wally Tan @ 9847 6178 / 6631 1506** located at **2 Pandan Crescent, Level 4** for an appointment to inspect our client's vehicle (currently vehicle is NOT in the workshop).

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you.

Warmest Regards,

SURAIDAH

TPR TEAM, CLAIMS DEPT

D: 6631 1887 | F: 6872 7260 | E: suraidahb.saidi@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.



AVG

This email has been checked for viruses by AVG antivirus software.

www.avg.com

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 21 May 2019 10:03 AM
To: SuraidahB.Saidi@inchcape.com.sg
Subject: RE: Our Ref: 18/19/19VP05/021688 Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M DOA 16.04.2019 [External General]

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents to us (LKK) to proceed on negotiate settlement.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)


From: ONG LI LI [<mailto:llong@lonpac.com>]
Sent: Thursday, 18 April 2019 3:52 PM
To: Suraidah B Saidi PTCBC <SuraidahB.Saidi@inchcape.com.sg>; assignments@lkkauto.com; Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: Our Ref: 18/19/19VP05/021688 Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M DOA 16.04.2019 [External General]

Lonpac External - General
Without Prejudice

Dear Sir/Mdm

Please check & confirm date of accident.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: ONG LI LI
Sent: Thursday, 18 April, 2019 3:33 PM
To: 'Suraidah B Saidi PTCBC'; assignments@lkkauto.com; 'Admin-D (LKKAuto)'
Cc: MT_Claim_SG
Subject: RE: Our Ref: 18/19/19VP05/021688 Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M DOA 16.04.2019 [External General]

Lonpac External - General

Without Prejudice

Dear Suraidah


Please liaise with LKK Auto Consultants Pte Ltd for assessment of liability as well.

All correspondences should be forward to them for handling.

Dear Nivitha

Fya

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Suraidah B Saidi PTCBC [<mailto:SuraidahB.Saidi@inchcape.com.sg>]
Sent: Thursday, 18 April, 2019 3:29 PM

To: ONG LI LI

Subject: RE: Our Ref: 18/19/19VP05/021688 Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M DOA
16.04.2019 [External General]

Dear Li Li,

Please be inform that our client vehicle has been survey by LKK today.
Hence, appreciate if you could revert on the liability the soonest.

Thank you.

Warmest Regards,

SURAIDAH

TPR TEAM, CLAIMS DEPT

D: 6631 1887 | F: 6872 7260 | E: suraidahb.saidi@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

From: ONG LI LI <llong@lonpac.com>

Sent: Thursday, 18 April 2019 12:56 PM

To: Suraidah B Saidi PTCBC <SuraidahB.Saidi@inchcape.com.sg>; assignments@lkkauto.com; Admin-D (LKKAuto) <admin-d@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: Our Ref: 18/19/19VP05/021688 Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M DOA
16.04.2019 [External General]

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

Lonpac External - General

Without Prejudice

Dear Suraidah

Please liaise with LKK Auto Consultants Pte Ltd for survey.

Dear Nivitha

FYA

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



Lonpac External - General data is for internal / external use.

From: Suraidah B Saidi PTCBC [mailto:SuraidahB.Saidi@inchcape.com.sg]
Sent: Thursday, 18 April, 2019 11:23 AM
To: MT_Claim_SG
Cc: GERALD POH WEE BIN; ONG LI LI
Subject: Direct Settlement (WT) - Accident Involving SFZ8778D & SLF9224M DOA 16.04.2019

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured **SLF9224M** thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with **Car Rental of @ \$150/day x no. of days** as recommended by your appointed surveyor.

Kindly have your surveyor contact our Motor Claim Accessor, **Wally Tan @ 9847 6178 / 6631 1506** located at **2 Pandan Crescent, Level 4** for an appointment to inspect our client's vehicle (currently vehicle is NOT in the workshop).

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you.

Warmest Regards,
SURAIDAH
TPR TEAM, CLAIMS DEPT
D: 6631 1887 | F: 6872 7260 | E: suraidahb.saidi@inchcape.com.sg
Inchcape Centre
Level 4, Bodycare Centre
2 Pandan Crescent
Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19007018/R1da3s2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 26-12-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 9224M	Veh. Inspected	SFZ 8778D
Policy No.	Z18VP05020052	Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021688	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	18/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA LEXUS GS350	c.c	3456
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTHBE1BL105024218	Colour	GREY
Odometer	57351	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/45 R18	MICHELIN	6 mm
L/H Front Tyre	235/45 R18	MICHELIN	6 mm
R/H Rear Tyre	235/45 R18	MICHELIN	6 mm
L/H Rear Tyre	235/45 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/04/2019	Inspection Date	18/04/2019
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFZ 8778D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	HOOD SUB-ASSY (SN)	BENT	2,754.60	2,754.60
11	CLIP (SN)	NECESSARY	26.40	26.40
1	LABEL, ENGINE (SN)	NECESSARY	4.20	4.20
1	LABEL, COOLER (SN)	NECESSARY	3.60	3.60
1	SHIELD SUB-ASSY, (SN)	SERVICEABLE	336.80	-
1	SHIELD SUB-ASSY, LH (SN)	SERVICEABLE	349.50	-
12	RETAINER, FR FENDER (SN)	NOT NECESSARY	34.80	-
10	CLIP (SN)	NOT NECESSARY	22.00	-
1	UNIT, HEADLAMP RH (SN)	SCRATCHED	3,735.30	3,735.30
1	UNIT, HEADLAMP LH (SN)	SCRATCHED	3,735.30	3,735.30
1	PROTECTOR RADIATOR (SN)	NOT NECESSARY	66.10	-
1	GRILLE, RADAITOR (SN)	SCRATCHED	981.30	981.30
1	BRACKET, GRILLE (SN)	NECESSARY	24.70	24.70
1	PROTECTOR, RADIATOR (SN)	NOT NECESSARY	3.10	-
1	EMBLEM, SYMBOL (SN)	NECESSARY	472.10	472.10
1	MOULDING, RADIATOR GR (SN)	SCRATCHED	379.20	379.20
9	BUMPER CLIPS (SN)	NECESSARY	36.00	36.00
1	RETAINER, FR BUMPER (SN)	NECESSARY	74.20	74.20
1	RETAINER, FR BUMPER (SN)	NECESSARY	74.20	74.20
1	SUPPORT, FR BUMPER (SN)	NECESSARY	63.80	63.80
1	SUPPORT, FR BUMPER (SN)	NECESSARY	63.80	63.80
1	SUPPORT, FR BUMPER (SN)	NECESSARY	35.50	35.50
1	SUPPORT, FR BUMPER (SN)	NECESSARY	35.50	35.50
1	ABSORBER, FR BUMPER (SN)	MISSING	126.00	126.00
1	COVER, FR BUMPER (SN)	DEFORMED	965.40	965.40
1	PAD, FR BUMPER (SN)	NECESSARY	5.90	5.90
1	COVER, FR BUMPER (SN)	MISSING	20.90	20.90
1	GRILLE, RADIATOR LWR (SN)	DEFORMED	183.50	183.50
1	BRACKET, EXTENTION (SN)	BENT	159.20	159.20
1	GARNISH, RADIATOR (SN)	SERVICEABLE	69.60	-
1	GARNISH, RADIATOR (SN)	SERVICEABLE	79.60	-

Report Ref No. CC4/LPC19007018/R1da3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COVER, FOG LAMP RH (SN)	SERVICEABLE	90.80	-
1	COVER, FOG LAMP LH (SN)	SERVICEABLE	90.80	-
2	FRT BUMPER RETAINER (SN)	NECESSARY	17.40	17.40
4	RETAINER, FR FENDER (SN)	NOT NECESSARY	67.20	-
4	CLIP (SN)	NOT NECESSARY	6.00	-
1	R/FRT FOG LAMP ASSY (SN)	SERVICEABLE	306.30	-
1	L/FRT FOG LAMP ASSY (SN)	SERVICEABLE	306.30	-
1	COVER, HEADLAMP (SN)	SERVICEABLE	14.10	-
1	ACTUATOR SUB-ASSY (SN)	CRACKED	586.00	586.00
2	SENSOR, ULTRASONIC (SN)	MISSING	981.60	981.60
4	RETAINER, ULTRASONIC (SN)	NECESSARY	86.80	86.80
2	CLIP, ULTRASONIC (SN)	NECESSARY	7.40	7.40
1	WIRE, ENGINE ROOM (SN)	CUT	122.80	122.80
1	BRACE, HOOD LOCK (SN)	BENT	79.60	79.60
1	GUIDE RADIATOR (SN)	SERVICEABLE	106.40	-
1	GUIDE RADIATOR (SN)	SERVICEABLE	99.70	-
1	COVER RADIATOR (SN)	CUT	586.70	586.70
11	CLIP (SN)	NOT NECESSARY	23.10	-
1	SUNDRIES (SN)	NECESSARY	80.00	50.00
1	SEALANT (SN)	NECESSARY	100.00	100.00
1	REGN PLATE FRONT (SN)	MISSING	96.00	96.00
1	COVER, ENGINE (SN) (ADDITIONAL)	DEFORMED	670.70	670.70
1	BULB (SN) (ADDITIONAL)	MISSING	35.50	35.50
			19,483.30	17,381.10
	LABOUR			
	TOWING CHARGES.		380.00	380.00
	CHECK WIRING SYSTEM AND FOCUS HEADLAMP.		216.50	216.50
	REMOVE / REFIX FRONT PARKING SENSORS.		216.50	216.50
	REMOVE / REFIX AIR-CON CONDENSER, RECEIVER DRYER, GAS PIPES TO ENABLE REPAIRING, REFIT AND REGAS.	NOT NECESSARY	866.00	-
	REMOVE ALL NECESSARY PARTS, TO ENABLE REPAIRING AND STRAIGHTEN FRONT SUPPORT PANEL, R/H AND L/H HEADLAMP PANELS AND FIT NEW PARTS.		3,464.00	2,598.00

Report Ref No. CC4/LPC19007018/R1da3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPRAY PAINT ON DAMAGED AFFECTED PORTION OF CAR.		2,597.00	1,855.00
	TO RESET ECU & REPROGRAMME.		216.50	216.50
			7,956.50	5,482.50
GRAND TOTAL			27,439.80	22,863.60
RECOMMENDED COST OF REPAIRS				22,863.60

Report Ref No. CC4/LPC19007018/R1da3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.