

1562100

INS. CASE OWNER:

Richard
RahulCC 4 ASM
AXA1900TODS, P27
6/3/19LKK:
IDAC:

Surveyor:

DOI:

ASSIGNMENT

M/4/19

Date / Time:

M/4/19

Registered in Merimen:

Pre-assign / CCU / FTE

SGU 13155



Insured Vehicle No.:

Claim No.:

S9M0208 / 11715

Name of Insured:

NEO LAM KHANUN

Policy No.:

GA336 44511

Insured Tel No.:

HP:

Make / Model:

SUZUKI

Excess Sec II :SS

D.O.A.:

Place of Accident:

SIN MINH ANG

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Young Hui Pang Dennis

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SHC 9805M

INSRS:
WSP:
Tel:
Liability:
RMKS:Ding
AutoINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/ Time

SHC 9805M - 4

Squawes - 4

STAGE

DATE / PIC

Non-Reporting ltr (1st)

Non-Reporting ltr (2nd)

Non-Reporting ltr (Final)

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

02/07/19 - Jimmy

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

2/7/19

*S. m. t. claim
to call OICalled both OI & OZO but no
answer, proceed to send letter msi.

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

27

Front to
rear

If NO or B 28, Ass, Lia:

Repair Cost:

SS

4761.50

Loss of Rental (LOR):

SS

591.84

(6 days) x

98.64

Loss of Use (LOU):

SS

300.00

(S 50 x 6 days)

Loss of Income (LOI):

SS

-

(S x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☐

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost:

SS

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

5655.34

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

SS

5655.34

Name 1:

Ding Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COMMENT
6/8/19

Asher

TO :

ESTIMATE REPORT 1ST Quotation

FAX NO:

22/04/2019 9:45

JOB-NO: 50111585

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

CONTACT: 65533880
64739522

VEHICLE DETAILS

LICENSE NO: SHC7805M TRANS: AUTO
MAKE / MODEL: HYUNDAI / Sonata 2.0 CRDi
OWNER'S INSURER: MS First Capital Insurance Limited
JOB-CODE: TP SA: Ding Auto User 1

CHASSIS: KMHET41VMDA834577
ENGINE: D4EAD306982

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REPAIR FENDER RH STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,600.00	0.00	1,600.00		Y	800
2 TO RUST PROOFING ON ACCIDENT AFFECTED AREAS	1.00	150.00	0.00	150.00		Y	60
3 TO APPLY SEAL JOINT ON WELDING AFFECTED AREAS	1.00	180.00	0.00	180.00		Y	60
4 REMOVE & REFIX REAR WINDSCREEN	1.00	150.00	0.00	150.00		Y	X
5 REMOVE & REFIX REVERSE SENSOR & CHECK WIRING	1.00	80.00	0.00	80.00		Y	60
6 REMOVE & REFIX REAR SEAT, SEAT BELT, SPARE TYRE COMPARTMENT PARTS	1.00	180.00	0.00	180.00		Y	X
7 REMOVE & REFIX BOOTLID COMPARTMENT	1.00	150.00	0.00	150.00		Y	X
8 RESPRAY REAR FENDER LH + FENDER RH	1.00	500.00	0.00	500.00		Y	200
9 RESPRAY REAR BUMPER + BUMPER LOWER	1.00	500.00	0.00	500.00		Y	200
10 RESPRAY REAR BUMPER PROTECTOR LH + PROTECTOR RH	1.00	400.00	0.00	400.00		Y	50
11 RESPRAY SPRAY TYRE PANEL + END PANEL	1.00	500.00	0.00	500.00		Y	400
12 RESPRAY SIDE PANEL LH +SIDE PANEL RH	1.00	400.00	0.00	400.00		Y	200
13 RESPRAY BOOTLID + DOOR REAR LH	1.00	500.00	0.00	500.00		Y	200
TOTAL:		5,290.00	0.00	5,290.00			

MATERIALS

1 BOOTLID repair	1.00	1,139.20	227.84	911.36	L	Y	
2 BOOTLID LOCK	1.00	109.45	21.89	87.56	L	Y	
3 BOOTLID CATCH	1.00	108.90	21.78	87.12	L	Y	
4 BOOTLID LOGO	1.00	21.54	4.31	17.23	L	Y	
5 BOOTLID EMBLEM "CRDI"	1.00	18.70	3.74	14.96	L	Y	
6 BOOTLID EMBLEM- HYUNDAI	1.00	28.12	5.62	22.50	L	Y	
7 BOOTLID EMBLEM -SONATA	1.00	40.92	8.18	32.74	L	Y	
8 BOOTLID LAMP LH	1.00	233.50	46.70	186.80	L	Y	
9 BOOTLID LAMP RH	1.00	233.50	46.70	186.80	L	Y	
10 BOOTLID SEAL STRIP LH	1.00	91.30	18.26	73.04	L	Y	
11 BOOTLID SEAL STRIP RH	1.00	91.30	18.26	73.04	L	Y	
12 BOOTLID DAMPER LH	1.00	114.50	22.90	91.60	L	Y	
13 BOOTLID DAMPER RH	1.00	114.50	22.90	91.60	L	Y	
14 BOOTLID WEATHER STRIP	1.00	124.50	24.90	99.60	L	Y	
15 BOOTLID INSULATOR	1.00	155.10	31.02	124.08	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
16 BUMPER REAR <i>pk</i>	1.00	523.93	104.79	419.14	L	Y	
17 BUMPER RETAINER REAR LH <i>re</i>	1.00	42.68	8.54	34.14	L	Y	
18 BUMPER RETAINER REAR RH <i>re</i>	1.00	42.68	8.54	34.14	L	Y	
19 BUMPER SPONGE REAR <i>2ea</i>	1.00	1,133.52	226.70	906.82	L	Y	
20 BUMPER REINFORCEMENT REAR <i>2ea</i>	1.00	462.30	92.46	369.84	L	Y	
21 REINFORCEMENT BRACKET REAR LH <i>pk</i>	1.00	79.75	15.95	63.80	L	Y	
22 REINFORCEMENT BRACKET REAR RH <i>pk</i>	1.00	79.75	15.95	63.80	L	Y	
23 BUMPER LOWER REAR <i>pk</i>	1.00	0.00	0.00	0.00	L	Y	
24 BUMPER PROTECTOR REAR LH <i>pk</i>	1.00	102.96	20.59	82.37	L	Y	
25 BUMPER PROTECTOR REAR RH <i>pk</i>	1.00	102.96	20.59	82.37	L	Y	
26 FENDER REAR LH <i>repair</i>	1.00	1,598.30	319.66	1,278.64	L	Y	
27 TAIL LAMP LH <i>X</i>	1.00	323.40	64.68	258.72	L	Y	
28 TAIL LAMP RH <i>ch</i>	1.00	323.40	64.68	258.72	L	Y	
29 END PANEL <i>pk</i>	1.00	338.29	67.66	270.63	L	Y	
30 END PANEL TOP GARNISH <i>pk</i>	1.00	52.02	10.40	41.62	L	Y	
31 SPARE TYRE PANEL <i>repair</i>	1.00	812.90	162.58	650.32	L	Y	
32 SPARE TYRE INNER TRIM LH <i>X</i>	1.00	164.14	32.83	131.31	L	Y	
33 SIDE PANEL REAR RH <i>repair</i>	1.00	229.30	45.86	183.44	L	Y	
34 SIDE PANEL REAR LH <i>repair</i>	1.00	229.30	45.86	183.44	L	Y	
35 BOOTLID STICKER -BOOKING 65521111 <i>re</i>	1.00	125.00	0.00	125.00	S	Y	
36 BOOTLID STICKER -CITYCAB <i>re</i>	1.00	100.00	0.00	100.00	S	Y	
37 BOOTLID INSULATOR CLIPS SET <i>re</i>	1.00	35.00	0.00	35.00	S	Y	
38 BUMPER PROTECTOR PAD REAR <i>re</i>	1.00	180.00	0.00	180.00	S	Y	
39 REVERSE SENSOR SET <i>re</i>	1.00	250.00	0.00	250.00	S	Y	
40 BUMPER CLIPS SET REAR <i>re</i>	1.00	35.00	0.00	35.00	S	Y	
41 FENDER SEALANT REAR <i>X</i>	1.00	50.00	0.00	50.00	S	Y	
42 WINDSCREEN SEALANT REAR <i>X</i>	1.00	50.00	0.00	50.00	S	Y	
43 END PANEL TOP GARNISH CLIPS <i>re</i>	1.00	35.00	0.00	35.00	S	Y	
44 END PANEL SEALANT <i>re</i>	1.00	50.00	0.00	50.00	S	Y	
45 SPARE TYRE PANEL SEALANT <i>X</i>	1.00	80.00	0.00	80.00	S	Y	
TOTAL:		10,256.61	853.32	8,403.29			

TOTAL PARTS & LABOUR :

15,546.61 1,853.32 13,693.29

EXCESS/LOADING:\$ \$ 0.00

No. Of Day:

*8 days*RE-SURVEY: BEFORE/ AFTER PAINTING
PART-BY-PART OF LUMP SUM \$ \$

DATE OF SURVEY:

22 / 04 / 19

SURVEYED BY:

Rasul

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00

*2732.05**2732.05**2230.00**615.00**5580.05**20%**4464.04**45-4, 450**8 days*

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

22/04/2019 9:45

JOB-NO: 50111585

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHC7805M TRANS: AUTO
 MAKE / MODEL: HYUNDAI / Sonata 2.0 CRDi
 OWNER'S INSURER: MS First Capital Insurance Limited
 JOB-CODE: TP SA: Ding Auto User 1

CHASSIS: KMHET41VMDA834577
 ENGINE: D4EAD306982

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO REPAIR FENDER RH .STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,600.00	0.00	1,600.00		Y	800
2 TO RUST PROOFING ON ACCIDENT AFFECTED AREAS	1.00	150.00	0.00	150.00		Y	60
3 TO APPLY SEAL JOINT ON WELDING AFFECTED AREAS	1.00	180.00	0.00	180.00		Y	60
4 REMOVE & REFIX REAR WINDSCREEN	1.00	150.00	0.00	150.00		Y	X
5 REMOVE & REFIX REVERSE SENSOR & CHECK WIRING	1.00	80.00	0.00	80.00		Y	60
6 REMOVE & REFIX REAR SEAT , SEAT BET , SPARE TYRE COMPARTMENT PARTS	1.00	180.00	0.00	180.00		Y	X
7 REMOVE & REFIX BOOTLID COMPARTMENT	1.00	150.00	0.00	150.00		Y	X
8 RESPRAY REAR FENDER LH + FENDER RH	1.00	500.00	0.00	500.00		Y	200
9 RESPRAY REAR BUMPER + BUMPER LOWER	1.00	500.00	0.00	500.00		Y	200
10 RESPRAY REAR BUMPER PROTECTOR LH + PROTECTOR RH	1.00	400.00	0.00	400.00		Y	50
11 RESPRAY SPRAY TYRE PANEL + END PANEL	1.00	500.00	0.00	500.00		Y	400
12 RESPRAY SIDE PANEL LH +SIDE PANEL RH	1.00	400.00	0.00	400.00		Y	200
13 RESPRAY BOOTLID + DOOR REAR LH	1.00	500.00	0.00	500.00		Y	200
TOTAL:		5,290.00	0.00	5,290.00			

MATERIALS

1 BOOTLID repair	1.00	1,139.20	227.84	911.36	L	Y	
2 BOOTLID LOCK	1.00	109.45	21.89	87.56	L	Y	
3 BOOTLID CATCH	1.00	108.90	21.78	87.12	L	Y	
4 BOOTLID LOGO	1.00	21.54	4.31	17.23	L	Y	
5 BOOTLID EMBLEM "CRDI"	1.00	18.70	3.74	14.96	L	Y	
6 BOOTLID EMBLEM- HYUNDAI	1.00	28.12	5.62	22.50	L	Y	
7 BOOTLID EMBLEM -SONATA	1.00	40.92	8.18	32.74	L	Y	
8 BOOTLID LAMP LH	1.00	233.50	46.70	186.80	L	Y	
9 BOOTLID LAMP RH	1.00	233.50	46.70	186.80	L	Y	
10 BOOTLID SEAL STRIP LH	1.00	91.30	18.26	73.04	L	Y	
11 BOOTLID SEAL STRIP RH	1.00	91.30	18.26	73.04	L	Y	
12 BOOTLID DAMPER LH	1.00	114.50	22.90	91.60	L	Y	
13 BOOTLID DAMPER RH	1.00	114.50	22.90	91.60	L	Y	
14 BOOTLID WEATHER STRIP	1.00	124.50	24.90	99.60	L	Y	
15 BOOTLID INSULATOR	1.00	155.10	31.02	124.08	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
16 BUMPER REAR <i>OK</i>	1.00	523.93	104.79	419.14	L	Y	
17 BUMPER RETAINER REAR LH <i>re</i>	1.00	42.68	8.54	34.14	L	Y	
18 BUMPER RETAINER REAR RH <i>re</i>	1.00	42.68	8.54	34.14	L	Y	
19 BUMPER SPONGE REAR <i>CRA</i>	1.00	1,133.52	226.70	906.82	L	Y	
20 BUMPER REINFORCEMENT REAR <i>re</i>	1.00	462.30	92.46	369.84	L	Y	
21 REINFORCEMENT BRACKET REAR LH <i>re</i>	1.00	79.75	15.95	63.80	L	Y	
22 REINFORCEMENT BRACKET REAR RH <i>re</i>	1.00	79.75	15.95	63.80	L	Y	
23 BUMPER LOWER REAR <i>re</i>	1.00	0.00	0.00	0.00	L	Y	
24 BUMPER PROTECTOR REAR LH <i>re</i>	1.00	102.96	20.59	82.37	L	Y	
25 BUMPER PROTECTOR REAR RH <i>X</i>	1.00	102.96	20.59	82.37	L	Y	
26 FENDER REAR LH <i>re repair</i>	1.00	1,598.30	319.66	1,278.64	L	Y	
27 TAIL LAMP LH <i>X</i>	1.00	323.40	64.68	258.72	L	Y	
28 TAIL LAMP RH <i>CRA</i>	1.00	323.40	64.68	258.72	L	Y	
29 END PANEL <i>re</i>	1.00	338.29	67.66	270.63	L	Y	
30 END PANEL TOP GARNISH <i>re</i>	1.00	52.02	10.40	41.62	L	Y	
31 SPARE TYRE PANEL <i>re</i>	1.00	812.90	162.58	650.32	L	Y	
32 SPARE TYRE INNER TRIM LH <i>X</i>	1.00	164.14	32.83	131.31	L	Y	
33 SIDE PANEL REAR RH <i>re</i>	1.00	229.30	45.86	183.44	L	Y	
34 SIDE PANEL REAR LH <i>re</i>	1.00	229.30	45.86	183.44	L	Y	
35 BOOTLID STICKER -BOOKING 65521111 <i>re</i>	1.00	125.00	0.00	125.00 80	S	Y	
36 BOOTLID STICKER -CITYCAB <i>re</i>	1.00	100.00	0.00	100.00 80	S	Y	
37 BOOTLID INSULATOR CLIPS SET <i>re</i>	1.00	35.00	0.00	35.00	S	Y	
38 BUMPER PROTECTOR PAD REAR <i>re</i>	1.00	180.00	0.00	180.00 120	S	Y	
39 REVERSE SENSOR SET <i>re</i>	1.00	250.00	0.00	250.00 200	S	Y	
40 BUMPER CLIPS SET REAR <i>re</i>	1.00	35.00	0.00	35.00	S	Y	
41 FENDER SEALANT REAR <i>X</i>	1.00	50.00	0.00	50.00	S	Y	
42 WINDSCREEN SEALANT REAR <i>X</i>	1.00	50.00	0.00	50.00	S	Y	
43 END PANEL TOP GARNISH CLIPS <i>re</i>	1.00	35.00	0.00	35.00	S	Y	
44 END PANEL SEALANT <i>re</i>	1.00	50.00	0.00	50.00 30	S	Y	
45 SPARE TYRE PANEL SEALANT <i>X</i>	1.00	80.00	0.00	80.00	S	Y	
TOTAL:		10,256.61	853.32	8,403.29			
TOTAL PARTS & LABOUR:		15,546.61	1,853.32	13,693.29			

EXCESS/LOADING:\$S 0.00

No. Of Day:

8 daysRE-SURVEY: BEFORE/ AFTER PAINTING
PART-BY-PART OR LUMP SUM \$SDATE OF SURVEY: 22 / 04 / 19

SURVEYED BY:

Rasul

CONTACT NO:

90010068

FAX NO:

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle No.:	SHC7805M
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)
Vehicle Attachment 1:	Air-Con (Taxi)
Vehicle Scheme:	Taxi (Company)
Vehicle Make:	HYUNDAI
Vehicle Model:	SONATA NF 2.0 CRDI AT ABS 2WD 4DR TURBO
Chassis No.:	KMHET41VMDA834577
Propellant:	Diesel
Engine No.:	D4EAD306982
Engine Capacity:	1991 cc
Maximum Power Output:	110.0 kW (147 bhp)
Maximum Laden Weight:	2150 kg
Unladen Weight:	1685 kg
Year Of Manufacture:	2013
Original Registration Date:	18 Jul 2013
Lifespan Expiry Date:	17 Jul 2021
COE Category:	A - Car (1600cc & below)
PQP Paid:	\$51,810.00
COE Expiry Date:	17 Jul 2021
Road Tax Expiry Date:	17 Jul 2019
PARF Eligibility Expiry Date:	17 Jul 2021
Inspection Due Date:	17 Jul 2019
Intended Transfer Date:	18 Apr 2019
CO2 Emission:	184.00 (g/km)
CEV/VES Rebate Utilised Amount:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

The current road tax expiry is 17 Jul 2019. You may renew the road tax from 18 Apr 2019 with all pre-requisite(s) fulfilled. If the road tax is renewed after 17 Jul 2019, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	2,635.00	-	2,635.00
Total Amount Payable:			2,660.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

You may print this page for reference.

OK

Print

Nivitha (LKK Auto)

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Monday, 22 April 2019 9:58 AM
To: assignments
Cc: Admin A
Subject: FW: ACCIDENT INVOLVING SHC7805M AND SGU1315S ON 18/04/2019 ARRANGE SURVEY
Attachments: SAS2587057 (1).PDF; Invoice.html

10:52am @ 22/4/19
Mr. Cheng.
vehicle in.
sup @ Panel

SMARTCLAIM NEW CASE

KINDLY ARRANGE

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: taxiscs@stengg.com <taxiscs@stengg.com>
Sent: Thursday, 18 April 2019 5:32 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Cc: ACCOUNTS@DINGAUTO.SG; ADMIN@DINGAUTOMOTIVE.COM.SG; Dd hashim <dd.hashim@dingauto.sg>; Claims@dingautomotive.com.sg; accounts@dingautomotive.com.sg
Subject: ACCIDENT INVOLVING SHC7805M AND SGU1315S ON 18/04/2019 ARRANGE SURVEY

Dear Officer ,

Please arrange surveyor come on to survey SHC7805M .

This vehicle SHC7805M already in 31 Corporation Road 649825 .

Thanks

Best Regards

Ding Automotive Pte Ltd
Guang
94669828 /62657130

[This e-mail is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any other person. Thank you]

[Home](#) [My Claims](#) [Cancelled/Rejected TP](#) [Help](#)

« Service Request Details

Claim

S9M01KSJ

Reference

None 

Loss Date

18 April 2019

Report Date

22 Apr 2019 9:08:00 AM

Request Date

22 April 2019

Due Date

22 April 2020

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Actions

Next Step

Finish the work

Complete Work	Done
---------------	------

Vehicle Information

Incident Vehicle Registration

SHC7805M

Make

TPVD

Model

HYUNDAI



Primary Contact/Insured

NEO LAY KHIANG
BLK 116B RIVERVALE DRIVE, #03-18, 542116, Singapore
90684719

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

[Additional Instructions](#)

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[View Messages](#)



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs.

Mandate:

Liability(TP)		100%
Proposed repair cost	\$	4,761.50 (\$4,450.00 +7%gst)
Loss of use	\$	-
Loss of rental	\$	633.24 (\$105.54 x 6days)
Loss of income	\$	300.00 (\$50.00 x 6 days)
GIA search fees	\$	2.00
Others	\$	-
Proposed Total	\$	5,696.74

English (default) ▾

LKK AUTO CONSULTANTS PTE LTD (TP) ▾



SERVICE REQUESTS

MESSAGES

CLAIMS



TP MANDATE IA < S9M01KSJ >

Type

Question

Message

Dear Richard, Liability: Insured driver collided into the rear of third party vehicle, Liability is down against our insured. We have send letter to OI to notify TP claim and NCD issue on 2nd July 2019. Immediate Advice (with mandate) have been uploaded in SMART CLAIM. We hereby seek your approval to offer Third Party repairer M/s "Ding Automotive Pte Ltd" is as follows: - 1) COR(w/gst): \$4,761,50 + 2) Loss of Rental (6 days x \$105.54): \$ 633.24 + 3) Loss of Income(6days x \$50.00): \$300.00 + 4) GIA: \$2.00 = Total: \$5,696.74. **8days recommendation for repair. **All the relevant documents had been uploaded in SMART CLAIM. For your approval please.
PohKin- LKK- 17/07/2019



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 17/07/2019

Survey Details:

Date of loss	18-Apr-19
Date of appointment	22-Apr-19
Date of survey	22-Apr-19
Location of survey	DING AUTO PTE LTD

Vehicle Details:

Claim Type:	Third party
Vehicle number	SHC 7805M
Make and Model	HYUNDAI SONATA NF 2.0 CRDI AT ABS 2WD
Date of registration	18/7/2013
Excess	
Market Value	\$0
Parf Rebate	\$0
Nett Loss	\$0

Repair details:

Initial Estimate	\$ 13,693.29
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 3,347.05	list price-20%
Check items (estimate)	\$ -	
Labour	\$ 2,230.00	
Total	\$ 5,577.05	
Lump Sum(if applicable)	\$ 4,450.00	after -20%

Number of days for repair	8
---------------------------	---



Re:TP MANDATE IA < S9M01KSJ >

Type

🔔 Question

Message

Hi, we agree to the mandate but pls ensure no objection from OI. TY.

Reply

Without Prejudice
to our driver's Injury claim

(Ashe)

DING AUTOMOTIVE PTE LTD
OUR REF: 50111585/TP/SHC7805M/AD/18/04/2019/HAILEY
YOUR REF: SGU1315S/-----
14 MAY 2019

MOTOR CLAIMS DEPARTMENT
AXA INSURANCE
8 SHENTON WAY, #24-01
AXA TOWER, 068811 SINGAPORE

ACCIDENT INVOLVING: SHC7805M AGAINST SGU1315S ON 18/04/2019
LOCATION ALONG: SIN MING AVE TOWARDS BISHAN
We refer to the above matter:

	Rate per day	Repair/ Claim days	AMOUNT BEFORE GST	GST 7%	AMOUNT AFTER GST
Cost of Repair	\$ -	7	\$ 4,450.00	\$ 311.50	\$ 4,761.50
Loss Of Rental	\$ 98.64	7	\$ 690.48	\$ -	\$ 690.48
Loss Of Income	\$ 80.00	7	\$ 560.00	\$ -	\$ 560.00
LTA/GIA Search Fee	\$ -	0	\$ 1.87	\$ 0.13	\$ 2.00
Towing Fee	\$ -	0		\$ -	\$ -
Surveyor Fee	\$ -	0	\$ -	\$ -	\$ -
Total	\$ 178.64	7	\$ 5,702.35	\$ 311.63	\$ 6,013.98

The accident was caused solely by the negligence of your insured and as a results. We had incurred the following costs of repair and losses of our insurer:

Enclosed are copies of the following documents for your perusal:

☺	Repair Estimate	☺	Discharge Voucher
☺	GIA/Accident Police Report	☺	Certificate Of Insurance
☺	LTA 3 rd Party Search Fee	☺	Final Bill/Repair Tax Invoice
☺	Mileage Record	☺	Confirmation Finalize/Liability Email Copy
☺	Rental Rates Agreement	☺	Letter Of Demand
☺	Letter Of Authority	☺	

Our insurer has authorized DING AUTOMOTIVE PTE LTD to deal with the claim in this accident case and also to receive and deal/negotiate with all payment as stated above.

Please look into our client's claim and revert soonest as possible.

Your Sincerely,
HAILEY
DING AUTOMOTIVE PTE LTD
OFFICE:64521208
FAX:64520614



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/ASM19007025/R1wb3s2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 06-08-2019	
ATTN: RICHARD ANG		Code : ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SGU 1315S	Veh. Inspected	SHC 7805M
Policy No.	GA336445/1	Coverage (\$)	0.00
Claim No.	S9M01KSJ	Excess (\$)	0.00
Assign From	RICHARD ANG	Assign Date	22/04/2019
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI SONATA 2.0	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	KMHET41VMDA834577	Colour	YELLOW
Odometer	184158	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60R16	WEST LAKE	5 mm
L/H Front Tyre	215/60R16	WEST LAKE	5 mm
R/H Rear Tyre	215/60R16	WEST LAKE	5 mm
L/H Rear Tyre	215/60R16	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/04/2019	Inspection Date	22/04/2019
Survey held at	31 CORPORATION ROAD		
Repairer	DING AUTO PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 7805M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BOOTLID (CONSISTENT)	TO REPAIR SEE LABOUR	1,139.20	-
1	BOOTLID LOCK (CONSISTENT)	NOT NECESSARY	109.45	-
1	BOOTLID CATCH (CONSISTENT)	NOT NECESSARY	108.90	-
1	BOOTLID LOGO (CONSISTENT)	NECESSARY	21.54	21.54
1	BOOTLID EMBLEM "CRDI" (CONSISTENT)	NECESSARY	18.70	18.70
1	BOOTLID EMBLEM - HYUNDAI (CONSISTENT)	NECESSARY	28.12	28.12
1	BOOTLID EMBLEM - SONATA (CONSISTENT)	NECESSARY	40.92	40.92
1	BOOTLID LAMP LH (CONSISTENT)	NOT NECESSARY	233.50	-
1	BOOTLID LAMP RH (CONSISTENT)	NOT NECESSARY	233.50	-
1	BOOTLID SEAL STRIP LH (CONSISTENT)	NOT NECESSARY	91.30	-
1	BOOTLID SEAL STRIP RH (CONSISTENT)	NOT NECESSARY	91.30	-
1	BOOTLID DAMPER LH (CONSISTENT)	NOT NECESSARY	114.50	-
1	BOOTLID DAMPER RH (CONSISTENT)	NOT NECESSARY	114.50	-
1	BOOTLID WEATHER STRIP (CONSISTENT)	CUT	124.50	124.50
1	BOOTLID INSULATOR (CONSISTENT)	NOT NECESSARY	155.10	-
1	BUMPER REAR (CONSISTENT)	DEFORMED	523.93	523.93
1	BUMPER RETAINER REAR LH (CONSISTENT)	NECESSARY	42.68	42.68
1	BUMPER RETAINER REAR RH (CONSISTENT)	NECESSARY	42.68	42.68
1	BUMPER SPONGE REAR (CONSISTENT)	CRACKED	1,133.52	1,133.52
1	BUMPER REINFORCEMENT REAR (CONSISTENT)	CRACKED	462.30	462.30
1	REINFORCEMENT BRACKET REAR LH (CONSISTENT)	BENT	79.75	79.75
1	REINFORCEMENT BRACKET REAR RH (CONSISTENT)	BENT	79.75	79.75
1	BUMPER LOWER REAR (NPA) (CONSISTENT)	DEFORMED	-	-
1	BUMPER PROTECTOR REAR LH (CONSISTENT)	DEFORMED	102.96	102.96
1	BUMPER PROTECTOR REAR RH (CONSISTENT)	NOT NECESSARY	102.96	-
1	FENDER REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	1,598.30	-
1	TAIL LAMP LH (CONSISTENT)	NOT NECESSARY	323.40	-
1	TAIL LAMP RH (CONSISTENT)	CRACKED	323.40	323.40
1	END PANEL (CONSISTENT)	BENT	338.29	338.29

Report Ref No. CC4/ASM19007025/R1wb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL TOP GARNISH (CONSISTENT)	DEFORMED	52.02	52.02
1	SPARE TYRE PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	812.90	-
1	SPARE TYRE INNER TRIM LH (CONSISTENT)	NOT NECESSARY	164.14	-
1	SIDE PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	229.30	-
1	SIDE PANEL REAR LH (CONSISTENT)	TO REPAIR SEE LABOUR	229.30	-
	LESS 20% DISCOUNT		-1,853.32	-683.01
			7,413.29	2,732.05
	SPECIAL NETT ITEMS			
1	BOOTLID STICKER - BOOKING 65521111 (SN) (CONSISTENT)	NECESSARY	125.00	80.00
1	BOOTLID STICKER - CITYCAB (SN) (CONSISTENT)	NECESSARY	100.00	80.00
1	SET BOOTLID INSULATOR CLIPS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	BUMPER PROTECTOR PAD REAR (SN) (CONSISTENT)	NECESSARY	180.00	120.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	NOT WORKING	250.00	200.00
1	SET BUMPER CLIPS REAR (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	FENDER SEALANT REAR (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	WINDSCREEN SEALANT REAR (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
1	END PANEL TOP GARNISH CLIPS (SN) (CONSISTENT)	NECESSARY	35.00	35.00
1	END PANEL SEALANT (SN) (CONSISTENT)	NECESSARY	50.00	30.00
1	SPARE TYRE PANEL SEALANT (SN) (CONSISTENT)	NOT NECESSARY	80.00	-
			990.00	615.00
	LABOUR			
	TO REPAIR FENDER RH, STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS. INCLUSIVE OF THE REPAIR OF BOOTLID, FENDER REAR LH, SPARE TYRE PANEL, SIDE PANEL REAR RH AND SIDE PANEL REAR LH.		1,600.00	800.00
	TO RUST PROOFING ON ACCIDENT AFFECTED AREAS.		150.00	60.00
	TO APPLY SEAL JOINT ON WELDING AFFECTED AREAS.		180.00	60.00
	REMOVE & REFIX REAR WINDSCREEN.	NOT NECESSARY	150.00	-
	REMOVE & REFIX REVERSE SENSOR & CHECK WIRING.		80.00	60.00
	REMOVE & REFIX REAR SEAT, SEAT BELT, SPARE TYRE COMPARTMENT PARTS.	NOT NECESSARY	180.00	-

Report Ref No. CC4/ASM19007025/R1wb3s2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REFIX BOOTLID COMPARTMENT.	NOT NECESSARY	150.00	-
	RESPRAY REAR FENDER LH + FENDER RH.		500.00	200.00
	RESPRAY REAR BUMPER + BUMPER LOWER.		500.00	200.00
	RESPRAY REAR BUMPER PROTECTOR LH + PROTECTOR RH.		400.00	50.00
	RESPRAY SPRAY TYRE PANEL + END PANEL.		500.00	400.00
	RESPRAY SIDE PANEL LH + SIDE PANEL RH.		400.00	200.00
	RESPRAY BOOTLID + DOOR REAR LH.		500.00	200.00
			5,290.00	2,230.00
GRAND TOTAL			13,693.29	5,577.05
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,450.00

Report Ref No. CC4/ASM19007025/R1wb3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.