

Asher

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

22/04/2019 9:45

OWNER'S PARTICULARS

JOB-NO: 50111585

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

Page 1 of 2

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 57517 0

64739522

VEHICLE DETAILS

LICENSE NO: SHC7805M

TRANS: AUTO

CHASSIS: KMHET41VMDA834577

MAKE / MODEL: HYUNDAI / Sonata 2.0 CRDI

ENGINE: D4EAD306982

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
<u>LABOUR</u>							
1 TO REPAIR FENDER RH STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	1,600.00	0.00	1,600.00		Y	800
2 TO RUST PROOFING ON ACCIDENT AFFECTED AREAS	1.00	150.00	0.00	150.00		Y	60
3 TO APPLY SEAL JOINT ON WELDING AFFECTED AREAS	1.00	180.00	0.00	180.00		Y	60
4 REMOVE & REFIX REAR WINDSCREEN	1.00	150.00	0.00	150.00		Y	X
5 REMOVE & REFIX REVERSE SENSOR & CHECK WIRING	1.00	80.00	0.00	80.00		Y	60
6 REMOVE & REFIX REAR SEAT, SEAT BELT, SPARE TYRE COMPARTMENT PARTS	1.00	180.00	0.00	180.00		Y	X
7 REMOVE & REFIX BOOTLID COMPARTMENT	1.00	150.00	0.00	150.00		Y	X
8 RESPRAY REAR FENDER LH + FENDER RH	1.00	500.00	0.00	500.00		Y	200
9 RESPRAY REAR BUMPER + BUMPER LOWER	1.00	500.00	0.00	500.00		Y	200
10 RESPRAY REAR BUMPER PROTECTOR LH + PROTECTOR RH	1.00	400.00	0.00	400.00		Y	50
11 RESPRAY SPRAY TYRE PANEL + END PANEL	1.00	500.00	0.00	500.00		Y	400
12 RESPRAY SIDE PANEL LH + SIDE PANEL RH	1.00	400.00	0.00	400.00		Y	200
13 RESPRAY BOOTLID + DOOR REAR LH	1.00	500.00	0.00	500.00		Y	200
TOTAL:		5,290.00	0.00	5,290.00			

2230

MATERIALS

1 BOOTLID <i>repair</i>	1.00	1,139.20	227.84	911.36	L	Y	
2 BOOTLID LOCK <i>X</i>	1.00	109.45	21.89	87.56	L	Y	
3 BOOTLID CATCH <i>X</i>	1.00	108.90	21.78	87.12	L	Y	
4 BOOTLID LOGO <i>NA</i>	1.00	21.54	4.31	17.23	L	Y	
5 BOOTLID EMBLEM *CRDI* <i>na</i>	1.00	18.70	3.74	14.96	L	Y	
6 BOOTLID EMBLEM - HYUNDAI <i>na</i>	1.00	28.12	5.62	22.50	L	Y	
7 BOOTLID EMBLEM - SONATA <i>na</i>	1.00	40.92	8.18	32.74	L	Y	
8 BOOTLID LAMP LH <i>X</i>	1.00	233.50	46.70	186.80	L	Y	
9 BOOTLID LAMP RH <i>X</i>	1.00	233.50	46.70	186.80	L	Y	
10 BOOTLID SEAL STRIP LH <i>X</i>	1.00	91.30	18.26	73.04	L	Y	
11 BOOTLID SEAL STRIP RH <i>X</i>	1.00	91.30	18.26	73.04	L	Y	
12 BOOTLID DAMPER LH <i>X</i>	1.00	114.50	22.90	91.60	L	Y	
13 BOOTLID DAMPER RH <i>X</i>	1.00	114.50	22.90	91.60	L	Y	
14 BOOTLID WEATHER STRIP <i>at</i>	1.00	124.50	24.90	99.60	L	Y	
15 BOOTLID INSULATOR <i>X</i>	1.00	155.10	31.02	124.08	L	Y	

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
16 BUMPER REAR <i>OK</i>	1.00	523.83	104.79	419.14	L	Y	
17 BUMPER RETAINER REAR LH <i>OK</i>	1.00	42.68	8.54	34.14	L	Y	
18 BUMPER RETAINER REAR RH <i>OK</i>	1.00	42.68	8.54	34.14	L	Y	
19 BUMPER SPONGE REAR <i>OK</i>	1.00	1,133.52	226.70	906.82	L	Y	
20 BUMPER REINFORCEMENT REAR <i>OK</i>	1.00	462.30	92.46	369.84	L	Y	
21 REINFORCEMENT BRACKET REAR LH <i>OK</i>	1.00	79.75	15.95	63.80	L	Y	
22 REINFORCEMENT BRACKET REAR RH <i>OK</i>	1.00	79.75	15.95	63.80	L	Y	
23 BUMPER LOWER REAR <i>OK</i>	1.00	0.00	0.00	0.00	L	Y	
24 BUMPER PROTECTOR REAR LH <i>OK</i>	1.00	102.96	20.59	82.37	L	Y	
25 BUMPER PROTECTOR REAR RH <i>OK</i>	1.00	102.96	20.59	82.37	L	Y	
26 FENDER REAR LH <i>repair</i>	1.00	1,598.30	319.66	1,278.64	L	Y	
27 TAIL LAMP LH <i>X</i>	1.00	323.40	64.68	258.72	L	Y	
28 TAIL LAMP RH <i>OK</i>	1.00	323.40	64.68	258.72	L	Y	
29 END PANEL <i>OK</i>	1.00	338.29	67.66	270.63	L	Y	
30 END PANEL TOP GARNISH <i>OK</i>	1.00	52.02	10.40	41.62	L	Y	
31 SPARE TYRE PANEL <i>repair</i>	1.00	812.90	162.58	650.32	L	Y	
32 SPARE TYRE INNER TRIM LH <i>X</i>	1.00	164.14	32.83	131.31	L	Y	
33 SIDE PANEL REAR RH <i>repair</i>	1.00	229.30	45.86	183.44	L	Y	
34 SIDE PANEL REAR LH <i>repair</i>	1.00	229.30	45.86	183.44	L	Y	
35 BOOTLID STICKER -BOOKING 65521111 <i>OK</i>	1.00	125.00	0.00	125.00 80	S	Y	
36 BOOTLID STICKER -CITYCAB <i>OK</i>	1.00	100.00	0.00	100.00 80	S	Y	
37 BOOTLID INSULATOR CLIPS SET <i>OK</i>	1.00	35.00	0.00	35.00	S	Y	
38 BUMPER PROTECTOR PAD REAR <i>OK</i>	1.00	180.00	0.00	180.00 120	S	Y	
39 REVERSE SENSOR SET <i>OK</i>	1.00	250.00	0.00	250.00 200	S	Y	
40 BUMPER CLIPS SET REAR <i>OK</i>	1.00	35.00	0.00	35.00	S	Y	
41 FENDER SEALANT REAR <i>X</i>	1.00	50.00	0.00	50.00	S	Y	
42 WINDSCREEN SEALANT REAR <i>X</i>	1.00	50.00	0.00	50.00	S	Y	
43 END PANEL TOP GARNISH CLIPS <i>OK</i>	1.00	35.00	0.00	35.00	S	Y	
44 END PANEL SEALANT <i>OK</i>	1.00	50.00	0.00	50.00 30	S	Y	
45 SPARE TYRE PANEL SEALANT <i>X</i>	1.00	80.00	0.00	80.00	S	Y	
TOTAL:		10,256.61	853.32	8,403.29			

TOTAL PARTS & LABOUR: 15,546.61 1,853.32 13,693.29

EXCESS/LOADING: \$5 0.00

No. Of Day: 8 days

RE-SURVEY: BEFORE/ AFTER PAINTING

PART-BY-PART OR LUMP SUM \$5

DATE OF SURVEY: 22, 04, 19

SURVEYED BY: Rasul

CONTACT NO: 90010068

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED
DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL: _____

FAX: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a 'Without Prejudice' basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

G:STAR-WI-ET-001-02-Rev00

2732.05

2732.05

2230.00

615.00

5580.05

20%

4464.04

45-4, 450

8 days