



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
6 Benoi Place Singapore 629927
Tel: 6861 0908 Fax: 6515 2948

Date: 22.04.2019

AXA Insurance Singapore Pte Ltd
8 Shenton Way #27-01/02
AXA Tower
Singapore 068811

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO VEHICLE SHD2417C HONDA GRACE (2017)

To Supply

1) 1pc Front bonnet *BH* ✓ \$ 688.00

Sub total parts	\$ 688.00
Less: 20% discount	\$ 137.60
	\$ 550.40

L/charges

1) To tuff kote \$ ~~30~~ ~~50.00~~

2) To remove & replace front bonnet. Align & adjust front bonnet and right fender \$ ~~250.00~~ *200*

3) To putty, respray painting front bonnet. To polish \$ ~~300.00~~ *200*

Sub total L/charges	\$ 600.00
Estimated Grand Total	\$ 1,150.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 96010068

2 days
P/P

22/04/19 @ 14/10

Resurvey before paint