

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD

8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK

Claim Type: Third Party

Accident Date: 17/04/2019

TP Veh Reg No: SLF9881R

Estimate No: ES1991415/AMK

Date: 18 Apr 2019

Policy No: 18-MV007992-R02

Veh Reg No: SGL1857S

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR053HY4204202149

Engine No: 1NZX472258

Reg. Date: 06/09/2006

Estimate Repair Cost to Vehicle No :SGL1857S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	245.90	1 PC	245.90	✓
2 REAR BUMPER RH RETAINER	12.50	1 PC	12.50	✓
3 REAR BUMPER CLIP	3.50	4 PC	14.00	✓
4 REAR BOOT	446.50	1 PC	446.50	✓
5 REAR BOOT INNER LOCK	22.90	1 PC	22.90	✓
6 REAR BOOT INNER RUBBER	42.40	1 PC	42.40	508m 21.0
7 REAR BOOT LOGO	12.90	1 PC	12.90	✓
8 REAR BOOT EMBLEM 'VIOS'	13.90	1 PC	13.90	✓
9 REAR BOOT EMBLEM '1.5'	7.10	1 PC	7.10	✓
10 REAR BOOT EMBLEM 'E'	30.94	1 PC	30.94	✓
11 REAR BOOT EMBLEM 'VVTI'	38.43	1 PC	38.43	✓
12 TAILLAMP	189.00	2 PC	378.00	✓
13 TAILLAMP INNER GASKET	18.20	2 PC	36.40	✓
14 REAR END PANEL	700.85	1 PC	700.85	✓
15 REAR END PANEL INNER TOP GARNISH	58.94	1 PC	58.94	✓
16 REAR SPARE TYRE COMPARTMENT PANEL TOP BOARD	51.45	1 PC	51.45	✓
17 REAR SPARE TYRE RH SIDE BOARD	59.70	1 PC	59.70	✓
18 FRONT BUMPER	238.49	1 PC	238.49	✓
19 FRONT BUMPER CLIP	3.50	4 PC	14.00	✓
20 FRONT BUMPER REINFORCEMENT	272.08	1 PC	272.08	✓
21 FRONT GRILLE	158.05	1 PC	158.05	✓
22 HEADLAMP RH	237.51	1 PC	237.51	✓
			3,092.94	
	Less 25%		773.24	2,319.71
Special Net				
23 REVERSE SENSOR	200.00	1 SET	200.00	✓
24 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
			235.00	235.00
Labour				
25 REMOVE & REFIX REAR BUMPER, TAILLAMPS, REAR BOOT & ATTACHMENTS, TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR FENDERS, REAR SPARE TYRE PANEL & REALIGN THE SAME	800.00	1 LA	800.00	700
26 PUTTY & RESPRAY REAR BUMPER, REAR BOOT, BOTH FENDERS, REAR END PANEL, REAR SPARE TYRE PANEL & ALL AFFECTED AERAS	950.00	1 LA	950.00	850

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
8 SHENTON WAY
#27-02 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 68804739

ATTN: Motor Claim Department

WS Ref: TP/AXA/AMK

Claim Type: Third Party

Accident Date: 17/04/2019

TP Veh Reg No: SLF9881R

Estimate No: ES1991415/AMK

Date: 18 Apr 2019

Policy No: 18-MV007992-R02

Veh Reg No: SGL1857S

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR053HY4204202149

Engine No: 1NZX472258

Reg. Date: 06/09/2006

Estimate Repair Cost to Vehicle No :SGL1857S

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
27 REMOVE & REFIX FRT BUMPER,GRILLE,HEADLAMP;KNOCKING & REPAIR FRT PANEL & REALIGN THE SAME	350.00	1 LA	350.00	300
28 PUTTY & RESPRAY FRT BUMPER,BONNET,FRT RH FENDER,FRT PANEL & ALL AFFECTED AREAS	600.00	1 LA	600.00	500
29 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,760.00	2,760.00
			Total	S\$ 5,314.71
			Add GST @ 7%	372.03
			Total Amount Payable	<u>S\$ 5,686.74</u>

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: