

INS. CASE OWNER:

CC4, LPL 1900 1051, UPA3 G/L

LEAD:

IDAC:

Surveyor:

M. P. P. S.

DOI:

ASSIGNMENT

2/4/19

Date / Time:

2/4/19

Registered in Morrim:

Pre-assign / CCU / FTE



Insured Vehicle No.:

GBE 1612M

Name of Insured:

Loopwill Bros Trading.

Insured Tel No.:

HP:

Claim No.:

18/19/19/1205/021699

Policy No.:

Make / Model:

Place of Accident:

Excess Sec II : S5

D.O.A.:

18/04/2019

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SJK 1054L



INSRS:

WSP:

Tel:

Liability:

RMKS:

Falcon - Av
(1)

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

SJK 1054L - X; GBE 1612M - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / CIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

18/5/19 - OIP recommended - up

21/5/19 - File -> Mandate to activate.

23/5/19 - File path to type mandate.
- E-mailed TPIC (John) to request LOD + DOCS.

* ORIGINAL DOCS WITH LPL

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: (Yes)

Repair Cost:

S\$1,000

(7 - days) Reduction:

47 %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 18-07-19

Confirm with: J. H. H. T.

Email ☒ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. 72

If NO or B 28, Ass. Lin:

Repair Cost:

S\$1,490.00

Loss of Rental (LOR):

S\$1,070.00

(10 days) * 410

Loss of Use (LOU):

S\$ -

(\$ x days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$2.00

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ independent)

Legal Cost

S\$ -

Total:

S\$8,562.00

Global Sum S\$8,500

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

* 450

FINAL PAYMENT

Date/Time: 18-07-19

Confirm with: J. H. H. T.

Email ☒ Call ☐

Payee 1:

S\$8,500.00

Name 1:

FRANCIS AIR AUTO SERVICES PTE. LTD.

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

COPY SENT



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/19/19/VC05/021699
Our ref: CC4/LPC19007031/Upa3

Date: 30/04/2019

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJK 1054L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 22/04/2019 at the premises of M/s Falcon-Air Auto Services Pte Ltd (Tampines) and have the following to report:-

Workshop Estimate Amount	: S\$	13,115.82
Revised Estimate Amount	: S\$	7,000.00
"Check" Items Amount	: S\$	-
Total (Including Check Items)	: S\$	7,000.00
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 7.0 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04 THE CONCOURSE SINGAPORE 199555

Attention: Motor Claim Department

Contact: (02) 6250 7388 Fax No.: 62963767

janet@falconair.com.sg

Estimate: ES707347

Date: 22/04/2019
Vehicle Num: SJK 1054L
Make/Model: TOYOTA ALLION
Chassis/Eng#: NZT260-3025804
Accident Date: 18/04/2019
Claim No:
Reference: 3PTY 1/2
Policy No:

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS:				
1	1 PC	BOOT LID		1,285.00 ✓
2	2 PC	BOOT LID HINGE	175.00	350.00 ✓
3	1 PC	BOOT LID ALLION EMBLEM	97.10	✓
4	1 PC	BOOT LID LOGO	90.80	✓
5	1 PC	BOOT LID A15 EMBLEM	89.60	✓
6	1 PC	BOOT LID CHROME MOULDING	scr	290.00 ✓
7	1 PC	BOOT LID INSULATOR	11	390.00 ✓
8	12 PC	BOOT LID INSULATOR CLIP	5.00	60.00 ✓
9	1 PC	BOOT LID LOCK	tw	475.00 ✓
10	1 PC	BOOT LID WEATHERSTRIP	tw	290.00 ✓
11	1 PC	REAR BUMPER	D.S	465.00 ✓
12	2 PC	REAR BUMPER SIDE RETAINER	n/s cm	125.00 250.00 17c
13	12 PC	REAR BUMPER CLIPS	5.00	60.00 ✓
14	1 PC	N/S REAR BUMPER REFLECTOR	cm	97.60 ✓
15	1 PC	N/S TAILLAMP	cm	595.00 ✓
16	2 PC	N/S TAILLAMP CLIP	10.00	20.00 ✓
17	1 PC	N/S TAILLAMP PANEL	no/sat	230.00 ✓
18	1 PC	N/S TAILLAMP SPONGE	ner	45.00 ✓
19	1 PC	N/S REAR FENDER	R	120.00 ✓
20	1 PC	N/S REAR FENDER INNER TRIM	DL	585.00 ✓
21	12 PC	N/S REAR FENDER INNER TRIM CLIPS	5.00	60.00 ✓
22	1 PC	REAR END PANEL	body m	985.00 ✓

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk 10) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04 THE CONCOURSE SINGAPORE 199555

Attention: Motor Claim Department

Contact: (02) 6250 7388 Fax No.: 62963767

Estimate: ES707347

Date: 22/04/2019
Vehicle Num: SJK 1054L
Make/Model: TOYOTA ALLION
Chassis/Eng#: NZT260-3025804
Accident Date: 18/04/2019
Claim No:
Reference: 3PTY 1/2
Policy No:

S/N	Quantity	Particular	Unit Price	Amount SS
-----	----------	------------	------------	-----------

23	2 PC	REAR END PANEL BRACKET	n/s id 98.00	196.00 1pc
24	1 PC	REAR END PANEL GARNISH	7.00	255.00 X
25	12PC	REAR END PANEL GARNISH CLIP	5.00 17	60.00 X
26	1 PC	SPARE TYRE PANEL	17	17.00 X
27	1 PC	REAR WINDSCREEN MOULDING	17	17.00 X
List Total SS				11,081.10
25.00% Discount SS				2,770.28
				8,310.82

SPECIAL NETT ITEMS				
1	1 PC	BOOT LID SEALANT	nbc 17	80.00 10
2	1 PC	REAR NUMBER PLATE	17	45.00 X
3	1 PC def	REVERSE SENSOR	slut 17	250.00 200
4	1 PC def	SPARE TYRE PANEL RUBBER INSULATOR	me 17	300.00 150
5	1 PC	REAR WINDSCREEN SEALANT	17	40.00 X
6	1 PC	REAR WINDSCREEN INNER SEAL	17	80.00 X
Special Nett Total SS:				795.00
LABOUR:				
TO TRANSFER REAR WINDSCREEN GLASS				17 150.00 X
TO CHECK WIRING AND LIGHT SYSTEM				50.00 30

CONTINUE / ...

P-7585.4
45.00
5689.05
5769.05

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04 THE CONCOURSE SINGAPORE 199555

Attention : Motor Claim Department

Contact : (02) 6250 7388, Fax No. : 62963767

Page 3 / 3 FALCON-AIR AUTO SERVICES PTE LTD

CO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D

Estimate : ES707347

Date : 22/04/2019
Vehicle Num : SJK 1054L
Make/Model : TOYOTA ALLION
Chassis/Eng# : NZT260-3025804
Accident Date : 18/04/2019
Claim No :
Reference : 3PTY 1/2
Policy No :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

APPLY BODY SEALANT TO CAR JOINTS
RE-SPRAY ANTI-RUST
CHECK FOR WATER LEAKAGE
INSTALL REVERSE SENSOR
TRANSFER BOOT LID PARTS
TO REMOVE/REFIX GARNISH, TRIM, SEAT, SPEAKER BOARD AND ETC
TO DROP FUEL TANK TO FACILITATE REPAIR AND TO FIX BACK
TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL, REPAIR
INNER PANEL, REWELD INNER PANEL, REPLACE ACCIDENT DAMAGED
TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS

180.00	50
180.00	100
50.00	X
150.00	50
150.00	60
200.00	80
300.00	60
1,200.00	1150
1,400.00	1100

Labour Total S\$

4,010.00

*not Actual
LKR
2/5 \$7000
7 hrs.*

E & O.E. Total S\$ 13,115.82

*Take pmt. After rep
22/4/19*

for FALCON-AIR AUTO SERVICES PTE LTD

(TAMPINES BRANCH)

LKK Auto Co.
the Repairer

- To resurvey by
- To display dam
- Parts prices a
- Third party su
- No illegal mo
- Supplementar
- is subject to f

Acknowledged

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Looip (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 6710A

Vehicle Details

Vehicle No.: SJK1054L

Vehicle to be Exported: No

Intended Deregistration Date: 22 Apr 2019

Vehicle Make: TOYOTA

Vehicle Model: ALLION 1.5 A

Primary Colour: Black

Manufacturing Year: 2008

Engine No.: 1NZD043212

Chassis No.: NZT2603025804

Maximum Power Output: 81.0 kW (108 bhp)

Open Market Value: \$14,975.00

Original Registration Date: 04 Oct 2008

First Registration Date: 04 Oct 2008

Transfer Count: 1

Actual ARF Paid: \$13,027.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 30 Sep 2023

COE Category: A - Car (1600cc & below)

COE Period(Years): 5

PQP Paid: \$16,170.00

COE Rebate Amount: \$14,355.00

Total Rebate Amount: \$14,355.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 22 Apr 2019

OK

Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house?

Sell it on Marketplace. Posting an advertisement is FREE!

Toyota Allion

Price Range

Depreciation

> 10 year

Vehicle Type

Submit

Advanced Search

Home > Used Cars > William Lee Car Aircon Engineering > Toyota Allion 1.5A (COE till 09/2023)

Toyota Allion 1.5A (COE till 09/2023)

Overview	Financial	Insurance	Accessories	Similar	Research	Photos	Map
Price	\$29,800						
Depreciation	\$6,710 /yr		Reg Date	29-Sep-2008 (4yrs 5mths 6days COE left)			
Mileage	N.A.		Manufactured	2008			
Road Tax	\$750 /yr		Transmission	Auto			
Dereg Value	\$14,354 as of today (change)		OMV	\$14,652			
COE	\$16,170		ARF	\$14,652			
Engine Cap	1,496 cc		Power	81.0 kW (108 bhp)			
Curb Weight	1,200 kg		No. of Owners	3			
Type of Vehicle	Mid-Sized Sedan						

Features

1.5L DOHC VVT-i Engine, CVT Automatic Transmission, SRS Airbags, Auto Climatic Aircon Control, Knockdown Rear Seats, Keyless Entry. View specs of the Toyota Allion (2007-2012)

Accessories

Full Factory Fitted Accessories, Leather Seat, Etc.

Description

Just Arrived! Well Maintained By Previous Owner! High Loan With High Trade In Available. Price Negotiable. Call Now Or Visit Our Showroom Today.

Category

COE Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more.



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Shortlist

Report Error

Compare

More Actions

Add note

Seller Information

Company	William Lee Car Aircon Engineering • Dealer's pricelist • 20 vehs sold 24 vehs available	
Address	61 Ubi Avenue 2 #08-04B Search cars nearby this location	
Location	Automobile Megamart	
Office No	63821006	
Contact Person (s)	Keith Erik Ben Shen Qiang	98290368 96812139 98274488 94557994

Posted on: 30-Mar-2019 | Last Updated on: 21-Apr-2019

Upfront Payment

Transfer Fee

\$25

> more Financial info

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 22 April 2019 9:58 AM
To: assignments@lkkauto.com
Cc: MT_Claim_SG
Subject: FW: 3pty claim for SJK1054L against your insured GBC1612M doa 18/04/2019
[External Confidential]
Attachments: sjk1054L.PDF

10:50am @ 22/4/19
per @ jeremiah
vehicle in
sur @ Menus.

Lonpac External - Confidential

Our Ref : 18/19/19/VC05/021699

Dear Nivitha,

Please proceed to conduct the survey accordingly.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Jeremiah Ng [mailto:jeremiah@falconair.com.sg]
Sent: Monday, 22 April, 2019 9:12 AM
To: GERALD POH WEE BIN
Subject: 3pty claim for SJK1054L against your insured GBC1612M doa 18/04/2019

Dear Mr Poh,

The above attachment is SJK1054L accident report.
Kindly assist with the list of 10 surveyors and also the liability for this case.

Thanks and regards,
Jeremiah Ng
Falcon-Air Auto Services (Tampines)
Tel:67897997

Mei Kwan (LKKAUTO)

From: Mei Kwan (LKKAUTO)
Sent: Friday, 3 May, 2019 11:57 AM
To: GERALD POH WEE BIN
Cc: MT_Claim_SG; Hsiao Tong (LKKAUTO); CS A Team; Admin A
Subject: RE: 3pty claim for SJK1054L against your insured GBC1612M doa 18/04/2019 [External Confidential]
Attachments: TP ESTIMATE - MARKED.pdf; Preliminary Advice.pdf
Categories: HMK

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SJK 1054L

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimated cost of repair
- Preliminary advice

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Monday, 22 April, 2019 4:11 PM
To: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>
Subject: RE: 3pty claim for SJK1054L against your insured GBC1612M doa 18/04/2019 [External Confidential]

Lonpac External - Confidential

Dear Mei Kwan,

Attached copy of insured's report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

Sent: Monday, 22 April 2019 9:58 AM

To: assignments@lkkauto.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: FW: 3pty claim for SJK1054L against your insured GBC1612M doa 18/04/2019 [External Confidential]

Lonpac External - Confidential

Our Ref : 18/19/19/VC05/021699

Dear Nivitha,

Please proceed to conduct the survey accordingly.


Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Jeremiah Ng [<mailto:jeremiah@falconair.com.sg>]

Sent: Monday, 22 April, 2019 9:12 AM

To: GERALD POH WEE BIN

Subject: 3pty claim for SJK1054L against your insured GBC1612M doa 18/04/2019

Dear Mr Poh,

The above attachment is SJK1054L accident report.

Kindly assist with the list of 10 surveyors and also the liability for this case.

Thanks and regards,

Jeremiah Ng

Falcon-Air Auto Services (Tampines)

Tel:67897997

This email has been checked for viruses by AVG antivirus software.

www.avg.com

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 18 May 2019 1:12 PM
To: CYSAUTO
Cc: Admin A
Subject: Your ref: SJJ 9114A *Our Ref: CC4/LPC19008218/Jpa3 [ACCIDENT INVOLVING XE 4676M(LONPAC) AND SJJ 9114A ON 06/05/2019]

Your ref: **SJJ 9114A** **Without Prejudice**
Our Ref: CC4/LPC19008218/Jpa3

Dear Sirs,

ACCIDENT INVOLVING XE 4676M(LONPAC) AND SJJ 9114A ON 06/05/2019

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Asher Sng (LKKAUTO)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 10 December 2019 10:08 AM
To: Asher Sng (LKKAUTO)
Cc: MT_Claim_SG
Subject: MANDATE REQUEST - SJK1054L [External Confidential]
Attachments: 10122019100407.pdf

Follow Up Flag: Follow up
Flag Status: Flagged

Lonpac External - Confidential


Our Ref : 18/19/19/VC05/021699

Dear Asher,

Attached copy of DV for your retention.

Kindly close your file and submit your bill.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

**FALCON-AIR AUTO SERVICES PTE LTD**CO. REG. NO.: 1995-01140-C
GST REG. NO.: 19-9501140-C

Tax Invoice TP106483

Invoice Date: 20/04/2019
Vehicle Num: SJK 1054L
Make/Model: TOYOTA ALLION
Mileage(Km):
POWQ/RO#: GBC1612M
Ref/Remark: SERCH FEE

S/N	Quantity	Particulars	Unit Price	Amount S\$
		BEING SEARCH FEE FOR VEHICLE NO: GBC1612M DOA 15/04/2019 @ 16.45 LONPAC INSURANCE BHD		1.87

Emp/Dollars Two Only

E & O.E	Total S\$	1.87
	GST 7% S\$	0.13
	Amount Due S\$	2.00

Terms: Cash

Customer's Signature/Co. Stamp

for FALCON-AIR AUTO SERVICES PTE LTD

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19007031/Uea3q2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 16-12-2019



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBC 1612M	Veh. Inspected	SJK 1054L
Policy No.	Z18VC05001312	Coverage (\$)	0.00
Claim No.	18/19/19/VC05/021699	Excess (\$)	0.00
Assign From		Assign Date	22/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALLION (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NZT2603025804	Colour	BLACK
Odometer	190503	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	18/04/2019	Inspection Date	22/04/2019
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 9006 TAMPINES ST 93 #01-200 SINGAPORE 528840		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJK 1054L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BOOT LID	BADLY DENTED	1,285.00	1,285.00
2	BOOT LID HINGE @\$175.00	TO REPAIR SEE LABOUR	350.00	-
1	BOOT LID ALLION EMBLEM	NECESSARY	97.10	97.10
1	BOOT LID LOGO	NECESSARY	90.80	90.80
1	BOOT LID A15 EMBLEM	NECESSARY	89.60	89.60
1	BOOT LID CHROME MOULDING	SCRATCHED	290.00	290.00
1	BOOT LID INSULATOR	NOT NECESSARY	390.00	-
12	BOOT LID INSULATOR CLIP @\$5.00	NOT NECESSARY	60.00	-
1	BOOT LID LOCK	TWISTED	475.00	399.00
1	BOOT LID WEATHERSTRIP	TWISTED	290.00	290.00
1	REAR BUMPER	DISTORTED	1,465.00	1,255.10
2	REAR BUMPER SIDE RETAINER @\$125.00	N/S CRACKED	250.00	125.00
12	REAR BUMPER CLIPS @\$5.00	NECESSARY	60.00	60.00
1	N/S REAR BUMPER REFLECTOR	CRACKED	97.60	97.60
1	N/S TAILLAMP	CRACKED	585.00	450.00
2	N/S TAILLAMP CLIP @\$10.00	NOT NECESSARY	20.00	-
1	N/S TAILLAMP PANEL	DENTED / BENT	230.00	230.00
1	N/S TAILLAMP SPONGE	NECESSARY	45.00	45.00
1	N/S REAR FENDER	TO REPAIR SEE LABOUR	1,120.00	-
1	N/S REAR FENDER INNER TRIM	DEFORMED	585.00	488.10
12	N/S REAR FENDER INNER TRIM CLIPS @\$5.00	NECESSARY	60.00	60.00
1	REAR END PANEL	BADLY DENTED	985.00	655.00
2	REAR END PANEL BRACKET @\$98.00	N/S DENTED	196.00	98.00
1	REAR END PANEL GARNISH	TWISTED	255.00	255.00
12	REAR END PANEL GARNISH CLIP @\$5.00	NOT NECESSARY	60.00	-
1	SPARE TYRE PANEL	CRUMPLED	1,385.00	1,225.10
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	265.00	-
	LESS 25% DISCOUNT		-2,770.28	-1,896.35
			8,310.82	5,689.05

Report Ref No. CC4/LPC19007031/Uea3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>SPECIAL NETT ITEMS</u>			
1	BOOT LID SEALANT (SN)	NECESSARY	80.00	50.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
1	SET SPARE TYRE PANEL RUBBER INSULATOR (SN)	NECESSARY	300.00	150.00
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	40.00	-
1	REAR WINDSCREEN INNER SEAL (SN)	NOT NECESSARY	80.00	-
			795.00	400.00
	<u>LABOUR</u>			
	TO TRANSFER REAR WINDSCREEN GLASS.	NOT NECESSARY	150.00	-
	TO CHECK WIRING AND LIGHT SYSTEM.		50.00	30.00
	APPLY BODY SEALANT TO CAR JOINTS.		180.00	50.00
	RE-SPRAY ANTI-RUST.		180.00	100.00
	CHECK FOR WATER LEAKAGE.	NOT NECESSARY	50.00	-
	INSTALL REVERSE SENSOR.		150.00	50.00
	TRANSFER BOOT LID PARTS.		150.00	60.00
	TO REMOVE /REFIX GARNISH TRIM SEAT SPEAKER BOARD AND ETC.		200.00	80.00
	TO DROP FUEL TANK TO FACILITATE REPAIR AND TO FIX BACK.		300.00	60.00
	TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL .REPAIR INNER PANEL,REWELD INNER PANEL ,REPLACE ACCIDENT DAMAGED .INCLUSIVE OF THE REPAIR OF BOOT LID HINGE AND N/S REAR FENDER .		1,200.00	1,150.00
	TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS.		1,400.00	1,100.00
			4,010.00	2,680.00
	GRAND TOTAL		13,115.82	8,769.05
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00

Report Ref No. CC4/LPC19007031/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.