

FALCON-AIR AUTO SERVICES PTE LTDCO. REG. NO.: 1995-01140-D
GST REG. NO.: 19-9501140-D**FALCON-AIR**LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04 THE CONCOURSE SINGAPORE 199555Attention : Motor Claim Department
Contact : (02) 6250 7388 Fax No. : 62963767

Estimate : ES707347

Date : 22/04/2019
Vehicle Num. : SJK 1054L
Make/Model : TOYOTA ALLION
Chassis/Eng# : NZT260-3025804
Accident Date : 18/04/2019
Claim No. :
Reference : 3PTY 1/2
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1 PC	BOOT LID		1,285.00 ✓
2.	2 PC	BOOT LID HINGE	175.00	350.00 ✓
3.	1 PC	BOOT LID ALLION EMBLEM		97.10 —
4.	1 PC	BOOT LID LOGO		90.80 —
5.	1 PC	BOOT LID A15 EMBLEM		89.60 —
6.	1 PC	BOOT LID CHROME MOULDING		290.00 —
7.	1 PC	BOOT LID INSULATOR		390.00 ✓
8.	12 PC	BOOT LID INSULATOR CLIP	5.00	60.00 ✓
9.	1 PC	BOOT LID LOCK	399.00	475.00 —
10.	1 PC	BOOT LID WEATHERSTRIP	125.00	290.00 —
11.	1 PC	REAR BUMPER		1,465.00 —
12.	2 PC	REAR BUMPER SIDE RETAINER	125.00	250.00 ✓
13.	12 PC	REAR BUMPER CLIPS	5.00	60.00 —
14.	1 PC	N/S REAR BUMPER REFLECTOR		97.60 —
15.	1 PC	N/S TAILLAMP		585.00 —
16.	2 PC	N/S TAILLAMP CLIP	10.00	20.00 ✓
17.	1 PC	N/S TAILLAMP PANEL		230.00 —
18.	1 PC	N/S TAILLAMP SPONGE		45.00 —
19.	1 PC	N/S REAR FENDER		1,120.00 ✓
20.	1 PC	N/S REAR FENDER INNER TRIM		585.00 —
21.	12 PC	N/S REAR FENDER INNER TRIM CLIPS	5.00	60.00 —
22.	1 PC	REAR END PANEL		985.00 —

CONTINUE / ...

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04 THE CONCOURSE SINGAPORE 199555

Attention : Motor Claim Department

Contact : (02) 6250 7388 Fax No. : 62963767

Estimate : ES707347

Date : 22/04/2019

Vehicle Num. : SJK 1054L

Make/Model : TOYOTA ALLION

Chassis/Eng# : NZT260-3025804

Accident Date : 18/04/2019

Claim No. :

Reference : 3PTY 1/2

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

23.	2 PC	REAR END PANEL BRACKET	98.00	196.00
24.	1 PC	REAR END PANEL GARNISH		255.00
25.	12PC	REAR END PANEL GARNISH CLIP	5.00	60.00
26.	1 PC	SPARE TYRE PANEL		1,385.00
27.	1 PC	REAR WINDSCREEN MOULDING		265.00

Handwritten notes: n/s rd, 1225.10, 117, 117, 117

List Total S\$:

25.00% Discount S\$:

11,081.10

2,770.28

8,310.82

SPECIAL NETT ITEMS :

1.	1 PC	BOOT LID SEALANT	80.00	80.00
2.	1 PC	REAR NUMBER PLATE	45.00	45.00
3.	1 PC set	REVERSE SENSOR	250.00	250.00
4.	1 PC set	SPARE TYRE PANEL RUBBER INSULATOR	300.00	300.00
5.	1 PC	REAR WINDSCREEN SEALANT	40.00	40.00
6.	1 PC	REAR WINDSCREEN INNER SEAL	80.00	80.00

Handwritten notes: rec, 117, 117, 117, 117, 117

Special Nett Total S\$:

795.00

LABOUR :

TO TRANSFER REAR WINDSCREEN GLASS
TO CHECK WIRING AND LIGHT SYSTEM

11 150.00
50.00

CONTINUE / ...

Handwritten calculations:
P-7585.4
257
5689.05
8769.05

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk I / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg



FALCON-AIR

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04 THE CONCOURSE SINGAPORE 199555

Attention : Motor Claim Department

Contact : (02) 6250 7388 Fax No. : 62963767

Estimate : ES707347

Date : 22/04/2019
Vehicle Num. : SJK 1054L
Make/Model : TOYOTA ALLION
Chassis/Eng# : NZT260-3025804
Accident Date : 18/04/2019
Claim No. :
Reference : 3PTY 1/2
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		APPLY BODY SEALANT TO CAR JOINTS	180.00	50
		RE-SPRAY ANTI-RUST	180.00	100
		CHECK FOR WATER LEAKAGE	50.00	X
		INSTALL REVERSE SENSOR	150.00	50
		TRANSFER BOOT LID PARTS	150.00	60
		TO REMOVE/REFIX GARNISH, TRIM, SEAT, SPEAKER BOARD AND ETC	200.00	80
		TO DROP FUEL TANK TO FACILIATE REPAIR AND TO FIX BACK	300.00	60
		TO REMOVE NECESSARY PARTS TO CUT OUT INNER PANEL, REPAIR	1,200.00	1150
		INNER PANEL, REWELD INNER PANEL, REPLACE ACCIDENT DAMAGED	1,400.00	1100
		TO PUTTY AND RESPRAY ACCIDENT DAMAGED AREAS		
		Labour Total S\$:		4,010.00

not Actual
LKK
L/S \$7000
7 hrs.

E. & O.E. Total S\$ 13,115.82

Take ph. After up
22/4/19

for FALCON-AIR AUTO SERVICES PTE LTD

(TAMPINES BRANCH)

- LKK Auto Corp to notify
the Repairer of
• To resurvey before writing
• To display damage for resurvey
• Parts prices are subject to quotation
• Third party survey on "No Prejudice" basis
• No illegal modification
• Supplementary survey resurveyed and
is subject to final insurance Company

Acknowledged by

Signature:

Date:

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare Singapore 575721 Tel: 6452-0880/6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No. 8 Pandan Loop (Blk 1 / Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110

Websites: www.falconair.com.sg E-mail: email@falconair.com.sg