

Thiam Heng Huat Pte Ltd

Block 176 Sin Ming Drive , Sin Ming Autocare

#05-14 Singapore 575721

Hp: 82636295 Fax: 62662881

Company Registration No: 201605960N

Estimate repair cost

GBG4389S DOA= 31-10-2018

Fiat Doblo

Chassis: ZFA2630006G87375

<u>Qty</u>	<u>Parts</u>		<u>List price</u>
1	Rear RH door "Professional" emblem	\$	120.00
1	Rear RH door "Fiat" emblem	\$	115.00
1	Rear LH door "Doblo" emblem	\$	110.00
1	Rear LH door "Maxi" emblem	\$	110.00
1	Rear LH door "90" emblem	\$	100.00
1	Rear LH door "Multijet" emblem	\$	120.00
1	Rear door frame weatherstrip	\$	380.00
1	Rear bumper	\$	720.00
1	Rear bumper step garnish	\$	240.00
1set	Rear bumper clips	\$	60.00
1	Rear bumper RH side reflector	\$	50.00
1	Rear bumper LH side reflector	\$	50.00
1	Rear bumper RH tow cover	\$	65.00
1	Rear bumper RH side retainer	\$	65.00
1	Rear bumper LH side retainer	\$	65.00
1	Rear bumper reinforcement	\$	420.00
1	End panel	\$	580.00
		\$	3,370.00
 <u>Special Nett</u>			
1	Rear RH door "6pax" sticker	\$	15.00
1	Rear LH door "70km/h" sticker	\$	15.00
1set	Rear bumper reverse sensor	\$	280.00

Labour and Misc charges

<i>Labour charges on affected areas</i>	\$	800.00
<i>Putty and respray affected areas</i>	\$	1,000.00
<i>Check wiring and lighting system</i>	\$	50.00
<i>Apply rust proofing on replaced and repaired panels</i>	\$	60.00
<i>Remove and replace rear inner trims and garnish</i>	\$	200.00
<i>Remove and replace rear bumper reverse sensor and wire harness</i>	\$	80.00
	\$	5,870.00