

ASS. REC. BY:

REF: CS/II 19007054K2d3 9

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person):

Gabriel Wee

of III

Date/Time:

22.4.19 4.10p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLM 3162K

Insured:

SHC 1661A

at Workshop m/s

E M Siewson

Tel:

9101 8302

of

160 sin ming Drive, #03-18/19

Policy No:

MCOH0015

Claim No:

MCT 19040548

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

18.4.2019

CA / REV / REP. / REV 24 HRS

23/4/19

H.O.D. Endorsement:

Date/Time:

22.4.19 4.50p.m

Person Contacted:

Bernard

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLM 3162K - X
	SHC 1661A - X
09/5/19 @ 3.17pm	confirmed with Bernard LS # 6200, 7 days.
	(Red @ 8409.60, 58%)

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 22 April 2019 4:10 PM
To: Sally Chong; 'sur@lkkauto.com'; Admin-D (LKKAuto)
Cc: Zuhaidah Samsuri
Subject: RE: OUR REF.: E21-110236.19 (SLM 3162K @ 18/4/2019) III'S REF NO : SHC 1661A

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLM3162K and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building
Singapore 049711
Tel: 6347 6100, Ext - 248

From: Sally Chong [mailto:sallychong@visionlawllc.com]
Sent: 22 April, 2019 1:26 PM
To: Motor Claim - III <motorclaim@iii.com.sg>
Cc: 'Judy Soh' <judysoh@visionlawllc.com>; EM Solution Pte Ltd <emautosolution@singnet.com.sg>; Tanvin13@yahoo.com.sg; derekkeh@singnet.com.sg
Subject: OUR REF.: E21-110236.19 (SLM 3162K @ 18/4/2019) III'S REF NO : SHC 1661A
Importance: High

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES
CLAIMANT: I N H BUS TRANSPORT SERVICE
ACCIDENT INVOLVING SLM 3162 K & SHC 1661A ON 18 APRIL 2019 ALONG PIE TOWARDS JURONG BEFORE STEVEN ROAD EXIT AT ABOUT 16:30 HRS

Thank you for your email of even date below with your list of surveyors.

Our client confirms the appointment of LKK Auto Consultants Pte Ltd - Kenneth Kong as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

Venue	:	E M SOLUTION PTE LTD 160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722
Contact	:	Mr. Bernard (Tel.: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

Sally Chong

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Monday, 22 April, 2019 9:58 AM

To: Judy Soh

Subject: RE: OUR REF.: E21-MISC.19 (SLM 3162K @ 18/4/2019) IIT'S REF NO : SHC 1661A

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,
Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext - 248

From: Judy Soh [mailto:judysoh@visionlawllc.com]
Sent: 20 April, 2019 11:50 AM
To: Motor Claim - III <motorclaim@iii.com.sg>; Gabriel Wee <Gabriel@iii.com.sg>
Cc: 'EM Solution Pte Ltd' <emautosolution@singnet.com.sg>; Andrew Lim <Andrew@iii.com.sg>; sallychong@visionlawllc.com; C Meenachi - III <Meenachi@iii.com.sg>
Subject: OUR REF.: E21-MISC.19 (SLM 3162K @ 18/4/2019) III'S REF NO : SHC 1661A
Importance: High

VERY URGENT

Dear Sir,

NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES
CLAIMANT: I N H BUS TRANSPORT SERVICE
ACCIDENT INVOLVING SLM 3162 K & SHC 1661A ON 18 APRIL 2019 ALONG PIE TOWARDS JURONG BEFORE STEVEN ROAD EXIT AT ABOUT 16:30 HRS

We are instructed by **I N H BUS TRANSPORT SERVICE** to notify you of a road traffic accident **ON 18 APRIL 2019 ALONG PIE TOWARDS JURONG BEFORE STEVEN ROAD EXIT AT ABOUT 16:30 HRS** involving our client's vehicle registration number **SLM 3162K** and vehicle registration number **SHC 1661A** driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

Judy Soh

VISION LAW LLC
133 NEW BRIDGE ROAD,
#18-01/02, CHINATOWN POINT,
SINGAPORE 059413
TEL.: 6534-2811 (ext 147)
FAX : 6535-6802

C.c. VEHICLE OWNER OF SHC 1661A
COMFORT TRANSPORTATION PTE LTD
383 Sin Ming Drive
GAS Building
Singapore 575717

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Head Office: 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

Branch: 490 Lorong 6 Toa Payoh #03-11 HDB Hub (Biz 3 Lobby 1), Singapore 310490

DISCLAIMER:

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email

by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any

person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email

transmission or any illegal or unauthorised usage or tampering of its email system.

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Shiau Chan (LKKAUTO)

From: EM Auto <emautosolution@singnet.com.sg>
Sent: Thursday, 9 May 2019 3:17 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: TP VEHICLE SLM 3162K (DOA: 18/04/2019)

Hi Shiau Chan,

Ok Accept

Thanks & regards,

Bernard

HP: 91018302

From: Shiau Chan (LKKAUTO) [mailto:siewsc@lkkauto.com]
Sent: Thursday, 9 May, 2019 2:59 PM
To: EM Auto <emautosolution@singnet.com.sg>; tanvin13@yahoo.com.sg
Cc: SUR <sur@lkkauto.com>
Subject: RE: TP VEHICLE SLM 3162K (DOA: 18/04/2019)

Dear Sir/Madam,

Re-send.

WITHOUT PREJUDICE

Offer Lump Sum \$6,200.00 and 7 repair days

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 25 April 2019 3:12 PM
To: EM Auto <emautosolution@singnet.com.sg>
Cc: tanvin13@yahoo.com.sg; SUR <sur@lkkauto.com>
Subject: TP VEHICLE SLM 3162K (DOA: 18/04/2019)

Dear Bernard,

WITHOUT PREJUDICE

Offer Lump Sum \$6,200.00 and 7 repair days

10 Sin Ming Drive Singapore 575701
www.lta.gov.sg

22 Apr 2019

Our ref 2204190901N036129196

IN H BUS TRANSPORT SERVICE
9 SIN MING INDUSTRIAL EST SECTOR C
#01-44 SIN MING INDUSTRIAL ESTATE
SINGAPORE 575644



Dear MISS TAN JIA HUI

RENEWAL OF CERTIFICATE OF ENTITLEMENT (COE) FOR VEHICLE NO. SLM3162K

We refer to your application on 22 Apr 2019 to renew COE for the above vehicle.

2. You may be pleased to know that the COE for this vehicle has been renewed until 30 Apr 2029.
3. The road tax for this vehicle will expire/has expired on 03 May 2019. Please renew the road tax promptly as it is an offence to use or keep a vehicle without valid road tax and insurance. Late renewal fee will be imposed if road tax is renewed after its expiry.
4. Please visit www.onemotoring.com.sg for more vehicle-related information and services or contact our customer service officers on tel: 1800-CALL LTA (1800-2255 582) if you have any questions.

Yours sincerely

Ng Lay Choo (Ms)
Deputy Director, VRL Service Operations
Vehicle Services Group
Land Transport Authority

[This letter is computer-generated, no signature is required.]

From 01 Jun 2019, your hardcopy letters will be replaced with SMSes and e-letters in your OneMotoring inbox. Hardcopy letters will only be sent for letters mandated by law, such as summonses. If you wish to continue receiving hardcopy letters, please notify LTA by 31 May 2019 by logging in to www.onemotoring.com.sg using your SingPass/CorpPass.



SINGAPORE POLICE FORCE



T/20190418/2166

1 of 3

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

Report No. T/20190418/2166

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 18/04/2019 20:17		Vide Report No.:		Station Diary No.: 37	
Informant's Particulars					
Name of Informant: KHOO CHENG KIAT			Address: APT BLK 20 LORONG 7 TOA PAYOH #11-742 SINGAPORE 310020		
ID Type / ID No.: NRIC NO / S13205011			Contact No.: Home/Office: Mobile: 92393296		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 61	Date of Birth: 03/02/1958	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Private Hire Driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 18/04/2019 16:30	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE towards Jurong, Before Steven road exit				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHC1661A	Car					0
SLM3162K	Car					1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20190418/2166

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

2 of 3

Report No. T/20190418/2166

CONTINUATION OF REPORT

Driver			
Name	KHOO CHENG KIAT		ID No. S13205011
Related Vehicle	SLM3162K (Car)		Contact No. 92393296
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	18/04/2019	Date Discharge	18/04/2019
No. of Days granted Medical Leave	05	Degree of Injury	NIL

Brief Details.

On 18/04/2019 at about 4:23pm, I was driving my vehicle, SLM3162K along PIE at the 1st lane. Suddenly, one vehicle had engaged his brake which caused me to engage my brake. I then heard something collided onto my vehicle's rear. I then came out and realised one vehicle, SHC1661A collided onto my vehicle. No traffic police or ambulance attended to us. I had made a check with my passenger who informed that he felt some pain at his neck and back area. I wanted to get his details but he refused to provide. We had taken down the vehicle number of the vehicle involved in the accident and left the scene.

After going back home, I felt pain and sore at my neck and back area. I then went to seek medical treatment and was issued with a 5 days Medical Certificate.



**SINGAPORE
POLICE FORCE**



T/20190418/2166

Police Station Of Origin:
Kim Keat NPP
231 Lorong 8 Toa Payoh #01-186
SINGAPORE 310231
Tel No: 1800-2529999

3 of 3

Report No. T/20190418/2166

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Staff Sgt TAN MENG SENG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

18/04/2019 20:17

Officer In Charge Of Case:

TP / GIA /

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

Classification Of Case:

SN 064

Authentication Stamp
NP168



SIGNATURE

K9

E M SOLUTION PTE LTD

160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722

Tel: 64560226

Fax:

64584500

Registration No: 201016308K

I N H Bus Transport Service

23.04.2019

Not Authorized
L1 Rep @ 6200k
Recovery After Paint

REPAIR ESTIMATE FOR HONDA FREED - SLM 3162 K

7day

1 pc	rear bumper		R	656.20	✓
1 pc	rear bumper tow hood cover	32.20	SL	64.40	X
2 pcs	rear bumper side retainers	38.50	DI	77.00	✓
2 pcs	taillamps	459.20		918.40	✓
1 pc	tailgate		R	1,464.30	✓
1 pc	tailgate emblem		na	32.40	✓
1 pc	tailgate badge "Freed"		na	44.40	✓
2 pcs	tailgate number plate lamps	38.80	SL	77.60	X
1 pc	tailgate outer garnish		na	238.90	✓
1 pc	tailgate rubber		ad/SL	126.30	50% na 63.15% na
2 pcs	tailgate hinges	75.40	R	150.80	X
2 pcs	tailgate dampers	155.80	SL	311.60	X
1 pc	tailgate inner lock		na	245.80	✓
1 pc	tailgate lock catch		DI	39.90	✓
1 pc	tailgate wiper motor		SL	325.30	X
1 pc	tailgate glass moulding		na	95.40	✓
1 pc	tailgate inner trim		mg/na	284.80	✓
1 pc	tailgate inner handle		SL	75.20	X
1 pc	rear end panel - inner		R	461.80	✓
1 pc	rear end panel - outer		R	521.20	✓
1 pc	rear end panel top garnish		BU	133.40	✓
1 pc	rear exhaust silencer		R	708.50	✓
2 pcs	rear exhaust mounting	28.60	SL	57.20	X
1 pc	rear exhaust heat shield		R	75.20	✓
1 pc	boot panel		R	786.20	X
1 pc	boot panel cover		DI	192.10	✓
2 pcs	rear fenders	1,152.60	R	2,305.20	X
2 pcs	rear fenders inner trim	277.50		555.00	✓
				11,024.50	
		Less 20%		2,204.90	
				8,819.60	
1 pc	rear windscreen sealant		na	60.00	SN 40% na
2 pcs	rear fender 1/4 glass sealant		na	120.00	SN X
1 set	reverse sensors		na	270.00	SN 200% na
1 pc	boot panel insulation padding		na	280.00	SN X
1 pc	rear number plate		na	60.00	SN 40% na

1)	Check electrical wiring.	60.00	200
2)	Remove and refit rear windscreen.	150.00	1200
3)	Remove and refit rear fender 1/4 glass	200.00	X
4)	Remove out boot interior upholstery.	150.00	1000
5)	Repair accident damages and renew above parts.	1,980.00	9000
6)	Spray paint on accident affected portions.	1,980.00	10000
7)	To renew exhaust silencer	100.00	600
8)	Rust proofing on accident affected portions.	160.00	600
9)	Renew reverse sensor.	100.00	500
10)	Towing charges.	120.00	X
		\$ 14,609.60	

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Apr 2019 Edit Reg		22 Apr 2019 00:00 Edit Adj Rpt	S\$6,200.00 Edit Estimates	S\$6,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: - ID: -									
Main Claimant: -									
Vehicle Reg. No.: SLM3162K		Date of Loss: 18/04/2019 16:00 - :59 [119 Months and 17 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / MCT19040548		Policy/Cover Note No.: MCOM0015 (Comprehensive)							
Vehicle Reg. No. (Insured): SHC1661A		Policy No. (Claimant):							
		Excess:							
Repairer: E M Solution Pte Ltd (HQ) 160 Sin Ming Drive, #03-18, Sin Ming Autocity, 575722 Sin Ming - Tel: 64560226									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 02/05/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents


































*SLM3162K (MCT19040548)
[SHC1661A]

TP

Apr 18 2019 4:00PM

[-]

E M Solution Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
2	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
3	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
4	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
5	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
6	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
7	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
8	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
9	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
10	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
11	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
12	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
13	10/05/19 11:55	General View						Load JPG	<input checked="" type="checkbox"/>	
14	10/05/19 11:55	Chassis Number						Load JPG	<input checked="" type="checkbox"/>	
15	10/05/19 11:55	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>	
16	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
17	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
18	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
19	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
20	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
21	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
22	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
23	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
24	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
25	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
26	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
27	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
28	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
29	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
30	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
31	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
32	10/05/19 12:00	Reinspection Photo						Load JPG	<input checked="" type="checkbox"/>	
Documentation							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	India International Insurance Pte Ltd (HQ)						Thumbnail	Print	
1	23/04/19 08:23	Singapore Accident Statement						Load PDF		

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III19007053/KQD3Q2

Date: 14/05/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

MCOM0015

Claimant Vehicle No: SLM3162K

Insured Vehicle No:

SHC1661A

Date of Loss: 18/04/2019

Nature of Claim:

TP

Claim No: MCT19040548

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLM3162K

Make & Model: HONDA FREED HYBRID, 1.5 (A)

Engine No: HIDDEN

Reg. Date: 01/05/2009 (Man. Year: 2009)

Chassis No: GB31040488

Colour: Metallic Dark Blue

Odometer: 189792 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/50 R16

Rear Tyre Size: 205/50 R16

Front Left Side: Haida 6 mm

Rear Left Side: Nexen 8 mm

Front Right Side: Haida 6 mm

Rear Right Side: Nexen 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,609.60	5,516.91	4,092.69	42.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	2,310.00	2,690.00	53.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,609.60	7,826.91	6,782.69	46.43
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	14,609.60	6,200.00	8,409.60	57.56
+ GST 7.00/7.00% (S\$)	1,022.67	434.00	588.67	57.56
Nett Amount (S\$)	15,632.27	6,634.00	8,998.27	57.56

INSPECTION

Date of Assignment: 22/04/2019

Date Inspected: 22/04/2019 Inspected At:

E M Solution Pte Ltd (HQ)
160 Sin Ming Drive., #03-18, Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 May 2019)
Parts: M1-MPV	HONDA FREED HYBRID 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLM3162K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	656.20 FL	*656.20 FL
2	1		*REAR BUMPER TOW HOOK COVER	Serviceable	64.40 FL	*- FL
3	2		*REAR BUMPER SIDE RETAINERS	Distorted	77.00 FL	*77.00 FL
4	2		*TAILLAMPS	Mtg Cracked	918.40 FL	*918.40 FL
5	1		*TAILGATE	Bent	1,464.30 FL	*1,464.30 FL
6	1		*TAILGATE EMBLEM	Necessary	32.40 FL	*32.40 FL
7	1		*TAILGATE BADGE FREED	Necessary	44.40 FL	*44.40 FL
8	2		*TAILGATE NUMBER PLATE LAMPS	Serviceable	77.60 FL	*- FL
9	1		*TAILGATE OUTER GARNISH	Warped	238.90 FL	*238.90 FL
10	1		*TAILGATE RUBBER (50%)	Dented / Cut	101.04 FS	*63.15 FS
11	2		*TAILGATE HINGES	Repair	150.80 FL	*- FL
12	2		*TAILGATE DAMPERS	Serviceable	311.60 FL	*- FL
13	1		*TAILGATE INNER LOCK	Dented	245.80 FL	*245.80 FL
14	1		*TAILGATE LOCK CATCH	Distorted	39.90 FL	*39.90 FL
15	1		*TAILGATE WIPER MOTOR	Serviceable	325.30 FL	*- FL
16	1		*TAILGATE GLASS MOULDING	Necessary	95.40 FL	*95.40 FL
17	1		*TAILGATE INNER TRIM	Mtg Cracked	284.80 FL	*284.80 FL
18	1		*TAILGATE INNER HANDLE	Serviceable	75.20 FL	*- FL
19	1		*REAR END PANEL -INNER	Bent	461.80 FL	*461.80 FL
20	1		*REAR END PANEL -OUTER	Bent	521.20 FL	*521.20 FL
21	1		*REAR END PANEL TOP GARNISH	Buckled	133.40 FL	*133.40 FL
22	1		*REAR EXHAUST SILENCER	Bent	708.50 FL	*708.50 FL
23	2		*REAR EXHAUST MOUNTING	Serviceable	57.20 FL	*- FL
24	1		*REAR EXHAUST HEAT SHIELD	Bent	75.20 FL	*75.20 FL
25	1		*BOOT PANEL	Repair	786.20 FL	*- FL
26	1		*BOOT PANEL COVER	Dented	192.10 FL	*192.10 FL
27	2		*REAR FENDERS	Repair	2,305.20 FL	*- FL
28	1		*REAR FENDERS INNER TRIM	N/S Mtg Cracked	555.00 FL	*277.50 FL
29	1		*REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
30	1		*REAR FENDER 1/4 GLASS SEALANT	Not Necessary	120.00 FS	*- FS
31	1		*SET REVERSE SENSORS	Dented	270.00 FS	*200.00 FS
32	1		*BOOT PANEL INSULATION PADDING	Not Necessary	280.00 FS	*- FS
33	1		*REAR NUMBER PLATE	Cracked	60.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,789.24	6,810.35
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,179.64	1,293.44
Total Parts (\$\$)	9,609.60	5,516.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK ELECTRICAL WIRING	New	60.00	20.00
2	REMOVE AND REFIT REAR WINDSCREEN	New	150.00	120.00
3	REMOVE AND REFIT REAR FENDER 1/4 GLASS	New	200.00	0.00
4	REMOVE OUT BOOT INERIOR UPHOLSTERY	New	150.00	100.00
5	REPAIR ACCIDENT DAMAGES AND RENEW ABOVE PARTS	New	1,980.00	900.00
6	SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS	New	1,980.00	1,000.00
7	TO RENEW EXHAUST SILENCER	New	100.00	60.00
8	RUST PROOFING ON ACCIDENT AFFECTED PORTIONS	New	160.00	60.00
9	RENEW REVERSE SENSOR	New	100.00	50.00
10	TOWING CHARGES	New	120.00	0.00
Gross Labour Cost (S\$)			5,000.00	2,310.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >